

AD-A241 911



91-13443



SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER Appendix V to the O&M Manual Longview Lake	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Multiple-Purpose Project; Little Blue River Basin Little Blue River, Missouri Longview Lake Operation and Maintenance Manual; Appendix V Embankment Criteria and Performance Report	5. TYPE OF REPORT & PERIOD COVERED Embankment Criteria and Performance Report Sep 79 to Sep 90	
7. AUTHOR(s) Ms. Lori L. Lynch-Project Engineer Mr. Francke C. Walberg-Asst.Ch., Geotechnical Br. Mr. Robert G. Dimmitt-Ch., Dams & Foundations Sect.	6. PERFORMING ORG. REPORT NUMBER	
9. PERFORMING ORGANIZATION NAME AND ADDRESS Dams and Foundations Section (CEMRK-ED-GD) Geotechnical Branch (CEMRK-ED-G) U.S. Army Corps of Engineers, Kansas City District 601 E. 12th Street, Kansas City, MO 64106	8. CONTRACT OR GRANT NUMBER(s)	
11. CONTROLLING OFFICE NAME AND ADDRESS Civil Engineering Drafting Section (CEMRK-ED-CE) Computer Aided Drafting Branch (CEMRK-ED-C) U.S. Army Corps of Engineers, Kansas City District 601 E. 12th Street, Kansas City, MO 64106	10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS PB-2b and ER1110-2-1901 (31 Dec 1981)	
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office)	12. REPORT DATE November 1990	
	13. NUMBER OF PAGES 333	
	15. SECURITY CLASS. (of this report) UNCLASSIFIED	
	15a. DECLASSIFICATION/DOWNGRADING SCHEDULE	
16. DISTRIBUTION STATEMENT (of this Report) Distribution in Accordance with ER 1110-2-1901, Paragraph 8, dated 31 December 1981 Distribution Statement "A"		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES Control Determination: This report conforms to the intent of the exempt report categories as set forth in AR 335-15 and under the paragraphs 1-2y of the AR.		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number)		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) This report provides the significant design, construction and operational information which can be used by engineers to (1) familiarize themselves with the project (2) reevaluate the embankment in the event unsatisfactory performance occurs and (3) provide guidance for designing comparable future projects.		

DD FORM 1 JAN 73 1473

EDITION OF 1 NOV 65 IS OBSOLETE

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

**Best
Available
Copy**

CEMRD-EP-C (CECW-EP-W/8 May 91) (10-1-7a) 1st End
Mr. Galligan/sg/7306
SUBJECT: Longview Lake, Missouri, Embankment Criteria and
Performance Report

WHL
Frank
GD

DA, Missouri River Division, Corps of Engineers, P.O. Box 103,
Downtown Station, Omaha, Nebraska 68101-0103 16 MAY 1991

FOR Commander, Kansas City District, ATTN: CEMRK-ED-GD

1. For appropriate action.
2. Please note the requested 30-day suspense.

FOR THE COMMANDER:

JH *DeStefano*
JOSEPH J. GRASSO, P.E.
Acting Director, Engineering and
Planning Directorate

CEMRK-ED-GD (CECW-EP-W/8 May 91) 1110-2-1150a 2d End
Ms. Lynch/sj/FTS 867-5352
SUBJECT: Longview Lake Missouri, Embankment Criteria and
Performance Report

DA, Kansas City District, Corps of Engineers, 700 Federal
Building, Kansas City, Missouri 64106-2896 11 June 1991

21 JUN 1991

~~THRU Commander, Missouri River Division, ATTN: CEMRD-EP-C~~ JJC

FOR Commander, Directorate of Civil Works, ATTN: CECW-EP-W

The following are like-numbered responses to CECW-EP-W comments provided in the memorandum dated 8 May 1991 referenced in the 1st End to Longview Lake, Missouri, Embankment Criteria and Performance Report.

a. The impervious blanket was constructed on the upstream right abutment to control seepage at the abutment. The majority of the seepage was expected to occur through the highly jointed Bethany Falls limestone which exists on both abutments. An impervious blanket was required for the right abutment since the upstream bedrock was exposed. A clay blanket was not necessary for the left abutment because the upstream bedrock is covered with overburden which acts as a natural clay blanket. For a complete description of the operation and performance of the abutments see paragraphs 7-05, 9-01c, and 9-01d.

b. Excavation details and foundation treatment for the abutments are discussed in more detail in the Longview Lake Construction Foundation Report dated February 1986.

c. A banded riprap design was used on the upstream slope to minimize the amount of stone protection required. Flatter grassed slopes (1 on 50) were also used between the upstream riprap zones. The riprap extends from elevation 878 to 898 corresponding to the zone of most frequent pool level roughly the 10 year drawdown and 10 year flood and elevation 915 to 925. The information used to determine the stone protection zones is provided on plate 32.


d. Reference paragraph 8-04f. Construction details for the upstream impervious blanket are provided on plate 30.

CEMRK-ED-GD

SUBJECT: Longview Lake Missouri, Embankment Criteria and
Performance Report

e. The 10 abandoned open tube piezometers were cut off
slightly below the ground, filled with grout and capped.

FOR THE COMMANDER:


PAUL D. BARBER
Chief, Engineering Division

CECW-EP-W (CECW-EP-W/8 May 1991) 3rd End WALLACE/tf/(202)272-8890
SUBJECT: Longview Lake Missouri Embankment Criteria and Performance
Report


20 AUG 1991

HQ, U.S. Army Corps of Engineers, Washington, DC 20314-1000

FOR Commander, Missouri River Division, ATTN: CEMRD-EP-C

The responses provided in the preceding endorsement satisfactorily
response to the concerns set forth in the basic letter.

FOR THE DIRECTOR OF CIVIL WORKS:


JOHN A. MCPHERSON
Acting Chief, Engineering Division
Directorate of Civil Works

10

FOR Commander, Kansas City District, ATTN: CEMRK-ED-GD

FOR THE COMMANDER:

For Kenneth Lane
R. HARVE WIETHOP, P.E.
Chief, Cost & Gen. Engrg. Division
Engineering and Planning Directorate

[illegible]



DEPARTMENT OF THE ARMY
U.S. Army Corps of Engineers
WASHINGTON, D.C. 20314-1000

REPLY TO
ATTENTION OF:

CECW-EP-W


08 MAY 1991

MEMORANDUM FOR Commander Missouri River Division, ATTN: CEMRD-EP-C

SUBJECT: Longview Lake, Missouri, Embankment Criteria and
Performance Report

1. Reference memorandum CEMRK-ED-GD, 27 February 1991, subject as above with CEMRD-EP-C, 21 March 1991, first endorsement thereon.
2. The following comments on the subject report are furnished for action. Request response within 30 days as to the disposition of these comments.
3. Geotechnical concerns.
 - a. Paragraph 4-01.b. Documentation should be provided to confirm the need for the impervious blanket.
 - b. Paragraph 4-02.c. Design details respecting the abutment treatment should be provided.
 - c. Paragraph 4-04, subparagraph 4. Clarify what slope details were selected in order to minimize slope protection requirements.
 - d. Paragraph 5-02.c. Include construction details such as thickness, zones and filters for the upstream impervious blanket.
 - e. Paragraph 7.02.a. The abandonment procedures for the ten open tube piezometers should be provided.

FOR THE DIRECTOR OF CIVIL WORKS:


JOHN A. MOBERG
Acting Chief, Engineering Division
Directorate of Civil Works

OPERATION AND MAINTENANCE MANUAL
LONGVIEW LAKE
LITTLE BLUE RIVER, MISSOURI

APPENDIX V
EMBANKMENT CRITERIA AND PERFORMANCE REPORT

FEBRUARY 1991

DEPARTMENT OF THE ARMY
Kansas City District, Corps of Engineers
Kansas City, Missouri

OPERATION AND MAINTENANCE MANUAL
LONGVIEW LAKE
LITTLE BLUE RIVER BASIN
LITTLE BLUE RIVER, MISSOURI

APPENDIX V
EMBANKMENT CRITERIA AND
PERFORMANCE REPORT

TABLE OF CONTENT

<u>Paragraph</u>	<u>Title</u>	<u>Page</u>
	Pertinent Data	V-A
	CHAPTER 1	
	INTRODUCTION	
1-01	Purpose and Scope of Report	V-1-1
1-02	Project Purpose	V-1-1
1-03	Project Authorization	V-1-1
	CHAPTER 2	
	PROJECT DESCRIPTION	
2-01	Project Location	V-2-1
2-02	Dam Description	V-2-1
2-03	Spillway	V-2-1
2-04	Outlet Works	V-2-1
2-05	Construction History	V-2-1
2-06	Lake Filling	V-2-2
	CHAPTER 3	
	GEOLOGY	
3-01	Regional Geology and Physiography	V-3-1
3-02	Site Geology	V-3-1
3-03	Description of Overburden	V-3-1
3-04	Bedrock	V-3-1
3-05	Subsurface Investigation Prior to Construction	V-3-2
	CHAPTER 4	
	FOUNDATION AND EMBANKMENT	
4-01	General	V-4-1
4-02	Foundation Treatment	V-4-2
4-03	Embankment Materials	V-4-3
4-04	Stone Protection	V-4-6
4-05	Settlement	V-4-7

<u>Paragraph</u>	<u>Title</u>	<u>Page</u>
CHAPTER 5		
SEEPAGE CONTROL		
5-01	Through Seepage	V-5-1
5-02	Underseepage	V-5-1
CHAPTER 6		
SLOPE STABILITY		
6-01	General	V-6-1
6-02	Design Strength Testing	V-6-1
6-03	Selection of Design Strengths	V-6-2
6-04	Design Stability Analysis	V-6-3
6-05	Stage II Stability Analysis	V-6-4
CHAPTER 7		
INSTRUMENTATION		
7-01	General	V-7-1
7-02	Piezometers	V-7-1
7-03	Embankment Piezometric Devices	V-7-4
7-04	Foundation Piezometric Devices	V-7-5
7-05	Abutment Piezometric Devices	V-7-5
7-06	Inclinometers	V-7-6
7-07	Alignment Monuments	V-7-7
7-08	Foundation Settlement Plates	V-7-8
7-09	Crest Settlement Monuments	V-7-8
7-10	Top of Dam Profiles	V-7-9
CHAPTER 8		
CONSTRUCTION NOTES		
8-01	General	V-8-1
8-02	Stage I Contract	V-8-1
8-03	Stage I Embankment Analysis	V-8-9
8-04	Stage II Contract	V-8-10
8-05	Embankment Materials Inspection and Testing	V-8-15
CHAPTER 9		
OPERATIONAL NOTES		
9-01	Embankment	V-9-1
9-02	Emergency Rock Stockpile	V-9-2

ENCLOSURE

<u>Encl No.</u>	<u>Subject</u>
1	Analysis of Stage I Embankment
2	Gas Sample Analysis
3	Water Sample Analysis

PHOTOGRAPHS

<u>Photo No.</u>	<u>Title</u>
1.	March 1990. Overview of completed embankment.

CONSTRUCTION EQUIPMENT

2. 1983. Two Caterpillar D-9s loading Cat 631 scrapers in upstream valley borrow area.
3. 09 October 1981. Cat 5310 scraper.
4. 26 July 1983. Cat D-9H compacting haul road ramp with tandem sheepsfoot roller.
5. 10 July 1983. Compacting impervious fill around sump in cutoff trench with a "BARCO" gas powered compactor.
6. 06 July 1983. Spreader box mounted on a Cat D3 used for placing the 6-foot wide pervious drain.
7. June 1980. Raygo "Rascal" 410-A 5 ton vibratory roller used to compact pervious fill.
8. 07 June 1983. "Wacker" DVU4001 small vibratory plate compactor used to compact pervious fill in restricted areas.
9. 07 May 1981. Small 4 wheel "Wacker" vibratory roller.
10. 11 June 1981. Backhoe mounted vibratory plate used to compact pervious fill along the right side of the conduit.
11. 18 September 1981. Wheel rolling upstream cutoff trench contact with left abutment Sni-A-Bar Limestone with Cat 920 front end loader.
12. 18 July 1983. Record control sample being taken.

STAGE I EMBANKMENT CONSTRUCTION

13. 05 March 1980. Looking west at slide on left side of outlet works excavation. Slide occurred on 18 November 1979.
14. 29 May 1980. Curtain grouting in cutoff trench.
15. July 1980. Removal of unacceptably wet impervious fill material and excavation for placement of pervious on the downstream side of the cutoff trench.
16. July 1980. Impervious and pervious fill placed in cutoff trench against right abutment.
17. 21 July 1980. Outlet works ogee section and 45 degree bend of twin sewer conduits.
18. 14 August 1980. Stair stepped surface of heavily fractured Middle Creek limestone of right abutment after excavation and cleaning.
19. 14 August 1980. Placement of dental concrete and slush grout to seal the surface of Middle Creek limestone.
20. 21 October 1980. Overview of fill placement, conduit construction, and left abutment cutoff trench.

PHOTOGRAPHS

<u>Photo No.</u>	<u>Title</u>
21.	06 May 1981. Selective loading with rock rake of left abutment Sni-A-Bar limestone to make rockfill.
22.	21 May 1981. Overview of conduit backfill, fill placement, and right abutment from left abutment.
23.	21 July 1981. First lift of impervious fill being placed over pervious on upstream side of bend in twin sewer conduits at approximate outlet works station 54+00.
24.	18 September 1982. Left abutment and cutoff trench.
25.	21 October 1982. Downstream impervious stockpile.
26.	16 November 1982. Stage I embankment investigation. Lowering inspection casing into 30 inch diameter observation hole (OH).
27.	November 1982. Sample showing typical smooth surface texture, probably caused by pumping action of loaded scraper.
28.	November 1982. Sample showing typical raindrop-type texture, probably mechanically induced from construction equipment.
29.	November 1982. First wet area encountered in OH-1.
30.	November 1982. One foot above area in previous photo; exposed boundary layer with the upper material moist and seepage exiting from lower material.
31.	November 1982. Wet area encountered in OH-1.
32.	24 November 1982. End of Stage I construction. Aerial view of construction.
33.	24 November 1982. End of Stage I construction. Aerial view of construction.

STAGE II EMBANKMENT CONSTRUCTION

34. January 1983. Ignition of gas from PPE99-9.
35. 10 June 1983. Impervious blanket against upstream right abutment.
36. 17 June 1983. Completed outlet works and stilling basin.
37. 06 July 1983. Aerial view of embankment, cofferdam, and closure section construction.
38. 06 July 1983. Aerial view of embankment and closure section construction.
39. 09 July 1983. Cleanup of cutoff trench and impervious placement in closure section.
40. 12 July 1983. Pervious placed at downstream edge of cutoff trench in closure section.
41. 18 July 1983. View of closure section showing pervious placement at downstream side of cutoff trench and in old river and diversion channels.
42. 22 July 1983. Pervious blanket placed over old river channel in closure section.
43. September 1983. Closure section embankment construction.
44. 13 September 1983. Downstream right abutment.
45. 13 September 1983. Upstream right abutment.
46. 26 October 1983. Fill placement in closure section.
47. 24 May 1984. Rockfill in clay blanket area on upstream right abutment.

PHOTOGRAPHS

Photo No.

Title

48. May 1984. Aerial view of embankment after completion of closure section fill placement.
49. May 1984. Aerial view of embankment, east borrow and west borrow.
50. May 1984. Aerial view of borrow areas from south of the west borrow area.
51. 16 July 1984. Upstream and downstream random zone fill placement.
52. 18 September 1984. Upstream slope before final grading.
53. 26 November 1984. Downstream left abutment grouted gutter construction.
54. 25 March 1985. Front end loaders placing riprap on upstream face of embankment.
55. 26 March 1985. Dressing of riprap adjacent to bridge abutment using large backhoe.
56. 26 March 1985. Completed upstream slope protection.
57. 23 May 1985. Completed slope protection at crest of embankment.
58. September 1985. Completed upstream slope from tower bridge.
59. September 1985. Completed downstream right abutment.
60. 24 September 1985. Eight foot flat bottom toe ditch.
61. 24 September 1985. "Enka-mat" erosion control fabric lined ditch above grouted gutter on downstream left abutment.
62. 05 March 1986. Downstream right abutment contact showing cleared sewer line alignment at upper left.
63. 22 April 1986. Closed expansion joint and tilted rocker due to movement of tower bridge abutment.
64. April 1986. Crown crack and leakage along left wall at monolith joint between tower and conduit.
65. 19 May 1986. Installation of finger drains into pervious blanket at embankment toe.
66. 19 May 1986. Completed finger drain installation at embankment toe.
67. 10 July 1986. Completed french drain installed in upstream right abutment clay blanket to intercept seepage from limestone.
68. 18 July 1986. Aerial view of completed embankment.
69. 19 September 1986. Upstream slope protection with pool at multipurpose elevation 891.
70. 04 October 1986. Upstream slope with pool at elevation 897.
71. 07 April 1987. Left abutment slope protection with the pool at multipurpose elevation 891.
72. 07 April 1987. Completed upstream right abutment clay blanket area.
73. 19 September 1986. Downstream left abutment contact and stilling basin.
74. 07 April 1987. Completed downstream slope.
75. March 1990. Completed emergency rock stockpile on downstream left abutment.

LONGVIEW EMBANKMENT CRITERIA REPORT

PLATE LIST

<u>Plate No.</u>	<u>Title</u>	<u>File No.</u>
1	LOCATION AND VICINITY	RBL-3-1401
2	GENERAL PLAN	RBL-3-1402
3	PLAN OF EXPLORATION BORINGS AND PROFILE LINES	RBL-3-1403
4	DAM SITE AREA PLAN OF EXPLORATION	RBL-3-1404
5	OUTLET WORKS PLAN OF EXPLORATION	RBL-3-1405
6	GENERAL GEOLOGIC COLUMN AND LEGEND	RBL-3-1406
7	PROFILE ALONG DAM AXIS: LOGS OF EXPLORATIONS	RBL-3-1407
8	OUTLET WORKS, APPROACH, & OUTLET CHANNELS LOGS AND PLAN OF EXPLORATIONS	RBL-3-1408
9	OUTLET WORKS, APPROACH, & OUTLET CHANNELS GEOLOGIC SECTIONS AND DETACHED BORINGS	RBL-3-1409
10	SPILLWAY PROFILE AND SECTIONS	RBL-3-1410
11	GENERAL PLAN OF EXCAVATION	RBL-3-1411
12	OUTLET WORKS, PLAN OF EXCAVATION	RBL-3-1412
13	APPROACH STRUCTURES EXCAVATION, PLAN, PROFILE, AND SECTIONS	RBL-3-1413
14	CURTAIN GROUTING PLAN AND PROFILE RIGHT ABUTMENT	RBL-3-1414
15	CURTAIN GROUTING PLAN AND PROFILE VALLEY AND CONDUIT FOUNDATION	RBL-3-1415
16	CURTAIN GROUTING PLAN AND PROFILE LEFT ABUTMENT	RBL-3-1416
17	EMBANKMENT AT COMPLETION OF STAGE I	RBL-3-1417
18	LEFT ABUTMENT AND EMBANKMENT TOPOGRAPHY	RBL-3-1418
19	DIVERSION AND CLOSURE: PLANS AND SECTIONS	RBL-3-1419
20	EMBANKMENT PLAN AND ALIGNMENT DATA	RBL-3-1420
21	DAM AXIS PROFILE AND MISC SECTIONS AND DETAILS	RBL-3-1421
22	TYPICAL EMBANKMENT SECTIONS 1 OF 4	RBL-3-1422
23	TYPICAL EMBANKMENT SECTIONS 2 OF 4	RBL-3-1423
24	TYPICAL EMBANKMENT SECTIONS 3 OF 4	RBL-3-1424
25	TYPICAL EMBANKMENT SECTIONS 4 OF 4	RBL-3-1425
26	TOP OF DAM AND SLOPE PROTECTION DETAILS	RBL-3-1426
27	EMBANKMENT DRAINAGE SCHEDULE SECTIONS, & DETAILS	RBL-3-1427
28	STILLING BASIN: PLAN, PROFILE, SECTIONS AND DETAILS	RBL-3-1428
29	RIGHT ABUTMENT SECTION AND PLAN OF EXCAVATION	RBL-3-1429
30	RIGHT ABUTMENT UPSTREAM IMPERVIOUS CLAY BLANKET PLAN AND SECTIONS	RBL-3-1430
31	ELM AVENUE DIKE, ACCESS LANE AND PIPE GATE DETAILS	RBL-3-1431
32	SLOPE PROTECTION STUDY	RBL-3-1432
33	SERVICE BRIDGE PLAN AND ELEVATION	RBL-3-1433
34	SERVICE BRIDGE MISCELLANEOUS DETAILS	RBL-3-1434
34A	SERVICE BRIDGE ALTERATIONS	RBL-3-1701

PLATE LIST CONT'D

<u>Plate No.</u>	<u>Title</u>	<u>File No.</u>
35	OBSERVATION DEVICES PLAN AND SCHEDULE 1 OF 2	RBL-3-1435
36	OBSERVATION DEVICES: PLAN AND SCHEDULE 2 OF 2	RBL-3-1436
37	INSTRUMENTATION CROSS SECTIONS 1 OF 5	RBL-3-1437
38	INSTRUMENTATION CROSS SECTIONS 2 OF 5	RBL-3-1438
39	INSTRUMENTATION CROSS SECTIONS 3 OF 5	RBL-3-1439
40	INSTRUMENTATION CROSS SECTIONS 4 OF 5	RBL-3-1440
41	INSTRUMENTATION CROSS SECTIONS 5 OF 5	RBL-3-1441
42	INSTRUMENTATION INSTALLATION DETAILS 1 OF 2	RBL-3-1442
43	EMBANKMENT OBSERVATION DEVICES: INSTALLATION DETAILS 2 OF 2	RBL-3-1443
43A	INCLINOMETER DETAILS	RBL-3-1696
44	PORE PRESSURE CONTOURS (JANUARY 1987) POOL ELEVATION 891.2	RBL-3-1444
45	PRECIPITATION AND LAKE FILLING RATE	RBL-3-1445
46	LIQUID LIMIT ZONE CROSS SECTIONS	RBL-3-1446
47	PLAN OF RECORD CONTROL SAMPLE LOCATIONS	RBL-3-1447
48	PROFILE OF RECORD CONTROL SAMPLE LOCATIONS	RBL-3-1448
49	PLAN OF BORING SAMPLE LOCATIONS	RBL-3-1449
50	RECORD CONTROL SAMPLE SCHEDULE	RBL-3-1450
51	LABORATORY SOILS TESTING LOG	RBL-3-1451
52	TEST DATA SUMMARIES LIQUID LIMIT 55 IMPERVIOUS ZONE STAGE I	RBL-3-1452
53	TEST DATA SUMMARIES LIQUID LIMIT 55 IMPERVIOUS ZONE STAGE I	RBL-3-1453
54	SHEAR TEST SUMMARIES LIQUID LIMIT 55 IMPERVIOUS ZONE STAGE I	RBL-3-1454
55	TEST DATA SUMMARIES LIQUID LIMIT 55 IMPERVIOUS ZONE STAGE II	RBL-3-1455
56	SHEAR TEST SUMMARIES LIQUID LIMIT 55 IMPERVIOUS ZONE STAGE II	RBL-3-1456
57	TEST DATA SUMMARIES LIQUID LIMIT 60 RANDOM ZONE STAGE I	RBL-3-1457
58	SHEAR TEST SUMMARIES LIQUID LIMIT 60 RANDOM ZONE STAGE I	RBL-3-1458
59	TEST DATA SUMMARIES LIQUID LIMIT 60 IMPERVIOUS ZONE STAGE II	RBL-3-1459
60	SHEAR TEST SUMMARIES LIQUID LIMIT 60 IMPERVIOUS ZONE STAGE II	RBL-3-1460
61	TEST DATA SUMMARIES LIQUID LIMIT 60 RANDOM ZONE STAGE II	RBL-3-1461
62	SHEAR TEST SUMMARIES LIQUID LIMIT 60 RANDOM ZONE STAGE II	RBL-3-1462
63	TEST DATA SUMMARIES LIQUID LIMIT 65 IMPERVIOUS ZONE STAGE II	RBL-3-1463
64	SHEAR TEST SUMMARIES LIQUID LIMIT 65 IMPERVIOUS ZONE STAGE II	RBL-3-1464

PLATE LIST CONT'D

<u>Plate No.</u>	<u>Title</u>	<u>File No.</u>
65	TEST DATA SUMMARIES LIQUID LIMIT 65 RANDOM ZONE STAGE II	RBL-3-1465
66	SHEAR TEST SUMMARIES LIQUID LIMIT 65 RANDOM ZONE STAGE II	RBL-3-1466
67	TEST DATA SUMMARIES LIQUID LIMIT 70 RANDOM ZONE STAGE II	RBL-3-1467
68	SHEAR TEST SUMMARIES LIQUID LIMIT 70 RANDOM ZONE STAGE IIR	BL-3-1468
69	TEST DATA SUMMARIES UNSPECIFIED LIQUID LIMIT BERM ZONE STAGE II	RBL-3-1469
70	SHEAR TEST SUMMARIES UNSPECIFIED LIQUID LIMIT BERM ZONE STAGE II	RBL-3-1470
71	LIQUID LIMIT 55 IMPERVIOUS ZONE STAGE I DENSITY AND COMPACTION TEST SUMMARIES	RBL-3-1471
72	LIQUID LIMIT 55 IMPERVIOUS ZONE STAGE II DENSITY AND COMPACTION TEST SUMMARIES	RBL-3-1472
73	LIQUID LIMIT 60 IMPERVIOUS ZONE STAGE II DENSITY AND COMPACTION TEST SUMMARIES	RBL-3-1473
74	LIQUID LIMIT 60 RANDOM ZONE STAGES I AND II DENSITY AND COMPACTION TEST SUMMARIES	RBL-3-1474
75	LIQUID LIMIT 65 IMPERVIOUS ZONE STAGE II DENSITY AND COMPACTION TEST SUMMARIES	RBL-3-1475
76	LIQUID LIMIT 65 RANDOM ZONE STAGE II DENSITY AND COMPACTION TEST SUMMARIES	RBL-3-1476
77	LIQUID LIMIT 70 RANDOM ZONE STAGE II DENSITY AND COMPACTION TEST SUMMARIES	RBL-3-1477
78	BERM ZONE (NO SPECIFIED LIQUID LIMIT) STAGE II DENSITY AND COMPACTION TEST SUMMARIES	RBL-3-1478
79	COMPACTION TEST SUMMARIES STAGE I	RBL-3-1479
80	COMPACTION TEST SUMMARIES STAGE I	RBL-3-1480
81	COMPACTION TEST SUMMAIRES STAGE I	RBL-3-1481
82	COMPACTION TEST SUMMARIES STAGE I	RBL-3-1482
83	COMPACTION TEST DATA SUMMARY STAGE II	RBL-3-1483
84	COMPACTION TEST SUMMARIES STAGE II	RBL-3-1484
85	COMPACTION TEST SUMMARIES STAGE II	RBL-3-1485
86	DERIVATION OF STABILITY EQUATIONS	RBL-3-1564
86A	TEST DATA SUMMARY COMPACTED EMBANKMENT MATERIAL Q-TESTS AND ATTERBERG LIMIT TESTS	RBL-3-1686
86B	TEST DATA SUMMARY COMPACTED EMBANKMENT MATERIAL R-TESTS AND ATTERBERG LIMIT TESTS	RBL-3-1687
86C	TEST DATA SUMMARY COMPACTED EMBANKMENT MATERIAL S-TESTS AND ATTERBERG LIMIT TESTS	RBL-3-1688
86D	TEST DATA SUMMARY COMPACTED EMBANKMENT COMPACTION CURVES GRADATIONS AND ACTIVITY DATA	RBL-3-1689

PLATE LIST CONT'D

<u>Plate No.</u>	<u>Title</u>	<u>File No.</u>
86E	TEST DATA SUMMARY UNDISTURBED FOUNDATION OVERBURDEN Q-TESTS	RBL-3-1690
86F	TEST DATA SUMMARY UNDISTURBED FOUNDATION OVERBURDEN R-TESTS	RBL-3-1691
86G	TEST DATA SUMMARY UNDISTURBED FOUNDATION OVERBURDEN S-TESTS DATA	RBL-3-1692
86H	TEST DATA SUMMARY UNDISTURBED FOUNDATION OVERBURDEN S-TEST, PLOTS	RBL-3-1693
86I	TEST DATA SUMMARY FOUNDATION OVERBURDEN CONSOLIDATION TESTS	RBL-3-1694
86J	TEST DATA SUMMARY FOUNDATION SHALES	RBL-3-1695
87	TYPICAL STABILITY ANALYSIS END OF CONSTRUCTION AND PARTIAL POOL CASE	RBL-3-1565
88	TYPICAL STABILITY ANALYSIS RAPID DRAWDOWN AND STEADY SEEPAGE	RBL-3-1566
89	EMBANKMENT STABILITY ANALYSIS SUMMARY VALLEY SECTION	RBL-3-1567
90	EMBANKMENT STABILITY ANALYSIS SUMMARY CONDUIT SECTION	RBL-3-1568
91	EMBANKMENT STABILITY ANALYSIS SUMMARY COFFERDAM	RBL-3-1569
92	STAGE II EMBANKMENT STABILITY ANALYSIS SUMMARY CONDUIT SECTION	RBL-3-1486
93	EMBANKMENT MATERIAL PLACEMENT REQUIREMENTS AND QUANTITIES	RBL-3-1487
94	TOP OF DAM PROFILE PLOTS	RBL-3-1570
95	CREST SETTLEMENT MONUMENTS PLOTS	RBL-3-1571
96	CREST SETTLEMENT MONUMENTS PLOTS	RBL-3-1572
97	SETTLEMENT PLATE DATA PLOTS SPPF 91-1 AND SPPF 93-7	RBL-3-1573
98	ALIGNMENT MONUMENT HORIZONTAL PROFILE ORIGINAL SURVEY BASE LINES LINES "A" AND "B" SUMMARY	RBL-3-1574
99	ALIGNMENT MONUMENTS HORIZONTAL AND VERTICAL DATA PLOTS MONUMENTS A-4, A-5, AND A-6	RBL-3-1575
100	ALIGNMENT MONUMENTS HORIZONTAL AND VERTICAL DATA PLOTS MONUMENTS B-1, B-2, AND B-3	RBL-3-1576
101	PIEZOMETER PLOTS OPEN TUBE PZ PPF 84-1	RBL-3-1577
102	PIEZOMETER PLOTS OPEN TUBE PZ PPF 86-1A	RBL-3-1578
103	PIEZOMETER PLOTS OPEN TUBE PZ PPF 87-3	RBL-3-1579
104	PIEZOMETER PLOTS OPEN TUBE PZ PPF 88-2	RBL-3-1580
105	PIEZOMETER PLOTS OPEN TUBE PZ PPF 88-3	RBL-3-1581
106	PIEZOMETER PLOTS OPEN TUBE PZ PZE 90-2	RBL-3-1582
107	PIEZOMETER PLOTS OPEN TUBE PZ PPE 92-1 1 OF 2	RBL-3-1583
108	PIEZOMETER PLOTS OPEN TUBE PZ PPE 92-1 2 OF 2	RBL-3-1584
109	PIEZOMETER PLOT 2" OPEN TUBE PVC PPE 92-2 1 OF 2	RBL-3-1585

PLATE LIST CONT'D

<u>Plate No.</u>	<u>Title</u>	<u>File No.</u>
110	PIEZOMETER PLOT 2" OPEN TUBE PVC PPE 92-2 2 OF 2	RBL-3-1586
111	PIEZOMETER PLOTS PNEUMATIC PZ PPE 94-1 1 OF 2	RBL-3-1587
112	PIEZOMETER PLOTS PNEUMATIC PZ PPE 94-1 2 OF 2	RBL-3-1588
113	PIEZOMETER PLOTS OPEN TUBE PZ PPF 99-3 2 OF 2	RBL-3-1589
114	PIEZOMETER PLOTS OPEN TUBE PZ PPF 99-4 1 OF 2	RBL-3-1590
115	PIEZOMETER PLOTS OPEN TUBE PZ PPF 99-4 2 OF 2	RBL-3-1680
116	PIEZOMETER PLOTS PNEUMATIC PZ PPE 99-8 1 OF 2	RBL-3-1681
117	PIEZOMETER PLOTS PNEUMATIC PZ PPE 99-8 2 OF 2	RBL-3-1682
118	PIEZOMETER PLOTS PNEUMATIC PZ PPE 99-11 1 OF 2	RBL-3-1683
119	PIEZOMETER PLOTS PNEUMATIC PZ PPE 99-11 2 OF 2	RBL-3-1684
120	PIEZOMETER PLOTS OPEN TUBE PZ W-6	RBL-3-1685
121	INCLINOMETER DISPLACEMENTS I-99-1	RBL-3-1697
122	INCLINOMETER DATA PLOTS I-99-1 AND I-99-2	RBL-3-1698
123	INCLINOMETER DISPLACEMENTS I-99-3	RBL-3-1699
124	INCLINOMETER DATA PLOTS I-99-3 AND I-97-1	RBL-3-1700

SUPPLEMENT A

<u>Plate No.</u>	<u>Title</u>	<u>File No.</u>
A1	LL 55 IMPERVIOUS STAGE I RECORD CONTROL R, R, AND GRADATION TESTS - 1 OF 16	RBL-3-1488
A2	LL 55 IMPERVIOUS STAGE I RECORD CONTROL R, R, AND GRADATION TESTS - 2 OF 16	RBL-3-1489
A3	LL 55 IMPERVIOUS STAGE I RECORD CONTROL R, R, AND GRADATION TESTS - 3 OF 16	RBL-3-1490
A4	LL 55 IMPERVIOUS STAGE I RECORD CONTROL R, R, AND GRADATION TESTS - 4 OF 16	RBL-3-1491
A5	LL 55 IMPERVIOUS STAGE I RECORD CONTROL R, R, AND GRADATION TESTS - 5 OF 16	RBL-3-1492
A6	LL 55 IMPERVIOUS STAGE I RECORD CONTROL R, R, AND GRADATION TESTS - 6 OF 16	RBL-3-1493
A7	LL 55 IMPERVIOUS STAGE I RECORD CONTROL R, R, AND GRADATION TESTS - 7 OF 16	RBL-3-1494
A8	LL 55 IMPERVIOUS STAGE I RECORD CONTROL R, R, AND GRADATION TESTS - 8 OF 16	RBL-3-1495
A9	LL 55 IMPERVIOUS STAGE I RECORD CONTROL R, R, AND GRADATION TESTS - 9 OF 16	RBL-3-1496

SUPPLEMENT A

<u>Plate No.</u>	<u>Title</u>	<u>File No.</u>
A10	LL 55 IMPERVIOUS STAGE I RECORD CONTROL R̄, R, AND GRADATION TESTS - 10 OF 16	RBL-3-1497
A11	LL 55 IMPERVIOUS STAGE I RECORD CONTROL R̄, R, AND GRADATION TESTS - 11 OF 16	RBL-3-1498
A12	LL 55 IMPERVIOUS STAGE I RECORD CONTROL R̄, R, AND GRADATION TESTS - 12 OF 16	RBL-3-1499
A13	LL 55 IMPERVIOUS STAGE I RECORD CONTROL R̄, R, AND GRADATION TESTS - 13 OF 16	RBL-3-1500
A14	LL 55 IMPERVIOUS STAGE I RECORD CONTROL R̄, R, AND GRADATION TESTS - 14 OF 16	RBL-3-1501
A15	LL 55 IMPERVIOUS STAGE I RECORD CONTROL R̄, R, AND GRADATION TESTS - 15 OF 16	RBL-3-1502
A16	LL 55 IMPERVIOUS STAGE I RECORD CONTROL R̄, R, AND GRADATION TESTS - 16 OF 16	RBL-3-1503
A17	LL 55 IMPERVIOUS STAGE II RECORD CONTROL R̄, R, AND GRADATION TESTS - 1 OF 3	RBL-3-1504
A18	LL 55 IMPERVIOUS STAGE II RECORD CONTROL R̄, R, AND GRADATION TESTS - 2 OF 3	RBL-3-1505
A19	LL 55 IMPERVIOUS STAGE II RECORD CONTROL R̄, R, AND GRADATION TESTS - 3 OF 3	RBL-3-1506
A20	LL 60 RANDOM STAGE I RECORD CONTROL R̄, R, AND GRADATION TESTS	RBL-3-1507
A21	LL 60 IMPERVIOUS STAGE II RECORD CONTROL R̄, R, AND GRADATION TESTS - 1 OF 3	RBL-3-1508
A22	LL 60 IMPERVIOUS STAGE II RECORD CONTROL R̄, R, AND GRADATION TESTS - 2 OF 3	RBL-3-1509
A23	LL 60 IMPERVIOUS STAGE II RECORD CONTROL R̄, R, AND GRADATION TESTS - 3 OF 3	RBL-3-1510
A24	LL 60 RANDOM STAGE II RECORD CONTROL R, R̄, AND GRADATION TESTS - 1 OF 4	RBL-3-1511
A25	LL 60 RANDOM STAGE II RECORD CONTROL R, R̄, AND GRADATION TESTS - 2 OF 4	RBL-3-1512
A26	LL 60 RANDOM STAGE II RECORD CONTROL R, R̄, AND GRADATION TESTS - 3 OF 4	RBL-3-1513
A27	LL 60 RANDOM STAGE II RECORD CONTROL R̄, R, AND GRADATION TESTS - 4 OF 4	RBL-3-1514
A28	LL 65 IMPERVIOUS STAGE II RECORD CONTROL R̄, R, AND GRADATION TESTS - 1 OF 5	RBL-3-1515
A29	LL 65 IMPERVIOUS STAGE II RECORD CONTROL R̄, R, AND GRADATION TESTS - 2 OF 5	RBL-3-1516
A30	LL 65 IMPERVIOUS STAGE II RECORD CONTROL R̄, R, AND GRADATION TESTS - 3 OF 5	RBL-3-1517
A31	LL 65 IMPERVIOUS STAGE II RECORD CONTROL R̄, R, AND GRADATION TESTS - 4 OF 5	RBL-3-1518
A32	LL 65 IMPERVIOUS STAGE II RECORD CONTROL R̄, R, AND GRADATION TESTS - 5 OF 5	RBL-3-1519
A33	LL 65 RANDOM STAGE II RECORD CONTROL R̄, R, AND GRADATION TESTS - 1 OF 3	RBL-3-1520
A34	LL 65 RANDOM STAGE II RECORD CONTROL R̄, R, AND GRADATION TESTS - 2 OF 3	RBL-3-1521

SUPPLEMENT A CONT'D

<u>Plate No.</u>	<u>Title</u>	<u>File No.</u>
A35	LL 65 RANDOM STAGE II RECORD CONTROL R, R, AND GRADATION TESTS - 3 OF 3	RBL-3-1522
A36	LL 70 RANDOM STAGE II RECORD CONTROL R̄, R, AND GRADATION TESTS - 1 OF 8	RBL-3-1523
A37	LL 70 RANDOM STAGE II RECORD CONTROL R̄, R, AND GRADATION TESTS - 2 OF 8	RBL-3-1524
A38	LL 70 RANDOM STAGE II RECORD CONTROL R̄, R, AND GRADATION TESTS - 3 OF 8	RBL-3-1525
A39	LL 70 RANDOM STAGE II RECORD CONTROL R̄, R, AND GRADATION TESTS - 4 OF 8	RBL-3-1526
A40	LL 70 RANDOM STAGE II RECORD CONTROL R̄, R, AND GRADATION TESTS - 5 OF 8	RBL-3-1527
A41	LL 70 RANDOM STAGE II RECORD CONTROL R̄, R, AND GRADATION TESTS - 6 OF 8	RBL-3-1528
A42	LL 70 RANDOM STAGE II RECORD CONTROL R̄, R, AND GRADATION TESTS - 7 OF 8	RBL-3-1529
A43	LL 70 RANDOM STAGE II RECORD CONTROL R̄, R, AND GRADATION TESTS - 8 OF 8	RBL-3-1530
A44	BERM ZONE STAGE II RECORD CONTROL R̄, R, AND GRADATION TESTS - 1 OF 4	RBL-3-1531
A45	BERM ZONE STAGE II RECORD CONTROL R̄, R, AND GRADATION TESTS - 2 OF 4	RBL-3-1532
A46	BERM ZONE STAGE II RECORD CONTROL R̄, R, AND GRADATION TESTS - 3 OF 4	RBL-3-1533
A47	BERM ZONE STAGE II RECORD CONTROL R̄, R, AND GRADATION TESTS - 4 OF 4	RBL-3-1534
A48	LL 55 IMPERVIOUS STAGE I RECORD CONTROL Q & S TESTS - 1 OF 8	RBL-3-1535
A49	LL 55 IMPERVIOUS STAGE I RECORD CONTROL Q & S TESTS - 2 OF 8	RBL-3-1536
A50	LL 55 IMPERVIOUS STAGE I RECORD CONTROL Q & S TESTS - 3 OF 8	RBL-3-1537
A51	LL 55 IMPERVIOUS STAGE I RECORD CONTROL Q & S TESTS - 4 OF 8	RBL-3-1538
A52	LL 55 IMPERVIOUS STAGE I RECORD CONTROL Q & S TESTS - 5 OF 8	RBL-3-1539
A53	LL 55 IMPERVIOUS STAGE I RECORD CONTROL Q & S TESTS - 6 OF 8	RBL-3-1540
A54	LL 55 IMPERVIOUS STAGE I RECORD CONTROL Q & S TESTS - 7 OF 8	RBL-3-1541
A55	LL 55 IMPERVIOUS STAGE I RECORD CONTROL Q & S TESTS - 8 OF 8	RBL-3-1542
A56	LL 55 IMPERVIOUS STAGE II RECORD CONTROL Q & S TESTS	RBL-3-1543
A57	LL 60 RANDOM STAGE I RECORD CONTROL Q & S TESTS	RBL-3-1544
A58	LL 60 IMPERVIOUS STAGE II RECORD CONTROL Q & S TESTS	RBL-3-1545
A59	LL 60 RANDOM STAGE II RECORD CONTROL Q & S TESTS	RBL-3-1546

SUPPLEMENT A CONT'D

<u>Plate No.</u>	<u>Title</u>	<u>File No.</u>
A60	LL 65 IMPERVIOUS STAGE II RECORD CONTROL Q & S TESTS - 1 OF 2	RBL-3-1547
A61	LL 65 IMPERVIOUS STAGE II RECORD CONTROL Q & S TESTS - 2 OF 2	RBL-3-1548
A62	LL 65 RANDOM STAGE II RECORD CONTROL Q & S TESTS - 1 OF 2	RBL-3-1549
A63	LL 65 RANDOM STAGE II RECORD CONTROL Q & S TESTS - 2 OF 2	RBL-3-1550
A64	LL 70 RANDOM STAGE II RECORD CONTROL Q & S TESTS - 1 OF 2	RBL-3-1551
A65	LL 70 RANDOM STAGE II RECORD CONTROL Q & S TESTS - 2 OF 2	RBL-3-1552
A66	BERM ZONE STAGE II RECORD CONTROL Q & S TESTS	RBL-3-1553
A67	LL 55 IMPERVIOUS STAGE I RECORD CONTROL COMPACTION TESTS - 1 OF 2	RBL-3-1554
A68	LL 55 IMPERVIOUS STAGE I RECORD CONTROL COMPACTION TESTS - 2 OF 2	RBL-3-1555
A69	LL 55 IMPERVIOUS STAGE II RECORD CONTROL COMPACTION TESTS	RBL-3-1556
A70	LL 60 RANDOM STAGE I RECORD CONTROL COMPACTION TESTS	RBL-3-1557
A71	LL 60 IMPERVIOUS STAGE II RECORD CONTROL COMPACTION TESTS	RBL-3-1558
A72	LL 60 RANDOM STAGE II RECORD CONTROL COMPACTION TESTS	RBL-3-1559
A73	LL 65 IMPERVIOUS STAGE II RECORD CONTROL COMPACTION TESTS	RBL-3-1560
A74	LL 65 RANDOM STAGE II RECORD CONTROL COMPACTION TESTS	RBL-3-1561
A75	LL 70 RANDOM STAGE II RECORD CONTROL COMPACTION TESTS	RBL-3-1562
A76	BERM ZONE STAGE II RECORD CONTROL COMPACTION TESTS	RBL-3-1563

PERTINENT DATA

GENERAL

Location of Dam	One mile south of I-470 and 1/2 mile east of Raytown Road. In SW 1/4 NW 1/4, Sec. 4, T. 47 N., R. 32 W., Jackson County, Missouri, at approximately 109th Street, Kansas City, Missouri, and at mile 42.9 on the Little Blue River.
Purposes	Flood control, recreation, water quality fish and wildlife.
Authorization	Flood Control Act of 1968 (Public Law 90-483, 13 August 1968)
Operating Agency	Corps of Engineers, Project Manager offsite
Drainage Area Above Longview Dam	50.3 square miles
Approximate Length of Lake	At multipurpose level (El. 891.0 ft., m.s.l.): from the dam, about 3.5 miles in a southeasterly direction.
Approximate Length of Shoreline	24 miles in length at multipurpose level (elevation 891.0 ft. m.s.l.)
Time of Water Travel at Bank-full Rates	13 hours to the Lake City gauge. 21 hours to the Missouri River.
Maximum Flood of Record Near Damsite	42,300 c.f.s., 13 August 1982
Channel Capacity	1,000 c.f.s.
Top of Dam Elevation	926.6 feet, m.s.l.
Length	1,900 feet
Type of Construction	Rolled earthfill
Fill Quantity	1,028,000 cubic yards impervious 915,000 cubic yards random
Freeboard	3.71 feet
Maximum Height Above Valley Floor	100 feet
Top Width	74 feet
Maximum Base Width	900 feet

PERTINENT DATA (CON.)

Date of Closure	16 June 1983
Date Storage Began	16 September 1985
Date Multipurpose Pool Initially Filled	23 September 1986

SPILLWAY

Type	Uncontrolled limited service
Location	Left abutment
Crest Elevation	911.3 feet, m.s.l.
Width	200 feet
Discharge Capacity	Top, surcharge pool El. 922.9 feet NGVD 22,970 c.f.s.

OUTLET WORKS

Location	Left abutment
Type	Uncontrolled hooded drop inlet
Conduit	5.5 foot by 5 foot arch
Length	916 feet
Invert Elevation at Intake	816.0 feet, m.s.l.
Invert Elevation at Outlet	812.0 feet, m.s.l.
Discharge Capacity at Elevation 922.9 (Top Surcharge Pool)	1,040 c.f.s.
Discharge Capacity at Elevation 909.0 (Top of Flood Control Pool)	990 c.f.s.
Emergency Drawdown Gate	1-6.0 foot by 7.0 foot hydraulically operated slide gate
Low Flow Intake	2-2.0 foot Dia knife gate valve
Low Flow Outlet	2-2.0 foot Dia knife gate valve

The outlet works also contain dual 54-inch sewers with two 54- by 54-inch sewer gates and two 54- by 54-inch crossover gates.

PERTINENT LAKE ELEVATION

<u>Storage Designation</u>	<u>Elevations (feet m.s.l.)</u>		<u>Storage Capacity* (acre-feet)</u>		<u>Area (acres)</u>
	<u>From</u>	<u>To</u>	<u>Initial</u>	<u>100-year</u>	<u>Top of Pool</u>
Surcharge	909.0	922.9	35,400		3,200
Flood Control	891.0	909.0	24,800	24,300	1,960
Multipurpose	816.0	891.0	22,100	20,600	930
Gross Storage	816.0	909.0	46,900	44,900	
Sedimentation Reserve			2,000		
Annual Sediment Inflow			20		

*100-year sediment allocation initially allocated 1/4 (500 acre-feet) to flood control zone and 3/4 (1,500 acre-feet) to the multipurpose zone.
Sediment allocation computed by 40 acre-feet per square mile per 100-year.

Fee Taking Line	Elevation 914.0 feet, m.s.l.
Fee Lands Acquired	4,762 acres
Easement Lands Acquired	63 acres

OPERATION AND MAINTENANCE MANUAL

LONGVIEW LAKE

LITTLE BLUE RIVER BASIN

LITTLE BLUE RIVER, MISSOURI

APPENDIX V

CHAPTER 1

INTRODUCTION

1-01. Purpose and Scope of Report. The purpose of this report is to provide in one volume the significant information needed by engineers to familiarize themselves with Longview Lake, reevaluate the embankment in the event unsatisfactory performance occurs, and provide guidance for designing comparable earth dams. The scope of this report provides a summary record of significant design data, design assumptions, specification requirements, construction equipment, construction procedures, construction experience, field control and record control test data, and embankment performance monitored by instrumentation during construction and during initial lake filling.

1-02. Project Purpose. Longview Lake is a multipurpose project realizing benefits from flood control, water quality control, recreation, and fish and wildlife.

1-03. Project Authorization. Longview Lake was authorized by the Flood Control Act of 1968 as a part of the "project for flood control and other purposes on the Little Blue River in the vicinity of Kansas City, Missouri, was authorized substantially in accordance with the recommendations of the Chief of Engineers in House Document No. 169, Ninetieth Congress First Session."

CHAPTER 2

PROJECT DESCRIPTION

2-01. Project Location. The Longview damsite is located on the Little Blue River at approximately 109th Street, Kansas City, Missouri. The entire lake is located in Jackson County, Missouri. Location and vicinity map are shown on Plate 1.

2-02. Dam Description. The dam is a zoned, compacted earthfill embankment with a crest length of approximately 1,900 feet and approximately 110 feet in height. The crest width is 74 feet to accommodate the 109th Street which is a 4-lane divided highway. A central impervious core with an impervious cutoff trench to bedrock was used for the total length of the dam. The embankment includes an inclined pervious drain as well as a pervious blanket across the valley and up the abutments. Compacted random zones and berm zones are used to support the impervious zones and add stability to the embankment. The theoretical top of dam is 926.6 which provides for 3.9 feet of freeboard above the maximum surcharge pool. However, the dam was constructed to elevation 925.7 with the remainder of the freeboard being provided by the New Jersey type concrete median barrier. The upstream slope is designed to have graded riprap in the zone of frequent fluctuation (elevations 878-898) and at the top 10 feet of the dam (elevations 915-925). Slope protection consists of 18-inch riprap on 9-inch of bedding. Between elevations 898 and 915 a grassed slope protects the embankment. The general embankment plan and sections are shown on Plates 2 and 22 through 25, respectively. A clay blanket was constructed on the right upstream abutment between elevations 848 and 898. A small dike was constructed west of Raytown Road near Elm Avenue to fill in a saddle in the left abutment. This dike is only about 3 to 4 feet high with a crest width of 10 feet.

2-03. Spillway. The spillway is an uncontrolled limited service spillway 200 feet wide with 1V on 6H side slopes cut in the left abutment overburden. The invert elevation is 911.3 which is 2.3 feet above the full pool elevation.

2-04. Outlet Works. The outlet works consist of an intake tower with a covered uncontrolled service drop-inlet, an arch-shaped conduit through the embankment, a parabolic drop into a stilling basin with an end sill and an outlet channel to the Little Blue River. The conduit crosses the dam centerline at station 98+70 and is skewed 3 degrees towards the downstream right abutment from the perpendicular to the dam axis. The concrete arch-shaped conduit is 4.83 foot wide and 5.5 foot high. Two 54-inch diameter sewer pipes encased in concrete are located below the conduit. The tower becomes submerged at elevations above 900 and a bridge at that elevation provides access to the tower from Service Road A.

2-05. Construction History. Since Longview Dam was located in a very urbanized area, there were many utility relocations which had to be completed prior to construction of the dam. The most extensive relocation was the existing 48-inch diameter sewer within the reservoir area which also crossed the dam centerline. It had to remain in service throughout the construction of the dam. It was unknown during the design phase exactly when the Little Blue Sewer District would complete their portion of the new sewer line within the reservoir area. Because of the uncertainty and the need to ensure closure

was not made until the sewer construction was complete within the reservoir area, construction of the dam was divided into two stages. The Stage I construction began in September 1979 and was completed October 1982. It consisted of foundation excavation for the cutoff trench and the outlet works including the outlet channel; foundation grouting; construction of the intake tower, conduit-sewer structure, and stilling basin; existing sewer relocation, diversion, and removal; placement of portions of the embankment on both sides of the river; and a 200,000 cubic yards impervious stockpile to be used for the Stage II contract. (See Plate 17 for Stage I construction.) The Stage II construction began in August 1982 and was completed September 1985. This contract included diversion of the river and embankment closure, completing the embankment, excavation the spillway, and construction of access and service roads. A 6-month construction halt was also included in the Stage II contract when the embankment reached elevation 890.

2-06. Lake Filling. After closure was made but before the embankment was topped out a lake formed several times due to excess runoff in the drainage basin. The highest lake level recorded during construction was elevation 865 on 10 June 1984 with the embankment at approximately elevation 885. This lake level was reached in less than 24 hours with the gates fully open. The embankment was topped out in September 1984 and the gates were closed to begin impoundment on 16 September 1985. The Initial Reservoir Filling Plan DM No. 20 was used as a guide during filling. The desired filling rate was 5 feet per month after the pool reached elevation 850. In October 1985 and November 1985 the pool rose faster than was acceptable and the emergency drawdown gate was opened to draw the lake down to the desired filling curve. On 23 September 1986 the lake reached multipurpose pool. The projected and actual filling curves are shown on Plate 45.

CHAPTER 3

GEOLOGY

3-01. Regional Geology and Physiography. Longview Lake is located in the extreme northern part of the Osage Plains Section of the Central Lowlands Physiographic Province. The Osage Plains Section is characterized by old scarp plains beveling faintly inclined strata. The Dissected Till Province which borders immediately to the north of the project is characterized by submaturely to maturely dissected till plains. A maturely dissected drainage pattern developed during pestilences time trends north into Missouri River. The project is located on the southern boundary of the Kansan Age Glacial Stage. Scattered loess deposits up to 7 feet thick are present on the uplands in the area. These deposits thicken to up to 90 feet along the Missouri River bluffs.

3-02. Site Geology. Gently rolling uplands surround Longview Lake. The Little Blue River flows generally north in a meandering, incised channel cut through alternating limestone and shale strata. At the damsite the valley is 1,800 feet wide from bluff top to bluff top and topographic relief is about 120 feet. The Bethany Falls limestone member of the Kansas City Group, Missourian Series, Pennsylvanian System is a prominent scarp forming ledge in the reservoir area. Its thickness is about 18 feet and it dips gently from elevation 885 on the right abutment to elevation 876 on the left abutment. Bedrock on the lower valley walls and valley floor is made up of less resistant shale and siltstone of the Pleasanton Group.

3-03. Description of Overburden. Overburden on the uplands in the general area consists of up to 30 feet of residual clay and scattered deposits of wind blown loess up to 20 feet thick. No loess deposits were encountered at the damsite. Overburden on the valley side slopes consists of residual clays and colluvium with clayey gravel at the base of the slopes. Alluvium in the valley ranges from 12 to 29 feet with the greatest thickness occurring in the terrace on the left side of the valley. The alluvium consists of predominately lean clay with lesser amounts of fat clay and silty, sandy gravel, in the basal 7 feet, resting on shale and siltstone bedrock. Generally the clays have medium to stiff consistencies although some soft clays were encountered in a few borings.

3-04. Bedrock. Bedrock at the damsite consists of alternating beds of limestone and shale of the Kansas City Group overlying a more massive section of less resistant clayey and silty shale, siltstone and sandstone beds of the Pleasanton Group. These rocks are classified as lower Pennsylvania Series. Underlying the Pennsylvanian rocks are about 2,200 feet of older sedimentary strata. Only the lower one-half of the Kansas City Group and the upper one-third of the Pleasanton group are exposed at the damsite. See the General Geologic Column and Legend on Plate 6. The regional dip of the bedrock ranges from 10 to 20 feet per mile west, northwest, but local variations in dip and strike occur. At the damsite bedrock dips 1 foot in 300 feet to the east into the right abutment and 1 foot in 65 feet to the west into the left abutment.

Jointing of beds may be very intense locally, due to dome-related flexures. Primary joints are generally vertical and strike north 50 degrees east spaced 5 to 35 feet apart. Secondary joints are generally, vertical,

tight, strike North 75 degrees West and spaced about 2 feet apart. A series of faults are known to exist in the road cut along a one mile reach of Highway I-470, located about 3/4 mile north of the damsite. However, faulting could not be traced into the soil profile and no evidence of faulting was found in the cutoff trench or foundation excavations during construction.

Depth and degree of weathering vary considerably with rock type and thickness of soil cover. The limestones are softened and stained to depths of a few inches to 5 feet below their surface. The Bethany Falls crops out prominently along the valley wall and partially filled joints, up to 5 feet in width, are apparent at the outcrop. By 50 feet into the abutment the effects of weathering of the Bethany Falls appears to have been moderated by the presence of overlying shale. Large blocks of Bethany Falls measuring up to 15 feet or so in their greatest dimension became detached at the joints due to the weathering and erosion processes with some blocks moving down slope. Neither the Winterset nor the Sniabar limestone formed prominent outcrops in the abutments and were commonly mantled by a 1 foot to 8 foot depth of overburden. Weathering effects extended as much as 12 feet beneath the bedrock surface of the interbedded limestones and shale. A more detailed description of the bedrock and bedrock units can be found in the Construction Foundation Report.

3-05. Subsurface Investigations Prior to Construction. Geological investigation of the damsite included field reconnaissance, review of geologic literature, analysis of air photos, survey of water wells, review of gas and oil well logs and exploratory drilling. A total of 339 borings and 11 test pits were completed by government drill crews prior to Stage I construction. Overburden exploration included 2-inch, 4-inch, and 6-inch diameter drive holes; 3-inch and 5-inch Shelby tube samples, auger samples, and samples obtained from test pits. The bedrock investigation included NQ, NX, 4-inch and 6-inch cores. Eleven NX, angled, core holes were drilled on the left abutment and five were drilled on the right abutment. Thirty-three bedrock borings were hydraulically pressure tested. Natural gas was encountered in hole DC-10 and C-145A between elevations 762 and 768. Gas pressure measured 11 psi with the packer set at elevation 801. A 5-minute pressure test with 35 psi yielded a "take" of 0.2 gallons per minute. The gas in both holes was found to be at low pressures and limited in volume as it quickly dissipated during drilling. A .5-foot cavity was logged in siltstone 13 feet below the top of the bedrock surface in hole UC-9. Two additional holes were drilled in the vicinity of the void; however, neither the cavity nor the evidence as to the geologic cause could be found.

CHAPTER 4

FOUNDATION AND EMBANKMENT

4-01. General. The main embankment consists of a compacted earthfill approximately 1,900 feet long with an outlet works and an uncontrolled limited service spillway (200 feet base width) located in the left abutment. The maximum height of the embankment above the valley floor is 110 feet. Theoretical top of dam is 926.6, but the embankment was only constructed to elevation 925.7 and the remaining freeboard is achieved by the New Jersey type median barrier. The dam was constructed with a centrally located impervious core to prevent seepage through the embankment. The impervious core is supported on either side with random and berm zones. The various embankment zones were designed to utilize the available borrow material. An inclined pervious drain was constructed on the downstream side of the impervious core and is connected to a horizontal blanket which extends along the base of the embankment and exits at the downstream toe. Any seepage which may occur through the impervious core is intercepted by the inclined drain and carried out the embankment through the horizontal blanket. The foundation overburden was relatively shallow with a layer of clayey or silty sandy gravel located directly above the bedrock. In order to cutoff any water flowing through the basal gravels an impervious cutoff trench was constructed into rock for the full length of the dam. Various foundation bedrock formations were highly jointed and fractured. A grout curtain was installed below the cutoff trench for the full length of the dam in order to control the seepage through the bedrock. A plan view is shown on Plate 2.

a. Valley Section. (Station 90+00 to 97+00) The embankment across the main valley varies from 100 to 120 feet in height with an average height of 110 feet above the valley floor. Zoning consists of centrally located impervious core supported by random and berm zones. Typical valley section is shown on Plate 23. The foundation overburden consisted of between 12 and 29 feet of alluvium which was predominantly lean clay with lesser amounts of fat clay. A clayey or silty sandy gravel was common in the basal portion (1 to 7 feet) of the alluvium. The underlying bedrock surface was Pleasanton Zone E (argillaceous siltstone).

b. Right Abutment. (Station 86+25 to 90+00) The right abutment embankment section is similar to the valley section except that the downstream slope is flattened to 1V on 6H, there is no downstream berm zone, and an impervious clay blanket was placed upstream on the far right portion of the abutment. Typical right abutment sections are shown on Plates 22 and 23. The natural slope of the upper portion of the abutment between approximate stations 86+00 and 87+50 was about 1V on 8H. From approximate station 87+50 to the toe of the abutment at station 90+00 the slope was irregular and considerably steeper, averaging 1V on 2.8H. The foundation overburden on the slopes consisted of residual clays and colluvium, while at the base of the abutment clayey gravel underlaid alluvial clay. Thickness of the overburden ranged from zero at the Bethany Falls outcrop to a maximum of about 15 feet at the base of the valley wall. The foundation bedrock consists of 12 stratigraphic units of interbedded limestone and shales (Plate 7).

c. Conduit Section. (Station 98+00 to 100+00) The conduit section is located basically at the toe of the left abutment (Plate 24). The centerline

of the conduit crosses the dam axis at station 98+70 and is skewed 3 degrees towards the downstream right abutment from perpendicular to the dam axis. The conduit section is constructed of impervious material with no random or berm zones. Since an all impervious zone with higher strength clays was used, the embankment slopes were steepened allowing for a shorter sewer-conduit structure. The overburden thickness on the right side of the conduit varied from 16 to 27 feet and consisted of alluvium similar to that in the valley section. At the toe of the left abutment from approximate station 99+00 to 100+00, the overburden was colluvium and clay alluvium consisting of clay, and fragments of shale and limestone ranging in size from gravel and cobbles to slabs and large blocks. The overburden rested on Pleasanton Zone C (argillaceous limestone) from the upstream end of the approach channel to near the dam axis. Except for a short horizontal extension of the Pleasanton Zone D (calcareous siltstone) the top of bedrock from the dam centerline to the downstream end of the outlet channel was Pleasanton Zone E (argillaceous siltstone). The outlet works profile is shown on Plate 8.

d. Left Abutment. (Station 100+00 to 107+00) This section is similar to the valley section except there is no upstream or downstream berm zone and the downstream slope is flattened to 1V on 6H. A typical left abutment section is shown on Plate 24. The natural slopes of the left abutment were generally not as steep as those of the right abutment. Between approximate stations 100+00 and 100+65, the average slope was 1V on 4H and it flattened to 1V on 6.5H between stations 100+70 and 103+00. The natural slope became progressively flatter between station 103+00 and the end of the embankment. From approximate station 100+00 to station 100+65 overburden ranged in thickness from 6 to 22 feet and consisted essentially of colluvium similar to that in the conduit section and residual clays. From the top of the Bethany Falls outcrop at approximate station 100+70 to the end of the embankment at station 107+00, the overburden consisted of residual soils of essentially lean and fat clays. Thickness of overburden ranged from 2 to 16 feet with the greater depths underlying the flatter upland slope. The foundation bedrock consists of the same 12 stratigraphic units of interbedded shales and limestones found on the right abutment (Plate 7).

4-02. Foundation Treatment.

a. Valley section. All of the embankment foundation was stripped of boulders, sod, roots, tree stumps, etc. and the overburden disked to a minimum depth of 8 inches and compacted with a minimum of three passes of a rubber tired roller. The 48-inch diameter reinforced concrete sewer pipe and pipe bedding, which crossed the dam axis at station 97+95, was removed under the entire embankment. Cleanup of the sewer excavation was accomplished and the backfill consisted of impervious under the impervious zone and random elsewhere.

b. Outlet Works Foundation. All overburden below the outlet works was excavated and backhoes and airspades were used to excavate the rock. A rock saw was used at the tower to excavate the vertical sides of the tower foundation. The final foundation in the outlet works except for the intake tower and stilling basin was excavated with a "roto mill" which consisted of a large track-mounted cutting roller. Air water jets were used to clean the final bedrock surface prior to placing a 6-inch layer of lean concrete. Lean concrete was also used downstream of the centerline of the dam in order to

meet the required grade for the outlet works. The lean concrete was as much as 4-feet thick at the lower end of the outlet works and stilling basin.

c. Abutment Foundations. The subcrop faces of several limestone ledges were trimmed back to either a 1V on 1H or 1V on .5H slope not only at the centerline but for a distance of as much as 400 upstream and 235 downstream. In some areas concrete bulkheads were placed against the bedrock faces to seal open bedding planes and vertical joints to achieve the desired slope to place fill (Photo 35). In other areas the open joints on top of the horizontal benches were gravity grouted (Photo 19). A total of 279.75 sacks of cement were used to dry pack joints or as poured grout at 35 separate locations. A total of 342.1 cubic yards of lean concrete was placed behind forms to seal joints and maintain the required slopes.

d. Cutoff Trench. In order to control seepage through the foundation overburden and to facilitate foundation grouting, the cutoff trench was excavated to bedrock from station 86+00 on the right abutment to station 104+00 on the left abutment. Side slopes in the overburden are 1V on 2H and in the bedrock are excavated to 1V on 1H. The floor of the cutoff trench is 30 feet which allows 24 feet of impervious and a 6 foot pervious drain backfill. Prior to curtain grouting, the cutoff trench was excavated to grade with the exception of the exposed shales which were left 2 feet high in order to protect the final shale surface from weathering or drying out. Grouting was performed from the floor of the cutoff trench through 2-3/4 inch steel pipes cemented 2 feet into the bedrock. Once the curtain grouting was complete the steel grout pipes were removed. The upper 2 feet of grout holes in the limestone were gravity grouted while the upper 2 feet of shale was removed to bring the shale surface to final grade. The final bedrock surface was cleaned with air-water jets. The cutoff trench backfill was performed in the dry utilizing small gasoline pumps in sumps. The main sources of seepage were small areas encountered within the basal clayey gravels. Details of the dewatering efforts are included in Chapter 8.

4-03. Embankment Materials. The embankment zoning was designed to economically use the available material from required excavation and upstream borrow, to provide seepage control, and to provide slope stability. Because of the distribution of materials in the borrow area and the need to maximize the strength of fill placed in the conduit section and in the lower portions of the embankment considerable effort was expended in defining quantities of various liquid limit materials in the borrow. For the most part the easily available lower liquid limit materials were in the low lying areas and were used in the Stage I embankment or were stockpiled to avoid inundation after closure. The remainder of the borrow had CL and CH materials interlayered and had to be differentiated to insure optimum use of higher strength material. See also Chapter 8.

a. Impervious. The specifications for Stage I and II required the impervious material consist of soil classified as CL and CH with the material placed upstream of the dam axis having no more than 5 percent gravel. For Stage I, the maximum liquid limit specified for all impervious material was 55. The maximum liquid limit specified for the Stage II impervious material varied from 55 to 65 depending on the embankment feature and elevation. Generally, the lower liquid limit material was placed in the lower portions of the embankment. The Stage II impervious zone liquid limits are shown on the table below:

STAGE II IMPERVIOUS ZONE LIQUID LIMITS

<u>Area</u>	<u>Maximum Liquid Limit</u>
Below elevation 867, including cutoff trench	55
Between stations 97+00 and 101+00 - Below elevation 887	55
Cutoff Trench above elevation 867	60
Inspection Trench	60
Between stations 97+00 and 101+00 - Above elevation 887	60
Impervious Clay Blanket	65
Above elevation 867, excluding cutoff trench, inspection trench, and between stations 97+00 and 101+00	65

Typical cross sections showing the impervious zone liquid limits are on Plate 46. The allowable moisture content at the time of placement ranged from 2 percent below optimum to 3 percent above optimum. It was required that the impervious material be compacted to at least 95 percent maximum density obtained by the standard Proctor compaction test. Most of the impervious material was placed in 8-inch lifts and compacted with 6 passes of a sheepsfoot roller except the material directly over the foundation rock. (See Chapter 8 for procedure used.) A total of 1,028,528 cubic yards of impervious were placed in the dam with 509,866 cubic yards being placed in Stage I and 518,662 being placed in Stage II.

b. Random. The random material consisted of overburden material except that soil classified as OH, PT, MH, and OL. The random material came from the required excavations and upstream borrow. Some of the random zone consisted of gravelly material not suitable for the impervious zone. Maximum liquid limit in the Stage I contract was 60, but varied between 60 and 70 in the Stage II contract. Lower maximum liquid limits were required in the lower portions of the embankment. The Stage II liquid limits are listed below:

RANDOM ZONE LIQUID LIMITS

<u>Area</u>	<u>Maximum Liquid Limits</u>
Below elevation 867 upstream of dam axis	60
Below elevation 867 downstream of dam axis	65
Above elevation 867	70
Spillway Dike and Elm Avenue Dike	*

* No liquid limit requirement but shall be a CL or CH material.

Plate 46 shows the various liquid limit zones on typical cross sections. Moisture requirements for random were the same as for impervious and compaction was either six passes with a sheepsfoot roller on 8-inch lifts or three passes with a rubber-tired roller on 12-inch lifts. A total of 914,813 cubic yards of random material was placed in the dam with 215,552 cubic yards being placed in the Stage I contract and 699,261 cubic yards being placed in the Stage II contract.

c. Berm. The upstream and downstream berm consisted primarily of fat clay (CH), however, according to the specifications could have been shale and other materials from the required excavations and borrow areas unsuitable for or in excess of the requirements for impervious, random, or rockfill. Fat clay (CH) was used in the upper 5 feet of berm normal to the upstream slope and for the closure Phase I and II cofferdams. The only moisture content requirements for Stage I was to the extent required for unassisted movement of compaction equipment. For Stage II the requirements were the same as Stage I on the wet side of optimum but on the dry side of optimum were limited to no more than 4 percent below optimum. On Stage I, the berm was compacted using two passes of a rubber-tired roller with 24-inch lifts or two passes of a sheepsfoot roller with an 8-inch lift. For the Stage II contract compaction was performed with either four passes of a sheepsfoot roller on an 8-inch lift or two passes of a rubber-tired roller on a 12-inch lift. A total of 965,971 cubic yards of berm were placed with 344,467 cubic yards being placed in Stage I and 621,504 cubic yards being placed in the Stage II contract.

d. Pervious. The pervious material was clean free-draining, durable, natural sand obtained from a commercial Missouri River sand plant having the following gradation:

<u>Sieve Size</u>	<u>Percent by Weight Passing</u>
No. 4	90-100
No. 16	55-85
No. 50	5-20
No. 200	0-5

The majority of the sand had less than .5 percent passing the 200 sieve. Stage I required the pervious material be compacted using 3 passes of a vibratory roller on 12-inch lifts. For hand compacted (special backfill) a plate vibratory roller on 4-inch lifts to obtain 80 percent relative density was required. During construction this was reduced to 70 percent (see paragraph 8.02 d.(2)). The compaction procedures for Stage II were the same as Stage I and based on the previous experience the required relative density was reduced to 70 percent for a plate vibratory compactor with 6-inch lifts. Moisture content of the sand was controlled such that the sand was saturated during compaction. A total of 104,584 cubic yards of pervious was placed with 30,387 cubic yards being placed in the Stage I contract and 74,197 cubic yards being placed in the Stage II contract. The outlet of the pervious zone is protected with a 12-inch thick layer of bedding which was placed using a track-mounted backhoe. The bedding has the following gradation:

12-Inch Bedding

<u>Dimension Sieve Size</u>	<u>Percent by Weight Passing</u>
6-inch	maximum allowable
3-inch	70-90
1-1/2-inch	55-75
1/2-inch	35-55
#4	15-35
#10	0-20
#20	0-5

e. Rockfill. The better quality limestone excavated from the abutments was used as rockfill (photo 21) to add stability and protection to the upstream clay blanket. The specification required the rockfill be reasonably well graded with a maximum size stone of 300 pounds and no more than 10 percent passing the 2-inch sieve. Shale and other soft friable particles were limited to 10 percent. The rockfill was placed in 36-inch lifts with no moisture control or compaction requirements except when the rockfill was placed within 2 feet of bedrock, berm or impervious clay blanket, at which time it was to be wheel-rolled with approved equipment.

f. Special Backfill. Special backfill is placed in the bedrock irregularities or other confined areas adjacent to structures where rollers could not operate effectively. The 2-foot thick zone of material against the bedrock surfaces was also considered as special backfill. This included the impervious and pervious zones for Stage I and the impervious and random zones for Stage II. The specifications required the special backfill be placed in 3-inch lifts. The impervious and random material was compacted with a power tamper to 95 percent of standard Proctor density, and the pervious was compacted with a plate vibrator to 80 percent relative density which was later reduced to 70 percent. The moisture requirements for Stage I were the same as the corresponding zone of material and for Stage II were between optimum and 3 percent above optimum. The rate of placement was controlled so that the relatively thin hand-compacted zones were covered with equipment-compacted material as soon as possible to prevent drying, excess wetting, or freezing and thawing.

g. Channel Fill. Material from required excavation and stockpiles which were not suitable for the embankment were used as channel fill. Rock excavation including shale was also allowed as channel fill as long the rock was covered with at least 2 feet of soil material. This material was placed in the old river channel downstream of the embankment with no moisture control except that required to allow traffic compaction of the 24-inch maximum lifts.

4-04. Stone Protection. The upstream stone protection consists of 18-inch riprap overlaying 9-inch bedding located between elevations 878 to 898 and 915 to 925. The bedding and riprap gradations are as follows:

9-Inch Bedding

Dimension Sieve Size	Percent by Weight Passing
5-inch	maximum allowable
3-inch	75-95
1-inch	40-60
1/2-inch	20-40
#4	0-20

18-Inch Riprap

Weight in Pounds Per Stone	Percent of Total Weight Lighter Than
400	100
200	60-90
100	30-50
25	0-15

All of the riprap and bedding was placed during the Stage II contract using either a track-mounted backhoe or a track-mounted front-end loader. (This equipment was not allowed on the placed stone.) (See Photos 54 and 55.) The upstream riprap is Bethany Falls limestone which was obtained from the Orrick Stone Co. Quarry in Clay County, Missouri. The upper 4.5 feet of material in the quarry was not used because of the poor quality rock.

The upstream riprap was designed in accordance with "Criteria for Riprap Wave Protection in Missouri River Division" dated June 1974 and ETL 1110-2-221 (29 Nov 76). The riprap design and the basis for the riprap limits are shown on Plate 32. The riprap was sized based on the design wave height (HD) which is equal to the significant wave height (HS) multiplied by 1.4. Significant wave height (HS) for the lower slope protection was 2.2 feet generated from 59 m.p.h. wind with a 20 minute duration. The critical combination for the upper area of stone protection is 56 m.p.h. wind for 30 minutes causing a significant wave height (HS) of 2.9 feet. The theoretical riprap necessary for the upper riprap zone is 21-inch, however, 18-inch was used instead since there is a very remote possibility the design condition will ever occur.

Based on economics, the embankment slope was designed to minimize the amount of required slope protection. The upstream riprap was placed between elevations 878 and 898 and elevations 915 and 925. These stone protection zones were determined from the Pool Elevation-Duration Curve, Lake Stage Frequency Curve and the chart showing the number of day per hundred years the pool is within the wave-height of a given elevation. In addition the upper slope has riprap to reduce wave run-up and protect the upper embankment during a full flood pool event.

The stilling basin riprap was also 18-inch and was placed similarly to the upstream slope. The stilling basin riprap is Winterset limestone from the lower 8.5 feet of the Courtney Road Quarry in Jackson County, Missouri. The riprap was designed based on methods described in ETL 1110-2-8 and ETL 1110-2-221. The design parameters used were an average flow velocity of 5.6 ft./sec. over the end sill, a design wave height of 2.8 feet, a safety factor of 1.5, and a specific gravity of 2.6. The riprap was designed based on wave height requirements, since the waves would cause more damage than the velocities.

4-05. Settlement. Settlement analyses were performed on the foundation overburden based on consolidation test results of select samples. These studies indicated a maximum total settlement of 2.2 feet in the valley foundation overburden and 1.9 feet in the terrace overburden. It was anticipated the majority of this settlement would occur during construction with only minor amounts occurring after construction. A 0.6 foot overbuild was constructed to compensate for post-construction settlement. During Stage

II construction, three settlement plates were installed in the valley section to measure settlement during and after construction. Two of the settlement plates are installed in the foundation overburden and one is installed in the embankment just above the pervious blanket in the random zone. As of April 1990, the maximum settlement in the two foundation plates is .71 foot with .66 foot occurring during construction and the settlement in the lower embankment plate is .8 foot with .54 foot occurring during construction. Also seven crest settlements monuments were installed to monitor settlement after construction. The crest settlement monuments indicate uniform settlement across the valley no more than .35 foot.

CHAPTER 5

SEEPAGE CONTROL

5-01. Through Seepage. Seepage through the embankment is controlled by a combination of embankment zoning and an inclined pervious drain. The impervious core prevents excessive seepage through the embankment. The random zones also assist in preventing through seepage since it was constructed primarily of impervious material. Any seepage which does occur is intercepted by the inclined pervious drain located on the downstream edge of the impervious core. The inclined pervious drain is connected to the horizontal sand blanket and together they will draw the phreatic surface down well within the embankment.

5-02. Underseepage. Seepage beneath the embankment is controlled by a cutoff trench, grout curtain and the extension of the sand blanket up the abutment. The impervious cutoff trench extends through the overburden and weathered rock down to firm bedrock. The grout curtain was constructed from the bottom of the cutoff trench and extends the full length of the dam.

a. Cutoff Trench. The cutoff trench was constructed to control seepage through the foundation overburden and weathered rock. It extends the full length of the embankment from station 86+00 on the right abutment to 104+00 on the left abutment. The trench is 30 feet wide along the bottom with excavated side slopes of 1V on 2H in the overburden and 1V on 1H in the bedrock. The cutoff trench was backfilled with impervious material to prevent seepage under the embankment. However, a 6 foot wide pervious drain which is connected to the horizontal sand blanket was placed on the downstream side of the trench to intercept any seepage which may occur.

b. Grout Curtain. The grout curtain was constructed to prevent underseepage through the bedrock. It consists of three lines of grout holes in the abutments and a single line of grout holes in the valley. Grouting was performed from the floor of the cutoff trench through 2 3/4-inch diameter steel pipe cemented about 2 feet into bedrock. The grout holes were drilled the total depth using rotary drilling methods. After drilling, the grout holes were washed through the drill rods, pressure tested, and grouted through a packer which was set at successively shallower depths. The grout pressure was not allowed to exceed the estimated vertical stress at the packer depth. All the grout holes were inclined 30 degrees from vertical and drilled parallel to the dam centerline into the abutments. The grouting plan and profile are shown on Plates 14, 15 and 16. Some variations to this plan were made during construction. A more detailed description of the actual grouting plan and operations are provided in the Construction Foundation Report. Line A is 10 feet downstream of the dam axis and actually extends from station 86+25 to 89+65 on the right abutment and between station 100+05 and 103+85 on the left abutment. Line B is located 10 feet upstream of the dam axis and was constructed from station 86+20 to 89+65 on the right abutment and 100+05 to 103+85 on the left abutment. Line C is along the dam axis and extends from station 84+00 to 112+00.

c. Abutment Seepage. In addition to the cutoff trench the grout curtain, and the sand blanket which extend up the abutments, the embankment slopes at the abutments were flared and a clay blanket was constructed on the

right abutment to control underseepage at the abutments. Excess rock from required excavation was used in an outer rockfill zone to protect the clay blanket. The majority of the abutment seepage was expected to occur through the Bethany Falls limestone rather than the relatively tight lower bedrock units. Therefore, additional readily available rockfill was placed along the abutment up to elevation 848. The clay blanket was then placed on top of the rockfill and carried up to elevation 898.

CHAPTER 6

SLOPE STABILITY

6-01. General. This chapter discusses slope stability investigations. It presents the design analysis and consists of slope stability which was performed in conjunction with establishing embankment slopes and internal zoning. The results of the design analysis were originally presented in Design Memorandum No. 5, Soil Data and Embankment Design dated June 1978. A stability analysis of the left embankment which was performed after Stage I construction when high construction induced pore water pressures were measured in the embankment is discussed in Chapter 8 and Enclosure 1. A stability analysis was also conducted after Stage II construction for the conduit section when movements were detected in a lower zone of the embankment.

6-02. Design Strength Testing. Laboratory tests to determine strength parameters for design were performed on samples of materials from the required excavations, proposed borrow areas, and from the foundation. The testing consisted of laboratory tests on undisturbed samples of foundation material and on remolded samples from required excavation and potential borrow material. The tests generally followed procedures outlined in EM 1110-2-1906 entitled "Laboratory Soils Testing", 30 November 1970. Compaction of remolded or disturbed strength test specimens of cohesive soils was in accordance with EM 1110-2-1902, "Engineering and Design Stability of Earth and Rockfill Dams", 1 April 1970. Test loads generally covered the range anticipated in the embankment or foundation.

a. Triaxial Compression Tests. Triaxial "Q" and "R" tests were performed on representative undisturbed and compacted samples under confining chamber pressures ranging from 0.5 to 6.0 tsf. Pore pressures were measured in some of the "R" tests for the purpose of determining the effective strength of the soil. The general procedure involved strain controlled tests on two or three specimens trimmed from a single sample horizon. Composite specimens were compacted in eight layers by kneading to the range of densities and moisture contents expected during construction. Specimen dimensions were 1.4 inch by 3.0 inch height. No attempt was made to saturate the "Q" test specimens. "R" tests were saturated with back pressure ranging from 1.9 to 6.0 tsf. The strain rates were 0.5 percent per minute for the "Q" tests and 0.12 percent per minute for the "R" tests. In "R" tests, consolidation under the assigned chamber pressure was continued until a plot of volume change versus log time indicated that primary consolidation was complete. Peripheral filter paper strips were used to accelerate drainage. The deviator stress at 15 percent strain was assumed to be the maximum if it had not peaked beforehand.

b. Direct Shear Tests. Direct shear tests were performed on representative undisturbed and compacted soil specimens and on undisturbed shale specimens. Composites were compacted by kneading to the assigned density and moisture content, generally 95 percent of standard effort maximum dry density at a moisture content 3 percent greater than optimum. Normally, two specimens were sheared under a normal load of 4, 5, or 6 tsf. Before shear, the specimens were allowed to consolidate under the applied normal load until primary consolidation was complete. Specimens were sheared at a constant rate of 0.0003 inches per minute. Normally, this rate of deformation

met the 50t₅₀ criterion. Residual shear tests on intact and pre-cut samples were performed with a direct shear machine capable of shearing the specimen, then reversing the direction of shear 180 degrees and shearing the specimen again without releasing the normal load in the process. In order to obtain the strength at large strain, this procedure was repeated until no reduction in shear strength occurred from additional shearing.

6-03. Selection of Design Strengths. In selecting design values, considerations were given to 1) stress-strain compatibility, 2) the relationship of maximum shear strength to ultimate shear strength, 3) the number of tests, 4) the nature of the material, and 5) the location of the material with respect to potential failure surfaces. Design shear strengths were selected with two-thirds of the test values exceeding the design values.

a. Foundation Overburden. Test results of the terrace and valley reaches showed that one design strength was appropriate for the entire valley section. The following shear strengths were selected.

<u>TYPE OF STRENGTH</u>	<u>c (TSF)</u>	<u>Tan ϕ</u>
Q	0.60	0.00
R	0.20	0.20
S	0.00	0.50

b. Foundation Shales. Only "S" strengths were used for shales in the design. Unconfined compression tests indicate that the "Q" strength is substantially greater than the overburden and therefore is not a factor in the stability analysis. Past experience in the Kansas City District indicates that because these shales are highly overconsolidated, "R" strength is generally greater than "S" strength over the range of normal stresses encountered. The design "S" strength for the shales in the abutments and valley is $c = 0$, $\tan \phi = 0.60$. A residual "c" strength of $c = 0$, $\tan \phi = 0.30$ was also used.

c. Compacted Embankment Material. In the original DM analysis higher strength lean and fat clays with liquid limit less than 55 from the low-lying borrow were to be used in the impervious zone and in the conduit section between stations 97+00 and 101+00. The higher liquid limit fat clays (with LL generally less than 70) from the upper borrow areas were expected to be used in both the impervious and the random zones for the remainder of the embankment. Thus the same strengths were assigned to the impervious and random zones for these reaches. (As a result of comments from higher authority, this was changed during the plans and specifications so that the lower liquid limit materials were used in the impervious zone to the extent possible and liquid limit restrictions were also applied to the random zone. The objective was to use the lowest available liquid limit materials in the lower part of the embankment to optimize strength and stability of the embankment. For a distribution of material requirements developed during the plans and specification phase of the design see Chapter 4.) The design strengths used in the DM stability analysis are shown in the following table. The pervious zone had a higher strength than the random or impervious but because of the limited extent of this zone the higher strength was ignored in the stability analysis.

RANDOM AND IMPERVIOUS

<u>TYPE OF STRENGTH</u>	<u>c (TSF)</u>	<u>Tan ϕ</u>
Q	0.90	0.00
R	0.20	0.20
S*	0.00	0.50
S**	0.00	0.36

* Liquid limit less than 55, conduit section.

** Higher liquid limit material from higher elevation borrow areas.

BERM ZONE

<u>TYPE OF STRENGTH</u>	<u>c (TSF)</u>	<u>Tan ϕ</u>
Q	0.45	0.00
R	0.10	0.20
S	0.00	0.30

6-04. Design Stability Analysis. The embankment was analyzed for stability at three locations in an effort to cover the various conditions existing in the dam. Those locations are the valley section, conduit section, and the cofferdam.

a. Method of Analysis. A force equilibrium wedge method was used to analyze the slope stability of the Longview embankment. A computer program titled "Stability Analysis - Wedge Method" (File No. 741-F5-cl020), commonly known as KC Wedge, was used to perform the stability analysis. This program satisfies force equilibrium only using an analytical technique discussed on Plate 86. It searches for the shear surface with the minimum factor of safety. The results were checked by searching from more than one starting point to make sure that the program did not miss potential failure areas. The slope of the effective "E" force was assumed to be one-half the average outer embankment slope. The computer program is compatible with Appendix VI of EM 1110-2-1902, except for: (1) the slope of the "E" force is assumed to be constant throughout the active wedge, and (2) the angle of the shear surface was assumed to be the same for each material in the active wedge. The critical shear surfaces were checked manually. In all cases, the manual checks confirmed the computer factors of safety. Typical analyses for the end of construction, partial pool, rapid drawdown from maximum surcharge and full pool, and steady seepage cases are discussed below and are shown on Plates 87 and 88.

b. Construction Case. The design analyses assumed that neither the embankment nor the foundation consolidates during construction. Submerged weights were used below and moist weights above the line of saturation, which was assumed near the ground surface. Upstream and downstream slopes were analyzed using "Q" (unconsolidated-undrained) shear strengths and were designed for a minimum factor of safety of 1.3. In order to meet the required 1.3 factor of safety in the valley section a construction halt at elevation 915 was needed to allow consolidation of the foundation clay. This was later

changed to elevation 890 and embankment fill placement rate restrictions were established (see Chapter 8).

c. Partial Pool Case. The upstream slopes were analyzed for pool elevations ranging from near the valley floor to near full pool to determine the critical pool level. The intermediate shear envelope $(S, (R+S)/2)$ was used. The saturation line was assumed to be horizontal at the pool elevation being considered. Submerged weights were used below and moist weights above the saturation line. The slopes were designed for a minimum factor of safety of 1.5 for a slide in the impervious and random zone. In the valley section a partial pool slide in the berm had a 1.22 factor of safety with the pool at elevation 855. The upstream berm slope was not flattened because of the improbability of the pool being at this elevation long enough for full saturation of the embankment to occur.

d. Steady Seepage Case. The downstream slopes were analyzed for a spillway crest pool, steady seepage case. Vertical equipotential lines were assumed. The shear envelopes and design factors of safety were the same as for the partial pool case. The slopes were also analyzed using residual strengths for the foundation shales, with a minimum factor of safety of 1.0 being required.

e. Sudden Drawdown Case. The upstream slopes were analyzed for a sudden drawdown condition, both from the spillway crest and from maximum surcharge. In both studies, it was assumed that the lake was drawn down to multipurpose pool. The combined "S" and "R" strength shear envelope was used. The analyses assumed that the embankment was saturated as shown and that the pool was instantaneously lowered with no dissipation of pore pressure occurring during drawdown. Slopes were designed for a minimum factor of safety of 1.2 for a drawdown from the spillway crest and a minimum factor of safety of 1.0 for a drawdown from the maximum pool.

f. Earthquake Case. The slopes of the embankment were subjected to a pseudo-static earthquake analysis during design. Longview Dam is located near the border between seismic zones 1 and 2. ER 1110-2-1806 requires the evaluation of potential liquefaction for all existing projects in zone 2 where embankment or foundation materials are present that are suspect of being susceptible to liquefaction or excessive deformation. Since the clay soils encountered are not vulnerable to liquefaction, a pseudo-static analysis was conducted.

g. Results. The results of the stability analyses performed for the design memorandum on the valley section, conduit section, and the cofferdam are shown on Plates 89 through 91.

6-05. Stage II Stability Analysis. Because of high construction induced pore pressures in the conduit embankment and a zone which developed deformation during Stage II construction, additional stability studies were made for the end of construction conditions. Analysis was performed on the upstream slope of the conduit section where both inclinometer data and observed bridge movements showed movement was occurring. The zone of movement roughly corresponded with the area of highest pore pressure. While pore pressures were experienced at the closure section and the right embankment, no significant movement was detected at other locations and the pore pressures

were some what less and tended to be confined to the cutoff trench backfill (See Plate 44). Although there was some indication that placement water contents were farther above optimum than indicated by the field test data (see Chapter 8), it is believed the left embankment experienced unusually high pore pressure response because of its differential foundation conditions and its relatively small size as constructed in Stage I. The pore pressure was concentrated in that portion of the embankment which was placed on relatively rigid rock foundations or conduit. The left embankment foundation has a considerable portion placed on rock or concrete: the conduit excavation, the old sewer trench excavation and the cutoff trench. It appears that the backfill, being some what stiffer than adjacent overburden, probably carries load from surrounding fill areas which would increase stresses and thus pore pressure. Both total and effective stress analyses were performed. The effective stress analysis used both a pore water pressure coefficient, Bishop's r_u , and pore pressure contours developed from measured induced construction pore pressures. Inclined meters showed a zone of movement occurring at approximately elevation 827 at range approximately 1+80 upstream and analyses were performed with the shear surface through this zone.

a. Method of Analysis. The computer program SSTAB2 (Spencer's method) was used for the Stage II analysis. It satisfies all requirements of static equilibrium by varying the safety factor and side force inclination simultaneously. This program was written by Stephen Wright, University of Texas, Austin.

b. Revised Soil Parameters. The shear strength for the soil was determined from field compaction results, record control testing, and from testing on undisturbed samples taken both during the installation of instrumentation and from the side walls of two large diameter auger holes installed at the end of Stage I construction. The unit weight used was 125 pcf. The "S" strength for the effective stress analyses was determined from record control direct shear and triaxial "K" tests with pore pressure measurements. An envelope of $c = 0.1$ tsf and $\tan \phi = 0.5$ was selected. "S" strengths were believed appropriate because of the movement experienced and that shear stress induced pore pressures were being measured. For the total stress analysis it was assumed a soft zone existed in the zone of movement. No attempt was made to specifically sample and test this zone since the embankment had been investigated previously during Stage I and no defined soft zone was found. Some strength test results showed strengths lower than the design value but a continuous layer was not identified. A reduced strength of 0.5 tsf was assumed for comparison purposes.

c. Results. Initial stability analysis was made using a simplifying assumption for the pore pressure of $r_u = .65$. This analysis showed $F = 1.10$ which was verified with a hand solution. It was believed that the pore pressure was not this high especially in the outer and upper 25 feet of the embankment. An analysis was conducted using pressure contours developed from the piezometer readings. A circular search showed a minimum $F = 1.63$ with the surface passing through a portion of the zone of movement. A wedge shaped shear surface through the zone showed $F = 1.87$. A total stress analysis with the shear surface passing through the zone of movement shows $F = 1.24$ using the conservative strength assumption ($c = .5$ tsf) in the zone of movement. Results of these analyses are shown on Plate 92.

CHAPTER 7

INSTRUMENTATION

7-01. General. The initial installation plan for observation devices included instrumentation to monitor pore pressure in the embankment and the foundation clays and shales, the effectiveness of the cutoff trench and grout curtain, the foundation and embankment settlement, and the horizontal and vertical movement of the embankment. The piezometers were to be installed in three lines at stations 93+00 (valley section), 97+00 (closure section), and 98+70 (conduit section). Based on previously experienced high construction pore pressures in the foundations at other dams in the Kansas City District, the majority of the instrumentation devices were open tube and gas operated piezometers installed in the foundation overburden and shales. Piezometers were also installed in the foundation overburden upstream and downstream of the cutoff trench to check its effectiveness and in the embankment to monitor construction pore pressure. Alignment monuments were installed to detect slope movement as the embankment was being topped out while crest settlement monuments were installed soon after the embankment was topped out to monitor vertical movement. The initial instrumentation plan included 14 open tube piezometers, 12 gas operated pore pressure cells, 7 crest settlement monuments, 3 foundation settlement plates, and 21 alignment monuments total in one upstream and one downstream line. However, because of high construction induced pore pressures in the left embankment which developed during Stage I construction, additional observation devices were installed to monitor movements and pore water pressures particularly in the embankment. The monitoring program was expanded and further complicated by the development of gas in the open tube devices and concerns for the reliability of the devices. A discussion is included in Chapter 8 and Enclosure 1. It should be noted that all devices are thought to be influenced by gas and that the magnitude of the measuring error has not been determined although considerable effort has been directed to that end. At the time of this report, the instrumentation includes: 52 open tube piezometers of various design, 22 gas operated pressure cells, one vibrating wire piezometer, 23 alignment monuments total in 3 lines, 3 foundation settlement plates, 7 crest settlement monuments, and 4 inclinometers. The locations of these devices are shown in plan view and cross section on Plates 35 through 41.

7-02. Piezometers.

a. Open Tube Piezometers. A total of 62 open tube piezometers have been installed in the embankment, foundation, and abutments of Longview Dam since construction began. Ten of these instruments were abandoned; 8 because they were to be submerged upon reservoir filling, one because it was on the embankment centerline and could not be read after embankment completion, and one because it was broken 29-feet below the top of the riser and could not be repaired. There are a total of 52 open tube piezometers remaining on the project of three basic types. There are forty-one 3/4-inch PVC piezometers with slotted tips, four 3/4-inch PVC piezometers with 1/16-inch perforations, and seven 2-inch PVC piezometers with slotted tips. The open tube piezometer installation details are shown on Plate 42.

The 3/4-inch piezometers with slotted tips consist of 6.5-foot long sections of 3/4-inch inside diameter, schedule 80, PVC pipe. On early

installations, the sections of pipe were connected with stainless steel threaded couplings whereas the later installations utilized flush joint PVC pipe. All of the 3/4-inch piezometers terminate in sensing tips consisting either of a 1.5-inch diameter by 18-inch long, #20 (0.020-inch) slotted PVC pipe or a 2-inch diameter by 24-inch long, #10 (0.010-inch) slotted PVC pipe. Sand surrounds each tip and fills the borehole so as to be in contact with the zone or zones to be monitored. Where a single zone was to be monitored, a 4-foot seal of bentonite balls was placed above the sand with a 5 percent bentonite-cement grout filling the remainder of the hole. Piezometers installed to monitor several strata are all located on the right abutment and have a one-foot seal of bentonite balls above the sand with the remainder of the hole (3-foot minimum) filled with a 1 to 1 sand and granular bentonite backfill.

The 3/4-inch piezometers with 1/16-inch perforations are similar to those described above with the exception that, on 6-foot centers, 1-foot long sections of the schedule 80 PVC riser pipe were patterned with 1/16-inch holes. This pattern of perforations and the sand backfill around the riser was continued to within approximately 14 feet of the ground surface where a 1-foot thick bentonite ball seal was placed. The remainder of the hole was then filled with a 1 to 1 granular bentonite and sand backfill. All of the 3/4-inch piezometers with perforated risers are located on the abutments.

The 2-inch diameter piezometers with slotted tips are also similar to the 3/4-inch piezometers with slotted tips with the exception that, regardless of slot size, all of the tips are 2 inches in diameter. All of the 2-inch piezometers except PPE92-2 are located in the foundation overburden downstream of the right abutment and carry the prefix "W-". PPE92-2, the only 2-inch open tube piezometer in the embankment is made of glued joint PVC pipe.

Where 3/4-inch piezometers were brought up through the embankment, 5-foot lengths of 2-inch I.D. PVC protective pipe surround the 3/4-inch pipe above the original installation borehole (Plate 43). The fill was compacted directly against the protective pipe. The 5 foot sections are joined using double bell slip couplings with rubber sealing rings to accommodate movement and settlement.

Several open tube piezometers produce large quantities of gas which makes evaluation of data difficult due to widely and rapidly fluctuating water levels. The presence of gas in open tube piezometers was identified early in construction and an investigation to identify the type of gas was undertaken. The collection and identification processes are documented in Enclosure 1. The piezometers that have experienced problems with g-s are PPE92-1, PPE95-1, PPE97-13, PPE97-14, PPE99-10, and PPE99-13, all of which are located either in the upstream or downstream random or impervious zones. A 2-inch diameter open tube piezometer (PPE92-2 data plots shown on Plates 109 and 110) was installed adjacent to a 3/4-inch open tube piezometer (PPE92-1 data plots shown on Plates 107 and 108) which had been giving inconsistent data due to gas. Both devices were installed with the tips at the same elevation. The 3/4-inch device had a water level at the top of the riser and would periodically overflow and would erupt after a pressure gauge was removed. The 2-inch piezometer stabilized at a level about 20-feet below the ground surface and showed a steady decrease in water level as would be expected. In attempts to prevent the 3/4-inch devices from overflowing and to stabilize the fluctuating

water levels, pressure gauges and air release valves were installed on the risers. Although 3/4-inch risers should de-air themselves, the air release valves have not proven entirely effective and in several cases the pressures indicated by the piezometers increase substantially when a gauge and air release valve are added due to gas partially displacing water in the riser (Plates 107 and 108). The existence of gas in the piezometers and its effect on water levels is not as extreme as it has been in the past, although it does continue to be a problem.

b. Gas Operated Piezometers. A total of 32 gas operated (pneumatic) piezometers have been installed in the embankment and foundation of Longview Dam, of which, 22 remain functional. Three instruments were destroyed by a 1982 flood, two were destroyed by construction equipment, four were abandoned because of water in the pressure leads or a diaphragm failure, and one indicated pressures above the range of the readout device. Of the 22 remaining gas operated piezometers at Longview, 18 are Sinco Model 51471 pore pressure transducers (2-tube) with "Norton" (low air entry) filters, 3 (PPE99-8, PPE99-12, and PPE99-15) are Petur model P-100 pneumatic piezometers (low air entry filter), and 1 (PPE99-11) is a Sinco Model 51471 pore pressure transducer with a "Coors" (high air entry) filter. PPE99-8 and PPE99-11 were installed within 5-feet horizontally and 12-feet vertically of each other for comparison purposes (Plates 116 through 119).

Each of the three types of gas operated piezometers were installed differently and the installation details are shown on Plate 42. The standard Sinco 51471 transducers were installed in 3.5 feet of saturated sand in a 6-inch diameter borehole. Above the sand, the hole was sealed with 4.5 feet of bentonite balls. The remainder of the hole was then filled with a 1 to 1 mixture of sand and granular bentonite. The Petur P-100 pressure cells were installed in existing 3/4-inch I.D. PVC open tube piezometers. The transducer was placed in the PVC riser and 8 feet of saturated sand was placed in the riser. A 1-foot thick plug was then formed around the pressure leads inside the riser using a water sensitive expanding polymer. The riser was cut off 1 foot below the surface of the fill under construction and the remainder of the riser was filled with sand. A 1-foot thick bentonite ball seal was placed over the top of the cut off PVC riser and embankment construction continued over the bentonite seal. The Sinco 51471 with the high air entry Coors filter was installed in an existing 2-inch diameter PVC piezometer. The 2-inch riser was filled with saturated sand to within 8 feet of the surface of the embankment. Bentonite balls were then placed in the remaining 8 feet of riser to form a seal. Again, embankment construction continued above the bentonite seal.

Five of the existing gas operated piezometers have begun, or continue, to provide erratic readings and have water in the pressure tubing at least intermittently. These problems are believed to be due to the piezometers and the associated tubing approaching the end of their useful life expectancy. The possibility of continuing to obtain useful readings from these devices is questionable. Difficulties have been encountered in reading the following devices: PPE93-1, PPE93-6A, PPF97-9, PPF99-1, and PPE99-6.

c. Vibrating Wire Pressure Cell. The vibrating wire piezometer, PPE99-18, is a Geokon Model 4500. The vibrating wire piezometer cell was placed in a 1.5-inch diameter vertically slotted PVC pipe filled with

11 pounds per gallon kaolinite slurry (Plate 42). The leads to the cell were extended from the top of the 1.5-inch diameter pipe through a length of 3/4-inch PVC pipe. This length of pipe was also filled with kaolinite slurry and sealed 4.7-feet above the piezometer tip with a plug of water sensitive expanding polymer. A 6-inch diameter leather collar was placed around the 3/4-inch pipe at the same location as the polymer seal. This entire assembly was then lowered to the bottom of a 6-inch borehole filled partially with the kaolinite slurry using a 0.4-foot long length of 3/4-inch PVC pipe to keep the unit off of the bottom of the borehole. A 4-foot seal of bentonite balls was placed above the leather plug and a 1.5-foot layer of saturated sand placed above that. The remainder of the borehole around the 3/4-inch pipe containing the piezometer leads was filled to the ground surface with a 5 percent bentonite-cement grout. The readout leads for this device are entirely encased in 3/4-inch PVC pipe between the top of the 1.5-inch diameter slotted pipe and monitor box 5 on the downstream crest road shoulder.

7-03. Embankment Piezometric Devices. Following completion of the Stage I left embankment, high pore pressures were measured in the lower part of the embankment. Between the Stage I and Stage II contracts, overflowing water levels and quick recoveries after pumping were found in the protective casings of several devices in the closure section. It appeared that the protective casings and the risers were acting as separate measuring devices. The protective casings were apparently registering higher pore pressures at points higher in the embankment, possibly near the mid-height. These pressure levels apparently exceeded 50 percent response. An extensive investigation was undertaken to determine the extent of the high pore pressures and the adequacy, including stability, of the embankment. The investigation involved undisturbed sampling and testing, inspection of in place embankment material from two large diameter auger holes, installation of additional instrumentation to monitor pore pressures and slope movement, dye injection, and pump tests. A complete discussion of the investigation is contained in Enclosure 1. The investigation revealed construction induced pore pressures in the left embankment backfilled excavations below approximate elevation 810 ranging up to about 75 percent. Between approximate elevations 820 and 830, above the backfilled excavations, pore pressure responses were between 50 and 60 percent. No pore pressures were present in the top 20 feet of the Stage I fill.

Most of the piezometers installed in the embankment measured induced construction pore pressures after completion of the embankment and continue to do so. In general, piezometers located in the cutoff trench and adjacent to the conduit registered the highest pore pressure levels upon embankment completion with some indicating pore pressure of up to 63 percent, or about 65-feet above the top of the dam.

Construction pressures in the embankment remain high especially in the cutoff trench and around the conduit (40 to 55 percent pore pressure response). Most of the piezometers are showing a pressure dissipation of about 1 to 5-feet per year in the embankment although some have not begun to show pore pressure dissipation.

Piezometers installed in the embankment indicate pore pressure levels above the pool elevation, therefore the effect of pool filling on the embankment piezometers has yet to be determined.

All piezometers on the project are currently being read quarterly.

7-04. Foundation Piezometric Devices. During construction, little pore pressure developed in the foundation shale or overburden. During reservoir filling, piezometers located in the foundation overburden on the upstream side of the cutoff trench indicated nearly full reservoir head which was apparently being transmitted through the basal gravel layers. The piezometers located in the upstream foundation overburden still indicate nearly full reservoir head, however, no significant pressures are being transmitted downstream. The only other foundation piezometer to show high pressures was PPF99-4 with its tip in the Pleasanton Zone E formation (Plates 114 and 115). It built up pore pressure to an elevation of 880 shortly after construction was completed and has dropped to elevation 837 as of the fall of 1990. Since filling of the reservoir in 1986, all of the piezometers in the Pleasanton Zone E siltstone on the upstream side of the grout curtain have shown a slow, but constant, increase in piezometric level. These increases have been anywhere from 8 to 14 feet with PPF86-1A on the upstream right abutment showing the largest increase (Plate 102). The piezometers in the Pleasanton Zone E siltstone on the downstream side of the grout curtain have shown general decreases in measured pore pressure from 1 to 14 feet except for PPF87-3 as noted in the "Abutment Piezometric Devices" section below.

7-05. Abutment Piezometric Devices. Piezometers located in the right abutment bedrock, downstream of the grout curtain, rose as the pool filled lagging the pool generally on the order of 14 feet. This prompted the installation of piezometers in various geologic members to determine which ones were transmitting pressure. Some pressure testing and bail tests were done as the holes were being drilled. It was found the formations transmitting the high pressures included the Pleasanton Zones A & B, as well as the Middle Creek limestone and Hushpuckney shale. Piezometers were also installed in the pervious drain after excessive water was noted exiting the pervious blanket. Piezometer readings indicated the pervious blanket was completely saturated and even pressurized in some areas. It was concluded that the excessive water was coming from seepage through the right abutment bedrock. No other problems have surfaced due to these high pressures and it appears that seepage through the right abutment is being controlled and collected by the pervious blanket.

The piezometers in the Pleasanton Zone E siltstone on the downstream side of the grout curtain have shown general decreases in measured pore pressure from 1 to 14 feet except for PPF87-3 (Plate 103). PPF87-3 has shown a 3 foot increase in the measured piezometric level in the Pleasanton siltstone since 1986. This increase is most likely due to migration of high pressures from the overlying Hushpuckney shale, Middle Creek limestone, and the Pleasanton Zones A and B.

Seepage pressures remain high in the right abutment bedrock and are influenced by the pool. A steady flow continues to exit the pervious blanket as a result of this seepage. This causes the toe ditch to remain wet and causes a maintenance problem in this area. No other problems have surfaced due to these high pressures.

7-06. Inclinometers. There are three inclinometers installed through the upstream slope and one through the downstream slope. All are between stations 97+00 and 99+00 (Plate 36). All of the inclinometers are constructed of 3.38-inch outside diameter, grooved aluminum casing (Plate 43A). The casing was installed in 10-foot lengths and joined with 3.63-inch outside diameter by 12-inch long telescoping aluminum couplings. The casings were pop-riveted to the couplings with aluminum rivets and a gap was left between subsequent casings to allow for settlement of the foundation or embankment. In the foundation overburden, a 12-inch gap was left between casings while a 6-inch space was left between casings that passed through the embankment. Each inclinometer is sealed at the bottom with a pop-riveted plastic cap and protected at the surface of the fill by a 6-inch diameter, lockable, galvanized steel pipe.

I-97-1 and I-99-2 were installed in 7-inch flight augured boreholes through the partially completed embankment and foundation overburden. The bases of the inclinometers are seated in holes drilled using a 5-5/8 inch rock bit in the foundation rock. Pea gravel was used as backfill material in the annulus around the inclinometer casings. A short length of 6-inch diameter steel pipe filled with pea gravel was placed around the inclinometer at the surface of the fill. As the embankment was brought up, the fill was compacted directly against the 6-inch pipe. After each few lifts, the pipe was raised to the new fill surface leaving the pea gravel in direct contact with the compacted embankment material. This process was repeated until the final surface of the fill was reached where a 1 to 1 cement grout seal was placed. I-99-1 was installed after completion of the embankment at the device, in a borehole drilled entirely with a 6-1/8 inch rockbit through the embankment, foundation, and into the foundation rock. Pea gravel was placed in the annulus around the inclinometer casing and a 4-foot long seal of bentonite balls was placed around each coupling. I-99-3 was also installed after completion of the embankment adjacent to the bridge abutment and the borehole was made using a 5-7/8 inch rockbit exclusively. A 1:1 cement grout fills the annulus between the inclinometer casing and the borehole walls.

Inclinometer I-99-1 was installed at station 95+40, range 2+57 downstream (Plate 41) in September of 1984, one month prior to topping out of the embankment. This device has shown a total movement of 4.7 inches most of which occurred between elevations 803 and 829 prior to September of 1986 (Plate 121 and 122).

Inclinometers I-97-1 (station 97+49, range 1+89 upstream) and I-99-2 (station 98+25, 0+85 upstream) were installed after the Stage I embankment was completed and were extended through the embankment as it was constructed (Plate 41). I-97-1 has shown a total upstream movement of 7.5 inches most of which occurred between elevations 823 and 842 (Plate 124).

I-99-2 has shown approximately 8.2 inches of upstream displacement, most of which took place in the top 4 feet of the fill and between elevations 819 at the bottom of the inclinometer and 856 (Plate 122). Most of the movement at the base of the device occurred as the embankment was being topped out or shortly after completion of the embankment. The movement shown in the top 4 feet of the embankment is attributable to the placement of a concrete work pad on the up slope (downstream) side of the device. The concrete pad was in contact with the protective pipe around the inclinometer and has caused the

top section of the inclinometer to lean upstream. Neglecting the movement shown in the top 4 feet of the embankment, I-99-2 shows 6 inches of total upstream movement.

Since October of 1987, I-99-2 has been experiencing a problem with "silting in". Between October of 1987 and September of 1990, the sounded depth of this inclinometer decreased 15 feet from 108.8 to 93.8 feet. This "silting in" is reflected by the progressive upward shifting of the bottom of the readings on the movement versus depth plots shown on Plate 122. The loss of the lower 15 feet of the instrument is also evidenced by the shifting of the data plots to the right as the incremental movement shown in the lower portion of the instrument is lost. The exact nature of the material in the inclinometer and the cause for the silting is currently unknown. Flushing of the casing and sampling of the material is planned. If it is found that substantial quantities of embankment materials are found in the instrument, it will be abandoned by grouting the casing full.

I-99-3 was installed at station 98+50, range 1+80 upstream adjacent to the tower bridge abutment (Plate 41). During and after construction, this device indicated lateral spreading of the embankment in the conduit section on the order of 4.5 inches (Plates 123 and 124). This spreading resulted in movement of the control tower bridge abutment and complete closure of the expansion joints at both the bridge abutment and pier. Most of the movement occurred between elevations 816 and 837 with a fairly concentrated zone of 1.9 inches of incremental movement at elevation 826.3. As a result of this movement the embankment stability was checked (see Chapter 6). Repair of the bridge abutment and reestablishment of the tower bridge expansion joints was accomplished by contract in the spring of 1990.

No substantial movement has been shown by any of the inclinometers since 1987. All four inclinometers are currently being read twice a year.

7-07. Alignment Monuments. The alignment monuments on the downstream line "A" and upstream line "B" consist of 18-inch diameter by 8-foot deep reinforced concrete monuments (Plate 43). Alignment line "A" is located 200-feet downstream of centerline between stations 87+50 and 101+00 and contains 8 monuments on 200-foot centers. Line "B" is located 170-feet upstream of the embankment centerline between stations 87+00 and 103+50 and contains 9 monuments on 200-foot centers (Plate 36). In addition to alignment monuments, each line has two instrument monuments; one on each abutment.

As previously noted, lateral spreading of the embankment in the conduit section caused movement of the control tower bridge abutment and complete closure of the expansion joints at both the bridge abutment and pier. Alignment line "C" was installed to monitor the tower bridge abutment movement and consists of only one alignment plate and two instrument monuments (Plate 43). The alignment plate is located at station 98+66, range 1+77 upstream, and is installed on the north end of the east bridge parapet over the abutment. There is not a concrete monument installed at that location, only a stainless steel instrument plate mounted on the bridge parapet. Line "C" uses the same left abutment instrument monument as the upstream line "B". A separate instrument monument for line "C" exists on the right abutment upstream of the monument for line "B" to allow a straight shot across the bridge abutment.

Initial readings on all three lines were taken three times and the results averaged to establish a zero reading. The initial readings of lines "A" and "B" were taken in July of 1985. The initial reading of line "C" was taken in March of 1986 after installation of the alignment plate. "A" on the downstream slope has experienced the most overall movement with a maximum total movement of 1.7 centimeters at monuments A-5 and A-6 at stations 95+00 and 97+00 respectively (Plate 98). The maximum total movement of 1.4 centimeters of the upstream line is shown by monument B-3 at station 91+00 (Plate 98). Vertical surveys taken on each monument indicate maximum settlements since installation on the downstream line at monument A-6 which shows a total settlement of 0.19 feet (Plate 99). The maximum settlement on the downstream line is 0.14 feet at monument B-4 at station 93+00 (Plate 100). Line "C" has indicated no movement or settlement since installation since all bridge abutment movement took place prior to installation of the monuments. All alignment monuments on the project are currently being surveyed semiannually.

7-08. Foundation Settlement Plates. Three mechanical foundation settlement plates were installed during construction in 1983. These devices were installed at stations 91+00, 93+00, and 96+00 and are downstream of the embankment centerline 40, 50, and 75 feet respectively (Plate 36). SPPF91-1 and SPPF93-7 consist of a 36-inch square, 1/2-inch thick steel plate set approximately 1-foot below the embankment/foundation contact (Plate 43). The plate of SP96-1 is also a 36-inch square steel plate but it is installed approximately 10-feet above the pervious blanket as opposed to below the blanket at the foundation contact as is the case with the other settlement plate installations. The location of the plate allows SP96-1 to monitor settlement in approximately the lower 13 feet of the embankment. To allow monitoring of changes in elevation of the plates, a 1-inch diameter standard galvanized pipe is connected to a flange bolted to the plate. The 10 inches of galvanized pipe immediately above the plate is perforated with 12, 1/16-inch holes to allow monitoring of pore pressures as well as settlement. (The use of all three settlement plates to monitor pore pressures was discontinued in May of 1986 due to the presence of heavy oil in the riser.)

As noted on the plots, there was no reliable settlement data recorded between August of 1984 and May of 1985 since the contractor failed to record a riser extension (Plate 97). It was assumed that no settlement took place during this period. The three settlement plates indicate that the bulk of foundation consolidation had occurred by October of 1984 with only small settlements since that time. The range of settlements indicated is between 0.5 and 0.8 feet with SPPF96-1 showing the greatest settlement. The maximum current rate of settlement shown by the settlement plates is less than 0.1-foot per year. See section "Crest Settlement Monuments" below for discussion and comparisons of the foundation settlement plates and crest settlement monuments. All foundation settlement plates on the project are currently being surveyed annually.

7-09. Crest Settlement Monuments. On completion of the dam in 1985, seven crest settlement monuments (CSM's) were installed in a single line on 200-foot centers along the crest of the dam (Plate 36). The monument line runs along the inside edge of the downstream guardrail of 109th street at approximate range 0+36 downstream. The monuments are 6-inch diameter by 6-foot deep auger holes filled with reinforced concrete. The monuments are

capped with a standard brass monument cap set flush with the bituminous roadway surface (Plate 43). Four of the brass monument caps were damaged by snowplows in 1987 and it may become necessary to relocate the crest settlement monuments to the downstream side of the guardrail to prevent this type of damage from recurring.

As noted above, the crest settlement monuments were installed in July of 1985 and have since shown between 0.1 and 0.35 feet of settlement (Plates 95 and 96). CSM-4 at station 94+50 over the old river channel shows the maximum crest settlement. The crest settlement monuments are currently being read once a year and currently indicate settlement rates of less than 0.1-foot per year.

CSM's 2, 3, and 5 are located at roughly the same respective stations as settlement plates SP91-1, SP93-7, and SP96-1. Comparisons of the total settlements shown by CSM's 2 and 3 and settlement plates SP91-1 and SP93-7 indicate that approximately 70 percent of the total settlement that has occurred since 1985 has been embankment settlement. As noted above, the plate for SP96-1 is installed approximately 10-feet above the pervious blanket which allows it to monitor settlement in approximately the lower 13 feet of the embankment. Settlements indicated by CSM-5 and SP-96-1 are closer in agreement than the other comparisons and it is indicated that approximately 90 percent of the embankment settlement shown by the crest settlement monuments is occurring in the lower portions of the embankment which are not monitored by SP91-1 and SP93-7.

7-10. Top of Dam Profiles. Surveys are made annually of the top of the New Jersey barriers and the top of the dam at the downstream edge of the barriers between the lanes of 109th street across the dam (Plate 94). As noted previously, the roadway surface across the dam is below the theoretical top of dam elevation of 926.6 by approximately 1.2 feet and the New Jersey barriers are considered to account for the remaining required freeboard. The elevations taken after the September 1989 repair of the low spot on the left abutment are shown in the top plot on Plate 94.

The maximum settlement shown by the top of dam surveys occurs at station 94+50 over the old river channel and is approximately 0.3 feet. This data confirms the location and magnitude of settlement shown by the crest settlement monuments.

CHAPTER 8

CONSTRUCTION NOTES

8-01. General. Major sewer construction work in the reservoir area was a significant concern in planning for the construction of the dam. Closure of the embankment could not occur until the sewer was complete because of the potential to inundate the sewer construction area within the reservoir. Since it was unknown at the time of preparation of plans and specification when the sewer construction would be complete, the District decided to construct the dam in two stages. This created some problems with trying to minimize the number of temporary slopes and "tie-ins," however, a construction plan was developed with this objective in mind. The plan was complicated not only by the existing sewer which crossed the proposed foundation and the necessity for the sewer to remain in service at all times, but also by the relatively narrow valley and the fact that the best available upstream borrow was located in low-lying areas next to the river channel. To minimize "tie-ins" the plan proposed building the minimum embankment necessary in Stage I prior to diversion and closure in Stage II. This embankment was to be only that necessary for the cofferdam (except the closure section). Stage I required construction of the outlet works (conduit and sewer), diversion of the sewer, and removal of the existing sewer. It required excavations for the outlet works including the outlet channel and a river diversion channel. Cutoff trench excavation and foundation grouting was included in Stage I as well as backfilling the cutoff trench for the right and left embankments. To minimize the amount of low-lying impervious material that had to be stockpiled, it was decided to include placement of the downstream conduit embankment to elevation 867. Stage II construction included diversion of the river, construction of the closure cofferdam, the remaining portions of the downstream embankment, and raising the entire embankment to final elevation. The construction plan allowed a considerable portion of the Stage II embankment to be constructed without temporary slopes or "tie-ins." However, the configuration of the Stage I embankment and the cofferdam was not ideal since it consisted of many small pieces.

8-02. Stage I Contract. The Stage I contract, DACW41-79-C-0114, was awarded to W. A. Ellis Construction Company, Kansas City, Missouri, on August 24, 1979, for the low bid of \$11,865,103.00. Construction began in September 1979 and was completed in October 1982. Ellis Construction Company's previous experience was primarily in highway and sewer construction projects, they had never constructed a dam, nor did anyone with the company have any dam building experience. This lack of experience was compounded, especially early in the contract, by the fact that the Government did not have a resident engineer on the job full-time. The project was administered by an area engineer who visited the project only periodically and an inadequate staff. This led to immediate problems with rock excavation, foundation treatment and preparation, care of rock surfaces and especially material usage. Early in the project the specifications were often totally ignored. After these administrative problems became apparent a full-time resident engineer was assigned to the project and was given a very capable staff. The project ran much better in that the specifications were being enforced; however, the early problems led to hostile relations between the contractor and the resident office. Strict interpretation and enforcement of the specifications led to a substantial claim involving a variety of issues, the most significant of which related to

material usage from the borrow. Additionally, because of these problems and unexplained observations of the left embankment and instrument monitoring devices, serious concerns for the integrity of the Stage I embankments surfaced. The embankment experienced relatively high pore pressures apparently related to fill placement which tended to be wet of optimum and the rather complex configuration of the embankment pieces. The high pore pressures were complicated by an unexplainable accumulation of gas in the monitoring devices. An extensive investigation was conducted to determine the stability and adequacy of the Stage I embankments. The borrow area problems, embankment investigation and other pertinent features are discussed below.

a. Borrow. Much of the low liquid limit material needed for the impervious fill and the stockpile for Stage II was easily available only in, close-in, low-lying areas along the river. The other areas of the borrow contained some low liquid limit material however, it was usually overlain by high liquid limit material unacceptable for use as impervious. On previous dam construction projects, as on this one, the Government had done enough exploratory work to ensure that sufficient quantities of the desired material were available in the borrow; but usually this exploratory work was not sufficiently detailed for the actual construction. Detailed explorations were expected of the contractor; specifications clearly state this as the contractor's responsibility. However, the contractor did no exploratory work to classify material in the borrow and placed a large quantity of the close-in low liquid limit materials in the berm and random fill zones early in the job. He then began experiencing problems finding acceptable material for use in the remaining impervious zone in the left embankment and to complete the impervious stockpile required for Stage II construction. This material could not be readily classified visually because there was not a discernible difference in color and the material typically ranged in liquid limit between about 45 and 60. Visual classification techniques using toughness of the PL thread are not precise enough for most individuals to differentiate between materials with LL just below 55 from those just above 55. The contractor was directed to do exploratory work in the borrow; however, not enough quantity was found to complete either the left embankment or the impervious stockpile. An analysis of the borrow area, and of materials placed in the berm and random zones for the claim revealed that more than enough impervious had been available in the borrow to meet the fill quantities required. In fact, the analysis showed that some 180,000 cubic yards of impervious was placed in the berm zone, and 75,000 cubic yards in the random zone. Only 40,000 cubic yards had to be deleted from the Stage I contract quantities for the left embankment and the impervious stockpile.

b. Outlet Works Excavation.

(1) Conduit-Sewer. The conduit-sewer excavation began in the fall of 1979. The floor of the excavation was 25-feet wide upstream of the cutoff trench and 30-feet wide downstream of the cutoff trench (see Plate 12 for excavation plan). The overburden excavation averaged 20-feet deep with 1V on 2.5H slide slopes. The majority of the excavated overburden was used for the impervious stockpile. The rock excavation averaged only 2 to 4-feet deep and was performed with backhoes, jackhammers, or dozers with the exception of the intake tower area where a rock saw was used to make the necessary vertical cuts. The rock surface was brought to final grade using a "roto mill," a large track-mounted cutting roller. Air-water jets were used to clean off the

final bedrock surface prior to placing the specified 6 inches of fill concrete. It was required the bedrock be excavated to firm rock, so in some places additional fill concrete had to be placed to bring the final fill concrete surface to grade. The contractor elected to over excavate the east slope to provide for a 30-foot wide workbench along the tower area (O.W. station 45+00 to 46+00) and 20-foot wide bench along the conduit section. During the conduit-sewer excavation several slides occurred along the left abutment.

(a) Sewer Excavation Slide. On November 18, 1979 a slide occurred on the left side of the sewer excavation between outlet works (O.W.) stations 55+00+ to 57+00+. The slide moved on a slickensided surface in the weathered shale which underlies the talus. The horizontal movement at the head of the scarp was in excess of 8 feet and the depth to the failure plane varied from a few feet to 8 or 10 feet. The failure took place just after the excavation had been made at the toe of the natural abutment slope. (See Photo 13.) After the initial failure, additional exploratory holes were drilled and the slide area was analyzed and monitored. Through the winter of 1980, additional movement was experienced and the slide area increased. Because of the continued movements, there were concerns regarding long-term stability of the area. It was felt the slide would not adversely effect the stilling basin or the outlet works; however, continued movement would not be tolerable to the relatively rigid new sanitary sewer pipe to be located on the left side of the outlet works. Therefore, the proposed new sanitary sewer was relocated to the right side of the outlet works by Modification 6. The new sewer alignment is shown on Plate 12. The slide area was repaired by removing the slide material from the excavation and backfilling the sewer excavation to elevation 820 with the excavated overburden from the left abutment as part of Modification 16. The backfill was placed in 8-inch lifts, compacted with even routing of hauling equipment and the final surface sloped to drain away from the abutment.

(b) Left Abutment Slides. During the winter of 1980, three additional shallow slides occurred in overburden on the abutment side of the conduit excavation between O.W. stations 50+00 and 52+00. These slides were each about 50-feet wide and extended about halfway up the slope from the base of the excavation. Then again in December 1980 another slide occurred in the same area. In order to prevent further sliding of the left abutment overburden, the contract was modified to require all left abutment overburden between the cutoff trench and the downstream toe of the embankment be excavated to rock.

(2) Outlet Channel. In the late summer of 1980, the outlet channel alignment was modified to avoid the guy wires of a newly relocated power line. The outlet channel was moved toward the east downstream of O.W. station 60+41. This new alignment also eliminated the need to relocate an existing gas line.

(3) Approach Channel. The approach channel parallels the new sewer relocation which was constructed under separate contract concurrently with Stage I construction. Originally the entire approach channel excavation was to be performed during Stage II to prevent the confusion of having separate contracts in the same area. However, the majority of the approach

channel excavation was performed by the sewer contractor during the installation of the adjacent sewer. Therefore, only minor excavation was necessary during Stage II to bring the approach channel to grade.

c. Sewer Relocation. Prior to constructing the embankment, the existing 48-inch sanitary sewer located on the right and parallel to the outlet works had to be diverted through the relocated sewer beneath the conduit without interrupting service and then removed. Construction of the dual 54-inch sewer pipes located under the conduit and the removal of the existing sewer pipe within the limits of the dam were included in the Stage I contract. The remaining sewer relocation work in the reservoir area and downstream from the dam was performed under a separate sewer contract. As previously discussed, the new sewer alignment originally located on the left side of the stilling basin was moved to the right side by Modification 6. Because of this alignment change the new and existing sewers crossed. Therefore, prior to constructing the new sewer, the existing sewer had to be temporarily taken under the new sewer by an inverted siphon which was added to the contract by Modification 37. The conduit-sewer structure was completed by the fall of 1980 but the actual sewer diversion did not take place until July 1981. The existing sewer and all of the bedding material was removed shortly after diversion. The majority of the existing sewer was located on bedrock so the excavation and foundation cleanup performed was similar to the cutoff trench. The contractor excavated and cleaned up to 50 feet at a time and used air jetting for final cleanup of the shale. The sewer excavation was to be backfilled with impervious (LL<55), however, the contractor was also allowed to use fat clay. The downstream pervious blanket was placed directly over the sewer backfill rather than along the excavation limits. All of the existing sewer pipe was removed except the inverted siphon. It was left in-place and pumped full of sand to prevent the water flowing through the sand blanket adjacent to the conduit from building up pressure upstream of the new sewer.

d. Cutoff Trench.

(1) Excavation. The cutoff trench was excavated to bedrock between station 86+00 and 104+00. The floor of the excavated trench is 30-feet wide and the side slopes are 1V on 2H in the overburden and 1V on 1H in the bedrock. (See Plate 11). The contractor began excavating the trench along the valley, then proceeded to the left abutment and finished the trench excavation with the right abutment. The overburden thickness varies from 0 feet on the abutments to as much as 29 feet in the valley. The majority of the excavated overburden was placed in the impervious stockpile or temporarily stockpiled for future use in Stage I. The rock excavation was performed primarily by backhoes or presplit blasting to minimize damage to the rock surface. The specifications restricted blasting within 100 feet of concrete or grout less than 7 days old or within 50 feet regardless of age. Therefore, the majority of the blasting along the cutoff trench was completed prior to curtain grouting and all of the blasting on the left abutment cutoff trench was completed prior to placing the outlet works structural concrete. As previously mentioned the cutoff trench was excavated to grade prior to grouting with the exception of the shales which were left 2-feet high to protect the underlying shale from drying out and weathering. All curtain grouting was performed from the floor of the cutoff trench (Photo 14) and is discussed in more detail in the Construction Foundation Report. The cutoff trench excavation and curtain grouting was performed in the dry. The river

had to be temporarily diverted to perform cutoff trench excavation and curtain grouting within the river channel. The contractor made little or no effort to control surface runoff or groundwater in the cutoff trench between grouting operations and backfilling.

(2) Backfilling. The cutoff trench was backfilled with impervious fill and a 6-foot wide pervious drain on the downstream side of the trench (see Photo 16). In mid June 1980, the contractor began backfilling the cutoff trench at approximately station 93+60 and proceeded towards the right abutment. There were several areas along the upstream slope where water was seeping from the clayey gravel zone directly above the shales. Initially the contractor only had two pumps with sumps located wherever low areas existed which resulted in the contractor chasing water from location to location. The first lift of backfill placed on the shale was 1 to 2-feet thick and in some cases was placed in standing water. Two test pits were dug between station 91+00 and 92+00 to observe the fill-shale contact and the overall backfill condition. They indicated a zone of very soft wet fill existed at the shale contact, varying in thickness from 1/4 inch to 1 inch. The contractor was required to remove and replace this unacceptable lift. The removal of this lift is shown in Photo 15. After these initial problems, the contractor's operation improved. In order to control lift thickness and ensure an adequate fill-shale contact, the contractor was directed to use special backfill for the initial shale covering which required 3-inch lift hand compacted. The backfill was brought up to a depth of 6 inches, then the next lift was compacted with a rubber tired loader. The seepage along the basal gravel was easily handled with additional pumps and pump pits.

Between station 90+10 and 91+10 several 5 gallon cans with the bottoms removed were used to collect the more concentrated seepage from the gravel zone directly above the bedrock. The 5-gallon cans were placed directly on bedrock and as the backfill progressed, additional cans with the tops and bottoms removed were placed on the initial cans. The water that collected in the cans was pumped out. After three layers of cans were installed (4.5 feet of head) the cans were filled with sand and the impervious fill placement continued.

The contractor was allowed to place fat clay rather than lean clay in the lower 5 to 6 feet of the cutoff trench (below the water table). The liquid limit restrictions were reportedly raised in this area because the excavation was wet and lean clay absorbs water more easily than fat clay, thus, the lean clay was thought to be more likely to become unworkable than fat clay. Prior to changing the liquid limit requirements the effect of the potentially lower shear strength on stability analyses was considered. It was determined that weaker material in this location near the top of rock at the centerline would not adversely affect the stability of the embankment.

The original specification required the pervious fill be placed in 12-inch lifts and compacted with three passes of a 5-ton vibratory roller or 4-inch lifts and compacted to 80 percent relative density with a plate vibratory compactor. The three passes with a vibratory roller were only achieving 75 to 80 percent relative density and the 80 percent relative density was extremely difficult to obtain using a hand compactor. Therefore, the compaction requirements for the plate vibratory compactor were reduced to 70 percent relative density for the pervious fill placement.

e. Abutments. Originally, only that portion of the excavation and foundation treatment within 75 feet of the cutoff trench and within the limits of the Stage I embankment was to be performed under Stage I. The excavation and foundation treatment was similar for both abutments. The excavation was performed with backhoes and presplit blasting to minimize damage to the rock surface. Dental concrete was used to fill joints along the excavated limestone slopes and gravity grouting was used to fill the joints along the horizontal ledges. In many places formed concrete was placed against the irregular bedrock face in order to achieve the desired slope and to seal the bedding planes and vertical joints. When the contractor began working on the left abutment it became evident the weathering extended further into the abutments than originally anticipated, therefore requiring additional excavation into the abutment to reach sound rock. Knowing the right abutment was steeper and more weathered, it became necessary to modify the contract and extend the right abutment excavation above the original limits of the top of the embankment (elevation 887). Modification 2 required the overburden and rock be excavated between station 86+00 and 87+40 above elevation 887 upstream and downstream of the cutoff trench within the final embankment limits. This additional excavation provided an adequate workbench for drilling the Bethany Falls limestone and flattened the hazardous near vertical slopes in the Winterset limestone. After the upper right abutment was excavated, the shale formations were covered with a 3-foot minimum layer of soil to protect it from drying out prior to Stage II embankment placement.

The Middle Creek limestone was present in both abutments but was more predominate on the right abutment. This formation was only about 1.5-feet thick and consisted of three distinct beds, two limestone beds with a thin shale bed in between. The upper layer of limestone was extremely jointed and had the appearance of precut limestone blocks thus requiring special care during the foundation treatment adjacent to the random and impervious zones. In order to minimize the disturbance of the rock to remain in-place, the final rock excavation was performed by equipment located on the fill not the bedrock. The three beds were stair stepped and cut to a relatively smooth vertical face. See Photos 18 and 19. The existing joints along the face of the slope were mortar treated and the joints on the top limestone surface were cleaned with air jetting and filled with grout. No heavy equipment was allowed over the Middle Creek formation until 2 feet of special backfill had been placed over it.

The Sniabar limestone was presplit in an effort to make a smoother face to compact fill against and to remove rock with solution cavities. However, on the right abutment the blasting badly fractured the formation resulting in the need for additional foundation treatment. The existing joints were opened and the upper ledge was lifted and broken up. The final treatment of the formation included the removal of upper ledge which caused undercutting of the underlying shales at various locations. The loose material was removed from the fractured face and dental concrete was placed against the irregular surface. Formed concrete was to be placed against the formation where shale undercutting occurred. The initial concrete placed against the Sniabar within the upstream random zone was placed too stiff and was not formed or vibrated. The concrete was simply dumped on the slope and towelled smooth. The contractor was required to remove and replace this concrete due to the voids and the inadequate bonding between the rock and the concrete.

f. Right Embankment. The first embankment to be placed in Stage I was on the right side of the river and was completed in 1980. Prior to any fill placement the diversion channel was excavated and the river was straightened to allow for construction of the embankment on both sides of the river. The Stage I right embankment included the upstream berm and random zones which were placed to elevation 887 and tied into the abutment at the top of the Bethany Falls limestone. It also included a small portion of impervious and downstream random zones. A plan view at the end of Stage I is shown on Plate 17 and the embankment sections are shown on Plates 23 and 24. Photo 22 shows an overall view of the right embankment. The contractor obtained the majority of the material for the right embankment from the nearby low lying borrow areas along the river which created considerable difficulty later in the contract. As previously discussed, the low lying borrow areas were the best source of the lean clay and should have been saved for the impervious zone (LL<55) in the conduit section and the stockpile. However, the contractor elected to place the lean clay in the random (LL<60) and berm (LL-unspecified) zones.

Because several bedrock zones along the right abutment had open joints or were highly fractured a 10-foot zone of clayey gravel was placed directly against the abutment to act as a filter. As the fill placement progressed the supply of clayey gravel diminished. At which time the clayey gravel was only placed against the jointed and broken up limestone formation.

g. Left Embankment. The conduit structure was completed in the fall of 1980 enabling placement of the adjacent embankment upstream of the centerline to begin. Embankment placement downstream of the centerline did not begin until the following spring, and that portion to the right of the conduit section until after removal of the sewer. The conduit section zoning extends from station 97+00 to 101+00 and consists of impervious material with the exception of the pervious blanket and inclined drain. See Plate 24. The internal zoning between station 101+00 and the left abutment originally included both berm and random zones. The contract was modified to change the upstream and downstream berm fill to random fill between stations 101+00 and 102+00. This allowed better utilization of available material, provided a better contact with the limestone surface and eliminated the need for separate zones in an isolated area.

The embankment was brought up evenly on both sides of the conduit. Downstream of the inclined pervious drain, the 3-foot thick pervious blanket was placed in contact with the foundation along the outlet channel excavation and around the conduit. Initially, the contractor had some difficulty obtaining relative density even after the requirements had been lowered to 70 percent. But once an adequate amount of water was placed in front of the compaction equipment, meeting the compaction requirements became easier.

Initially the impervious material (LL<55) for the conduit section was taken from the remaining low lying borrow areas along the river. As the impervious fill placement progressed, the contractor began to deplete the easily identified lean clay sources and had to utilize material from the higher borrow areas upstream of Longview Road. As previously discussed, the material in the higher borrow areas consisted of intermixed lean and fat clay which were difficult to distinguish visually without testing. The contractor did not have an adequate method of classifying and identifying the suitable

impervious material at the borrow pit resulting in the continual direction by the Contracting Officer to remove unsuitable material after placement in the embankment. The problem of identifying suitable material prior to its placement in the embankment and the need for extensive testing continued throughout the remaining fill placement and eventually was the basis for a major claim. Due to the contractor's mismanagement of the borrow areas, there was an insufficient amount of impervious material remaining which could be practically excavated. Therefore, the downstream portion of the embankment was topped out at elevation 867 and the upstream portion at elevation 870 even though the original plan called for a small portion of the upstream left embankment to extend to elevation 887.

h. Impervious Stockpile. As part of Stage I an impervious stockpile was constructed downstream in order to ensure the Stage II contractor a ready source of impervious after closure (Photo 25). This was necessary since the majority of the impervious (LL<55) material was located in the low lying borrow areas along the river which could periodically become inundated after closure. The contractor began working on the impervious stockpile very early in the contract utilizing the majority of the required overburden excavation from the outlet works and cutoff trench. Placement of stockpile material continued off and on throughout the length of the contract. As discussed previously, the contractor misused most of the easily accessible impervious borrow material and had to use the upper borrow areas where the impervious material was not easily identifiable. As with the impervious zone for the left embankment, extensive testing was performed both at the borrow area and in the stockpile to ensure the material placed had a liquid limit less than 55. Any material found which did not meet these requirements was removed and replaced. The specification for the gravel percentage in the stockpile was not specific and the contractor was allowed to utilize lean clay with more than 5 percent gravel. In the spring of 1982, it was discovered the impervious stockpile was located too far upstream (approximately 120 feet) within the Stage II embankment limits. The contractor was required to remove and relocate about 30,000 cubic yards of material so that it would not interfere with the Stage II embankment. The original stockpile was to be 200,000 cubic yards; however the final stockpile was actually only 170,000 cubic yards. This quantity was reduced at the end of the contract because there was very little impervious material (LL<55) remaining in the designated Stage I borrow areas. This shortage of impervious was basically due to the contractor's mismanagement of the borrow areas as previously discussed.

i. Modifications. A total of 60 modifications were made to Stage I contract. Only the following 16 pertained to the construction of the embankment.

- | | |
|--------|--|
| No. 2 | Required additional overburden and rock excavation on the right abutment above elevation 887 upstream and downstream of the cutoff trench within the embankment toe trace. |
| No. 6 | Changed the sewer alignment from the left side of stilling basin to the right side. |
| No. 14 | Required the excavation and backfill of test pit in cutoff trench at station 90+70+. |

- No. 16 Required 1.) The removal of the slide material near O.W. station 52+00 and all left abutment overburden to rock downstream of the cutoff trench to the embankment toe 2.) sewer excavation adjacent to the stilling basin be backfilled with excavated overburden.
- No. 17 Required the removal of additional limestone at station 102+98.
- No. 19 Required two presplit blasting test section in the Sniabar limestone on the left abutment.
- No. 20 Change the outlet channel alignment to miss existing powerline guy wires.
- No. 22 Required the removal of two overhangs in the Bethany Falls limestone on the right abutment approximately 125-feet and 147-feet upstream of the dam axis.
- No. 25 Required the removal of overhang and the adjacent vertical face of Bethany Falls limestone at station 87+35₊, 90-feet ₊ upstream of the dam axis.
- No. 26 Required removal of fractured rock and resetting nipples for grouting in the cutoff trench between station 89+50 and 88+90.
- No. 33 Required the Sniabar limestone upstream of the cutoff trench be fractured and removed using a non-explosive demolition agent on a 1V on 1H slope.
- No. 40 Required the additional rock excavation of the Sniabar limestone in Modification 33 be extended downstream through the cutoff trench using the same non-explosive demolition agent.
- No. 41 Changed the upstream and downstream internal embankment zoning from berm fill to random fill between station 101+00 and 102+00.
- No. 46 Provided additional compensation to the contractor for slower rate of placement during curtain grouting due to a tighter rock formation.
- No. 48 Required additional presplit and production shooting of Bethany Falls limestone upstream of cutoff trench at approximate station 87+75.
- No. 55 Required the additional excavation of the unsuitable material below the bottom of the existing 48-inch sewerline and backfilling excavation with impervious fill.

8-03. Stage I Embankment Analysis. During construction of the Stage I left embankment, high pore pressures (up to about 75 percent response) were

measured in the lower part of the embankment primarily in the cutoff trench, sewer trench and conduit excavation backfills. When overflowing water levels and quick recoveries after pumping were found in the protective casing of several devices, an extensive investigation was undertaken to determine the extent of the high pore pressures and the adequacy, including stability, of the embankment. The investigation involved undisturbed sampling and testing, inspection of in-place embankment material from two large diameter auger holes OH-1 and OH-2, installation of additional instrumentation to monitor pore pressures and slope movement, and dye injection and pump tests. The investigation revealed high pore pressures in excess of 50% in the lower half of the embankment. Equipment induced shear planes or other fractures or surfaces discovered during the investigation were determined to be discontinuous. It was determined that gas escaping from the open tube devices was not from anaerobic decomposition in the fill but was apparently natural gas from deposits in the foundation rock, or might possibly have originated from gas trapped in the low lying borrow deposit. The results of the gas sample analysis are provided in Enclosure 2. Slope stability studies conducted with both total and effective stress (using measured pore pressures) analyses showed an adequate safety factor for the embankment slopes. The steepest existing slope, 1V on 3H, was found to have a safety factor of 1.8 and a safety factor of greater than 2 was found for the embankment constructed to the construction halt elevation 890. It was further concluded the embankment should perform satisfactorily as a water retention structure. A more detailed description of the investigation and its findings are provided in the "Analysis of Stage I Embankment" published in April 1983. An updated version of the write-up only is included in this report as Enclosure 1.

8-04. Stage II Contract. The Stage II contract, DACW41-82-C-0204, was awarded in August 1982 to the second low bidder, W.A. Ellis Construction Company for the amount of \$9,181,143.00, after the low bidder, Jack B. Anglin Company claimed an error and withdrew his bid. Construction began in August 1982 and was completed in September 1985. This contract included the spillway excavation, diversion and closure, completion of the embankment, construction of the service bridge, and the construction of the access and service roads. Because of the experiences in the Stage I contract and the concerns for the embankment stability, considerable effort was expended in revising and tightening the specifications and investigating the quantities of specific types of fill material available in the borrow. Based on these quantities and stability considerations, liquid limit requirements were established in detail for the embankment zones. A 6-month construction halt was scheduled in the Stage II contract when the embankment reached elevation 890. This construction halt elevation was originally specified in the DM as elevation 915; however, the construction halt was later changed because of the high pore pressures which developed in the left embankment, the actual timing of the 6-month construction halt and the relative fill quantities involved before and after the halt. In addition to the construction halt, fill placement rates were established which limited placement to 5 feet per 7-day period and no more than two lifts of fill in any 24-hour period.

a. Stage II Borrow Study. During the preparation of the Stage II plans and specifications an extensive re-analysis of the Stage II borrow area was completed. Additional drilling, sampling and testing was necessary to reanalyze the borrow area to assure that sufficient quantities of the

necessary liquid limit material were available to complete the Stage II embankment. The liquid limit requirements in the embankment zones were adjusted consistent with shear strength requirements to make best use of the material available in the borrow.

A total of 59 additional borings were completed in the west borrow area located west of old Raytown Road and 8 borings were completed in the east borrow area located south of old Longview Road. (See Plate 3.) All borings were 6-inch drive borings with a jar sample taken every 2 feet. Liquid limit, plastic limit and moisture tests were conducted to classify the material. An additional 421 liquid limit tests were completed on samples from the west borrow and 87 were completed on samples from the east borrow. The specifications called for additional testing by the contractor and placed responsibility on him to determine proper disposition of materials.

b. Diversion and Closure. The diversion and closure plan consisted of diverting the river and constructing a cofferdam in two phases. The Phase I cofferdam was to be constructed after diversion in the upstream closure area berm and random zones to elevation 878. The Phase II cofferdam was to be constructed downstream of the Phase I cofferdam and consisted of berm, random and impervious fill including backfill of the cutoff trench to elevation 887. The diversion and closure plan including sections of the Phase I and II cofferdam are shown on Plate 19.

The cofferdam heights were established in the DM based on routing various floods through the lake with the outlet works gates completely opened. The DM recommended the Phase I cofferdam height to be elevation 867 based on the October 1949 flood (fourth highest flood) which would create a lake of elevation 862.5. However, comments from MRD resulted in the height of the Phase I cofferdam being increased to elevation 878 which would protect against the second largest flood (September 1961) or lake elevation 874.4. This change was made because of the high degree of development downstream and the potential damage which could occur if the cofferdam were to fail. The height of the Phase II cofferdam, elevation 887, was designed to protect against the record flood of July 1951 which would have resulted in a lake elevation 882.3.

The contract required that diversion of the river be made between June 15, 1983 and August 1, 1983 and the Phase II cofferdam be completed by December 15, 1983. Prior to diversion the contractor had to complete the following items:

1. The left embankment cofferdam to elevation 887 as originally included in Stage I.
2. The outlet channel, including: placing bedding and riprap, grouting riprap, constructing access walk and stairs; and the removal of the protection dike adjacent to the outlet channel.
3. Final approach channel excavation.
4. The stilling basin inspection.

Within the contract there was also a list of optional items which could be completed prior to diversion. Of this list, the contractor only completed the placement of the pervious blanket and the overlying 3 feet of the corresponding embankment zones on the right side of the river.

The contractor diverted the river and began closure operations on June 16, 1983. The diversion and closure operation was performed in the following sequence:

1. The protective dike downstream of the stilling basin across the outlet channel was excavated.
2. On June 16, construction of the upstream diversion dike began and the river was diverted through the outlet works after the approach channel plug was removed.
3. The remainder of the upstream diversion dike was rapidly placed to elevation 823.
4. A portion of the fill for service road "D" between station 23+60 and 24+70 was constructed to elevation 810 to serve as a downstream cofferdam.
5. Within the Phase I cofferdam area, the material from the river channel was excavated and foundation preparation was performed on the exposed bedrock surfaces.
6. The Phase I cofferdam was rapidly constructed of berm and random material to elevation 878. Aerial views of this phase is shown in Photos 37 and 38.
7. The cutoff trench in the closure area which was not completed during Stage I (between approximately stations 93+45 and 95+80) was excavated to final grade (excavation for grouting and grouting operations were performed during Stage I) and foundation preparation was performed. The foundation treatment and fill placement in the cutoff trench closure section is shown in Photo 39.
8. The next step was to construct the Phase II cofferdam to elevation 887 before December 15, 1983. However, since diversion was made fairly early and the Phase I closure operations had gone rather quickly, the contractor elected to bring the remaining embankment up all at once rather than just the Phase II cofferdam. This fill placement is shown in Photos 43 and 46.

Shortly after diversion, heavy rains caused the Little Blue River to overtop the Phase I cofferdam which, at the time, was only a few feet above the existing ground surface adjacent to the old river channel. Some embankment material was washed away and a considerable amount of cleanup was required. The contract was modified to provide for the flood damage repair which restored the permanent work to the field conditions which existed prior to the flood damage.

Within the closure section, the pervious blanket was placed in direct contact with the foundation after the river channel was cleaned up, while the river channel downstream of embankment was backfilled with channel fill. Photo 41 shows the pervious fill placement in the old river channel and Photo 42 shows the tie-in between the adjacent pervious blanket and the pervious fill in the old river channel. The embankment toe detail within the river channel is shown on Plate 25. Downstream between station 91+00 and 93+50 an old river meander was discovered and the contract had to be modified (Modification 12) to require the removal of the debris and the low strength material. This excavation was then backfilled to the approximate adjacent ground surface with gravelly random material. The pervious blanket was then placed over the backfill rather than the foundation material.

By early November 1983, the upstream Phase II cofferdam was at the required elevation 887 while the downstream embankment averaged about elevation 880. Throughout November, adverse weather conditions prevailed and it appeared there would not be enough good working days remaining in the 1983 construction season to bring the embankment to the required construction halt elevation 890. The contractor requested the 6-month construction halt elevation be changed to elevation 880+ beginning December 1983. The Government approved the request but required the contractor do the following items prior to the construction halt: level up the embankment at station 93+00; raise the abutment contacts to provide positive drainage; level and seal the upstream cofferdam; provide erosion control for right abutment drainage ditch; and cover all pervious material with 1-foot of cover similar to the adjacent embankment material.

c. Embankment. The six month construction halt ended on June 1, 1984. The contractor had requested an early start-up date, however this was rejected because of continued high pore pressures in the embankment. In early June, heavy rains caused a lake to form which peaked at elevation 865. Although the borrow areas were inundated and numerous gullies formed on the embankment, no major damage or abnormal seepage occurred. After the high pool, the contractor removed the 1-foot impervious cover from the pervious drain and began placing fill on the downstream side. The contractor continued placing more fill on the downstream side of the embankment until the pervious drain became the highest part of the embankment and positive drainage away from the pervious drain was established. The rate of placement for fill above elevation 867 was restricted to only 5 feet of compacted fill in a 7-day period and no more than two lifts of fill in any 24-hour period. The embankment was topped out in September 1984.

d. Spillway. The 200-foot wide spillway located on the left abutment has a crest elevation 911.3 which is 2.3-feet above full pool and has a predicted use of once in 200 years. The left abutment location was selected in lieu of the right abutment due to the reduced amount of required excavation. The contractor began excavating the spillway after making diversion. The entire 550-foot length of spillway excavation was overburden consisting of relatively high liquid limit fat clay with a maximum depth of 14 feet and 1V on 6H side slopes. The contractor utilized the excavated overburden as road fill, berm or random fill. The spillway was over excavated 9 inches and brought back to grade with topsoil.

e. Service Bridge. The service bridge as shown on Plates 33 and 34 was constructed when the embankment fill reached elevation 899 (bridge deck elevation). As the fill placement progressed, the embankment began moving outward causing the service bridge expansion joints to close. Photo 63 shows a closed expansion joint and the tilted rocker. Daily monitoring of the service bridge expansion joints began in early September 1984. The movement averaged about .05-inches per day until there was concrete to concrete contact at all three expansion joints. This movement began spalling the concrete at the bridge abutment expansion joint. The joints were not repaired until the Spring 1990. A separate contract was awarded to restore the expansion joints at the abutment and the pier. Plate 34A shows the service bridge after the expansion joint repair.

f. Clay Blanket. A clay blanket was placed on the right abutment as shown on Plate 30. The clay blanket was placed between elevations 848 and 898 to control seepage thru the Bethany Falls and the Winters limestone. To utilize excess rock from the required excavations, rockfill was placed against the bedrock formations below elevation 848. Rockfill was also used to protect the upstream slope of the clay blanket (see Photo 47). Once the rockfill sources were depleted, the contract was modified (modification 26) to require 9-inch bedding and 18-inch riprap be placed between elevation 884 to 898 on the remaining face of the clay blanket slope. The complete right abutment clay blanket can be seen in Photo 72.

g. Stage II - Modifications. A total of 38 modifications were made to Stage II contract. Only the following 16 pertained to the construction of the embankment.

- | | |
|--------|---|
| No. 1 | Required that all material in the impervious stockpile be reserved for use after closure. |
| No. 8 | Provided payment for the rock excavation overrun. |
| No. 10 | Required the repair of flood damage which occurred June 28, 1983 when heavy rains caused the Little Blue River to overtop the partially completed Phase I cofferdam, and flood the old river channel. |
| No. 11 | Required the construction of a concrete headwall at the west end of the grouted riprap drainage ditch adjacent to service road "C". |
| No. 12 | Required the area of the embankment between station 91+00 and 93+50 (downstream of the centerline which had been excavated to remove debris and low strength material from the old slough) be backfilled with gravelly random material to approximately natural ground prior to placing the pervious blanket. |
| No. 13 | Required: The open tube piezometers PPE 99-13, PPE 97-13, PPE 97-14, PPE 99-10, PPE 89-2, PPE 89-3, PPE 93-10A and inclinometers I-97-1, and I-99-2 be extended thru the embankment; PPE 93-4 be changed from a pneumatic piezometer to an open tube piezometer; the location of PPE 93-4A be |

changed from station 93+00 R0+40U to station 93+00 R 2+30U; the construction of tubing ditches and the extension of tubing for 11 pneumatic piezometers; the extensions for PPE 90-1, PPE 90-2, and PPE 93-10 be deleted; and steel protective casing be installed for 9 new piezometers.

- No. 14 Changed the downstream "V" grouted gutter to a 4-foot wide flat bottom grouted toe gutter between station 87+00 and 91+00.
- No. 17 Required the borrow areas below elevation 891 be cleared completely except for the area west of Raytown Road and south of Pittenger Road; and the small area located southeast of the river immediately east of Raytown Road be cleared only to the extent necessary to obtain material.
- No. 20 Provided four lean concrete cutoff walls across the 4-foot flat bottom toe gutter on the right abutment.
- No. 22 Required: the extension of piezometers PPE 92-1, PPE 95-1, and PPE 97-16 thru the embankment and the installation of steel protective casing for each; the construction of tubing ditches and the installation of tubing for piezometers PPE 97-17, PPE 98-1, PPE 99-17, PPE 99-16.
- No. 23 Provided payment for foundation clean up overrun.
- No. 25 Required the following changes on the instrumentation monuments: changed concrete compression strength from 4000 psi to 5000 psi in 28 days; changed surface sealer from 2-inch thickness of black roofing cement to 1-inch thickness of Dow Corning 100% Silcon Rubber 795 Construction Sealant; changed rebar from 2-#4 rebars and 4-#8 rebars to 6-#4 vertical rebars equally spaced and #3 rebar circumferential horizontal ties on 8-inch centers.
- No. 26 Required 9-inch bedding and 18-inch riprap be placed on the face of the impervious clay blanket above elevation 884.
- No. 29 Required the repair of flood damage that occurred in May 1983 when rains caused the Little Blue River to overflow its banks and damage the pervious zone between stations 91+00 and 93+50.
- No. 30 Provide compensation for grouted riprap overrun.
- No. 32 Deleted the requirements for toe gutter to elevation 887+ on the upstream side of the dam near the left abutment and other minor changes.

8-05. Embankment Materials Inspection and Testing. An Excavation, Embankment, and Grouting Manual and a Field and Laboratory Testing Manual were prepared for both stages. These manuals were based on the plans and specifications and were intended as a technical guide to the Government

Inspectors and the Resident Engineer. They provided a means to better monitor the contractors work and included instructions pertaining to inspection requirements. The embankment manual also served to further explain the intent of the specification to the field inspectors. The Government inspection staff was present to witness all pertinent operation procedures and to conduct field tests. Design engineering personnel made periodic inspections, particularly during critical operations such as initial excavations, exposure of foundation surfaces, initial fill placement, diversion, and instrumentation installation.

a. Field Control Tests. Field control tests were performed to monitor moisture content, gradation, compacted density, and classification of fill material to ensure the specification requirements were satisfied. These tests were performed by the Government after the fill was compacted. The contractor was responsible for all sampling and testing to assure that materials met specified requirements prior to compaction. Monthly summaries of the field control tests were sent through Construction Division to Engineering Division and reported to MRD. Tests were performed on all material types.

(1) Impervious, Random and Berm. The field control testing for the impervious, random and berm zones consisted primarily of liquid limit and field compaction determinations. The sand cone method was used for determining the compacted density. The maximum density and optimum water content were determined in accordance with EM 1110-2-1906, Appendix VI, Standard Compaction Tests. A family of compaction curves was developed for each material source. Subsequent field tests then relied on a one-point compaction test to determine which compaction curve was appropriate. Although no fill density was specified, it was required that the fill be compacted to a minimum of 95 percent of that obtained from the standard effort compaction test. Experience had indicated that the specified moisture content and number or roller passes would achieve these densities. If the desired compaction was not achieved additional rolling was required. Due to the previously discussed problems with liquid limits on this project, liquid limits were performed on all field control samples to check compliance of the material in the various zones. If Government tests showed noncompliance with the specifications it was the contractor's responsibility to do additional testing to define limits of the "out of spec" area and to remove and replace it. The area was then rechecked by the Government.

(2) Pervious. The pervious field control testing consisted of a combination of gradation testing and in place relative density determinations. The relative density value represents a density ratio defined as the extent compaction has progressed from the loosest state toward the densest state. The minimum density was determined by placing the material dry in its loosest practical state. The maximum density was then found by vibrating the sample at a given frequency for a set time period. The detailed procedure was presented in EM 1110-2-1906 (10 May 1965).

b. Record Control Tests. Record control samples were obtained periodically from the impervious, random and berm zones. They served the purpose of checking the physical properties of the materials actually used in the dam against those properties assumed for design. Schedules of the record control sample locations and testing are shown on Plates 50 and 51 respectively. Most of the record control samples consisted of one sack and

one hand trimmed undisturbed sample 6-inches in diameter by 6-inches long (Photo 12). These samples were sent to the Missouri River Division laboratories for testing. This testing included compaction, Atterberg limits, gradations including hydrometer, moisture content, density, and shear strength determinations. Summaries of these test results are provided on Plates 52 through 85. While the actual test results are provided on half-size plates as Supplement A. The inspection staff performed standard field control tests at each record control test location. The duplication of testing by the Division laboratory and the field laboratory served to check the accuracy of the field results. A comparison between laboratories can be made by reviewing the compaction test summaries presented on Plates 79 through 85. There were some substantial variations between the laboratories in-place moisture content, compacted density, optimum moisture content and maximum dry density values. The majority of these variations are probably due to minor material changes and slightly different laboratory procedures or equipment. There is, however, a very interesting consistent variation between the laboratories' optimum moisture content results. As shown on Plates 80 and 84, the field laboratory's optimum moisture content was consistently higher than the Division laboratory's results. All of the embankment material was placed within the specified compaction requirements based on the field laboratory's standard Proctor compaction test results (95 percent maximum dry density at a moisture content between 2 percent below and 3 percent above optimum). According to the graphs on Plates 82 and 85, 26 percent of the Stage I field tests and 20 percent of the Stage II field test were outside the specified moisture range based on the field laboratory's standard Proctor test results. All of this material was supposedly removed or reworked to meet the specifications. However, these plates also show that 54 percent of the Stage I record control tests and 14 percent of the Stage II record control tests were outside the required moisture range based on the Missouri River Division laboratory's standard Proctor test results. The Division laboratory results are believed to be accurate and indicate some of the embankment material may have been placed 3 to 6 percent above optimum moisture which could have contributed to the high embankment pore pressure that developed during construction.

CHAPTER 9

OPERATIONAL NOTES

9-01. Embankment.

a. Upstream Slope. During initial filling some erosion and undercutting of the riprap occurred on the 1 on 4 slope of the conduit section. Overall, the 18-inch riprap has held up relatively well with only some minor breakdown along the waterline at multipurpose pool elevation. During the high pool in October 1986 as shown in Photo 70, the water was near the top of the lower riprap (elevation 898). Wave action displaced the riprap leaving the bedding exposed between stations 89+00 and 92+00. In August 1989, this 300 foot section was repaired with the same Bethany Falls limestone that was used for the emergency rock stockpiles. During the May 1990 record pool (elevation 897.2) no damage was caused to the lower riprap or grassed slopes because the pool rose and fell rapidly.

b. Crest. The crest road remains in good condition except for some longitudinal cracking along the downstream shoulder caused by lack of lateral support along the pavement edge. Shortly after construction, the upstream edge of the road near the right abutment grouted gutter ravelled back past the guard rail. In 1989, the edge of the road had to be repaired to prevent any undermining of the grouted gutter. After completion of the embankment, a low area in the dike on the left abutment at approximately station 104+00 was noted. This low area was approximately elevation 925.2, 1.4 feet below the design elevation of 926.6. During the spring 1990, this low area was filled and brought up to the design elevation.

c. Downstream Slope. Since completion of the embankment, the grass cover has become established with only a few sparse areas remaining (Photo 74). There are several areas along the upper interceptor ditch which do not drain properly, causing overtopping of the ditch and the formations of erosion gullies. The lower interceptor ditch at the entrance to the left abutment grouted gutter is too low causing water to pond in the interceptor ditch. This area and a few other areas along both the upper and lower interceptor ditches have been filled to provide proper drainage. Shortly after construction, erosion control fabric was installed in the toe ditch as shown in Photo 60. Since then some silting of the ditch has occurred due to runoff from the embankment and Foreman Road. After initial filling, the sand blanket between station 91+00 and 95+50 began to seep more than initially expected. This is believed to be caused by abutment seepage. See the paragraph below. During construction, the bedding covering the sand blanket was contaminated with fines washing down the slope prior to establishing grass cover. The contractor only removed and replaced the upper 6-inches of bedding material. In 1987, drains (6-inch perforated pipe) were installed through the bedding in order to reduce the head of water exiting the sand blanket. This drain installation can be seen in Photos 65 and 66. Although all drains flow, this had no effect on the piezometer level in the sand blanket. Flow from the drains and excess seepage have caused a maintenance problem in this area. The installation of a french drain between the sand blanket and the toe ditch has been recommended to monitor the seepage and alleviate the maintenance problem.

d. Abutments. Since initial filling high piezometric levels have existed in the right abutment bedrock upstream and downstream of the grout curtain. The pressurized zones appeared to be limited to the Pleasanton Zone A, B, and Middle Creek limestone/Hushpuckney shale. The seepage is probably making its way through the grout curtain, however, with the Pleasanton Zones A and B in direct contact with the upstream rockfill zone, the seepage could also be coming around the end of the grout curtain. The seepage in any case is being intercepted by the sand blanket which extends up the abutment slope. It appears the sand blanket is adequately controlling the seepage and no other problems have developed due to those high pressures. (See previous discussion in Chapter 7.) Since completion of the dam, numerous seeps from the Winterset limestone along the right abutment have caused wet areas on the impervious clay blanket. Although this is not a dam safety concern it became a maintenance problem. In 1987, a french drain was installed to dry up the area (Photo 67). However, the french drain did not extend into the draw far enough and does not intercept all of the drainage. Therefore, some wet areas in the impervious blanket still exist. The downstream right abutment grouted gutter has held up well since end of construction because it was constructed with concrete cutoff walls every 50 feet. These cutoff walls were added as a modification during construction which widen the gutter to intercept a natural draw coming down the right abutment. The downstream left abutment grouted gutter was not constructed with cutoff walls and consequently began undermining. In September 1989, concrete head walls were constructed on the left and right abutment grouted gutter where the interceptor ditches flow into the grouted gutters. Also, concrete cutoff walls were installed about every 75 feet along the left abutment grouted gutter to prevent the undermining.

9-02. Emergency Rock Stockpile. The construction of two emergency rock stockpiles were completed in March 1990, on both abutments. Photo 75 shows the completed left abutment emergency rock stockpile. The stockpiles consist of 8,084 tons of Type "A" rock 1,826 tons on the left abutment and 6,259 tons on the right abutment, and 3,231 tones of Type "B" rock, 747 tons on the left abutment and 2,484 tons on the right abutment. Rock for the stockpiles was produced from the 16-foot ledge of Bethany Falls limestone in Carefree Quarries on the northeast corner of the intersection of Highway 291 and Kentucky Road in Sugar Creek, Missouri. Listed below is the specified rock gradations:

Type "A" (Riprap)

<u>Weight</u>	<u>Specified Percent of Weight Lighter Than</u>
760#	100
570#	75-95
190#	30-50
55#	0-2

Type "B" (Bedding)

<u>Sieve Size</u>	<u>Specified Percent By Weight Passing</u>
6"	100
4"	82-95
2"	62-83
1"	32-64
3/8"	0-20

ENCLOSURES

ENCLOSURES

ENCLOSURE 1

LONGVIEW DAM
ANALYSIS OF STAGE I EMBANKMENT

TABLE OF CONTENTS

	Abstract	Page
I.	Introduction	1
II.	Embankment Pore Pressure, End-of-Construction	1
III.	Field Geotechnical Investigation	6
IV.	Laboratory Testing	10
V.	Analysis of Instrumentation Data	11
	A. Embankment Pore Pressure Measurements	11
	B. Inclinometers	13
VI.	Stability Analysis	13
VII.	Conclusions and Recommendations	14

TABLES

<u>Table No.</u>	<u>Description</u>	
1.	Listing of Instrumentation	2

I. Introduction

1. The purpose of this report is to present the results of a geotechnical investigation of the Longview Stage I embankment. At the completion of embankment construction, high pore pressures were known to exist in the lower part of the embankment. However, when overflowing water levels and quick recoveries following pumping were found in the protective casing of several devices an investigation was undertaken to determine the extent of the high pore pressures and the adequacy, including stability, of the embankment.

2. Longview Dam is constructed on the Little Blue River in southeast Kansas City, Missouri. The dam, an earthfill zoned embankment, was built in two stages. The Stage I contract, completed in the fall of 1982 (see Photos 32 and 33), consisted of foundation excavation and preparation including grouting; construction of the intake tower, conduit, relocated sewer, and stilling basin; excavation of the outlet channel; and placement of a portion of the embankment on both sides of the river. Stage II includes diversion and closure, and completion of the embankment.

3. The Stage I contract began in late summer of 1979 with the outlet works excavation. The right embankment and cutoff trench were completed during the 1980 construction season. By fall of 1980 the outlet works conduit was completed which enabled placement of impervious backfill upstream of centerline. In the spring of 1981, the outlet works backfill downstream of centerline began. Sewer diversion through the conduit took place in July and was followed by excavation and removal of the old sewer line and backfill of the excavation. Heavy rainfall throughout the spring and summer delayed work, but the fill had been raised above the conduit, El. 822+, by the end of August. By mid-November the downstream embankment was topped out to El. 867 and the upstream cofferdam to El. 870. The finished height of the Stage I cofferdam was reduced from El. 887 because of a shortage of impervious borrow for the Stage I contract.

II. Embankment Pore Pressures, End-of-Construction

4. During the Stage I construction period, 19 pore pressure devices were installed in the left embankment and foundation area (see table 1). Five of these, PPE97-1, PPE97-6, PPE99-2, PPE99-5, and PPE99-6, whose tips were located in the embankment clay showed pore pressure responses of 78, 68, 53, 13, and 56 percent, respectively, following the embankment construction in October 1981. PPE99-5 is located near the inclined sand drain which probably accounts for its lower response. It was concluded at the time (fall of 1981) that even though the responses were 50 percent and above, the tips were located within the backfill of the excavations and these pressures did not extend into the upper part of the embankment where they might contribute to slope instability. Pore pressures in the overburden and foundation shale were low or nonexistent, with one exception. PPF99-4 showed about 50 percent response. Its tip was located deep in the foundation shale and did not influence stability.

5. In January 1982, ice was observed at the top of the protective casing around PPE99-2. This was concluded to be either communication between the riser and the protective casing (since at that time the water level in the riser was higher than in the protective casing) or that water could have

TABLE 1
LISTING OF INSTRUMENTATION

Number	Station	Range	Type	Installation Date	Material Type	Tip Elevation	Zone of Sand Backfill	Bottom of Protective Casing	Ground Elevation at Installation	Ground Elevation Present	Remarks
Left Embankment											
FFE97-1	97+00	325' US	Pneumatic	3 Sep 81	Embankment-Sewer Backfill	820.2	819.6-822.2	—	823.2	870 ±	dry hole (1)
FFE97-2	97+00	210' US	Pneumatic	3 Sep 81	Embankment-Sewer Backfill/Fdn Overburden	820.6	819.6-822.6	—	827.6	870 ±	dry hole (1)
FFE97-3	97+00	200' US	Open Tube	4 Sep 81	Fdn Shale	794.8	794.5-797.5	801.5	827.5	866 ±	groundwater at EL. 810.8 (2)
FFE97-4	97+00	90' US	Open Tube	25 Feb 80	Fdn Gravel	810.5	810.2-813.3	817.7	828.2	844 ±	dry hole (3)
FFE97-5	97+00	40' US	Open Tube	2 Sep 81	Fdn Shale	785.0	784.8-788.0	792.0	825.5	839 ±	no water noted (3)
FFE97-6	97+00	15' US	Pneumatic	3 Sep 81	Embankment-Cut-off Trench	807.0	805.2-809.0	—	825.2	839 ±	dry hole (1)
FFE97-8	97+00	85' DS	Open Tube	25 Feb 80	Fdn Overburden	817.8	817.4-820.4	821.0	823.4	839 ±	dry hole (3)
FFE97-9	97+00	100' DS	Pneumatic	24 Sep 81	Fdn Shal	789.9	789.5-792.5	—	836.9	839 ±	no water noted (1)
FFE97-10	97+00	120' DS	Open Tube	2 Oct 80	Fdn Gravel	805.0	803.4-808.0	812.0	825 ±	839 ±	no water noted (3)
FFE97-11	97+00	180' DS	Open Tube	22 Sep 81	Embankment-Imp./Sand Drain	824.6	824.5-827.6	831.5	834.5	839 ±	dry hole (3)
FFE97-12	97+00	200' US	Open Tube	29 Oct 82	Embankment-Inferrious	853.6	853.4-855.6	866.6	869.6	869.6	.9' of rainwater in hole overnight; water added to fill riser to top
FFE97-13	97+00	190' US	Open Tube	30 Oct 82	Embankment-Inferrious	839.9	839.5-842.2	867.9	869.7	869.7	dry hole; water added to fill riser to top

TABLE 1 (Cont'd)

Number	Station	Depth	Type	Installation Date	Material Type	Tip Elevation	Zone of Sand Backfill	Bottom of Protective Casing	Ground Elevation at Installation	Ground Elevation Present	Remarks
PFE97-14	97+00	195' US	Open Tube	1 Nov 82	Exhaustment- Imperious	829.7	829.2-832.0	867.7	869.7	869.7	dry hole; water added to fill riser to top
PFE97-15	97+00	202' US	2" O.T.	6 Nov 82	Exhaustment- Imperious	825.4	824.9-842.7	—	869.7	869.7	dry hole; added 12 gal. of water
PFE99-1	98+51	220' US	Pneumatic	19 Aug 81	Fdn Shale	800.0	799.5-802.5	—	825.7	872	no water noted (1)
PFE99-2	98+44	80' US	Open Tube	18 Aug 81	Exhaustment- Imperious	812.0	811.3-814.3	818.8	824.3	867 ±	dry hole; 5 ga. water added
PFE99-3	98+42	40' US	Open Tube	20 Aug 81	Fdn Shale	789.7	789.4-792.7	796.7	824.7	867 ±	no water noted (3)
PFE99-4	98+38	40' DS	Open Tube	21 Aug 81	Fdn Shale	772.8	770.8-773.9	777.9	823.9	867 ±	water encountered at sand blanket El. 811.9 ± (2)
PFE99-5	98+37	60' DS	Pneumatic	21 Aug 81	Exhaustment- Imperious	818.0	817.5-820.6	—	823.5	867 ±	no water noted (1) located near inclined sand drain
PFE99-6	99+12	220' US	Pneumatic	18 Aug 81	Exhaustment- Imperious	822.5	822.0-824.0	—	826.5	867 ±	no water noted (1)
PFE99-7	98+40	70' US	Open Tube	11 Jan 82	Fdn Overburden/ Fdn Shale	810.3	808.5-811.0	816.5	866.5	866.5	no water noted (2)
PFE99-8	98+45	80' US	Open Tube	27 Oct 82	Exhaustment- Imperious	823.8	823.0-834.2	863.8	867.0	867.0	9' of water in hole after 35 min.; water added to fill riser to top
PFE99-9	99+00	50' US	Open Tube	3 Nov 82	Exhaustment- Imperious	823.4	823.3-832.2	865.2	867.2	867.2	dry hole (4)
PFE99-10	99+00	150' DS	Open Tube	5 Nov 82	Exhaustment- Imperious	823.0	822.9-832.9	863.5	866.9	866.9	.1' water overnight (5)

TABLE 1 (Cont'd)

Number	Station	Range	Type	Installation Date	Material Type	Tip Elevation	Zone of Sand Backfill	Bottom of Protective Casing	Ground Elevation at Installation	Ground Elevation Present	Remarks
PPE99-11	98+44	85' US	2" O.T.	8 Nov 82	Embankment-Impervious	821.2	820.5-839.2	—	867.2	867.2	water in hole but depth not noted (2)
PPE99-12	98+40	6	Open Tube	12 Nov 82	Embankment-Impervious	838.6	838.6-849.0	864.0	867.0	867.0	4' of water 30 minutes after drilling (4)
PPE99-13	98+40	200' US	Open Tube	16 Nov 82	Embankment-Impervious	824.8	824.5-834.9	865.9	868.9	868.9	.1' water 30 minutes after drilling (4)
PPE99-14	98+40	280' US	Open Tube	17 Nov 82	Embankment-Impervious	823.2	823.1-833.1	864.1	867.1	867.1	trace of water 45 minutes after drilling (4)
PPE99-15	98+35	6	Open Tube	13 Nov 82	Embankment-Impervious	823.2	823.1-832.9	864.0	867.0	867.0	dry hole (4)
PPE100-1	99+70	200' US	Open Tube	10 Nov 82	Fdn/Overburden Fdn Shale	815.7	813.9-825.7	866.7	869.7	869.7	.5' water in hole 30 Min. after drilling (2)
PFF 61	99+85	400' US	Open Tube	13 Apr 71	Fdn Shale	805.1	804.6-808.6	809.6	842.6	851 ±	no water noted (4)
PFF 61A	99+95	400' US	Open Tube	16 Apr 71	Fdn Overburden	813.1	812.6-816.6	817.6	842.6	851 ±	no water noted (4)
PFF 359	99+99	295' US	Open Tube	26 Feb 80	Fdn Overburden/Top of Fdn Limestone	816.0	814.5-835.0	838.0	840.0	862 ±	no water noted (4) (5)
CH-1	98+00	143' US	4" O.T.	24 Nov 82	Embankment-Impervious	825.0	825.0-864.0	—	870.0	870.0	38" auger hole backfilled with compacted sand
CH-2	98+12	6	4" O.T.	6 Dec 82	Embankment-Impervious	820.0	820.0-861.8	—	867.0	867.0	38" auger hole backfilled with compacted sand

TABLE 1 (Cont'd)

Number	Station	Range	Type	Installation Date	Material Type	Tip Elevation	Zone of Sand Backfill	Bottom of Protective Casing	Ground Elevation at Installation	Ground Elevation Present	Remarks
Night Embankment											
PZF 229	91+60	80' US	Open Tube	16 Dec 75	Fdn Gravel/ Fdn Shale	805.5	804.5-811.5	812.5	820.0	848 ±	Groundwater at El. 810.2 (2)
PFE89-1	89+50	199' US	Open Tube	29 May 82	Embankment- Random	835.1	834.8-838.8	884.0	886.8	886.8	dry hole (3)
PFE89-2	89+45	199' US	Open Tube	20 Nov 82	Embankment- Bern	862.2	862.0-866.1	884.4	886.8	886.8	dry hole (3)
PFE89-3	89+55	199' US	Open Tube	1 Dec 82	Fdn Overburden	814.3	813.3-818.1	883.4	887.3	887.3	dry hole (3)
Inclinometers											
I 97-1	97+49	189' US	Inclinometer	11 Nov 82	Fdn Shale	797.8	Top of bedrock - 807.8		870 ±	870 ±	water encountered at El. 827
I-99-1	98+36	256' DS	Inclinometer	15 Jan 82	Fdn Shale	796.5	Top of bedrock - 800.0		867 ±	867 ±	dry hole
I-99-2	98+25	85' US	Inclinometer	20 Nov 82	Fdn Shale	797.8	Top of bedrock - 809.6		867 ±	867 ±	water encountered at El. 835.5

Legend

PFE	Pore Pressure Device - Embankment
PFF	Pore Pressure Device - Foundation
PZE	Piezometric Device - Embankment
PZF	Piezometric Device - Foundation
OH	Observation Hole - Large Diameter (38") Auger Hole
I	Inclinometer

- (1) Pneumatic cell filter stone was saturated prior to installation and sand surrounding cell was saturated prior to sealing off cell.
 (2) Wet installation, no additional water added to riser.
 (3) Sand surrounding device saturated after riser installed.
 (4) Dry installation, no water added to riser.
 (5) Station and Range as of February 1983

* Abandoned as of March 1983

entered the casing by a number of external sources such as rainfall, or by someone inadvertently or deliberately pouring water down the casing.

6. To determine the source of this water and to obtain additional undisturbed record control samples, PPF99-7, an open tube device, was installed in early January 1982 in the foundation overburden/foundation shale contact 10 feet downstream from PPE99-2. By the end of the month, water had filled the casing of PPF99-7. On this basis, it was concluded the water was coming from unknown external sources and not from the fill itself. Communication between the riser and the casing was not likely since the water level in the riser was 45 feet lower than in the casing. In addition, water had not been observed in the casings on other KCD projects unless the riser had overflowed. It was believed that the casing with slip joint couplings supplied with "O" rings would be watertight. In addition, it was not believed possible that pore water in an impervious fill could accumulate that fast in the casing when the usual experience is that a large amount of water must be added to open tube devices to bring them to equilibrium.

7. By fall of 1982 the devices began showing varying degrees of dissipation of pore pressure. However, in September 1982 in preparation for winter, the water levels in the casings of PPE99-2 and PPF99-7 were lowered as much as 10 feet to prevent freezing, but one week later the water had recharged to its original level in PPE99-2 and had recharged halfway in PPE99-7. In addition gas bubbles were being released from the casing water of PPE99-2. There was no known external source of water. It appeared that the protective casings and the risers were acting as separate measuring devices. The protective casings were apparently registering higher pore pressures at points higher in the embankment, possibly near the mid-height. These pressure levels apparently exceeded 50 percent response.

8. An extensive investigation was undertaken to determine: 1) the extent and magnitude of pore pressure levels in the embankment, and 2) the source of apparently excess water in the impervious zone of the embankment.

III. Field Geotechnical Investigation

9. Starting on 25 October 1982, twelve open tube pore pressure devices were installed at various locations and depths in the left embankment between station 97+00 and station 101+00 to determine if a zone of high pore pressure did exist near the mid-height of the fill and if it did, to define its limits. All instrumentation holes were continuously sampled with a 5-inch Hvorsley Shelby tube sampler. Since it was suspected that use of drilling fluid may have caused hydraulic fracturing of the fill at PPF99-7, all succeeding holes were cleaned after each push with a 6-inch box auger and no drilling fluid was used. Some squeezing of the hole occurred after the holes had been advanced to about 30 feet. (This was also about the same depth water was encountered in several of the holes.) In taking the undisturbed sample the driller lowered the Hvorsley sampler usually until a slight seating resistance was encountered (normally .2 to .3 feet above the clean-out depth). This allowed space for any material reamed from the hole sides by the sampler. Inspection of the samples (some were sliced thin and air dried) did reveal a few cases of disturbance at the top of the sample which may have been caused by seating or heaving of the hole. Generally the quality of the undisturbed samples was excellent.

10. Drilling started with hole PPE99-6, located about 11 feet from PPF99-7. Free water was encountered while it was being drilled. Thirty-five minutes after drilling was completed, the hole had 9 feet of water in it. There was concern the fill was cracked or had been hydraulically fractured from the earlier use of drilling fluid in hole PPF99-7.

11. To investigate the lateral extent of these fractured zones dye was added to piezometers PPE99-8 and to subsequently drilled PPE97-13 on 3, 4, and 5 November. Drilling began on PPE99-11 located 5 feet from PPE99-8 on 7 November 1982. Free water was encountered in drilling this hole, however no dye was found, either in the water or in the undisturbed samples. When the water was bailed to the bottom of the hole, water levels in adjacent devices PPE99-8 and PPE99-2 were affected. The casing water level in PPE99-2 (about 6 feet from PPE99-11) dropped 3.1 feet and the riser water level in PPE99-8 dropped 8 feet. PPE97-15, located 5-1/2 feet from PPE97-13, was drilled on 6 November. No free water or dye was encountered. No trace of dye was found in any of the undisturbed samples.

12. In addition, after adding water to the top of the riser in PPE99-8 shortly after installation, the water was observed surging up and flowing out the riser. This phenomenon was not understood at the time, however it was speculated this could have been sudden movement (shearing) of the fill or could possibly be associated with the escape of gas from the riser since the fluid was very "bubbly." Gas bubbles were observed escaping from several of the devices. There was also speculation the fill might contain a shear zone or cracks from differential settlement over the conduit and the adjacent alluvium, but it was still considered more likely that this area of the fill had been hydraulically fractured. There was also concern that the gas was an indication of organic material in the fill.

13. The undisturbed samples from all holes were closely examined to determine if shear surfaces, cracks, free water, or organic material could be found. The samples usually had a tendency to break on both smooth horizontal planes (see Photo 27) and on more irregular surfaces which had a raindrop-type texture (see Photo 28), as if they had been wet at one time. However, no free water was found, except from one sample from hole PPE99-14, El. 835.3, where a slight indication of free water was found, and from one sample from PPE97-13, El. 839.3, which appeared even wetter. More samples were examined from other holes and these planes were found in most samples examined except to perhaps a lesser extent in those from near the ground surface. Some of the planes could be lift surfaces, however close spacing and orientation precluded others from being lift planes. Most of the planes did not give any indication that free water had traveled over their surfaces. The planes often seemed to be coated with silt or appeared to be a silt parting. No organic material was found in any of the samples. A high angle fracture was found in sample 8 from PPE97-14, depth 40.0' to 40.5', El. 829.2-829.7. This fracture did not extend to any adjacent holes and may have been caused by drilling and sampling procedures.

14. Two inclinometers in addition to I-99-1 (previously installed in January of 1982 on the downstream slope) were installed to determine if any significant slope movement was taking place on the temporary IV on 3H and IV on 3.5H slopes parallel to the river. To date, these devices have not shown any indication of significant movement.

15. The open tube devices with tip below a depth of about 30 feet began showing water levels either close to the top of the riser or began overflowing. In several installations (PPE99-9, PPE99-10, PPE99-11, PPE99-13, PPE99-14, and PPE99-15) the tip was installed dry. No water was added to bring the device to equilibrium. Yet, the water level in the riser rose typically 1 to 2 feet per day. PPE99-13 rose at a rate of about 9 feet per day. As noted previously, this is contrary to behavior observed previously at KCD projects. Those which overflowed, PPE97-14 PPE99-9, PPE99-10, and PPE99-13, were equipped with pressure gauges and air eliminator valves. The pressure began approaching and in some cases exceeded previously monitored pore pressures in the lower portion of the embankment. However, the air eliminator valves were later found not to be effective in completely removing gas from the devices. It was later concluded the readings were higher than the actual pore pressures since gas partially displaced the water in the riser.

16. The right embankment area was originally instrumented with only one piezometer located in the foundation gravels. When these higher pore pressures were found on the left embankment, three pore pressure devices were installed in November 1982. Their tips were located in the foundation overburden, the random fill zone, and the berm fill zone. The berm shows no evidence of pore pressure. Pore pressure response in the random zone was 30 percent, while the response in the foundation was 25 percent.

17. In order to be sure the embankment was suitable and in fact stable, it was considered prudent to auger two large diameter (38-inch) holes to allow detailed inspection of the fill (see Photo 26). The locations were selected at station 98+00, range 143 u/s and at centerline near the edge of the intersection of the 1V on 3H and 1V on 3.5H slopes. This was considered the most likely location for differential settlement cracks or for a shear zone associated with slope instability to appear. Holes OH-1 and OH-2 (see Plate 49) were drilled in ten foot increments to depths of 45 and 47 feet, El. 825 and El. 820 respectively. Temporary casing was installed to allow personnel to safely enter for inspection and sampling (both bars and hydraulically jacked 5-foot diameter undisturbed samples were taken).

18. In OH-1, water seeps were observed at 22 feet, El. 848 (see Photos 29 and 30); 24 feet, El. 846; and 34 feet, El. 836 (see Photo 31). Gas bubbles were observed forming on some of the wet surfaces. At a depth of 32 feet the air in the auger hole contained 10 percent combustible gas according to measurements from a portable gas "sniffer." Although the quantity of water coming from the seeps was not large enough to collect, after about a week the sidewalls had become wet below the seep areas. Concentric cracking also had developed and these cracks had free water on the surfaces.

19. The second hole, OH-2, was drilled on the centerline to determine if any fracturing extended through the central impervious core of the dam. Water was encountered only at 23 feet, El. 844. A thin, very silty lean clay zone was encountered at 37.3 feet, El. 829.7. The rest of the embankment material seem to be well placed and well compacted with only the usual material color changes taking place along with minor variations in stiffness. The planes or fractures were not as evident as they had been in the undisturbed Shelby tube samples. It appeared some planes on the side wall and in the cuttings (similar to ones previously observed) were in fact caused by mechanical

shearing from the auger. It is considered likely that many of planes observed in the undisturbed samples were caused by mechanical shearing from construction equipment (e.g. scraper pan, motor patrol blade, or pumping action from heavily loaded scraper tires), or could be related in some way to the drilling and sampling procedures. Similar planes were observed at Blue Springs Dam following stripping operations performed with scrapers. These planes were of limited extent (equipment width) and tended to dip only slightly from horizontal and in the direction of equipment movement. They appeared to have been caused by shearing action of the scraper pan. Their length was relatively short, generally 5 feet or less.

20. Gas samples were collected from the open tube devices after the observation of gas in the instrumentation risers and casing and after combustible gas was detected in the auger hole. Initial attempts were made with a small neoprene balloon. A local commercial lab analyzed the gas as a "50 percent methane/50 percent air" mixture. (See Enclosure 2.) Since no organic material other than undecomposed small roots was found in any drill hole the source of the methane was unexplained. The flammability of the gas in all the open tubes which had pressure gauges was checked by holding the air release valve open. In all cases where a quantity of gas had built up, the gas could be ignited (see Photo 34). Taking care to avoid dilution or contamination, two additional gas samples were taken in stainless steel "bombs" and analyzed by the Environmental Lab at the Waterways Experiment Station. These were taken from PPE99-9 and PPE99-10. Both have tips located in the impervious embankment, but PPE99-10 is isolated by the sand blanket from other suspected sources of gas such as the abutment, the foundation, and the relocated sewer. It is also isolated from the impervious core and upstream fill by the inclined sand drain.

21. Results of the WES tests on samples from both locations show the content of methane (percentage by volume) varies from 65 to 70 percent and that of carbon dioxide varies from 16 to 20 percent. An aerobic decomposition of organic material normally results in a lower methane content and a much higher carbon dioxide content than was found in the samples. The gas analysis showed that the fill was not producing methane as a result of decomposition of organic material. The results of the gas tests are provided as Enclosure 2. Analysis of water samples from the devices showed no indication of treated water or sewage. The results from the water analysis are provided in Enclosure 3. It was initially hypothesized that the gas was present in the soil voids in the low lying borrow deposit, either as a result of underlying gas fields or overflow of sewerage. It is difficult to believe the gas could escape from the foundation or the sewer, pass through the pervious zone and into the impervious fill, considering the high pore pressures present in the latter as opposed to no excess pressures in the former. However, if enough capillary tension existed in the sand fill it may be possible for the gas to pass through the pervious zone.

22. In addition to dye injection, pump tests were conducted at two of the installations (PPE97-15 and PPE99-11) which were installed with 2-inch diameter PVC risers and a 15-foot section of 2-inch slotted well screen. Each were located adjacent to piezometers to provide monitoring of drawdown. Initial pump testing drew the water level down only 12 feet, the drawdown being limited by the pump suction. This had no discernible effect on adjacent devices. Subsequent "pump testing" was actually done by bailing rather than

pumping in order to draw the water surface down farther. Pumping PPE97-15 affected the water level only in PPE97-13 (5.5 feet away). It did not affect PPE97-12 (7 feet away), and PPE97-14 at (8 feet away). Pumping PPE99-11 immediately affected the water level in PPE99-8 (5.0 feet away) and the casing water level of PPE99-2 (6.5 feet away). Casing and tip water levels in PPE99-7 (approximately 17 feet away) were not affected. This data and data from the dye injection indicate some fractures or cracks do exist over at least limited areas and may be capable of transmitting water only short distances, say less than about 10 feet.

23. Coefficients of permeability were determined. Using the results of dye injection, field falling head permeability tests conducted in conjunction with the dye injection, and recharge data from pump tests. Dye injection showed a seepage velocity of .0019 cm/sec or a k of 10^{-3} cm/sec. Falling head permeability data yield a k on the order of about 10^{-5} to 10^{-6} ; recharge data shows a range from about 10^{-4} to 10^{-6} . These permeability values are also consistent with the rather rapid rise of the water level in several of the installations at station 99+00. It is difficult to believe this quantity of water could flow at this rate (about .5 gallons per day) from a compacted "impervious" fill. It can only be theorized that the presence of fractures or cracks increase the area of the drainage boundary. This allows faster collection of water produced from consolidation or pore pressure dissipation in the area surrounding the borings. Since the induced construction pore pressures obviously have only dissipated slightly these numbers can be indicative of only localized areas

IV. Laboratory Testing

24. The laboratory investigation consisted of classification testing of both jar and undisturbed samples; and strength and permeability testing of undisturbed samples. Jar samples were obtained both during the installation of instrumentation and from the side walls of the two large diameter auger holes. Undisturbed samples along with sack samples were obtained for record control testing during construction. Additional undisturbed samples were obtained from push samples taken both during the installation of instrumentation and from the side walls of the two large diameter auger holes. Testing was also done on a sack sample taken from a small seep area located on the IV on 3.5H slope of the left embankment.

25. Water content, Atterberg limits, and/or mechanical analysis tests were performed on representative jar samples. Specifications for the left embankment between station 97+00 and station 101+00 required a liquid limit of less than 55 and a moisture content between 2 percent below and 3 percent above the standard Proctor optimum moisture content. Very few of the liquid limit results exceeded the liquid limit requirement. A review of the field compaction data compiled as the embankment was constructed indicates a mean moisture content of 1.2 percent above optimum with a standard deviation of ± 1.4 percent. (See also paragraph 8-04.b. for discussion of moisture content vs optimum water content.)

26. Testing of undisturbed samples consisted of unconsolidated-undrained triaxial compression "Q" tests; consolidated-undrained (with pore pressure measurement during shear) triaxial compression \bar{R} tests, drained direct shear "S" tests, and constant head permeability tests. The record control samples

taken during construction had "Q", "R" and direct shear "S" tests run on each sample. At the time of this report there had been a total 14 "Q", 20 "R", 15 "S" and 16 direct shear "S" tests performed on material from the left embankment. The results of the "Q" tests confirm the design strength of $c = .9$ tsf (see Plate 54). The effective stress "R" or "S" strength envelope developed from record control and recent testing indicated strength parameters of $c = .15$ tsf and $\tan \phi = .49$. This compares with the design strength envelope of $c = 0.0$, $\tan \phi = .50$ shown on Plate 54.

27. Three horizontal constant head permeability tests were performed on samples from OH-2 with the first sample being oriented with existing planes. The two other tests were run on a silty lean clay material encountered deeper in hole. The permeability of the first sample was 1.9×10^{-7} cm/sec while the permeability of the two samples in the silty material was 2.2×10^{-8} and 2.6×10^{-8} cm/sec.

28. Moisture density tests were run on a sack sample obtained from a seep area on the LV on 3.5H slope at station 97+35, range 60' u/s, El. 848. Triaxial "Q" and "R" testing was done on samples remolded with a water content of 3 percent above optimum. Results from the "Q" test were slightly below design strength. Effective stress data from the "R" testing indicated a strength above the design envelope.

V. Analysis of Instrumentation Data

A. Embankment Pore Pressure Measurements

29. The pore pressure in the devices installed in the embankment during construction peaked shortly after the cessation of Stage I fill placement in November 1981 and dissipated slowly until resumption of construction. Pressure in PPE97-1, installed in the old sewer-excavation backfill, peaked at a level of almost 28 feet above the top of the embankment, El. 898, and dissipated 10 feet. Pressure in PPE99-6, installed near the foundation, upstream of centerline and left of the conduit, rose to 6 feet above the fill and dissipated 3 feet. The water level in PPE99-2, the only open tube with its tip installed in the fill, peaked at a level of 3 feet above the fill and dissipated 16 feet.

30. The twelve additional open tube pore pressure devices, installed in the left embankment area since October 1982 were all in the embankment impervious zone. Two devices (PPE97-12, PPE99-12) installed in the upper 20-30 feet of the fill showed no pore pressure. PPE97-13 (tip at about 30 feet) showed about 30 percent response.

31. Three pore pressure devices stabilized with their water level within about 10 feet or less below the top of the embankment. They include PPE99-8, PPE99-11, PPE97-15. These devices had tips at elevations of about 821 to 832. The remaining six devices (PPE97-14, PPE99-9, PPE99-10, PPE99-13, PPE99-14, and PPE99-15) had pore pressures in excess of 50 percent. All had tips in a zone from about El. 823 to 833. All were equipped with pressure gauges and air eliminator valves. Although these valves have been used successfully in the past on other KCD projects to remove gas from piezometers they have not worked well here. As long as the gas accumulated slowly and at relatively low pressures, the air eliminator system worked. However, when gas accumulated

rapidly and at higher pressures the valve did not release the gas and allowed it to build up and cause an abnormally high gauge reading making the magnitude of the pore pressure impossible to determine. When the gauges were removed a mixture of both water and gas bubbles would overflow the riser. Some of these bubbles were from gas coming out of solution as the pressure was reduced. However the earlier described phenomenon with the piezometer surging, then overflowing had occurred prior to the installation of a gauge. It is believed possible that gas was somehow trapped in the riser and had to develop a certain volume or pressure before it would rise to the top. Evidently a larger diameter riser (e.g. PPE99-11 and PPE97-15) allows gas that collects in the riser to escape more easily with less effect on the water column. It appears, therefore, that the column of water in the riser was not all water but a mixture of water and highly concentrated trapped gas bubbles.

32. This was further evidenced when gauges were initially removed from PPE99-9, PPE99-10, and PPE97-14, and a collector was fabricated to catch any overflow from the risers. The collector allowed the monitoring of both the amount of overflow and the fluctuation of the water level in the riser. The devices do not overflow at a constant rate over any given period of time. As an example, PPE99-10 overflowed 38 ounces between 14 February and 17 February. By 18 February it had overflowed an additional 18 ounces. On 1 March, the collector contained 99 ounces after just 4 days but the water level in the riser had fallen to a depth of 29 feet. The next day, 2 March, the water level had come up 10 feet to a depth of 19 feet. By 3 March it had come up an additional 5.5 feet and was rising at a rate 1/4-foot per hour. It was rechecked on 11 March and found that it had overflowed and was frozen. Fluctuations of the water level in the other riser are not as extreme, but all devices have shown fluctuations up to 2 feet within a few minutes.

33. The water level in the casings of PPE99-2, PPF99-7, PPF99-3, and PPF99-4 are also acting as separate devices. All water levels are slightly above the top of the embankment. Both PPF99-3 and PPF99-4 casings have consistently bubbled with escaping gas.

34. Based on the above data it is believed the pore pressure response in this zone between El. 820+ to 830+ is probably on the order of 50 to 60 percent.

B. Inclinerometers

35. Three inclinometers have been installed in the left embankment. I-99-1, installed in January 1982, is located on the downstream LV on 4H slope adjacent to the river closure section. The maximum movement indicated has been to 1/10-inch downstream and 4/10-inch riverward. Movement is toward the river where the embankment slope is LV on 3.5H. I-99-2 and I-97-1 were installed in November 1982 near the riverward slope of the embankment, upstream of centerline. I-99-2, on the LV on 3.5H slope, has indicated a maximum movement of approximately 1/10-inch in the downstream direction and essentially no movement toward the river. I-97-1 has indicated a maximum movement of approximately 1/10-inch both in the downstream direction and the riverward direction.

VI. Slope Stability

36. Stability studies were made for the end-of-construction condition using both total stress and effective stress methods. The computer program used was STABR developed by the University of California at Berkeley which uses Bishop's modified method of analysis and a circular failure surface. The program contains a searching routine which varies both the center of the circle and the radius of the circle until the minimum safety factor is found. Critical minimum slides were checked by a hand analysis to verify the computer safety factor. Pore pressure contours developed from measured induced construction pore pressures were used for the effective stress analysis. The shear strength for the soil was determined from record control testing and from testing on undisturbed samples taken during the field investigations. The total stress analysis used "Q" strength and the effective stress analysis used drained "S" and undrained "R" strength with pore pressure measurements.

37. Two slope configurations have been studied on the left embankment: (1) the IV on 3H slope along the closure area with the embankment at El. 871 which is the existing condition, and (2) the upstream IV on 4H slope in the conduit section with the embankment completed to the construction halt, El. 890. Pore pressures used for this latter case were based on measured pore pressures and the assumption that the additional embankment load would cause a pore pressure response of 50 percent. A 50 percent response is reasonable based on previous KCD experience where pore pressure has been allowed to dissipate after a construction halt. Generally the additional response should be less after some dissipation (consolidation) has occurred.

38. Initial studies begun in December 1982 (with construction induced pore pressures reflecting the highest pressure gauge readings) showed a minimum safety factor of 1.47 for the temporary IV on 3H slope. Both a total stress and an effective stress analysis was conducted for the IV on 4H upstream slope constructed to El. 890. The minimum safety factor for the effective stress analysis was 1.23 while the minimum safety factor for the same slide for a total stress analysis resulted in a safety factor of 2.1. Later it was concluded the high pore pressures indicated by the pressure gauges were not valid because of the influence of gas and further analyses were conducted with the pore pressure contours believed to be more representative of actual conditions. Minimum safety factors for the IV on 3H slope were found to be 1.8 and for the IV on 4H upstream slope were found to be 2.3 (compared with the total stress safety factor of 2.1).

VII. Conclusions and Recommendations

39. Conclusions from the investigation are as follows:

a. Induced construction pore pressures in the left embankment ranged up to about 75 percent in a zone within backfilled excavations, El. 810+. Above this area, El. 820+ to 830+, pore pressure responses were about 50 to 60 percent. No pore pressures are present in the top 20+ feet of the fill. Pore pressures induced in the foundation overburden and shale are generally low or nonexistent.

b. Shear planes or other fractures or surfaces do not affect the integrity of the embankment. These fractures or planes apparently are a major

factor in the relatively fast response in some of the open tube devices and in the protective casings. However, all evidence, (dye tests, pump tests, the very existence of high pore pressure in the fill, and the conclusion that the fractures or planes were mechanically induced by construction equipment or in some cases by drilling and sampling procedures) suggests these planes, while numerous, are of limited extent and are not continuous.

c. The gas sampled from the fill is not coming from decaying organic material in the fill, or from the sewer in the conduit structure. The exact source of the gas is unknown but may have been present in the soil as it came from the low lying borrow deposit or may be coming from the foundation. The presence of the gas makes it very difficult to determine the magnitude of the pore pressure with open tube devices.

d. Inclinometers installed at the most critical locations indicate no significant movement of any of the slopes.

e. Stability analyses show an adequate safety factor (1.8) for the steepest existing slope and current pore pressure conditions. An adequate safety factor (2.1 to 2.3) was also found for the embankment constructed to the construction halt elevation.

f. In summary the embankment is found to be stable and is expected to perform satisfactorily as a water retention structure.

40. As a result of the investigation the following recommendations were made:

a. Given the relatively high construction pore pressures close monitoring of pore pressure and slope movement (inclinometers) should continue as the Stage II embankment is constructed. In addition because of the presence of fractures, continued close monitoring will be necessary during initial reservoir filling.

b. To facilitate ease of construction (i.e. to reduce the number of risers brought up with fill) and to resolve problems with the effect of gas on measured pore pressures, small diameter pneumatic air cells should be installed at the tips of the 3/4-inch open tube risers.

c. Stability should be reanalyzed at the time of the construction halt.

ENCLOSURE 2
LANGSTON LABORATORIES, INC.

Laboratory Report

Date Received: December 8, 1982
Time Received: 10:30 am
Date Completed: December 15, 1982

Submitted by: U.S. Army Corps of Engineers
700 Federal Building
Kansas City, MO 64110
Attn: Mr. Robert Dimmitt

LLI Project No.: 82-9415

Sample Description: Balloon

Sample
Identification

Analysis

Results

Gas in Balloon


Methane

approximately 50%

Air

approximately 50%

Comments:

Approved: 

Alan Kerschen
Laboratory Director



DEPARTMENT OF THE ARMY
WATERWAYS EXPERIMENT STATION, CORPS OF ENGINEERS
P. O. BOX 631
VICKSBURG, MISSISSIPPI 39180
18 January 1983

REPLY TO
ATTENTION OF:
Environmental Laboratory

Mr. Robert Dimmitt
USCE, Kansas City District
Room 816
700 Federal Building
601 E. 12th Street
Kansas City, MO 64106

Dear Mr. Dimmitt:

The analysis of the gas samples taken at wells 99-9 and 99-10 are enclosed (enclosure). The analytical results shown are averages of duplicate gas chromatographic runs.

The ratio of gases in the samples is not what has normally been observed in gas mixture formed by anaerobic decomposition of organic matter. Most decomposition gases would have less methane and greater proportion of carbon dioxide. This suggests gas is not forming in the fill material itself. If there are any questions regarding the analyses please contact Richard A. Shafer at FTS 542-3943.

Sincerely,

Philip G. Malone
Philip G. Malone, Ph.D.
Geologist
Water Supply & Waste
Treatment Group

RESULTS OF GAS ANALYSES FROM
PIEZOMETERS AT LONGVIEW DAM

Sample	<u>% By Volume</u>			
	Oxygen	Nitrogen	Methane	Carbon Dioxide
99-9-1	0.24	13.4	69.3	16.5
99-9-2	0.20	13.0	66.5	19.5
99-10-1	1.46	17.0	65.0	16.0
99-10-2	6.04	32.0	51.0	10.0

APPENDIX

Gas Sample Collection

Pertinant Data:

PPE 99-9

PPE 99-10

Station 99+00

Station 99+00

Range 50' US

Range 1+50' DS

Bottom of Hole El. 823'

Bottom of Hole El. 823'

Zone of sand backfill at tip 8.9'

Zone of sand backfill at tip 10'

Installation Date: 3 November 1982

Installation Date: 5 November 1982

No water encountered during drilling.

No water encountered during drilling.

No water added after backfill.

Sand backfill saturated with 4.0
gallons of water (initial water
level convert to El. 831.3)

A water trap device was assembled to aid in obtaining gas samples. The unit used two pressure gages, one on the line leading from the piezometer riser into the water trap and the other attached to the water trap chamber. Four valves are used to regulate flow through the device. One valve was located between the riser and the water chamber, one between the water trap chamber and the sampling tube, and two located at the bottom and top of chamber to aid in the filling and de-airing of the chamber. The chamber was filled with water to minimize the amount of air that would have to be chased out of the system to obtain a pure sample.

The procedure used to obtain gas samples is as follows:

1. If the piezometer has been winterized, remove as much diesel as possible.
2. Fill riser to the top with water.
3. Fill water trap with water removing as much trapped air as possible.
4. Attach metal connect to open tube riser using teflon tape or other sealer.
5. With all valves closed attach water trap to riser.

83/27

ENCLOSURE 3
DEPARTMENT OF THE ARMY
MISSOURI RIVER DIVISION, CORPS OF ENGINEERS
DIVISION LABORATORY
OMAHA, NEBRASKA 68102

MRD Lab. No.

717

13 JAN 1983

Subject: Tests of Water

Project: _____

Intended Use: _____

Source of Material: Longview PD 97-3

Submitted by: _____

Date Sampled: _____

Date Received: _____

Method of Test or Specification: APHA Standard Methods

References: _____

<u>Tests Run</u>	<u>Test Result</u> ①
COD	24
PH	7.8
Suspended Solids	28
Dissolved Solids	324
Alkalinity to Phenolphthalein as CaCO_3	0
Alkalinity to Methyl Orange as CaCO_3	198
Bicarbonate (HCO_3)	242
Carbonate (CO_3)	0
Total Hardness as CaCO_3	153
Calcium (Ca)	30
Magnesium (Mg)	19
Carbonate Hardness as CaCO_3	198
Non-carbonate Hardness as CaCO_3	0
Sulfate (SO_4)	55
Chloride (Cl)	13
Nitrate (NO_3)	0.02
Sodium (Na)	55
Potassium (K)	3
Iron (Fe)	} dissolved .024 ppm total } 1.936
Manganese (Mn)	
Silica	13
Ammonia (NH_3)	0.13

Remarks

① All values shown except pH are expressed as parts per million

83/27

DEPARTMENT OF THE ARMY
MISSOURI RIVER DIVISION, CORPS OF ENGINEERS
DIVISION LABORATORY
OMAHA, NEBRASKA 68102

MRD Lab. No. 718
13 JAN 1983

Subject: Tests of Water

Project: _____

Intended Use: _____

Source of Material: Kouquinn P299-2

Submitted by: _____

Date Sampled: _____

Date Received: _____

Method of Test or Specification: APHA Standard Methods

References: _____

<u>Tests Run</u>		<u>Test Result</u> ①
COD		79
PH		7.3
Suspended Solids		275
Dissolved Solids		1170
Alkalinity to Phenolphthalein as CaCO ₃		0
Alkalinity to Methyl Orange as CaCO ₃		785
Bicarbonate (HCO ₃)		956
Carbonate (CO ₃)		0
Total Hardness as CaCO ₃		1025
Calcium (Ca)		314
Magnesium (Mg)		58
Carbonate Hardness as CaCO ₃		785
Non-carbonate Hardness as CaCO ₃		240
Sulfate (SO ₄)		3
Chloride (Cl)		18
Nitrate (NO ₃)		0.00
Sodium (Na)		24
Potassium (K)		7
Iron (Fe)	} dissolved 0.146 ppm 0.649 ppm	} 43.02 10.6
Manganese (Mn)		
Silica		18
Ammonia (NH ₃)		1.06

Remarks

- ① All values shown except PH are expressed as parts per million.
② See back

83/27

DEPARTMENT OF THE ARMY
MISSOURI RIVER DIVISION, CORPS OF ENGINEERS
DIVISION LABORATORY
OMAHA, NEBRASKA 68102

MRD Lab. No. 719

13 JAN 1983

Subject: Tests of Water

Project: _____

Intended Use: _____

Source of Material: Konguian P2 99-4

Submitted by: _____

Date Sampled: _____

Date Received: _____

Method of Test or Specification: APHA Standard Methods

References: _____

Tests Run	Test Result ^①
COD	77
PH	8.1
Suspended Solids	93
Dissolved Solids	680
Alkalinity to Phenolphthalein as CaCO_3	0
Alkalinity to Methyl Orange as CaCO_3	486
Bicarbonate (HCO_3)	593
Carbonate (CO_3)	0
Total Hardness as CaCO_3	286
Calcium (Ca)	83
Magnesium (Mg)	19
Carbonate Hardness as CaCO_3	486
Non-carbonate Hardness as CaCO_3	0
Sulfate (SO_4)	53
Chloride (Cl)	26
Nitrate (NO_3)	0.00
Sodium (Na)	107
Potassium (K)	16
Iron (Fe)	} dissolved 0.171 ppm 1233 ppm total 3
Manganese (Mn)	
Silica	22
Ammonia (NH_3)	0.00

Remarks

① All values shown except pH are expressed as parts per million

93/27

DEPARTMENT OF THE ARMY
MISSOURI RIVER DIVISION, CORPS OF ENGINEERS
DIVISION LABORATORY
OMAHA, NEBRASKA 68102

MRO Lab. No.

720

13 JAN 1983

Subject: Tests of Water

Project: _____

Intended Use: _____

Source of Material: Longview P2-99-3

Submitted by: _____

Date Sampled: _____

Date Received: _____

Method of Test or Specification: APHA Standard Methods

References: _____

<u>Tests Run</u>	<u>Test Result</u> ①
COD	63
PH	7.3
Suspended Solids	155
Dissolved Solids	632
Alkalinity to Phenolphthalein as CaCO_3	0
Alkalinity to Methyl Orange as CaCO_3	550
Bicarbonate (HCO_3)	671
Carbonate (CO_3)	0
Total Hardness as CaCO_3	516
Calcium (Ca)	158
Magnesium (Mg)	30
Carbonate Hardness as CaCO_3	550
Non-carbonate Hardness as CaCO_3	0
Sulfate (SO_4)	26
Chloride (Cl)	16
Nitrate (NO_3)	0.00
Sodium (Na)	19
Potassium (K)	4
Iron (Fe)	} dissolved 0.073 ppm total } 57.36
Manganese (Mn)	
Silica	14
Ammonia (NH_3)	0.20

Remarks

① All values shown except pH are expressed as parts per million

83/27

DEPARTMENT OF THE ARMY
MISSOURI RIVER DIVISION, CORPS OF ENGINEERS
DIVISION LABORATORY
OMAHA, NEBRASKA 68102

HRD Lab. No. 721
13 JAN 1983

Subject: Tests of Water

Project: _____

Intended Use: _____

Source of Material: Bongman P2-99-7

Submitted by: _____

Date Sampled: _____

Date Received: _____

Method of Test or Specification: APHA Standard Methods

References: _____


<u>Tests Run</u>	<u>Test Result</u> ①
COD	68
PH	7.8
Suspended Solids	33
Dissolved Solids	1010
Alkalinity to Phenolphthalein as CaCO_3	0
Alkalinity to Methyl Orange as CaCO_3	872
Bicarbonate (HCO_3)	1064
Carbonate (CO_3)	0
Total Hardness as CaCO_3	477
Calcium (Ca)	137
Magnesium (Mg)	33
Carbonate Hardness as CaCO_3	872
Non-carbonate Hardness as CaCO_3	0
Sulfate (SO_4)	75
Chloride (Cl)	50
Nitrate (NO_3)	0.00
Sodium (Na)	200
Potassium (K)	11
Iron (Fe)	} dissolved 0.805 ppm total } 0.8
Manganese (Mn)	
Silica	2.8
Ammonia (NH_3)	0.96

Remarks

① All values shown except PH are expressed as parts per million
725 Small

PHOTOGRAPHS

PHOTOGRAPHS




1. March 1990. Overview of completed embankment from downstream of right abutment.


CONSTRUCTION EQUIPMENT



2. 1983. Two Caterpillar D-9s loading Cat 631 scrapers in upstream valley borrow area.



3. 09 October 1981. Cat 5310 scraper.




4. 26 July 1983. Cat D-9H compacting haul road ramp with tandem sheepsfoot roller Looking toward downstream right abutment.



5. 10 July 1983. Compacting impervious fill around sump in cutoff trench with a "BARCO" gas powered compactor.




6. 06 July 1983. Spreader box mounted on a Cat D3 used for placing the 6 foot wide pervious drain.




7. June 1980. Raygo "Rascal" 410-A 5 ton vibratory roller used to compact pervious fill. , Looking downstream in cutoff trench.



8. 07 June 1983. "Wacker" DVU4001 small vibratory plate compactor used to compact pervious fill in restricted areas.



9. 07 May 1981. Small 4 wheel "Wacker" vibratory roller. Attempts were made to use this roller to compact pervious around conduit. Roller buried itself frequently and could not be used.




10. 11 June 1981. Backhoe mounted vibratory plate used to compact pervious fill along the right side of the conduit.




11. 18 September 1981. Wheel rolling upstream cutoff trench contact with left abutment Sni-A-Bar Limestone with Cat 920 front end loader.



12. 18 July 1983. Record control sample being taken.
STAGE I EMBANKMENT CONSTRUCTION




13. 05 March 1980. Looking west at slide on left side of
outlet works excavation. Slide occurred on 18 November 1979
between approximate outlet works stations 55+00 and 57+50.
Estimated volume approximately 39000 cubic yards.



14. 29 May 1980. Curtain grouting in cutoff trench.
Looking toward downstream left abutment.



15. July 1980. Removal of unacceptably wet impervious fill
material and excavation for placement of pervious on the
downstream side of the cutoff trench. Looking toward left
abutment from right abutment.




16. July 1980. Impervious and pervious fill placed in cutoff trench against right abutment. Looking toward right abutment.



17. 21 July 1980. Outlet works ogee section and 45 degree bend of twin sewer conduits. Looking downstream.



18. 14 August 1980. Stair stepped surface of heavily fractured Middle Creek limestone of right abutment after excavation and cleaning. Looking downstream.



19. 14 August 1980. Placement of dental concrete and slush grout to seal the surface of Middle Creek limestone of the right abutment. Looking downstream.




20. 21 October 1980. Overview of fill placement, conduit construction, and left abutment cutoff trench from right abutment.



21. 06 May 1981. Selective loading with rock rake of left abutment Sni-A-Bar limestone to make rockfill.



22. 21 May 1981. Overview of conduit backfill, fill placement, and right abutment from left abutment.




23. 21 July 1981. First lift of impervious fill being placed over pervious on upstream side of bend in twin sewer conduits at approximate outlet works station 54+00. Looking toward left abutment.




24. 18 September 1982. Left abutment and cutoff trench.



25. 21 October 1982. Downstream impervious stockpile.
Looking downstream of right abutment.




26. 16 November 1982. Stage I embankment investigation. Lowering inspection casing into 30 inch diameter observation hole (OH). Looking toward downstream right abutment.




27. November 1982. Sample showing typical smooth surface texture, probably caused by pumping action of loaded scraper; PPE-97-15, Depth 31-32 feet; Elevation 837.7 to 838.7.




28. November 1982. Sample showing typical raindrop-type texture, probably mechanically induced from construction equipment; PPE-97-15; Depth 29.0 to 30.8 feet; Elevation 838.9 to 840.7.




29. November 1982. First wet area encountered in OH-1; Depth 23 feet; Elevation 847.




30. November 1982. One foot above area in previous photo; exposed boundary layer with the upper material moist and seepage exiting from lower material; OH-1; Depth 22 feet; Elevation 848.



31. November 1982. Wet area encountered in OH-1; Depth 34 feet; Elevation 836.



32. 24 November 1982. End of Stage I construction. Aerial view of construction from downstream of left abutment looking southeast.



33. 24 November 1982. End of Stage I construction. Aerial view of construction from downstream of right abutment looking southwest.


STAGE II EMBANKMENT CONSTRUCTION




34. January 1983. Ignition of gas from PPE99-9.



35. 10 June 1983. Impervious planket against upstream right abutment.



36. 17 June 1983. Completed outlet works and stilling basin. Looking downstream.



37. 06 July 1983. Aerial view of embankment, cofferdam, and closure section construction from downstream of right abutment.



38. 06 July 1983. Aerial view of embankment and closure section construction from upstream left abutment.



39. 09 July 1983. Cleanup of cutoff trench and impervious placement in closure section.



40. 12 July 1983. Pervious placed at downstream edge of cutoff trench in closure section. Looking toward right embankment.




41. 18 July 1983. View of closure section showing pervious placement at downstream side of, cutoff trench and in old river and diversion channels. Looking downstream.



42. 22 July 1983. Pervious blanket placed over old river channel in closure section. Looking downstream.



43. September 1983. Closure section embankment construction. Looking toward downstream right abutment from left abutment.



44. 13 September 1983. Downstream right abutment.




45. 13 September 1983. Upstream right abutment.




46. 26 October 1983. Fill placement in closure section.
Looking toward right abutment.



47. 24 May 1984. Rockfill in clay blanket area on upstream
right abutment. Looking upstream.



48. May 1984. Aerial view of embankment after completion of closure section fill placement. From above left abutment looking toward right abutment.



49. May 1984. Aerial view of embankment looking upstream from downstream of the right abutment. The east borrow is visible in the center of the photo and the west borrow is at the upper right center.



50. May 1984. Aerial view of borrow areas from south of the west borrow area looking north toward the east borrow area and the embankment.



51. 16 July 1984. Upstream and downstream random zone fill placement. Looking toward right abutment.




52. 18 September 1984. Upstream slope before final grading. Looking toward upstream left abutment.




53. 26 November 1984. Downstream left abutment grouted gutter construction. Looking upstream.



54. 25 March 1985. Front end loaders placing riprap on upstream face of embankment. Looking downstream.




55. 26 March 1985. Dressing of riprap adjacent to bridge abutment using large backhoe.



56. 26 March 1985. Completed upstream slope protection. Looking toward upstream right abutment.



57. 23 May 1985. Completed slope protection at crest of embankment. Looking toward left abutment.



58. September 1985. Completed upstream slope from tower bridge. Looking toward upstream right abutment.



59. September 1985. Completed, downstream right abutment from stilling basin parking lot.




60. 24 September 1985. Eight foot flat bottom toe ditch. Looking toward stilling basin.



61. 24 September 1985. "Enka-mat" erosion control fabric lined ditch above grouted gutter on downstream left abutment.



62. 05 March 1986. Downstream right abutment contact showing cleared sewer line alignment at upper left.



63. 22 April 1986. Closed expansion joint and tilted rocker due to movement of tower bridge abutment.



64. April 1986. Crown crack and leakage along left wall at monolith joint between tower and conduit.



65. 19 May 1986. Installation of finger drains into pervious blanket at embankment toe.



66. 19 May 1986. Completed finger drain installation at embankment toe..



67. 10 July 1986. Completed french drain installed in upstream right abutment clay blanket to intercept seepage from limestone.



68. 18 July 1986. Aerial view of completed embankment. Looking upstream from downstream of the right abutment.



69. 19 September 1986. Upstream slope protection with pool at multipurpose elevation 891. , Looking toward upstream left abutment from right abutment.



70. 04 October 1986. Upstream slope with pool at elevation 897. Looking toward right abutment from left abutment.



71. 07 April 1987. Left abutment slope protection with the pool at multipurpose elevation 891.




72. 07 April 1987. Completed upstream right abutment clay blanket area.



73. 19 September 1986. Downstream left abutment contact and stilling basin.




74. 07 April 1987. Completed downstream slope. Looking toward downstream left abutment.



75. March 1990. Completed emergency rock stockpile on downstream left abutment. Looking northwest.


DRAWINGS


DRAWINGS




JRPC

1909





LOCATION



Symbol	Revisions Descriptions	Date	Approved

U.S. ARMY ENGINEER DISTRICT
CORPS OF ENGINEERS
KANSAS CITY, MISSOURI

LITTLE BLUE RIVER, MISSOURI
LONGVIEW LAKE
EMBANKMENT CRITERIA
AND PERFORMANCE REPORT

LOCATION AND VICINITY


REVISIONS
1. RGD
2. PST
3. RGD/WBE


DATE
11/1/50


BY
H. L. CHILTON

Sheet
Number


RBL-S-1401











Revisions			
Symbol	Descriptions	Date	Approved

<p align="center">U.S. ARMY ENGINEER DISTRICT CORPS OF ENGINEERS KANSAS CITY, MISSOURI</p>			
Designed by: R.G.D.	 U.S. Army Corps of Engineers	LITTLE BLUE RIVER, MISSOURI LONGVIEW LAKE EMBANKMENT CRITERIA AND PERFORMANCE REPORT	
Drawn by: J.W.T.	<p align="center">GENERAL PLAN</p>		
Checked by: R.G.D.	Scale: AS SHOWN	Sheet number	Plot Scale: Design File: File No: RRL-3-1402
Submitted by: R.G.D.	Date: Used No.		














GENERAL GEOLOGIC COLUMN						
SYSTEM	GROUP	FORMATION	MEMBER OR ZONE	SYMBOL	APPROX THICKNESS	GENERALIZED DESCRIPTION
TRIASSIC	CANYON	WESTERVELL	WESTERVELL	W	1000	1. Limest. - massive, gray, with thin, dark, gray, shaly, and silty, thin bedded, etc. fossils.
			1000	2. Limest. - massive, gray, with thin, dark, gray, shaly, and silty, thin bedded, etc. fossils.		
			1000	3. Limest. - massive, gray, with thin, dark, gray, shaly, and silty, thin bedded, etc. fossils.		
			1000	4. Limest. - massive, gray, with thin, dark, gray, shaly, and silty, thin bedded, etc. fossils.		
			1000	5. Limest. - massive, gray, with thin, dark, gray, shaly, and silty, thin bedded, etc. fossils.		
		CANYON	1000	6. Limest. - massive, gray, with thin, dark, gray, shaly, and silty, thin bedded, etc. fossils.		
			1000	7. Limest. - massive, gray, with thin, dark, gray, shaly, and silty, thin bedded, etc. fossils.		
			1000	8. Limest. - massive, gray, with thin, dark, gray, shaly, and silty, thin bedded, etc. fossils.		
			1000	9. Limest. - massive, gray, with thin, dark, gray, shaly, and silty, thin bedded, etc. fossils.		
			1000	10. Limest. - massive, gray, with thin, dark, gray, shaly, and silty, thin bedded, etc. fossils.		
		CANYON	1000	11. Limest. - massive, gray, with thin, dark, gray, shaly, and silty, thin bedded, etc. fossils.		
			1000	12. Limest. - massive, gray, with thin, dark, gray, shaly, and silty, thin bedded, etc. fossils.		
			1000	13. Limest. - massive, gray, with thin, dark, gray, shaly, and silty, thin bedded, etc. fossils.		
			1000	14. Limest. - massive, gray, with thin, dark, gray, shaly, and silty, thin bedded, etc. fossils.		
			1000	15. Limest. - massive, gray, with thin, dark, gray, shaly, and silty, thin bedded, etc. fossils.		





Wgs 12, 14 and 15 are 1, 1 in cross and penetrated









AT CLAY. m
mp, red b
u mst
e bld
red, we' d
h ha f


[illegible]




SECTION AT INTAKE TOWER-STA 46+00 (LOOKING UPSTREAM) D
8/9




SECTION AT OUTLET WORKS-STA 0+00



SECTION AT STILLING BASIN-STA 55+15 (LOOKING UPSTREAM) F
8/9





SECTION OUTLET CHANNEL STA 60+30 (LOOKING UPSTREAM) G
8/9



LOGS OF DETACHED BORINGS





Revisions			
Symbol	Descriptions	Date	Approved



U S ARMY ENGINEER DISTRICT
CORPS OF ENGINEERS
KANSAS CITY, MISSOURI



Designed by: R. D.
Drawn by: R. H.
Checked by: R. G. D. / W. B. E.
Date: AS SHOWN

LITTLE BLUE RIVER, MISSOURI
LONGVIEW LAKE
EMBANKMENT CRITERIA
AND PERFORMANCE REPORT
OUTLET WORKS, APPROACH, & OUTLET
CHANNELS GEOLOGIC SECTIONS &
DETACHED BORINGS

Sheet number: 1
Date: 10/1/59

RBL-3-1409







NOTES


1 Spillway floor El 911.3 between Sta 4+00 and Sta 5+00






1. Spillway floor El 911.3 between Sta 4+00 and Sta 5+00

Symbol	Revisions Descriptions	Date	Approved
Designed by RCD	 U.S. Army Corps of Engineers	LITTLE BLUE RIVER, MISSOURI LONGVIEW LAKE EMBANKMENT CRITERIA AND PERFORMANCE REPORT	
Drawn By JWP	SPILLWAY PROFILE AND SECTIONS		
Checked by RGD/WBE	Scale AS SHOWN	Sheet number	
Submittal by RGD	Date		
	Tag No.	*RBL-3-1410	





DAM, CUTOFF TRENCH
AND GROUT CURTAIN

CUTOFF TRENCH EXCAVATION

ABUTMENT FOUNDATION
EXCAVATION

ABUTMENT FOUNDATION
EXCAVATION

OUTLET WORKS

PROTECTION DIKE
EL 823

DIVERSION
CHANNEL

DIVERSION DIKE
EL 823


ABUTMENT FOUNDATION
EXCAVATION

DAM, CUTOFF TRENCH
AND GROUT CURTAIN

- Notes
1. After the removal of the existing structure, the channel shall be widened to 20 feet.
 2. Additions made to the existing structure shall be made in accordance with the plans and specifications.
 3. The existing structure shall be removed in accordance with the plans and specifications.
 4. The existing structure shall be removed in accordance with the plans and specifications.
 5. The existing structure shall be removed in accordance with the plans and specifications.
 6. The existing structure shall be removed in accordance with the plans and specifications.




PLATE NO. 11



Notes

Add foundation work required in the
outlet works Sta 52+00, left
Bank, to remove the and slide material
Add 100 yds of slide material removed
Add 100 yds of additional material
to fill
Additional clearing and grubbing etc.



Notes

1. Additional excavation was required in the vicinity of Outlet works Sta 52+00, left Bank, to remove the land slide material at
 - A 20,000 cu yds of slide material removed
 - B 20,000 cu yds of additional impervious backfill
 - C Additional clearing and grubbing required

Revisions			
Symbol	Descriptions	Date	Approved

U.S. ARMY ENGINEER DISTRICT
CORPS OF ENGINEERS
KANSAS CITY, MISSOURI

Designed by: R.G.D. LITTLE BLUE RIVER, MISSOURI
LONGVIEW LAKE
EMBANKMENT CRITERIA
AND PERFORMANCE REPORT

Drawn by: J.E.R.

Checked by: R.G.D.

Entered by: R.G.D.

Scale: AS SHOWN


Sheet Number: 1

Plot Scale: 1" = 100'


Design Date: 10/1/54

File No: RBL-3-1412


V A - I - A - S I - O - E - T - I - C V E R T - I - C A L D A T U M O F 1 9 2 9




OF APPROACH STRUCTURE




APPROACH STRUCTURE



SECTION STA. 44+51.8






SECTION STA. 45+00



SECTION STA. 45+07.3

DESIGNER	
CHECKER	
APPROVED	
DATE	
BY	
FOR	
REMARKS	



Symbol	Revisions Descriptions	Date	Approved

U.S. ARMY ENGINEER DISTRICT
CORPS OF ENGINEERS
KANSAS CITY, MISSOURI

Designed by: R.G.D.

Drawn by: J.G.S.

Checked by: R.G.D.

Approved by: R.G.D.

LITTLE BLUE RIVER, MISSOURI
LONGVIEW LAKE
EMBANKMENT CRITERIA
AND PERFORMANCE REPORT

APPROACH STRUCTURES EXCAVATION
PLAN, PROFILE, & SECTIONS

AS SHOWN



Under
Number


Project
Number

Design
Files


File
No.

RBL-3-1413







GROUTING PLAN - RIGHT ABUTMENT



GROUTING PROFILE - RIGHT ABUTMENT

NOTES

For plan of Borings, See Plate No. 3
 For General Geologic Column and Legend, See Plate No. 6
 For boring logs showing soil and bedrock description, See Plate No. 7
 Only primary holes are shown on plans. Within the limits of the cutoff trench, secondary grout holes shall be mandatory
 Indicates direction of grout holes (Direction may be changed by the Contracting Officer)



GROUTING PLAN-RIGHT ABUTMENT

OF DAM EL 926.6


FLOOD CONTROL POOL EL 909.0

MULTIPURPOSE POOL EL 891.0

APPROXIMATE EXCAVATION LIMITS FOR CUTOFF TRENCH

Revisions		Date	Approved
Number	Description		

U.S. ARMY ENGINEER DISTRICT
 CORPS OF ENGINEERS
 KANSAS CITY, MISSOURI

Design by: R.G.D.  Little Blue River, Missouri
 LONGVIEW LAKE
 EMBANKMENT CRITERIA
 AND PERFORMANCE REPORT

Checked by: J.G.S.

Drawn by: R.G.D. AS SHOWN

Reviewed by: R.G.D.

Project Number: RBL-3-1414





GRADING PROFILE - RIGHT ABUTMENT

69+00

70+00

71+00

72+00



ENGINEER

ENGINEERING PROJECT

ENGINEERING

CUTOFF TRENCH LIMITS

GROUT LINE "C"
(CENTERLINE OF CUTOFF TRENCH)

GROUTING PROFILE - VALLEY

APPROXIMATE EXCAVATION LIMITS
FOR CUTOFF TRENCH

Little Blue River

Zone I
Zone II

UC-9A
UC-9
25 D

LOW 100%
LOW 50%
LOW 25%
P. 30
LOW 100%

GROUT LINE "C" LIMITS
TO BE MODIFIED AS DIRECTED

93+00


94+00

95+00

96+00

97+00

GROUTING PROFILE - VALLEY



Note:
Conduit foundation grouting
shall be performed after com-
pletion of a cut and haul
after construction of conduit.

810

800

790

98+50

98+70


98+90

CONDUIT FOUNDATION GROUTING DETAIL
(LOOKING UPSTREAM)

CUTOFF TRENCH LIMITS

Outlet Works

GROUTING PROFILE - VALLEY






GROUTING PROFILE - VALLEY

For grout hole logs, see Plate No. 3
For grout hole logs, see Plate No. 4
For grout hole logs showing soil and bedrock description, see Plate No. 5
Grout hole logs are shown on plans. Within the limits of the cutoff trench, secondary grout holes shall be mandatory.
• indicates direction of grout holes. (Direction may be changed by the Contracting Officer)


FOR THE
ENGINEER
OF THE
ARMY
CORPS OF ENGINEERS
P.O. BOX 100
LITTLE BLUE RIVER, MISSOURI
LITTLE VIEW LAKE
EMBANKMENT CRITERIA
AND PERFORMANCE REPORT

**CURTAIN GROUTING PLAN AND PROFILE
VALLEY AND CONDUIT FOUNDATION**

RBL-3-1415




CINER




CUTOFF LIMITS

AN - LEI



G PRC

- FAR L



ILE - F

GROUTING PROFILE - FAR LEFT ABUTMENT

for actual
abutment and

See clarification drawing
LTR Nov 4, 1982

LEFT
ABUTMENT
EXCAVATION
AND BACKFILL

Repaired Sewer
(Existing)

Roadway

STA. 61+00


EL. 824.5

60+00


Protective dike
EL. 823.0
To be removed in Stage II

Impervious
Stockpile

NOTE: See Plate No. 29 for actual
contours of right abutment and
embankment.



Revisions			
Symbol	Descriptions	Date	Approved
U.S. ARMY ENGINEER DISTRICT CORPS OF ENGINEERS KANSAS CITY, MISSOURI			
Designed by:	R.G.D.	LITTLE BLUE RIVER, MISSOURI LONGVIEW LAKE EMBANKMENT CRITERIA AND PERFORMANCE REPORT	
Drawn by:	J.W.T.	EMBANKMENT AT COMPLETION OF STAGE I	
Checked by:	R.G.D.	Scale	Sheet number
		AS SHOWN	
		Date	Design
			File
		Dwg. No.	REL-3-1417




1003,600

1003,800

1004,000

1004,200

14



Notes

- 1. Limits of Stage II excavation shown are approximate. A full vertical and horizontal survey of the area should be made and the limits of excavation should be directed by the Contract Engineer.
- 2. Existing Stage I rock surfaces should be foundation cleanup or preparation as directed by the Contract Engineer.
- 3. Areas within the Stage II excavation limits should be excavated to depths as directed by the Contract Engineer, and any other materials as determined by the Contract Engineer.

CORPS OF ENGINEERS

1,004,000

1,004,200

1,004,400




Notes:

- 1 Limits of Stage II excavation shown are approximate. Actual vertical and horizontal limits will depend upon conditions encountered and shall be as directed by the Contracting Officer.
- 2 Existing Stage I rock surfaces shall receive foundation cleanup or preparation as directed by the Contracting Officer and removal of temporary protective soil cover.
- 3 All areas within the Stage II excavation limits shall be excavated to depths as directed, which will remove all highly organic material, loose rock and any other objectionable foundation materials as determined by the Contracting Officer.
- 4 Sand and rock piles to be removed by Stage I contractor.

STAGE II ABUTMENT LIMITS

TIMBER



CORPS OF ENGINEER'S SURVEY-MARCH, 1982


1,004,000

1,004,200

1,004,400

Revisions			
Symbol	Descriptions	Date	Approved

U.S. ARMY ENGINEER DISTRICT
CORPS OF ENGINEERS
KANSAS CITY, MISSOURI

Designed by: R.G.D.  LITTLE BLUE RIVER, MISSOURI
LONGVIEW LAKE
EMBANKMENT CRITERIA
AND PERFORMANCE REPORT

Drawn by: T.L.G.

Checked by: R.G.D.

Submitted by: R.G.D.


Scales: AS SHOWN

Sheet numbers:



Plot scales:



Design files:

File No: RBL-3-M18



ELEVATION IN FEET BASED ON NATIONAL GEODETIC VERTICAL DATUM OF 1929






PHASE II COFFERDAM COMPLETED TO EL. 887

ous cover placed
until closure
constructed -

TREAM

45.5
49.8
DAM


6' Pervious
cutoff trench and pervious
completed across river
Sta 93+45± to Sta 95+80±




TYPICAL PHASE II COFFERDAM SECTION B
19/19


NOTE

(Topsoiled and seeded) all upstream embankment
slopes above EL 898 and all downstream
slopes except areas with slope protection
as shown on plan and sections



Revisions			
Symbol	Descriptions	Date	Approved
U S ARMY ENGINEER DISTRICT CORPS OF ENGINEERS KANSAS CITY, MISSOURI			
Designed by R G D.		LITTLE BLUE RIVER, MISSOURI LONGVIEW LAKE EMBANKMENT CRITERIA AND PERFORMANCE REPORT DIVERSION AND CLOSURE: PLANS AND SECTIONS	
Drawn by S L M		Scale AS SHOWN	Sheet number
Checked by R G D / W B E		Date	
Submitted by R C U		Dwg No	File No





Symbol	Revisions	Descriptions	Date	Approved

U.S. ARMY ENGINEER DISTRICT
CORPS OF ENGINEERS
KANSAS CITY, MISSOURI

DESIGNED BY: R.G.D.

DRAWN BY: R.D.


CHECKED BY: R.G.D.

DATE: AS SHOWN


PROJECT: LITTLE BLUE RIVER, MISSOURI
LONGVIEW LAKE
EMBANKMENT CRITERIA
AND PERFORMANCE REPORT

EMBANKMENT PLAN
AND ALIGNMENT DATA


RBL-3-1420



PROFILE ALONG DAM
LOOKING



TYPICAL SECTION
RIVERBANK EXCAVATION INCLUDING ABANDONED
RIVER CHANNEL AND EXISTING CHANNEL



PERVIOUS
AND R

Top of Embankment

Top of Embankment El. 925.7

El. 890 Cont.

El. 890 Construction halt (6 months)

protective plug and so
I embankment was
tractor

Closure section
Stage II contract, see
Detail

El. 867.0

Stage I emb.
removed by the
Stage II Contractor

Temporary protective plug and backfill including
some Stage I embankment was removed by
Stage II Contractor

Cutoff Trench closure section
placed under Stage II contract, see
Cutoff Trench Detail

El. Varies

Stage I
Embankment

Final fill to approx
Sta 93+45 on Stage I

Final fill to approx
Sta 95+80 on Stage I

Slope to drain



Stage I
Embankment

Outlet works
Sta 98+70 at Dam


the Blue River Channel

DAM AXIS AND
LOOKING UPSTREAM


PROFILE ALONG DAM AXIS AND CUTOFF TRENCH
LOOKING UPSTREAM




**TYPICAL SECTION
RIVER CHANNEL BACKFILL
DOWNSTREAM OF CUTOFF TRENCH**
Not to Scale



**SECTION
INCLUDING ABANDONED
AND EXISTING CHANNEL**




VIOUS TIE-IN CUT
AND RIVER CHANNEL




**PERVIOUS TIE-IN CUTOFF TRENCH
AND RIVER CHANNEL DETAIL**

SCALE IN FEET


VALUE ENGINEERING PAYS



DAM AXIS AND CUTOFF TRENCH LOOKING UPSTREAM




**TYPICAL SECTION
RIVER CHANNEL BACKFILL
DOWNSTREAM OF CUTOFF TRENCH**
Not to Scale



**CUTOFF TRENCH DETAIL
STA. 93+45± TO STA. 94+80±**
SCALE IN FEET


CUTOFF TRENCH
STA. 93+45± TO





At the location of the Little Blue River Channel, see Typical Section River Channel Backfill; Pervious Tie in Cutoff Trench and River Channel Detail.




**US TIE-IN CUTOFF TRENCH
RIVER CHANNEL DETAIL**
SCALE IN FEET


Revisions		Date	Approved
Symbol	Descriptions		
U S ARMY ENGINEER DISTRICT CORPS OF ENGINEERS KANSAS CITY, MISSOURI			
Designed by R G D		LITTLE BLUE RIVER, MISSOURI LONGVIEW LAKE EMBANKMENT CRITERIA AND PERFORMANCE REPORT	
Drawn by S L M		DAM AXIS PROFILE AND MISC. SECTIONS & DETAILS	
Checked by R G D / W B E		Scale AS SHOWN	Sheet number
Submitted by R G D		Date	File No. RBL-3-1421
Dep No.			






Symbol	
Designed by	R G D
Drawn by	R D T
Checked by	R G D
Submitted by	R G D






RIG




Removed existing impervious core




Constructed prior to diversion and closure

Removed existing


EM



RIGHT ABUTMENT SECTION - STA. 88+00




VALLEY SECTION - STA. 90+00




EMBANKMENT SECTION - STA. 97+00


Notes 1 Hatched area represents approx. Stage I embankment
2 Top, oiled and seeded all upstream embankment slopes, EL 898 and all downstream embankment slopes, areas having slope protection as shown on plan sections



RIGHT ABUTMENT SECTION - STA. 88+00





VALLEY SECTION - STA. 90+00




EMBANKMENT SECTION - STA. 97+00

- Notes: 1 Hatched area represents approx Stage I embankment
2 Ripraped and seeded all upstream embankment slopes above EL 898 and all downstream embankment slopes except areas having slope protection as shown on plan and sections


Revisions			
Symbol	Descriptions	Date	Approved
<p>U S ARMY ENGINEER DISTRICT CORPS OF ENGINEERS KANSAS CITY, MISSOURI</p>			
Designed by	R G D	<p>LITTLE BLUE RIVER, MISSOURI LONGVIEW LAKE EMBANKMENT CRITERIA AND PERFORMANCE REPORT</p>	
Drawn by	S E S	<p>TYPICAL EMBANKMENT SECTIONS</p>	
Checked by	R G D / W B E	Scale	AS SHOWN
Submitted by		Date	
		Drawn by	
		Sheet Number	2 of 4
		File No	RBL-3-1423




LEFT ABUTMENT SECTION - STA 102+00 (AXI)



LEFT ABUTMENT SECTION - STA 103+00 (AXI)








DETAIL 1




DETAIL 2

Top of Existing Stage I Embankment







CONDUIT SECTION - STA. 98+70 (D) 20/24



AXIS OF DAM (E) 20/24



AXIS OF DAM (F) 20/24



DETAIL 3

* The tie-in location for the pervious fill may vary from that shown on the drawings. The Stage II Contractor will transition from the actual location of the tie-in to the plan location in 50'

Notes: 1 Hatched area represents approx Stage I embankment. See Dwg Nos B12 and B13 for existing condition. 2 Topsoil and seed all upstream embankment slopes above EL 898 (EL 891 between Sta 102+00 to left abutment) except areas with slope protection and all downstream embankment slopes.

Revisions			
Symbol	Descriptions	Date	Approved


U.S. ARMY ENGINEER DISTRICT
CORPS OF ENGINEERS
KANSAS CITY, MISSOURI

Designed by: R.G.D.
Drawn by: S.E.S.
Checked by: R.G.D.
Submitted by: R.G.D.

LITTLE BLUE RIVER, MISSOURI
LONGVIEW LAKE
EMBANKMENT CRITERIA
AND PERFORMANCE REPORT

TYPICAL EMBANKMENT SECTIONS

Scales: AS SHOWN
Sheet numbers: 3 OF 4
Plot scales: Design Time
File No: RBL-3-1424




TYPICAL DOWNSTREAM TOE DETAIL

RIGHT ABUTMENT TO STA. 87+00
STA. 88+00 TO STA. 91+00
STA. 97+00 TO LEFT ABUTMENT
Scale 1"=5'-0"

4' FLAT BOTTOM GROUTED TOE GUTTER




SECTION "B"



TYPICAL DOWNSTREAM TOE DETAIL


THROUGH SECTION

STA. 104+00




NOTE: THE REVISED GUTTER SHALL BE CONSTRUCTED AS SHOWN DATED 1983. THE FLOWLINE OF THE DITCH AT STA. 104+00 SHALL BE AT THAT ELEVATION SINCE THE GROUND ELEVATION AT THAT POINT OF THE 8-FOOT FLAT BOTTOM DITCH BETWEEN STA. 103+00 AND STA. 104+00 IS TO ACCOMMODATE RAISING THE DITCH GRADE EXACT OR IN THE FIELD BUT ARE TO BE NO FLATTER THAN SHOWN.

VALUE ENGINEERING PAYS



SECTION "A"



SECTION "C"

TYPICAL DOWNSTREAM TOE DETAIL

STA 91+00 TO STA 97+00
Scale: "1"=5'0"



SECTION "B"


4' FLAT BOTTOM GROUTED TOE GUTTER

TYPICAL DOWNSTREAM TOE DETAIL

THRU RIVER CHANNEL


STA 94+00 TO STA 95+50:
Scale: "1"=5'0"

to rock and excavate existing
bank steeper than 1 on 3 or as
Contracting Officer




LEFT ABUTMENT SECTION STA. 104+00 (AXIS OF DAM)


20125



SEC



ION H
20125




TRANSITION DETAIL


TOE DRAIN DITCH DETAILS

NOTE:
THE REVISED GUTTER SHALL BE CONSTRUCTED AS SHOWN ON THE ABOVE DRAWING TOE DRAIN DITCH DETAIL
DATED 1993. THE FLOWLINE OF THE DITCH AT ST. 91+00 SHALL BE REVISED TO MAINTAIN A 2-FOOT
DEPTH SINCE THE GROUND ELEVATION AT THAT POINT IS APPROXIMATELY ELEVATION 819.23. THE GRADE
OF THE 8-FOOT FLAT BOTTOM DITCH BETWEEN STA 91+00 AND STA 95+50 WILL HAVE TO BE STEEPENED TO
ACCOMMODATE RAISING THE DITCH GRADE. EXACT GRADES OF THE 8-FOOT FLAT BOTTOM DITCH ARE TO BE DETERMINED
IN THE FIELD BUT ARE TO BE NO FLATTER THAN SHOWN ON THE ABOVE DRAWING. ALSO SEE PLATE NO 27





EL. IN FT. BASED ON M.S.V. DATUM OF 1922





TOP OF DAM DETAIL








SLOPE PROTECTION DETAIL
Scale: 1"=2'-0"














TRANSVERSE CONTRACTION JOINT




SECTION C-C
Scale: 3" = 1'-0"




SECTION D-D
Scale: 3" = 1'-0"



- NOTES**
1. Provided reinforcing as required for handling and to meet Missouri Highway and Transportation Commission Concrete Median Barrier Drawing 617 OOP
 2. For keyway and other details not shown, see Drawing 617 OOP, Concrete Median Barrier, Missouri Highway Transportation Commission
 3. Anchors for transition sections similar to those shown for other barrier precast sections.



Revisions			
Symbol	Descriptions	Date	Approved
U S ARMY ENGINEER DISTRICT CORPS OF ENGINEERS KANSAS CITY, MISSOURI			
Designed by	R G D	LITTLE BLUE RIVER, MISSOURI LONGVIEW LAKE EMBANKMENT CRITERIA AND PERFORMANCE REPORT	
Drawn by	S E S	TOP OF DAM AND SLOPE PROTECTION DETAILS	
Checked by	R G D / W B E	Scale AS SHOWN	Sheet number
Submitted by	R G D	Date	File No
			RBL-3-1426




SCHEDULE OF EMBANKMENT DRAINAGE

Scale 1"=5'-0"

NOTE: Also see TOE DRAIN DITCH DETAIL

8' TOE DITCH SECTION (F)
Scale 1"=5'-0"


STA 91+00 THRU STA 93+00




4' FLAT BOTTOM TOE GUTTER (B)
Scale 1"=5'-0"

TOE GUTTER DITCH SECTION (C)
Scale 1"=5'-0"


DAM STA 97+15 THRU STA 99+00




TOE DITCH DETAIL SECTION (E)
DAM STA 103+00 THRU STA 107+50.2
Scale 1"=5'-0"




SECTION AA CUTOFF WALL




CUTOFF WALL



SECTION AA CUTOFF WALL



TYPICAL INTERCEPTOR DITCH TOE GUTTER CONNECTION DETAIL
Not to Scale











TYPICAL INTERCEPTOR DITCH DETAIL

Notes
For embankment slope of 1 on 3, use slopes of 1 on 2 and 2'5\"/>


Symbol	
Designation	
Material	
Quantity	
Remarks	

ELEVATION IN FEET BASED ON NATIONAL GEODETIC VERTICAL DATUM OF 1929







STILLING BASIN PLAN
SCALE IN FEET




ACCESS WALK & STAIRS
Not to scale




STA 54+51 TO STA 55+16.25




STA 55+16.25 TO STA 56+24.25
STILLING BASIN OUTLET DRAIN
Not to scale



HANDRAIL DETAILS
Not to Scale



Revisions			
Symbol	Descriptions	Date	Approved
U. S. ARMY ENGINEER DISTRICT CORPS OF ENGINEERS KANSAS CITY, MISSOURI			
Designed by RGD	LITTLE BLUE RIVER, MISSOURI LONGVIEW LAKE EMBANKMENT CRITERIA AND PERFORMANCE REPORT STILLING BASIN: PLAN, PROFILE, SECTIONS AND DETAILS		
Drawn by SES			
Checked by RGD/WBE			
Submitted by RGD			
Scale AS SHOWN	Sheet number 	File No RBL-3-1428	



SECTION A
29/29

Constructed bench as necessary to excavate Shinarump Limestone

Constructed bench as necessary to excavate Bethany Falls

Not steeper than IV on 2H

El. 835

Not steeper than IV on 2H

Excavated IV on 0.5H through Shinarump Limestone

APPROXIMATE ABUTMENT EX LIMITS

Cut slope in Bethany Falls Limestone

6 Dam

1 on 3.5

El. 887 R + 1

STAGE I EMBANKMENT

El. 887 R + 37.9

El. 878.3 R + 64

10x 10

1 on 4

5' 0"

as necessary
Bethany Falls Limestone

Constructed bench as
necessary to excavate
Sniabar Limestone

Constructed bench as necessary
to excavate Bethany Falls Limestone

Notes:

- ① Limits of Stage II excavation shown are approximate. Actual vertical and horizontal limits depend upon conditions encountered and were as directed by the Contracting Officer.
- ② Stage I rock surfaces received foundation cleanup or preparation as directed by the Contracting Officer and removal of temporary protective soil cover.
- ③ All areas within the Stage II excavation limits were excavated to depths as directed, which removed all highly organic material, loose rock and any other objectionable foundation materials as determined by the Contracting Officer.

APPROXIMATE STAGE II
ABUTMENT EXCAVATION

El. 835

Not steeper
than IV on 2H

Excavated IV on 0.5H
through Sniabar
Limestone

APPROXIMATE STAGE II
ABUTMENT EXCAVATION
LIMITS

Approximate embankment
toe trace

Cut in slope
in overburden

Cut slope in
Bethany Falls
Limestone

Slope in Wea
and Block Members

Temporary protective soil
cover removed

STAGE I EMBANKMENT

El. 887 R2+37.9



El. 878.3 R2+64

El. 877 R3+02

Cut slope in
Winterset Limestone

Cut slope in
Bethany Falls Limestone

Constructed bench as
necessary to excavate
Bethany Falls Limestone



EMBANKMENT

7.9

6.4

El. 877 R3

El. 877 R3

El. 877 R3

El. 877 R3

El. 877 R3

El. 877 R3

El. 877 R3

El. 877 R3

El. 877 R3

El. 877 R3

El. 877 R3

El. 877 R3

El. 877 R3

El. 877 R3

El. 877 R3

El. 877 R3

El. 877 R3

El. 877 R3

VALUE ENGINEERING PAYS

as necessary
Bethany Falls Limestone

Approx. then

Bethany Falls Limestone
Hushpuckney
Snider Limestone
Critzler
Pleasanton

Excavated IV on Q5H through
Bethany Falls Limestone

Approximate embankment
toe trace

**STAGE II
EXCAVATION**

Symbol

Designed by

Drawn by

Checked by

Submitted by

Cut in slope
in overburden

Slope in Wea
and Block Members

Temporary protective soil
cover removed

Cut slope in
winterset Limestone

Cut slope in
Bethany Falls Limestone

APPROXIMATE
EXCAVATION LIMITS

APPROXIMATE STAGE II ABUTMENT
EXCAVATION LIMITS

Excavated IV on Q5H through
Bethany Falls Limestone

Not steeper
than IV on Q5H

Constructed bench as
necessary to excavate
Bethany Falls Limestone

Notes:

- ① Limits of Stage II excavation shown are approximate. Actual vertical and horizontal limits depend upon conditions encountered and were as directed by the Contracting Officer.
- ② Stage I rock surfaces received foundation cleanup or preparation as directed by the Contracting Officer and removal of temporary protective soil cover.
- ③ All areas within the Stage II excavation limits were excavated to depths as directed, which removed all highly organic material, loose rock and any other objectionable foundation materials as determined by the Contracting Officer.

Approximate ground surface

Approximate Limits of
Excavation

Bethany Falls Limestone

Hushpuckney Shale

Snider Limestone

Mound City Shale

Critzler Limestone

Ladore Shale

Middle Creek Limestone

Pleasanton Group

Approximate top of bedrock

SECTION **B**
29/29

Revisions			
Symbol	Descriptions	Date	Approved

U. S. ARMY ENGINEER DISTRICT
CORPS OF ENGINEERS
KANSAS CITY, MISSOURI

Designed by
RGD

Drawn by
JWP

Checked by
RGD/WBE

Submitted by
RGD

**LITTLE BLUE RIVER, MISSOURI
LONGVIEW LAKE
EMBANKMENT CRITERIA
AND PERFORMANCE REPORT
RIGHT ABUTMENT SECTION
AND PLAN OF EXCAVATION**

Scale: AS SHOWN

Date

Draw No

Sheet number

File No **RBL-3-1429**

CORPS OF ENGINEERS SURVEY - JUNE, 1984

PI. AT. F. NO. 29

- VALUE ENGINEERING PAYS**

Notes:

 - Limits of Stage II excavation shown are approximate. Actual vertical and horizontal limits depend upon conditions encountered and were as directed by the Contracting Officer.
 - Stage I rock surfaces received foundation cleanup or preparation as directed by the Contracting Office and removal of temporary protective soil cover.
 - All areas within the Stage II excavation limits were excavated to depths as directed, which removed all highly organic material, loose rock and any other objectionable foundation materials as determined by the Contracting Officer.

Approximate ground surface
Approximate Limits of Excavation
 Bethany Falls Limestone
 Hushpuckney Shale
 Snider Limestone
 Critzer Limestone
 Ladore Shale
 Middle Creek Limestone
 Pleasanton Group
 Approximate top of bedrock

SECTION B
 29/29

Revisions			
Symbol	Description	Date	Approved

U. S. ARMY ENGINEER DISTRICT
 CORPS OF ENGINEERS
 KANSAS CITY, MISSOURI

Designed by: RGD
 Drawn by: JWP
 Checked by: RGD/WBE
 Submitted by: RGD

**LITTLE BLUE RIVER, MISSOURI
 LONGVIEW LAKE
 EMBANKMENT CRITERIA
 AND PERFORMANCE REPORT
 RIGHT ABUTMENT SECTION
 AND PLAN OF EXCAVATION**

Scale: AS SHOWN
 Date: Sheet number:
 Drawing No.: File No: RBL-3-1429

APPROXIMATE STAGE II ABUTMENT EXCAVATION LIMITS

Excavated IV on QSH through Bethany Falls Limestone
 Not steeper than IV on QSH

Constructed benches necessary to excavate Bethany Falls Limestone

Cut slope in winterset Limestone
 Cut slope in Bethany Falls Limestone

Slope in Wea and Block Members

Temporary protective soil cover removed

Approximate embankment toe trace


Excavated IV on QSH through Bethany Falls Limestone

Approximate top of bedrock

SCALE IN FEET

CORPS OF ENGINEERS SURVEY - JUNE, 1984

PLATE NO 29



VALUE ENGINEERING PAYS

as necessary
Bethany Falls Limestone

Approx. then

Bethany Falls Limestone
Hushpuckney
Snider Limestone
Critzler
Pleasanton

Excavated IV on Q5H through
Bethany Falls Limestone

Notes:

- ① Limits of Stage II excavation shown are approximate. Actual vertical and horizontal limits depend upon conditions encountered and were as directed by the Contracting Officer.
- ② Stage I rock surfaces received foundation cleanup or preparation as directed by the Contracting Officer and removal of temporary protective soil cover.
- ③ All areas within the Stage II excavation limits were excavated to depths as directed, which removed all highly organic material, loose rock and any other objectionable foundation materials as determined by the Contracting Officer.

Approximate embankment toe trace

Approximate Stage II Excavation

Cut in slope in overburden

Slope in Wea and Block Members

Temporary protective soil cover removed

Cut slope in winterset Limestone

Cut slope in Bethany Falls Limestone

APPROXIMATE EXCAVATION LIMITS

APPROXIMATE STAGE II ABUTMENT EXCAVATION LIMITS

Excavated IV on Q5H through Bethany Falls Limestone

Not steeper than IV on Q5H

Constructed bench as necessary to excavate Bethany Falls Limestone

SECTION B

Approximate ground surface

Approximate Limits of Excavation

Bethany Falls Limestone

Hushpuckney Shale

Snider Limestone

Mound City Shale

Critzler Limestone

Ladore Shale

Middle Creek Limestone

Pleasanton Group

Approximate top of bedrock

U. S. ARMY ENGINEER DISTRICT
CORPS OF ENGINEERS
KANSAS CITY, MISSOURI

Designed by
R G D

Drawn by
J W P

Checked by
R G D / W B E

Submitted by
R G D

Scale: AS SHOWN

Date

Draw No

Sheet number

File No RBL-3-1429

LITTLE BLUE RIVER, MISSOURI
LONGVIEW LAKE
EMBANKMENT CRITERIA
AND PERFORMANCE REPORT
RIGHT ABUTMENT SECTION
AND PLAN OF EXCAVATION

CORPS OF ENGINEERS SURVEY - JUNE, 1984

PLATE NO 29

Notes:

- ① Limits of Stage II excavation shown are approximate. Actual vertical and horizontal limits depend upon conditions encountered and were as directed by the Contracting Officer.
- ② Stage I rock surfaces received foundation cleanup or preparation as directed by the Contracting Officer and removal of temporary protective soil cover.
- ③ All areas within the Stage II excavation limits were excavated to depths as directed, which removed all highly organic material, loose rock and any other objectionable foundation materials as determined by the Contracting Officer.

Revisions

Symbol	Descriptions	Date	Approved

**U. S. ARMY ENGINEER DISTRICT
CORPS OF ENGINEERS
KANSAS CITY, MISSOURI**


DESIGNED BY: RGD
DRAWN BY: JWP
CHECKED BY: RGD/WBE
SUBMITTED BY: RGD

**LITTLE BLUE RIVER, MISSOURI
LONGVIEW LAKE
EMBANKMENT CRITERIA
AND PERFORMANCE REPORT
RIGHT ABUTMENT SECTION
AND PLAN OF EXCAVATION**

Scale: AS SHOWN
Sheet number:
Date:
Draw No:


File No: RBL-3-1429

CORPS OF ENGINEERS SURVEY - JUNE, 1984




PLAN OF UPSTREAM CLAY BLANKET


Wint
Stark
Beth





UPSTREAM CLAY BLANKET SECTION A




PLAN OF UPSTREAM CLAY BLANKET



UPSTREAM CLAY BLANKET SECTION B



UPSTREAM CLAY BLANKET SECTION C




30130

UPSTREAM CLAY BLANKET SECTION

30130


SCALE IN FEET



UPSTREAM CLAY BLANKET SECTION

30130

SCALE IN FEET



UPSTREAM CLAY BLANKET SECTION

30130

SCALE IN FEET

Revisions			
Symbol	Descriptions	Date	Approved

U.S. ARMY ENGINEER DISTRICT
CORPS OF ENGINEERS
KANSAS CITY, MISSOURI


Designed by: R.G.D. LITTLE BLUE RIVER, MISSOURI
LONGVIEW LAKE
EMBANKMENT CRITERIA
AND PERFORMANCE REPORT
RIGHT ABUTMENT
UPSTREAM IMPERVIOUS
CLAY BLANKET PLAN AND SECTIONS

Drawn by: J.W.T.

Checked by: R.G.D. Scale: AS SHOWN Sheet number: 20461 Date: 2/5/57


Approved by: R.G.D. Date: 2/9/57

RBL-3-1430




ELM AVE. DIKE PLAN
SCALE IN FEET

ELEVATION IN FEET BASED ON NATIONAL GEODETIC VERTICAL DATUM OF 1929




PROFILE ALONG ELM AVE. DIKE A
31/31




ELM AVE. DIKE-TYPICAL SECTION
SCALE IN FEET

ELM AVE. DIKE ALINEMENT DATA				
POT. STATION	LATITUDE	DEPARTURE	AZIMUTH	DIST
0+00 BEGIN DIKE	1,003,643.793	507,035.036		
5+82 END DIKE	1,003,937.374	506,521.346	118° 02' 20"	582.00


DEPTH IN FEET




ELM DIKE BORROW AREA-LOG OF BORING



EMERGENCY ACCESS LANE
Typical Fill Section
Scale 1"=5'



ELM AVE. DIKE PLAN




PROFILE ALONG ELM AVE. DIKE


Elm Ave dike
El. 925.6
1 on 6
Stripped as required
Sloped all slopes to
top of dike

ELM AVE. DIKE ALINEMENT DATA				
POT. STATION	LATITUDE	DEPARTURE	AZIMUTH	DIST
0+00 BEGIN DKE	1,003,663.793	807,035.036		
5+82 END DKE	1,003,937.374	806,521.346	118° 02' 20"	882.00

L SECTION



LOG OF BORING




PLAN PIPE GATE

PIPE GATE DETAILS


Not to Scale

NOT:
1. A,
2. F
a1
3. P
pr
e)



EMERGENCY ACCESS LANE PLAN

Scale 1"=100'






EMERGENCY ACCESS LANE

Typical Fill Section

Scale 1"=5'



REINFORCING PAYS



- NOTES:
1. All pipe Sch. 40
 2. Pipe Gate completely welded at all joints and watertight.
 3. Painted with one coat red lead primer and two coats yellow exterior enamel.

PIPE GATE DETAILS
Not to Scale

- NOTES:
1. All pipe Schedule 40 Steel
 2. Pipe Gate completely welded at all joints and watertight.
 3. Painted with one coat red lead primer and two coats yellow exterior enamel.




EMERGENCY ACCESS LANE PLAN
Scale 1"=100'


2 1/2 Tons/sq. yd.
Aggregate surfacing

as required to maintain
grade of 15% or less


Revisions		Date	Approved
Symbol	Descriptions		
<p>U S ARMY ENGINEER DISTRICT CORPS OF ENGINEERS KANSAS CITY, MISSOURI</p>			
Designed by	R G D	<p>LITTLE BLUE RIVER, MISSOURI LONGVIEW LAKE EMBANKMENT CRITERIA AND PERFORMANCE REPORT</p>	
Drawn by	J W P	<p>ELM AVENUE DIKE ACCESS LANE AND PIPE GATE DETAILS</p>	
Checked by	R.S.D./W.B.E.	Scale	AS SHOWN
Submitted by	R G D.	Date	
		Dwg No	
		Sheet Number	
		File No	RBL-3-1431



POOL ELEVATION-EXCEEDANCE FREQUENCY CURVE



AVERAGE NUMBER OF DAYS PER YEAR BELOW GIVEN ELEVATION
POOL ELEVATION-DURATION CURVE




DAYS PER 100 YRS THAT POOL IS ABOVE ELEVATION

WIND VELOCITY-FREQ			
DIRECTION	FREQUENCY YRS	TOPEKA, KS MPH	CS
SSW	20	20	
S	20	20	
SSW	20	20	
SW	20	20	
SSW	20	20	
S	20	20	
SSW	20	20	
SW	20	20	
SSW	20	20	
S	20	20	
SSW	20	20	
SW	20	20	

Notes:
Average wind speed
data from Post 1st
at a point near to the


CURRENCE

90 95 98 99 99.8




POOL IS WITHIN
FREQUENCY CURVE

GIVEN ELEVATION



GIVEN ELEVATION
CURVE




DAYS PER 100 YRS THAT POOL IS WITHIN ONE WAVE HEIGHT OF EACH ELEV

WIND VELOCITY-FREQUENCY CHART

DIRECTION	FREQUENCY YRS	TOPEKA, KS MPH	COLUMBIA, MO MPH	KANSAS CITY, MO MPH
SSE	100	49	34	31
S	100	56	42	38
SSW	100	45	43	41
SW	100	51	44	40
SSW	5	42	33	29
S	5	47	37	36
SSW	5	42	33	29
SW	5	47	37	36
SSE	5	42	33	29
S	5	47	37	36
SSW	5	42	33	29
SW	5	47	37	36

Notes
Average wind speed
Data from first 10 years of Bureau recording station
at airport near residence



Notes
Wind velocity computed from
data from first 10 years of Bureau recording station
at airport near residence

RIPRAP ST

LOCATION	FETCH	DESIGN WIND	DESIGN
STA	ELEV	SLOPE	LENGTH
89+30	920	1 on 3	14 SW
95+30	920	1 on 3	12 SW
101+90	920	on 3	8 SW
89+90	891	on 3	66 SW
95+30	891	1 on 3	67 SW
101+90	891	on 3	40 SW
99+20	891	on 3	67 SW

Note
1 Fetch length in miles
2 A rough estimate of the wind velocity was obtained from
upper 10 of dam...
for... Design...
for... Design...
for... Design...

CRITICAL WIND VELOCITY

WIND VELOCITY MPH	WIND
48	
49	
50	
51	
52	
53	
54	
55	
56	
57	
58	
59	
60	
61	
62	
63	
64	
65	
66	
67	
68	
69	
70	
71	
72	
73	
74	
75	
76	
77	
78	
79	
80	
81	
82	
83	
84	
85	
86	
87	
88	
89	
90	
91	
92	
93	
94	
95	
96	
97	
98	
99	
100	

Symbol

Designed by


Drawn by

Check by

Scale

Date


AP STUDY



POOL IS WITHIN ONE WAVE HEIGHT OF EACH ELEV

DVELOCITY

FREQUENCY CHART		
RIPRAP AT ELEV	COLUMBIA, MO MPH	KANSAS CITY, MO MPH
WIND DURA MIN	34	31
	40	38
	43	41
	46	44
	54	50
	56	53
	59	56
	63	60



WIND VELOCITY DURATION CURVE

Note
Wind velocity computed from E.T.C. 10-2-12
(29 Nov. 1963) converted to over water velocities
by ratio of 1.0113

RIPRAP STUDY

(SPECIFIC GRAVITY = 2.6)

SPECIFIC GRAVITY = 2.65

LOCATION		FETCH			DESIGN WIND		DESIGN FETCH (MILES)		DESIGN WAVE		RIPRAP			
STA	ELEV	SLOPE	LENGTH	DIRECT	DURATION (MIN)	SPEED (MPH)	LENGTH	DIRECT	H _s	H _D	W _o	W _o PROPOSED	THICK	S F
89130	920	1 on 3	74	SW										
95130	920	1 on 3	12	SW	30	56	14	SW	29	41	117	100	18"	See note
101190	920	1 on 3	8	SW										
89190	891	1 on 3	66	SW										
95130	891	1 on 3	67	SW										
101190	891	1 on 3	46	S	20	59	07	SW	22	31	51	100	18"	13
98120	891	1 on 3	67	SW										



Note
1 Fetch length in miles.
2 A reduced thickness of riprap was utilized for the upper 10' of dam in accordance with "Criteria for Riprap Design" in Missouri River Division June 1964"


CRITICAL WIND VELOCITY - DURATION CHART

RIPRAP AT ELEV 891		
WIND VELOCITY M.P.H.	WIND DURATION MIN	FORECAST HS - HT
48	120	5 (Fetch limited)
49	90	18 (Fetch limited)
51	60	18 (Fetch limited)
53	50	20 (Fetch limited)
54	40	20 (Fetch limited)
56	30	21 (Fetch limited)
59	20	22 (Fetch limited)
63	10	23 (Duration limit)
RIPRAP AT ELEV 920		
48	120	26 (Fetch limited)
49	90	26 (Fetch limited)
51	60	26 (Fetch limited)
53	50	28 (Fetch limited)
54	40	28 (Fetch limited)
56	30	29 (Fetch limited)
59	20	24 (Duration limit)
63	10	22 (Duration limit)

XX indicates critical wind velocity and duration

Revisions			
Symbol	Descriptions	Date	Approved
U.S. ARMY ENGINEER DISTRICT CORPS OF ENGINEERS KANSAS CITY, MISSOURI			
Designed by R.G.D.	LITTLE BLUE RIVER, MISSOURI LONGVIEW LAKE EMBANKMENT CRITERIA AND PERFORMANCE REPORT SLOPE PROTECTION STUDY		
Drawn by J.E.B.			
Checked by R.G.D./W.B.E.			
Submitted by R.G.D.	Scale AS SHOWN	Sheet number	File No. RBL-3-1432





PLAN
Scale 1"=10'-0"




ELEVATION
Scale 1"=10'-0"

GENE


- 1.
- 2.
- 3.
- 4.
- 5.
- 6.
- 7.
- 8.
- 9.
- 10.

Sym



GENERAL NOTES

1. Design
2. Material
3. Construction
4. Foundation
5. Drainage
6. Other



GENERAL NOTES - BRIDGE

1. Design Specification: AASHTO 1977 Edition
2. Live load: H 5-44 or normal stresses
3. Material: 35 tons carrying 90 kips
4. Construction: 3/4" chamfered
5. Foundation: compacted impervious material
6. Other: Stationing measured along centerline of Outlet Works with starting point at Intake Tower

Symbol	Revisions	Date	Approved

U. S. ARMY ENGINEER DISTRICT
CORPS OF ENGINEERS
KANSAS CITY, MISSOURI

Designed by: RGD

Drawn by: PRL

Checked by: RGD/WBE

Submitted by: RGD

LITTLE BLUE RIVER, MISSOURI
LONGVIEW LAKE
EMBANKMENT CRITERIA
AND PERFORMANCE REPORT


SERVICE BRIDGE
PLAN AND ELEVATION

Scale: AS SHOWN

Sheet number: _____


Date: _____

File No: **RBL-3-1433**



EXPANSION BEARING DETAIL.

Scale: 3" = 1'-0"







FIXED BEARING DETAIL

Scale: 3" = 1'-0"

ROCKER AND EXPANSION R SETTING			
	INTAKE TOWER	PIER AND/OR ABUTMENT	
Temperature at time of setting			
0°F	1/2"	3 1/2"	1/2"
50°F	1/2"	3"	0
100°F	1/2"	2 1/2"	+ 1/2"



NOTE:

Axis of rocker is vertical at 50° F
 For temperatures other than those shown, use straight line interpolation to determine proper position




ROCKER AND EXPANSION R SETTING		
RAIL TOWER	PIER AND/OR ABUTMENT	
2	3 1/2"	1/2"
2	3"	0
1/2"	2 1/2"	+ 1/2"


is vertical at 50° F
other than those
straight line interpolation
number position



PIN
Not to Scale



FIXED BEARING




EXPANSION BEARING





SWEDGE ANCHOR BOLTS
Not to Scale

NOTES

- 1 Shoes fabricated from structural steel plates. Where machined surfaces were required, sufficient stock was allowed to provide the dimensions as shown. Shoes were stress relieved by heat treating after welding.
- 2 Nuts for the anchor bolts on fixed bearings were tightened and the threads punched to lock nuts. Expansion bearings had the nuts tightened against each other.
- 3 Bolts may be deformed cold or heated to make swedge anchor bolts.
- 4 Anchor bolts for bearings are 1 1/2" swedge bolts and extend 18" into concrete.
- 5 Used a Non-Ferrous, Non-Shrinking grout.

Revisions			
Symbol	Descriptions	Date	Approved
<p>U. S. ARMY ENGINEER DISTRICT CORPS OF ENGINEERS KANSAS CITY, MISSOURI</p>			
Designed by R. G. D.	 <p>LITTLE BLUE RIVER, MISSOURI LONGVIEW LAKE EMBANKMENT CRITERIA AND PERFORMANCE REPORT</p> <p>SERVICE BRIDGE MISCELLANEOUS DETAILS</p>	Scale AS SHOWN	Sheet Number
Drawn by P. R. C.		Date	
Checked by R. G. D. / W. B. E.			
Submitted by R. G. D.			File No. RBL-3-1434





* Care should be taken not to drill through the existing reinforcement of the abutment beam


ELEVATION A

SECTION C


NEW ABUTMENT

NEW ABUTMENT BACKWALL Scale 1/4" = 1'-0"


A




DRAIN DETAIL Not to Scale




RAILING POST AND APPROACH SLAB DETAIL Scale 1/4" = 1'-0"



DETAIL (RUSTICATION) Full Scale




ROADWAY SLAB CROWN Not to Scale



SECTION D Scale 1/4" = 1'-0"

* All fill material will be compacted by plate vibrator






NEW ABUTMENT BACKWALL (A)
Scale: 1/8" = 1'-0"

SE
Scale: 1/8" = 1'-0"

GENERAL NOTES:
1. Concrete f'c = 3,070 psi
2. Reinforcing steel f_s = 24,000 psi
3. Structural steel f_s = 20,000 psi
4. Clear distance of reinforcement shall be 2" unless otherwise noted
5. Top of backwall and expansion devices to conform to the crown of the roadway slab
6. CRES = Corrosion resisting steel
7. C.U. = Construction Joint
8. Curb and roadway plates will be preheated before welding
9. All exposed concrete shall be chamfered 3/4"



DETAIL (RUSTICATION) 5/5
Full Scale

2'-5" W

At road
slab

1'-6" base

SLAB DETAIL

Symbol	Change
(A)	Revise

Designed by

RCL

Drawn by

PWM


Checked by

RCL

Submitted by

T.D.W.


Material will
be impacted by plate



ROADWAY SLAB CROWN
Not to scale

PIER AND/OR ABUTMENT	
Temperature at time of setting	
0°F	3 1/2"
50°F	3"
100°F	2 1/2"

Note:
For temperatures other than those shown, use straight line interpolation to determine proper dimension.



SECTION (F)
Scale: 1" = 1'-0"

GENERAL NOTES

- Concrete f'c = 3,070 psi
- Reinforcing steel f_s = 24,000 psi
- Structural steel f_s = 20,000 psi
- Clear distance of reinforcement shall be 2" unless otherwise noted
- Top of backwall and expansion devices to conform to the crown of the roadway slab
- CRES = Corrosion resisting steel
- C.U. = Construction Joint
- Curb and roadway plates will be preheated before welding
- All exposed concrete shall be chamfered 3/4"

RECORD DRAWING

JANUARY 1990
CONTRACT NO. DACW1-88-C-0181

Symbol	Revisions	Date	Approved
(A)	Change size of rebar	6-21-89	JCL
	Revised for "As Built" conditions	3-13-90	JCL

U. S. ARMY ENGINEER DISTRICT
CORPS OF ENGINEERS
KANSAS CITY, MISSOURI

Designed by

RCL

Drawn by

PWM

Checked by

RCL

Submitted by

T.D.W.

Scale

AS SHOWN

Date

MAY 1989

Sheet

number

File


number

LITTLE BLUE RIVER, MISSOURI
LONGVIEW LAKE
EMBANKMENT CRITERIA
AND PERFORMANCE REPORT

SERVICE BRIDGE ALTERATION

PLATE NO. 34A

OBSERVATION DEVICE SCHEDULE						
DEVICE	STATION	RANGE	UP ELEVATION	TOP ELEVATION	INSTALLATION	DETAILS
PPF 05-1	85+00	0+00	927.4	805.8	FDN. SHALE	1
PPF 05-1A	85+00	0+00	929.2	783.5	FDN. SHALE	1
PPF 07	96+19	2+00	686.7	773.1	FDN. CL	1
PPF 07-2	86+70	0+00	936.5	754.5	FDN. SANDSTONE	1
PPF 07-3	86+85	0+00	926.5	766.5	FDN. SILTSTONE	1
PPF 07-4	87+10	2+00	691.4	763.4	FDN. ROCK STRATA	70
PPF 07-5	86+40	0+00	927.5	859.5	FDN. ROCK STRATA	70
PPF 08-1	87+99	1+00	903.0	837.4	FDN. ROCK STRATA	70
PPF 08-2	87+88	1+00	902.9	837.4	FDN. ROCK STRATA	70
PFE 08-3	87+77	1+00	902.4	879.9	SAND DRAIN	1
PZF 229	91+00	0+00	919.1	809.9	FDN. CC	1
PPE 09-1	89+80	1+00	903.1	834.9	EMB. CL	1
PPE 09-2	89+45	1+00	902.1	861.8	EMB. CH	1
PPE 09-3	89+88	1+00	902.9	818.0	EMB. CL	1
PZE 09-9	89+13	1+00	888.0	819.8	SAND DRAIN	1
PZE 09-2	90+01	2+00	849.6	823.9	SAND DRAIN	1
PPE 02-1	92+00	1+00	908.3	823.0	EMB. CL	1
PPE 02-2	92+00	1+10	904.9	823.3	EMB. CL	2
PPE 03-1	93+00	3+00	818.9	818.9	EMB. CH	3
PPF 03-2	93+00	0+00	921.3	811.4	FDN. CH	1
PPF 03-2A	93+00	1+00	---	775.0	FDN. SILTSTONE	3
PPE 03-4	93+00	0+00	924.0	819.5	EMB. CH	1
PPE 03-4A	93+00	2+00	897.2	819.4	EMB. CH	1
PPE 03-5A	93+00	0+10	---	812.0	EMB. CL	3
PPE 03-5A	93+00	0+50	---	830.0	EMB. CH	3
PPF 03-8	93+00	0+50	923.3	785.0	FDN. SILTSTONE	1
PZF 03-9	93+00	1+00	900.4	864.9	FDN. CC	1
PZF 03-10A	93+00	3+00	867.2	805.9	FDN. CLAYEY SAND AND GRAVEL	1
PZF 03-11	93+00	5+30	820.4	803.7	FDN. CLAYEY GRAVEL AND SAND	1
PPE 03-12	93+00	1+10	---	830.0	EMB. CH	3
PPE 06-1	96+00	1+00	---	820.0	EMB. CH	3
PPE 06-1	96+70	1+00	907.2	826.4	EMB. CL	1
PZE 06-2	96+70	3+00	846.6	796.3	SAND DRAIN	1
PPE 07-1	97+00	3+25	---	820.3	EMB. CL SEWER BACKFILL	3
PPF 07-2	97+00	2+10	---	820.6	EMB. CL	1
PPF 07-3	97+00	1+00	---	---	EMB. CL	1
PPF 07-4	97+00	1+00	---	---	EMB. CL	1
PPF 07-5	97+00	1+00	---	---	EMB. CL	1
PPF 07-6	97+00	1+00	---	---	FDN. SHALE	3
PZF 07-10	97+00	1+00	899.2	802.8	FDN. CC	1
PZE 07-11	97+00	1+00	890.9	824.4	SAND DRAIN	1
PPE 07-13	97+32	1+00	901.8	839.7	EMB. CL	1
PPE 07-14	97+36	1+00	902.2	830.0	EMB. CL	1
PPE 07-15	97+35	2+00	---	829.1	EMB. CL	5
PPE 07-16	97+00	0+00	916.8	840.0	EMB. CL	1
PPE 07-17	97+00	0+75	---	838.0	EMB. CL	3
PPE 08-1	97+80	1+00	---	829.4	EMB. CL	3
PPE 08-2	98+00	1+00	---	830.0	EMB. CL	3
PPF 09-1	98+40	2+00	---	800.0	FDN. SHALE	3
PPE 09-2	98+00	0+00	913.6	811.8	EMB. CL	1
PPF 09-3	98+00	0+00	923.6	789.7	FDN. SHALE AND SILTSTONE	1
PPF 09-4	98+00	0+00	923.4	771.3	FDN. SHALE AND SILTSTONE	1
PPE 09-5	98+00	0+00	---	818.0	EMB. CL	1
PPE 09-6	99+00	2+00	---	822.5	EMB. CL	2
PPE 09-7	98+00	0+70	916.8	804.5	EMB. CL FDN. SHALE CONTACT	1
PPE 09-8	98+45	0+00	---	836.7	EMB. CL	5
PPE 09-10	99+00	1+00	891.8	823.1	EMB. CL	1
PPE 09-11	98+44	0+00	---	827.4	EMB. CL	6
PPE 09-12	98+40	---	---	839.0	EMB. CL	5
PPE 09-13	98+00	2+00	896.9	849.2	EMB. CL	1
PPE 09-16	99+10	0+00	---	836.4	EMB. CL	3
PPE 09-17	98+00	1+00	---	830.8	EMB. CL	3
PPE 09-18	98+03	0+00	---	801.5	EMB. CH FDN. SANDSTONE CONTACT	6
PPF-C691A	85+00	1+00	929.7	803.1	FDN. ROCK STRATA	6
PPF-C692	86+50	0+00	926.7	799.4	FDN. ROCK STRATA	6
PPF-C693	103+00	1+00	914.0	811.1	FDN. ROCK STRATA	6
PPF-C694	103+00	1+00	913.2	847.1	FDN. ROCK STRATA	6
M-1	88+04	8+50	859.4	811.6	FDN. OVERBURDEN	70
M-2	87+33	13+00	865.2	880.3	FDN. OVERBURDEN	70
M-3	89+31	13+00	882.9	806.0	FDN. OVERBURDEN	70
M-4	91+39	12+00	826.9	806.8	FDN. OVERBURDEN	70
M-5	91+68	10+00	827.9	---	FDN. OVERBURDEN	70




MONITOR BOX SCHEDULE

NUMBER	STATION	RANGE	TYPE
MB-1	93+00	0+40 U	24" CMP
MB-2	97+00	0+40 U	24" CMP
MB-3	97+00	1+20 D	24" CMP
MB-4	98+40	0+40 U	24" CMP
MB-5	98+40	0+40 D	24" CMP
MB-6	93+00	1+05 D	24" CMP
M-7	96+40	1+70 U	3" I.P. CASING
M-8	97+32	1+98 U	3" I.P. CASING
M-9	93+00	2+30 U	3" I.P. CASING

TYPE
CMP
CMP
CMP
CMP
CMP
CMP
CASING
CASING
CASING

MONITOR BOX SCHEDULE			
NUMBER	STATION	RANGE	TYPE
MS-1	93+00	0+40 U	24" CMP
MS-2	37+00	0+40 U	24" CMP
MS-3	97+00	1+20 D	24" CMP
MS-4	98+40	0+40 U	24" CMP
MS-5	98+40	0+40 D	24" CMP
MS-6	93+00	1+05 D	24" CMP
M-7	96+40	1+70 U	3" I P CASING
M-8	97+32	1+88 U	3" I P CASING
M-9	93+00	2+30 U	3" I P CASING



3

2

1

D

C

B

A

TP-1, 2 & 3

TP-5

TP-4

C688

C684

100+00

95+00

90+00

10A

RD "B"

DITCH

DRAINAGE

OW-4

OW-3

OW-2

OW-5

WW

WW

3


2


1


PLATE NO 35

- LEGEND
- PZ OPEN TUBE PIEZOMETER
 - VW VIBRATING WIRE PIEZOMETER
 - PP PRESSURE CELL PORE PRESSURE DEVICE
 - AP OPEN TUBE PORE PRESSURE DEVICE
 - F FOUNDATION
 - E EMBANKMENT
 - SP FOUNDATION SETTLEMENT DEVICE
 - AL ALIGNMENT MONUMENT
 - LS LREST SETTLEMENT MONUMENT
 - IM IMMONUMENT MONUMENT
 - PH MONITOR BOX
 - I IN INCHMETER
 - TP TPLA E

DETAIL NO.	PIEZOMETER TYPE
1	3/4" OPEN TUBE PIEZOMETER
2	2" OPEN TUBE PIEZOMETER
3	PNEUMATIC PIEZOMETER
4	VIBRATING WIRE PIEZOMETER
5	PNEUMATIC CELL INSTALLED IN EXISTING 1" OPEN TUBE PIEZOMETER
6	PNEUMATIC CELL INSTALLED IN EXISTING 1" OPEN TUBE PIEZOMETER
7a	3/4" OPEN TUBE PIEZOMETER INSTALLING SEVERAL STRATA 1 1/2" x 24" 820 TO 020" SLOTTED TIP
7b	2" OPEN TUBE PIEZOMETER INSTALLING SEVERAL STRATA 2" x 16" 820 TO 020" SLOTTED TIP
8	3/4" OPEN TUBE PIEZOMETER INSTALLING SEVERAL STRATA 1 1/2" x 24" 820 TO 020" SLOTTED TIP

Revisions			
Symbol	Descriptions	Date	Approved
U S ARMY ENGINEER DISTRICT CORPS OF ENGINEERS KANSAS CITY, MISSOURI			
Designed by RGO	 LITTLE BLUE RIVER, MISSOURI LONGVIEW LAKE EMBANKMENT CRITERIA AND PERFORMANCE REPORT OBSERVATION DEVICES PLAN AND SCHEDULE	Scale AS SHOWN	Sheet number
Drawn by RAH		Date	File No
Checked by RGO/WEE			
Submitted by RGO			










SCHEDULE OF FOUNDATION SETTLEMENT DEVICES		
NO	STATION	RANGE
SPPF-91-1	91+00	0+40 D
SPPF-93-7	93+00	0+50 D
SPPF-96-1	96+10	0+75 D


INCLINOMETER SCHEDULE		
NUMBER	STATION	RANGE
I 99-1	98+40	2+57 D
I 99-2	98+25	0+85 U
I 99-3	98+50	1+80 U
I 97-1	97+49	1+89 U

TILTPLATE SCHEDULE		
NUMBER	POSITION	LOCATION
TP-1	HORIZONTAL	SE CORNER TOP TOWER DECK
TP-2	VERTICAL	SE COR TOP TOWER DECK, S GUARDRAIL
TP-3	VERTICAL	SE COR TOP TOWER DECK, S GUARDRAIL
TP-4	VERTICAL	1/2 FACE TOWER BR G ABUT EL 890.5
TP-5	VERTICAL	1/2 FACE TOWER BRIDGE PIER, EL 886.5

CREST SETTLEMENT MONUMENT SCHEDULE		
NUMBER	STATION	RANGE
CSM-1	88+50	0+36 D
CSM-2	90+50	0+36 D
CSM-3	92+50	0+36 D
CSM-4	94+50	0+36 D
CSM-5	96+50	0+36 D
CSM-6	98+70	0+36 D
CSM-7	100+50	0+36 D











ELEVATION IN FEET BASED ON NATIONAL GEODETIC VERTICAL DATUM OF 1929


D




C









B




A








PZ OPEN T
PP PRESSU
PP OPEN T
F FOUNDAT
E EMBANK
SP FOUNDA
ALIGNM
CREST
INSTUM
MB MONIT
TM TILT M
PIEZOM
MULTI
OPEN T
PNEUM








LEGEND


PZ OPEN TUBE PIEZOMETER.....○
PP PRESSURE CELL PORE PRESSURE DEVICE.....■
PP OPEN TUBE PORE PRESSURE DEVICE.....◆
F FOUNDATION.....
E EMBANKMENT.....
SP FOUNDATION SETTLEMENT DEVICE.....●
ALIGNMENT MONUMENT.....▲
CREST SETTLEMENT MONUMENT.....○ #4
INSTRUMENT MONUMENT.....⊙
MB MONITOR BOX.....⊞
TM TILT METER.....●
PIEZOMETER WATER LEVEL AT
MULTIPURPOSE POOL.....
OPEN TUBE PIEZOMETER (7-13-89)
PNEUMATIC PIEZOMETER (4-24-90)



Revisions			
Symbol	Descriptions	Date	Approved
U S ARMY ENGINEER DISTRICT CORPS OF ENGINEERS KANSAS CITY, MISSOURI			
Designed by R G D	LITTLE BLUE RIVER, MISSOURI LONGVIEW LAKE EMBANKMENT CRITERIA AND PERFORMANCE REPORT		
Drawn by P S T	INSTRUMENTATION CROSS SECTIONS		
Checked by R U D / W B E	Scale AS SHOWN	Sheet number 2 OF 5	
Submitted by R G D	Date 		File No RBL-3-1438







Revisions			
Symbol	Descriptions	Date	Approved


U S ARMY ENGINEER DISTRICT
CORPS OF ENGINEERS
KANSAS CITY MISSOURI





Designed by: RGD
Drawn by: SEV
Checked by: RGD/WBF
Submitted by: RGD

INSTRUMENTATION CROSS SECTIONS

Scale: AS SHOWN
Date: 3 OF 5
Draw No: RBL-3-1439

LITTLE BLUE RIVER, MISSOURI
LONGVIEW, LAKE
EMBANKMENT CRITERIA
AND PERFORMANCE REPORT





LEGEND

- PZ OPEN TUBE PIEZOMETER
- PP PRESSURE CELL PORE PRESSURE DEVICE
- PP OPEN TUBE PORE PRESSURE DEVICE
- F FOUNDATION
- E EMBANKMENT
- SP FOUNDATION SETTLEMENT DEVICE
- AL ALIEMENT MONUMENT
- CR CREST SETTLEMENT MONUMENT
- IN INSTRUMENT MONUMENT
- MB MONITOR BOX
- TM TILT METER
- PZ PIEZOMETER WATER LEVEL AT MULTIPURPOSE POOL
- OP OPEN TUBE PIEZOMETER (7-13-89)
- PN PNEUMATIC PIEZOMETER (4-24-90)

Revisions			
Symbol	Descriptions	Date	Approved

U. S. ARMY ENGINEER DISTRICT
CORPS OF ENGINEERS
KANSAS CITY, MISSOURI

Designed by: R. G. D.

Drawn by: P. S. T.

Checked by: R. G. D. / W. B. E.

Approved by: R. G. D.


Scale: AS SHOWN





Sheet number: 4 of 5


INSTRUMENTATION CROSS SECTIONS

LITTLE BLUE RIVER, MISSOURI
LONGVIEW LAKE
EMBANKMENT CRITERIA
AND PERFORMANCE REPORT

RBL-3-1440















LEGEND

- PZ OPEN TUBE PIEZOMETER.....○
- VIBRATING WIRE PIEZOMETER.....■
- PP PRESSURE CELL PORE PRESSURE DEVICE.....■
- PP OPEN TUBE PORE PRESSURE DEVICE.....◆
- F FOUNDATION
- E EMBANKMENT
- SP FOUNDATION SETTLEMENT DEVICE.....●
- ALIGNMENT MONUMENT.....▲
- CREST SETTLEMENT MONUMENT.....○ #4
- INSTRUMENT MONUMENT.....⊙
- MB MONITOR BOX.....⊞
- TM TILT METER.....●
- PIEZOMETER WATER LEVEL AT MULTIPURPOSE POOL.....⊥
- OPEN TUBE PIEZOMETER.....7-13-89
- PNEUMATIC PIEZOMETER.....4-24-90

Revisions		Date	Approved
Symbol	Descriptions		
<p>U. S. ARMY ENGINEER DISTRICT CORPS OF ENGINEERS KANSAS CITY, MISSOURI</p>			
Designed by R G D	 <p>LITTLE BLUE RIVER, MISSOURI LONGVIEW LAKE EMBANKMENT CRITERIA AND PERFORMANCE REPORT</p>	<p>INSTRUMENTATION CROSS SECTIONS</p>	
Drawn by SEV			
Checked by R G D / W B E	Scale AS SHOWN	Sheet number	
Submitted by R G D	Date		
	Dep No	5 of 5	RBL-3-1441









DETAIL NO	PIEZOMETER TYPE
1	3/4" OPEN TUBE PIEZOMETER
2	2" OPEN TUBE PIEZOMETER
3	PNEUMATIC PIEZOMETER
4	VIBRATING WIRE PIEZOMETER
5	PNEUMATIC CELL INSTALLED IN EXISTING 3/4" OPEN TUBE PIEZOMETER
6	PNEUMATIC CELL INSTALLED IN EXISTING 2" OPEN TUBE PIEZOMETER
7A	3/4" OPEN TUBE PIEZOMETER CONTACTING SEVERAL STRATA 1 1/2" x 24" #20(0.020") SLOTTED TIP
7B	2" OPEN TUBE PIEZOMETER CONTACTING SEVERAL STRATA 2" x 16" #20(0.020") SLOTTED TIP
8	3/4" OPEN TUBE PIEZOMETER CONTACTING SEVERAL STRATA 10' SECTIONS OF 1/16" PERFORATIONS ON 6 0' CENTERS


[illegible]



**OPEN TUBE PIEZOMETER
INSTALLATION AND EXTENSION
DETAIL-A**




**FINAL POSITION OF PIEZOMETERS
AND SETTLEMENT DEVICES
DETAIL-E**




**LOCKING DEVICE
DETAIL-K**

**LOCKING DEVICE
SECTION A'**




**ALIGNMENT MONUMENTS
DETAIL-L**




**INSTRUMENT MONUMENT
DETAIL-M**

**MONITOR BO
DETAIL-F**


Temporary protective
pipe cover removed
and installed on top of each
extension. See Detail E for
extension. See Detail F for
final extension.



PIEZOMETER
WITH TUBING EXTENSION
DETAIL-A



OPEN TUBE PIEZOMETER
WITH TUBING FROM PNEUMATIC PIEZOMETER
DETAIL-C



METERS
ICES


BOX
-F

MONITOR BOX
DETAIL-E

PROTECTIVE
PIPE COUPLING
DETAIL-G

TEE CONNecT
DETAIL-I

LOCKING DEVICE
SECTION A




INSTRUMENT MONUMENT
DETAIL-M


CREST SETTLEMENT MONUMENT
DETAIL-N




TEMPORARY
PROTECTIVE PIPE
DETAIL-O




SETTLE



SETTLEMENT DEVICE INSTALLATION AND EXTENSION
DETAIL-D




TUBING DITCH
DETAIL - J



R BOX
 IL-E

PROTECTIVE
PIPE COUPLING
DETAIL-G


TEE CONNECTION
DETAIL-H




CREST SETTLEMENT MONUMENT
DETAIL-N

TEMPORARY
PROTECTIVE PIPE COVER
DETAIL-0

[illegible]



INCLINOMETER PROTECTIVE PIPE DETAIL



INCLINOMETER EXTENSION

- NOTES
1. TREMIE CASING TO BE PULLED
 2. MAKE SURE GROOVES IN TREMIE PE
 3. TREMIE PE CASING, IN
 4. POP RIVET TO STAND


or hole bored thru cap
cover, 4" X 18" std galvanized
with cap

1/2" galvanized pipe (1'-0" long)
pipe cover

locking device see detail K on
B-16 of contract drawings

grade
meter casing
Std galvanized steel
pe flange on bottom

PIPE DETAIL



INCLINOMETER EXTENSION

NOTES

1. TREME CASING (12" DIA PLASTIC PIPE (SCHEDULE 40))
TO BE PULLED AS EXTENSION PROGRESSES
2. MAKE SURE THAT THE FOUR INTERNAL LONGITUDINAL
GROOVES IN UPPER AND LOWER CASING MATCH UP
3. TREME PEA SIZE GRAVEL AROUND INCLINOMETER
CASING, IN AN OUTER PROTECTIVE PIPE
4. POP RIVET UPPER AND LOWER INCLINOMETER CASING
TO STANDARD COUPLING IN FOUR PLACES











PLATE NO 43A







Symbol	Reviser's Descriptions	Date	Approved

U S ARMY ENGINEER DISTRICT
CORPS OF ENGINEERS
KANSAS CITY, MISSOURI

Designation: RDG

Location: PST

Project: RDG/WBE

Drawn by: RDG

Checked by: AS SH WN

Date: []



Drawn: []



Sheet: []

UNIT: []


LITTLE BLUE RIVER, MISSOURI
LONGVIEW LAKE
EMBANKMENT CRITERIA
AND PERFORMANCE REPORT
PORE PRESSURE CONTOURS
(JANUARY 1987) POOL EL. 891.2

RBL-3-1444






VALUE ENGINEERING PAYS



NOTE:
THE PROJECTED POOL ELEVATION SHOWN ON THIS PLATE WAS COMPUTED USING AVERAGE MONTHLY INFLOW AND MINIMUM RELEASES INFLOW IS BASED ON A 16 YEAR PERIOD OF RECORD OF LITTLE BLUE RIVER FLOWS AT LONGVIEW ROAD IN KANSAS CITY, MO (LATER BELOW LONGVIEW DAMSITE) PUBLISHED BY U.S. GEOLOGICAL SURVEY



	1985				1986			
	SEPT	OCT	NOV	DEC	JAN	FEB	MAR	APR
BEGINNING POOL ELEVATION	844.4	849.4	857.9	864.3	872.0	873.2	875.3	877.3
ENDING POOL ELEVATION	844.4	857.9	864.3	872.0	873.2	875.3	877.3	879.4
MAXIMUM POOL ELEVATION	849.4	861.7	870.0	872.0	875.2	875.3	877.3	879.4
POOL RISE	32.7	8.5	6.4	7.7	12.1	2.1	2.0	2.1
MAX. POOL RISE	32.7	12.3	12.1	7.7	12.1	2.1	2.0	2.1

1 GATES CLOSED 15 SEPT 1985
2 MULTIPURPOSE POOL REACHED 22 SEPT 1986

Symbol	Revisions	Descriptions	Date	Approved
WBE				
MAW				
WBE/RGD				
PCW				


U.S. ARMY ENGINEER DISTRICT
CORPS OF ENGINEERS
KANSAS CITY, MISSOURI

LITTLE BLUE RIVER, MISSOURI
LONGVIEW LAKE
EMBANKMENT CRITERIA
AND PERFORMANCE REPORT


PRECIPITATION AND
LAKE FILLING RATE

AS SHOWN


FILE NO. RBL-3-1445



VALLEY SECTION - STA 90+00




CLOSURE SECTION - STA 93+00




CONDUIT SECTION - STA 98+70






VALLEY SECTION - STA 90+00






CLOSURE SECTION - STA 93+00



CONDUIT SECTION - STA 98+70

- NOTES
- 1 EMBANKMENT ZONING APPLIES BETWEEN STA 97+00 AND STA 101+00
 - 2 CROSS-SECTION APPLIES BETWEEN STA 98+00 AND STA 100+00



- NOTES
1. EMBANKMENT ZONING APPLIES BETWEEN STA 97+00 AND STA 101+00
 2. CROSS-SECTION APPLIES BETWEEN STA 98+00 AND STA 100+00

SYMBOL	ALLOWABLE LIQUID LIMIT	ZONE
	55	<ul style="list-style-type: none"> IMPERVIOUS, BELOW 887.0, INCLUDING CUTOFF TRENCH IMPERVIOUS BETWEEN STA 97+00 AND STA 101+00 - BELOW EL 887.0 RIVERBANK EXCAVATION BACKFILL IMPERVIOUS, FINISH STAGE I - NO CUTOFF TRENCH
	60	<ul style="list-style-type: none"> IMPERVIOUS, CUTOFF TRENCH ABOVE EL 867.0 IMPERVIOUS, INSPECTION TRENCH IMPERVIOUS, BETWEEN STA 97+00 AND STA 101+00 - ABOVE EL 887.0 RANDOM, BELOW EL 867.0 UPSTREAM OF DAM AXIS
	65	<ul style="list-style-type: none"> IMPERVIOUS, ABOVE EL 867.0, EXCLUDING CUTOFF TRENCH, INSPECTION TRENCH, & BETWEEN STA 97+00 & STA 101+00 IMPERVIOUS, CLAY BLANKET - RT ABUTMENT RANDOM, BELOW EL 887.0 DOWNSTREAM OF DAM AXIS
	70	<ul style="list-style-type: none"> RANDOM, ABOVE EL 867.0

Revisions		Date	Approved
Symbol	Descriptions		


U.S. ARMY ENGINEER DISTRICT
CORPS OF ENGINEERS
KANSAS CITY, MISSOURI


Designation: WBE
Drawn by: MAW
Checked by: WBE/RGD
In Charge: FCW

LITTLE BLUE RIVER, MISSOURI
LONGVIEW LAKE
EMBANKMENT CRITERIA
AND PERFORMANCE REPORT


LIQUID LIMIT ZONE
CROSS SECTIONS


Scale: AS SHOWN
Sheet Number: 1
Date:
Job No:
File No: RBL-3-1446









NOTE
FOR STAGE I THE NUMBER AFTER (RC) IS THE RECORD
CONTROL SAMPLE NUMBER FOR STAGE II, THE FIRST
NUMBER AFTER (RC) CORRESPONDS TO THE FIELD CONTROL
TEST NUMBER AND THE SECOND NUMBER IS THE RECORD
CONTROL SAMPLE NUMBER.









LEGEND

- △ - STAGE I RECORD CONTROL SAMPLE LOCATION
- - STAGE II RECORD CONTROL SAMPLE LOCATION

Revisions			
Symbol	Descriptions	Date	Approved

U. S. ARMY ENGINEER DISTRICT
CORPS OF ENGINEERS
KANSAS CITY, MISSOURI


Designed by: WBE
Drawn by: EGM
Checked by: WBE/RGD
Submitted by: FCW

**LITTLE BLUE RIVER, MISSOURI
LONGVIEW LAKE
EMBANKMENT CRITERIA
AND PERFORMANCE REPORT
PROFILE OF RECORD CONTROL
SAMPLE LOCATIONS**

Scale: AS SHOWN
Date:
Drawn by:

Sheet Number:
File No: RBL-3-1448





LEGEND

- △ STAGE I BORING LOCATION
- STAGE II BORING LOCATION
- OH 36" DIA, DRILLED HOLE
- W OBSERVATION WELL
- U UNDISTURBED BORING
- PPE PORE PRESSURE DEVICE IN EMBANKMENT
- PPF PORE PRESSURE DEVICE IN FOUNDATION
- PZF PIEZOMETER IN FOUNDATION
- I INCLINOMETER

NOTE:
THE MAJORITY OF THESE BORINGS WERE FOR
INSTRUMENTATION SAMPLES WERE TAKEN TO
SUPPLEMENT THE RECORD CONTROL TESTING

Revisions			
Symbol	Descriptions	Date	Approved

U S ARMY ENGINEER DISTRICT
CORPS OF ENGINEERS
KANSAS CITY, MISSOURI

Designed by: WBE
Drawn by: RAC
Checked by: WBE/RGD
Reviewed by: FCW

**LITTLE BLUE RIVER, MISSOURI
LONGVIEW LAKE
EMBANKMENT CRITERIA
AND PERFORMANCE REPORT
PLAN OF BORING SAMPLE
LOCATIONS**

Scale: AS SHOWN
Date:
Sheet Number:
File No: RBL-3-1449

LIQUID LIMIT - 55 IMPERVIOUS ZONE					
STAGE I					
SAMPLE	STATION	RANGE	ELEV.	SAMPLE NO.	SAMPLE DEPTH
RC-35	92+85	0+06 1/2	805.5		
RC-46	90+35	0+15 1/2	817.0		
RC-57	91+55	0+15 1/2	827.0		
RC-68	89+20	0+10 1/2	836.5		
RC-100	89+20	0+30 1/2	835.0		
RC-122	44+50	0+15 1/2	815.0		
RC-171	37+75	0+08 1/2	873.0		
RC-197	51+25	0+16 1/2	811.0		
RC-290	98+20	2+50 1/2	832.0		
RC-333	101+05	2+20 1/2	847.5		
RC-405	98+05	0	864.0		
RC-408	101+32	0+55 1/2	857.5		
OH-1	98+00	1+45 1/2	853.0	1	17.0
			846.0	3	24.0
			836.0	4	34.0
			830.5	6	39.5
OH-2	98+12	0	847.8	1	19.2
			839.6	3	27.4
			837.1	4	29.9
			833.3	5	33.7
			829.3	6	37.7
			825.1	8	41.9
U-595	88+85	1+16 1/2	864.0	WAX 1	3.0
			855.5	5	11.5
PPF-99-1	98+51	2+20 1/2	822.7	1	3.0
			816.7	4	9.0
			815.2	5	10.5
I-99-1	98+36	2+56 1/2	857.5	4	9.5
			840.0	7	17.0
			824.0	12	27.0
			814.0	19	43.0
			805.5	22	53.0
				26	61.5
PPE-99-7	98+40	0+70 1/2	863	1	3.5
			855	5	11.5
			837	11	29.5
			829	14	37.5
			821.5	18	45.0
			810.5	23	56.0
PPE-99-11	98+35	0+86 1/2		20	
			839.2	14	26.0
			827.7	20	39.5
PPF-99-4	98+38	0+40 1/2	823.0	1	

LIQUID LIMIT - 55 IMPERVIOUS ZONE			
STAGE II			
SAMPLE	STATION	RANGE	ELEV.
RC-530-19	94+25	0+50 1/2	815.0
RC-591-20	95+30	0+65 1/2	828.0
RC-661-23	95+50	0+30 1/2	857.0
RC-682-26	93+00	0+25 1/2	862.0
RC-701-27	99+30	1+85 1/2	865.0

LIQUID LIMIT - 60 RANDOM ZONE			
STAGE I			
SAMPLE	STATION	RANGE	ELEV.
RC-8	92+00	1+50 1/2	821.7

LIQU
STAC
SAM
RC-E
RC-F
U-7
U-7

LIQUID LIMIT - 60 IMPERVIOUS ZONE					
STAGE II					
SAMPLE	STATION	RANGE	ELEV	SAMPLE NO	SAMPLE DEPTH
RC-888-98	98+00	1+50 %	898.0		
RC-808-28	99+00	0+90 %	891.0		
U-746	98+40	1+70 %	828-827.5	4	70.6-71.1
			828.3-825.8	5	72.3-72.8
U-747	99+00	0	921.0-920.5	2	34-39

LIQUID LIMIT - 65 RANDOM ZONE					
STAGE II					
SAMPLE	STATION	RANGE	ELEV	SAMPLE NO	SAMPLE DEPTH
RC-659-22	95+70	2+60 %	849.0		
RC-582-21	95+10	1+10 %	825.5		
RC-452-16	91+20	0+60 %	822.0		
PPE-92-1	92+00	1+00 %	841.7		58.3
PPE-95-1	94+70	1+00 %	862.2	8	18.8-19.3
			852.0	12	28.8-29.3
PPE-93-12	93+00	1+15 %	835.7	3	54-59

LIQ
STA
SA
RC-
RC-
PPE

LIQUID LIMIT - 60 RANDOM ZONE					
STAGE II					
SAMPLE	STATION	RANGE	ELEV	SAMPLE NO	SAMPLE DEPTH
RC-479-17	93+00	1+80 %	818.0		
RC-674-24	94+75	1+10 %	861.5		
PPE-94-1	94+00	1+40 %	842.5-842.3	3	55-59
			836.5-836.1	6	11.5-11.9
			823.5-823.0	13	24.5-25.0

LIQUID LIMIT - 70 RANDOM ZONE					
STAGE II					
SAMPLE	STATION	RANGE	ELEV	SAMPLE NO	SAMPLE DEPTH
RC-855-31	94+00	0+30 %	908.0		
RC-877	86+50	0+22 %	919.5		
RC	102+90	0+90 %	924.0		
PPE-92-1	92+00	1+00 %	898.7	1	13-1.8
			893.7	3	6.3-6.8
			861.2	16	38.8-39.3
PPE-95-1	94+70	1+00 %	880.5	1	0-0.5
			869.7	5	11.3-11.6
U-744	94+00	0+30 %	917.4-916.9	3	6.4-6.9
			913.3-912.8	5	10.5-11.0
			903.7-903.2	7	20.1-20.6

LIQUID LIMIT - 65 IMPERVIOUS ZONE					
STAGE II					
SAMPLE	STATION	RANGE	ELEV	SAMPLE NO	SAMPLE DEPTH
RC-445-15	100+10	2+30 %	886.0		
RC-724-28	90+20	0+05 %	874.0		
RC-821-30	93+20	0+10 %	900.0		
RC-882-35	106+15	0+08 %	921.0		
RC-892-34	93+75	0+10 %	923.5		
U-745	91+00	0	918.0-917.5	3	6.4-6.9
			908.0-907.5	7	16.4-16.9

* INSPECTION TRENCH

BERM ZONE - NO SPECIFIED LIQUID LIMIT					
STAGE II					
SAMPLE	STATION	RANGE	ELEV	SAMPLE NO	SAMPLE DEPTH
RC-675-25	93+30	2+20 %	864.0		
RC-514-18	96+56	2+35 %	853.5		
PPE-93-10A	93+00	3+00 %	825.4-824.9	2	2.0-2.5
U-594	89+60	2+80 %	884	1	3.0
			873	6	13.0

SACK #4 COMPOSITE SAMPLE FROM SPENCER SEEP AREA


Revisions			
Symbol	Descriptions	Date	Approved
U S ARMY ENGINEER DISTRICT CORPS OF ENGINEERS KANSAS CITY, MISSOURI			
Designed by ROG	 LITTLE BLUE RIVER, MISSOURI LONGVIEW LAKE EMBANKMENT CRITERIA AND PERFORMANCE REPORT		
Drawn by PST			
Checked by ROG/WBE	Scale AS SHOWN	Sheet number	
Submitted by ROG	Date	1 of 1	File No RBL-3-1450

PLATE NO 50

D

C

B

A

SAMPLE	DEPTH (FT)	NO. OF GRADATION TESTS	TRIAXIAL 'Q' TEST	TRIAXIAL 'R' TEST	DIRECT SHEAR 'S' TEST	DENSITY TEST	COMPACTION TEST	PERMEABILITY TEST
STAGE I, LIQUID LIMIT - 55 IMPERVIOUS ZONE								
RC-35	2	X	X		X		X	
RC-46	2	X	X		X		X	
RC-57	2	X	X		X		X	
RC-68	2	X	X		X		X	
RC-109	2	X	X		X		X	
RC-122	2	X	X		X		X	
RC-171	2	X	X		X		X	
RC-197	2	X	X		X		X	
RC-290	2	X	X		X		X	
RC-333	2	X	X		X		X	
RC-405	3	X	X		X		X	
RC-406	1	X	X		X		X	
OH-1	17.0		X	X		X		
	24.0		X	X	X		X	
	34.0		X	X		X		
	39.5		X	X	X		X	
OH-2	19.2		X	X	X		X	
	27.4	1		X	X		X	X
	29.9			X	X		X	
	33.7			X	X		X	X
	37.7		X	X	X		X	
	41.9		X	X	X		X	
I-99-1	9.5					X		
	17.0	1	X					
	27.0	1				X		
	43.0	1	X	X	X			
	53.0	1				X		
PPF-99-1	61.5		X	X	X			
	3.0	1				X		
	9.0	1				X		
PPF-99-4	10.5	1				X		
		1				X		
PPE-99-7	3.5					X		
	11.5					X		
	29.5	1				X		
	37.5		X	X	X			
	45.0					X		
PPE-99-11	56.0		X	X				
	29	1				X		
U-595	39.5	2					X	
	3.0	1		X	X			
	11.5	1		X	X			

SAMPLE	DEPTH (FT)	NO. OF GRADATION TESTS	TRIAXIAL 'Q' TEST	TRIAXIAL 'R' TEST	TRIAXIAL 'S' TEST
STAGE II, LIQUID LIMIT - 55 IMPERVIOUS ZONE					
RC-530-19	3	X	X	X	
RC-581-20	1	X	X	X	
RC-661-23	2				X
RC-662-26	2	X			X
RC-701-27	2				X
STAGE I, LIQUID LIMIT - 60 RANDOM ZONE					
RC-8	2	X	X		X
STAGE II, LIQUID LIMIT - 60 IMPERVIOUS ZONE					
RC-803-29	2	X	X	X	
RC-899-36	1				
U-746	70.8-71.1	1	X	X	X
	72.3-72.8	1	X	X	X
U-747	34-39	1	X	X	X
STAGE II, LIQUID LIMIT - 60 RANDOM ZONE					
RC-479-17	2	X	X	X	
RC-674-24	2	X	X	X	
PPE-94-1	5.5-5.9	1	X	X	X
	11.5-11.9	1	X	X	X
	24.5-25.0	1	X	X	X
STAGE II, LIQUID LIMIT - 65 IMPERVIOUS ZONE					
RC-445-15	1	X	X	X	X
RC-724-28	2	X	X	X	
RC-821-30	2	X	X	X	
RC-882-33	2	X	X	X	
RC-892-34	1				
U-745	6.4-6.9	2	X	X	X
	16.4-16.9	1	X		

SAMPLE	DEPTH (FT)	NO OF							
		TRIAxIAL	TRIAxIAL	TRIAxIAL	DIRECT	CORRECTION			
STAGE II, LIQUID LIMIT - 55 IMPERVIOUS ZONE									
RC-690-19		3	X	X	X		X	X	
RC-691-20		1	X	X	X		X	X	
RC-691-23		2					X	X	X
RC-692-26		2	X				X	X	X
RC-701-27		2					X	X	X
STAGE I, LIQUID LIMIT - 60 RANDOM ZONE									
RC-8		2	X	X			X		X
STAGE II, LIQUID LIMIT - 60 IMPERVIOUS ZONE									
RC-803-29		2	X	X	X		X	X	
RC-809-36		1							X
U-746	70.8-71.1	1	X	X	X		X	X	
	72.3-72.8	1	X	X	X		X	X	
U-747	34.3-39	1	X	X	X				
STAGE II, LIQUID LIMIT - 60 RANDOM ZONE									
RC-875-17		2	X	X	X		X	X	
RC-874-24		2	X	X	X		X	X	
PPE-94-1	5.5-5.9	1	X	X	X		X		
	11.5-11.9	1	X	X	X				
	24.5-25.0	1	X	X	X				
STAGE II, LIQUID LIMIT - 65 IMPERVIOUS ZONE									
RC-445-15		1	X	X	X	X	X	X	X
RC-724-28		2	X	X	X		X	X	
RC-921-30		2	X	X	X		X	X	
RC-802-33		2	X				X	X	X
RC-692-34		1							X
U-745	5.4-6.9	2	X	X	X				
	6.4-16.9	1	X						

SAMPLE	DEPTH (FT)	NO. OF GRAINS						
		TRIAXIAL	TRIAXIAL	TRIAXIAL	DIRECT	DRIFT		
STAGE II, LIQUID LIMIT - 65 RANDOM ZONE								
RC-452-16		1	X	X	X	X	X	X
RC-592-21		2	X	X	X		X	X
RC-659-22		2	X	X	X		X	X
PPE-93-12	54-59	1	X	X	X		X	
PPE-95-1	18.8-19.3	1					X	
	28.8-29.3	1	X	X	X			
STAGE II, LIQUID LIMIT - 70 RANDOM ZONE								
RC-855-31		2	X	X	X		X	X
RC-878-32		2	X	X	X		X	X
RC-896-33		1						X
PPE-92-1	1.3-1.8	1	X	X	X			
	6.3-6.8	1	X	X	X			
	13.8-15.0	1					X	
	38.8-39.3	1	X	X	X			
PPE-95-1	00-05	1	X	X	X			
	11.3-11.8	1	X	X	X			
U-744	6.4-6.9	1	X	X	X			
	10.5-11.0	1	X	X	X			
	20.1-20.4	1	X	X	X			
STAGE II, BERM ZONE (UNSPECIFIED LIQUID LIMIT)								
RC-514-18		2	X	X	X		X	X
RC-675-25		2	X	X	X		X	X
PPE-93-10A		1	X					
U-594	3.0	-		X	X			
	13.0	-	X	X	X			
SACK #1		1	X	X	X			X

Revisions			
Symbol	Descriptions	Date	Approved


U S ARMY ENGINEER DISTRICT
CORPS OF ENGINEERS
KANSAS CITY MISSOURI

Designed by
RDG

Drawn by
PST

Checked by
RDG / WBE

Submitted by
RDG



**U.S. Army Corps
of Engineers**

LITTLE BLUE RIVER, MISSOURI
LONGVIEW LAKE
EMBANKMENT CRITERIA
AND PERFORMANCE REPORT

LABORATORY SOILS TESTING LOG

Soil No.	AS SHOWN	Sheet Number
Date		
49		

1 of 1 RBL-3-1451

DATA ON RECORD CONTROL SAMPLES													
STAGE I LIQUID LIMIT - 55 IMPERVIOUS ZONE													
HOLE NO	SAMPLE DEPTH	CLASSIFICATION				DRY DENSITY		WATER CONTENT			"Q" TEST		"R"
		SYM	L L	P.L	P.I.	MAX.	INITIAL RANGE	OPT	INITIAL RANGE	PERCENT SATURATION	TAN ϕ	C T.S.F	TAN δ
RC - 35		CH	65	22	43	97.2	96.8 - 97.1	23.5	26.6 - 27.4	97-99	0.052	1.08	
RC - 48		CL	40	18	22	105.2	106.4 - 107.5	16.5	19.9 - 20.2	97-98	0.096	1.00	
RC - 57		CL	48	16	32	105.0	107.6 - 108.3	17.8	18.5 - 18.6	88-89			
RC - 68		CH	50	20	30	97.4	98.5 - 98.7	21.2	24.0 - 24.1	91-92	0.070	1.25	
RC-109		CL	48	18	28	103.0	107.3 - 107.8	19.0	18.9 - 19.1	90	0.016	2.15	
RC-122		CL	44	18	26	102.2	106.5 - 107.5	18.7	20.2 - 20.7	95	0	1.35	
RC-171		CL	46	19	27	103.8	99.3 - 101.0	18.8	24.8 - 25.9	100	0.035	1.25	
RC-197		CH	57	17	40	99.7	93.1 - 93.3	21.3	29.3 - 29.5	100	0.123	0.55	
RC-290		CL	43	20	23	105.3	104.6 - 104.9	18.7	21.6 - 21.9	99-100	0.044	1.70	
RC-333		CL	45	25	20	101.6	97.5 - 97.8	20.3	25.7 - 25.9	100	0.121	0.75	
RC-405		CH	56	22	34	95.6	99.0 - 100.7	24.3	23.6	92-96	0.155	1.23	
RC-406		CH	56	20	36	97.7	105.7 - 106.1	22.2	20.6 - 20.8	94-95	0.070	2.38	
OH-1	17.0	CH	53	16	37		104.8 - 105.7		21.6 - 22.0	100			0.521
	24.0	CL	43	15	28		107.2 - 108.1		20.1 - 20.4	98-100	0.035	1.35	0.613
	34.0	CL	41	16	25		99.5 - 103.6		21.5 - 23.8	92-95			0.53
	39.5	CL	40	16	24		102.8 - 104.4		20.5 - 22.2	93-97	0.070	0.40	0.53
OH-2	19.2	CL	48	16	32		105.7 - 107.9		18.9 - 19.7	92-98	0.167	1.15	0.46
	27.4	CL	36	18	18		106.6 - 107.3		18.3 - 18.7				0.58
	29.9	CL	39	18	21		106.9 - 107.8		19.4 - 20.1	93-97			0.57
	33.7	CL	41	16	25		110.2 - 110.9		18.8 - 19.0	100			0.57
	37.7	CL	32	16	16		113.0 - 115.0		16.4 - 17.1	98-99	0.456	1.45	0.68
	41.9	CL	43	16	27		102.0 - 102.3		22.7 - 23.0	98-100	0.437	0.75	0.57
U-595	3.0	CH	53	17	36		100.8 - 101.8		23.1 - 23.4	94-95			0.48
	11.5	CL	45	17	28		108.6		17.5	86			
PPF-99-1	3.0						91.2 - 94.5		26.0 - 27.1	89-97			
	9.0						100.8 - 105.4		19.8 - 21.3	90-94			
	10.5						102.4 - 104.4		21.7	94-99			
I-99-1	9.5						102.3 - 105.1		21.3 - 21.9	93-98	0.035	1.50	
	17.0	CL	46	17	29		101.1 - 103.9		22.3 - 24.0	97-98			
	27.0						103.2 - 107.8		18.5 - 21.0	90-93			
	43.0	CL	41	15	25		106.5 - 107.4		19.8 - 20.4	95-99	0.100	0.75	0.60
	53.0						103.9 - 104.3		23.8 - 23.9	100			
PPF-99-4	61.5	CL	41	14	27		102.4 - 110.3		18.2 - 23.1	96-100	0.315	0.40	0.46
							99.1 - 103.4		21.5 - 22.0	92-96			0.41
PPF-99-7	3.5						100.0 - 100.7		22.1 - 22.5	89-90			
	11.5						100.0 - 101.6		23.3 - 24.2	92-99			
	29.5						106.4 - 106.7		18.9 - 19.1	89-96			
	37.5	CL	33	17	16		104.9 - 107.3		20.3 - 21.4	95-96			
	45.0						104.7 - 105.0		21.8	97-98			0.5
	56.0	CL	48	17	31		104.2 - 105.4		19.8 - 21.0	96-98			

NOTE: EXCEPT FOR THE "R" TEST, ALL SHEAR STRENGTH PARAMETERS PROVIDED ON THE SUMMARY TABLE ABOVE WERE DERIVED FROM A BEST FIT TANGENT TO THE "R" TEST-EFFECTIVE STRESS STRENGTH PARAMETERS WERE DERIVED FROM THE POINTS PLOTTED AS DESIGNATED BY THE CORRESPONDING MOHR C DIAGRAM


* SUSPECT TEST

LIQUID LIMIT - 55 IMPERVIOUS ZONE

1 INL
DIAGRAM

WERE DERIVED FROM A BEST-FIT TANGENT TO THE MOHR'S CIRCLES FOR EACH SAMPLE TESTED.
IS DESIGNATED BY THE CORRESPONDING MOHR'S DIAGRAM.

[illegible]



LIQUID LIMIT - 55
IMPERVIOUS ZONE
STAGE I

SAMPLE

OH-2

DIFFERENTIAL HEAD -
HORIZONTAL SPECIMEN

MATI

BERM
HILLSIDE BO
VALLEY BOF
FOUNDATION
SHALE - PE
SHALE - RE







PLATE NO. 53

5

4


3

D






C

B



A





Revisions		Date	Approved
Symbol	Descriptions		

U S ARMY ENGINEER DISTRICT
 CORPS OF ENGINEERS
 KANSAS CITY, MISSOURI

DESIGNED BY: RDG
 DRAWN BY: MAW
 CHECKED BY: RDG / WBE
 SUBMITTED BY: RDG

LITTLE BLUE RIVER, MISSOURI
LONGVIEW LAKE
EMBANKMENT CRITERIA AND
PERFORMANCE REPORT
SHEAR TEST SUMMARIES
LIQUID LIMIT-55 IMPERVIOUS ZONE
STAGE I


AS SHOWN

Sheet number: _____
 Date: _____
 File No: **RBL-3-1454**

DATA ON RECORD CONTROL SAMPLES **STAGE II LIQUID LIMIT - 55 IMPERVIOUS ZONE**



HOLE NO.	SAMPLE DEPTH	CLASSIFICATION				DRY DENSITY		WATER CONTENT		PERCENT SATURATION	"Q" TEST		"R" TEST	
		SYM.	L.L.	P.L.	P.I.	MAX.	INITIAL RANGE	OPT.	INITIAL RANGE		TAN ϕ	C T.S.F.	TAN ϕ	C T.S.F.
RC-530-19		CL	48	16	32	100.6	103.0 - 104.8	20.6	20.7 - 21.9	94-96	0.087	1.05	0.532	0.19
RC-59-20		CH	55	15	40	98.3	102.5 - 103.8	22.1	22.6 - 23.0	100	0.018	0.85	0.404	0.21
RC-66-23		CL	46	16	30	98.1		22.7						
RC-682-26		CL	44	16	28	100.5	101.1 - 106.4	19.8	18.6 - 19.0	77-87	0.298	1.15		
RC-701-27		CH	51	18	33	98.3		22.5						




NOTE: EXCEPT FOR THE "R" TEST, ALL SHEAR STRENGTH PARAMETERS PROVIDED ON THE SUMMARY TABLE ABOVE WERE DERIVED FROM A BEST FIT TANGENT TO THE MOHR'S CIRCLES. THE "R" TEST-EFFECTIVE STRESS STRENGTH PARAMETERS WERE DERIVED FROM THE POINTS PLOTTED AS DESIGNATED BY THE CORRESPONDING MOHR'S DIAGRAM.



LIQUID LIMIT - 55 IMPERVIOUS ZONE STAGE II
 GRADATION LIMITS FOR RECORD CONTROL SAMPLES TESTED.

PHYSICAL SOIL				
MATERIAL	UNIT WEIGHT P.C.F.	SAT. MOIST (C.T.S.F.)	WATER CONTENT (%)	LIQUID LIMIT (%)
BERM	125	140	0.45	0.00
HILLSIDE BORROW	125	145	0.90	0.00
VALLEY BORROW	125	145	0.90	0.00
FOUNDATION OVERBURDEN	115	140	0.60	0.00
SHALE - PEAK	140	140		
SHALE - RESIDUAL	140	140		






3

2

1

D




C

B

A

35
VE

CH

3.0
NORMAL

Revisions		Date	Approved
Symbol	Descriptions		
U. S. ARMY ENGINEER DISTRICT CORPS OF ENGINEERS KANSAS CITY, MISSOURI			
Designed by	WBE	LITTLE BLUE RIVER, MISSOURI LONGVIEW LAKE EMBANKMENT CRITERIA AND PERFORMANCE REPORT	
Drawn by	MAW	SHEAR TEST SUMMARIES LIQUID LIMIT-55 IMPERVIOUS ZONE STAGE II	
Checked by	WBE/RGD	Scale	AS SHOWN
Submitted by	FCW	Date	
		Sheet number	
		File No.	RBL-3-1456

PLATE NO. 56

3

2

1

D

C

B

A

5


4

3

DATA ON RECORD CONTROL SAMPLES STAGE I LIQUID LIMIT - 60 RANDOM ZONE

HOLE	SAMPLE	CLASSIFICATION				DRY DENSITY		WATER CONTENT			
NO	DEPTH	SYM	L.L.	P.L.	PI	MAX	INITIAL RANGE	OPT	INITIAL RANGE	PER CENT SATURATION	TA
RC-8		CH	51	15	36	100.8	99.8 - 103.7	20.4	22.3 - 24.6	98	0.0



NOTE: ALL "Q" AND "R" SHEAR STRENGTH PARAMETERS PROVIDED ON THE SUMMARY TABLE ABOVE WERE DERIVED FROM A BEST FIT LINE TANGENT TO THE MOHR'S CIRCLES FOR EACH SAMPLE.












LIQUID LIMIT - 60 RANDOM ZONE STAGE I
GRADATION LIMITS FOR RECORD CONTROL SAMPLES TESTED.

PHYSICAL SOIL C

MATERIAL	UNIT WEIGHT		O	T
	SAT. MOIST	P.C.F.		
BERM	115	110	0.45	0.00
HILLSIDE BORROW	125	115	0.90	0.00
VALLEY BORROW	125	115	0.90	0.00
FOUNDATION OVERBURDEN	115	110	0.60	0.00
SHALE - PEAK	140	140	-	-
SHALE - RESIDUAL	140	140	-	-







Revisions			
Symbol	Descriptions	Date	Approved

U S ARMY ENGINEER DISTRICT
CORPS OF ENGINEERS
KANSAS CITY, MISSOURI

Designed by: RDG
Drawn by: SEY
Checked by: RDG/WBE
Submitted by: RDG

LITTLE BLUE RIVER, MISSOURI
LONGVIEW LAKE
EMBANKMENT CRITERIA AND
PERFORMANCE REPORT
SHEAR TEST DATA SUMMARIES
LIQUID LIMIT-60 RANDOM ZONE
STAGE I


Scale: AS SHOWN
Date:
Dwg No:

Sheet number:
File No: RBL-3-1458

D

DATA ON RECORD CONTROL SAMPLES										
STAGE II LIQUID LIMIT - 60 IMPERVIOUS ZONE										
HOLE NO.	SAMPLE DEPTH	CLASSIFICATION				DRY DENSITY		WATER CONTENT		
		SYN.	L.L.	P.L.	P.I.	MAX.	INITIAL RANGE	OPT.	INITIAL RANGE	PERCENT SATURATION
RC-80369		CH	53	24	29	98.0	101.3 - 103.6	23.2	22.9 - 24.4	100
U-746	70.8-71.1	CL	43	18	25		105.5 - 106.3		20.8 - 21.4	97-98
	72.3-72.8	CL	45	20	25		101.1 - 101.4		23.2 - 23.5	97
U-747	34-39	CH	67	16	51		103.5 - 105.2		21.3 - 22.3	93-95


NOTE: EXCEPT FOR THE \star TEST, ALL SHEAR STRENGTH PARAMETERS PROVIDED ON THE SUMMARY TABLE ABOVE WERE DERIVED FROM A BEST FIT LINE. THE \star TEST-EFFECTIVE STRESS STRENGTH PARAMETERS WERE DERIVED FROM THE POINTS PLOTTED AS DESIGNATED BY THE CORRESPONDING SYMBOL.




LIQUID LIMIT - 60 IMPERVIOUS ZONE STAGE II
GRADATION LIMITS FOR RECORD CONTROL SAMPLES TESTED.

PHYSICAL SOIL				
MATERIAL	UNIT WEIGHT		C.T.S.F.	T
	P.C.F.	SAT. MOIST		
BERM	115	110	0.45	0.00
HILLSIDE BORROW	125	115	0.90	0.00
VALLEY BORROW	125	115	0.90	0.00
FOUNDATION OVERCLODEN	115	110	0.60	0.00
SHALE - PEAK	140	140	-	-
SHALE - RESIDUAL	140	140	-	-

B



A



ZONE

DATA ON RECORD CONTROL SAMPLES
PAGE II LIQUID LIMIT- 60 IMPERVIOUS ZONE

"Q" TEST	WATER CONTENT	"Q" TEST	"R" TEST	"R" TEST	"R" TEST	"S" TEST DIRECT SHEAR
TAN ϕ	INITIAL RANGE	PERCENT SATURATION	TAN ϕ	C T.S.F.	TAN ϕ	C T.S.F.
0.141	103.6	23.2	22.9 - 24.4	100	0.141	1.50
0.35	106.3	20.8 - 21.4	97-98	0.35	1.25	0.287
0.35	101.4	23.2 - 23.5	97	0	0.35	0.344
0.110	105.2	21.3 - 22.3	93-95	0.110	1.10	0.38

A BEST FIT TANGENT TO THE MOHR'S CIRCLES FOR EACH SAMPLE TESTED.
ON THE SUMMARY TABLE ABOVE WERE DERIVED FROM A BEST FIT TANGENT TO THE MOHR'S CIRCLES FOR EACH SAMPLE TESTED.
FROM THE POINTS PLOTTED AS DESIGNATED BY THE CORRESPONDING MOHR'S DIAGRAM.


SOIL CONS

PHYSICAL SOIL CONSTANTS

DES	MATERIAL	UNIT WEIGHT		DESIGN SHEAR STRENGTHS									
		SAT. MOIST	P.C.F.	Q	TAN ϕ	C (T.S.F.)	R	TAN ϕ	C (T.S.F.)	S	TAN ϕ	C (T.S.F.)	TAN ϕ
DO	BERM	15	10	0.45	0.00	0.00	0.10	1.3	0.20	0.00	16.7	0.30	0.00
DO	HILLSIDE BORROW	125	15	0.90	0.00	0.00	0.20	1.3	0.20	0.00	19.8	0.36	0.00
DO	VALLEY BORROW	125	15	0.90	0.00	0.00	0.20	1.3	0.20	0.00	26.6	0.50	0.00
DO	FOUNDATION OVERBURDEN	15	10	0.60	0.00	0.00	0.20	1.3	0.20	0.00	26.6	0.50	0.00
	SHALE - PEAK	140	140	-	-	-	-	-	-	0.00	31.0	0.60	-
	SHALE - RESOUL	140	140	-	-	-	-	-	-	0.00	16.7	0.30	-


ACTIVITY IN LIQUID LIMIT

LIQUID LIMIT-60
IMPERVIOUS ZONE
STAGE II



Revisions	Date	Approved
Symbol	Description	
<p>1st S. ARMY ENGINEER DISTRICT CORPS OF ENGINEERS KANSAS CITY, MISSOURI</p> <p>DESIGNED BY: WBE DRAWN BY: EGM CHECKED BY: RGD/WBE SUBMITTED BY: FCW</p> <p>LITTLE BLUE RIVER, MISSOURI LONGVIEW LAKE EMBANKMENT CRITERIA AND PERFORMANCE REPORT TEST DATA SUMMARIES LIQUID LIMIT-60 IMPERVIOUS ZONE STAGE II</p> <p>AS SHOWN</p> <p>RBL-3-1459</p>		




PLATE NO 59



3

2

1



Revisions			
Symbol	Descriptions	Date	Approved

U. S. ARMY ENGINEER DISTRICT
CORPS OF ENGINEERS
KANSAS CITY, MISSOURI

Designed by WBE		LITTLE BLUE RIVER, MISSOURI LONGVIEW LAKE EMBANKMENT CRITERIA AND PERFORMANCE REPORT SHEAR TEST SUMMARIES LIQUID LIMIT-60 IMPERVIOUS ZONE STAGE II	
Drawn by JGS		Scale AS SHOWN	Sheet number
Checked by RGD/WBE	Date		
Submitted by FCW	Dwg No.		File No. RBL-3-1460

3

2

1

PLATE NO. 60

D

C


B

A

DATA ON RECORD CONTROL SAMPLES STAGE II LIQUID LIMIT - 60 RANDOM ZONE

HOLE NO.	SAMPLE DEPTH	CLASSIFICATION				DRY DENSITY		WATER CONTENT				TAN ϕ
		SYM.	L.L.	P.L.	P.I.	MAX	INITIAL RANGE	OPT	INITIAL RANGE	PERCENT SATURATION		
RC-479-17		CH	52	18	34	97.8	103.4-104.5	22.7	22.2-22.8	100		0.05
RC-674-24		CH	52	15	41	98.0	98.4-99.7	22.8	24.6-25.1	96-97		0.03
PPE-94-1	5.5-5.9	CH	53	17	36		99.6-102.4		22.9-24.6	96		0.024
	11.5-11.9	CL	49	16	33		106.5-108.0		20.4-21.3	100		0.005
	24.5-25.0	CL	38	14	24		107.6-110.6		19.4-20.8	96-100		0.04



NOTE: EXCEPT FOR THE "R" TEST, ALL SHEAR STRENGTH PARAMETERS PROVIDED ON THE SUMMARY TABLE ABOVE WERE DERIVED FROM A BEST FIT. THE "R" TEST-EFFECTIVE STRESS STRENGTH PARAMETERS WERE DERIVED FROM THE POINTS PLOTTED AS DESIGNATED BY THE CORRESPONDING



LIQUID LIMIT - 60 RANDOM ZONE STAGE II
GRADATION LIMITS FOR RECORD CONTROL SAMPLES TESTED.

PHYSICAL SOIL CONSTANTS

MATERIAL	UNIT WEIGHT		DESIGN			
	SAT. MOIST	P.C.F.	ϕ (T.S.F.)	ϕ	TAN ϕ	ϕ (T.S.F.)
BERM	15	10	0.45	0.00	0.00	0.00
HILLSIDE BORROW	125	15	0.90	0.00	0.00	0.2
VALLEY BORROW	125	15	0.90	0.00	0.00	0.2
FOUNDATION OVERBURDEN	15	10	0.60	0.00	1.00	0.0
SHALE - PEAK	140	140				
SHALE - RESIDUAL	140	140				



ACTIVITY = $\frac{PI}{\% \text{ PASS } 2 \text{ MI}}$

3

2

1

DATA ON RECORD CONTROL SAMPLES

PAGE II LIQUID LIMIT-60 RANDOM ZONE


SITY	WATER CONTENT			"Q" TEST		"R" TEST		"R" TEST		"S" TEST DIRECT SHEAR	
	OPT	INITIAL RANGE	PERCENT SATURATION	TAN θ	C T.S.F.	TAN θ	C T.S.F.	TAN θ	C T.S.F.	TAN θ	C T.S.F.
1045	227	22.2-22.8	100	0.052	1.00	0.456	0.20	0.222	0.50		
997	228	24.6-25.1	96-97	0.035	1.03	0.456	0.07	0.240	0.20		
1024		22.9-24.6	96	0.026	1.03	0.414	0.20	0.096	1.25		
1080		20.4-21.3	100	0.009	1.18	0.466	0.28	0.259	0.73		
1106		19.4-20.8	98-100	0.044	0.78	0.577	0	0.335	0		

IN THE SUMMARY TABLE ABOVE WERE DERIVED FROM A BEST FIT TANGENT TO THE MOHR'S CIRCLES FOR EACH SAMPLE TESTED.
FROM THE POINTS PLOTTED AS DESIGNATED BY THE CORRESPONDING MOHR'S DIAGRAM.

PHYSICAL SOIL CONSTANTS

MATERIAL	UNIT WEIGHT P.C.F.		DESIGN SHEAR STRENGTHS									
	SAT. MOIST	CIT.S.F.	θ	TAN θ	CIT.S.F.	θ	TAN θ	CIT.S.F.	θ	TAN θ	CIT.S.F.	θ
BORROW	15	95	0.45	0.00	0.00	0.10	11.3	0.20	0.00	16.7	0.30	
FOR	125	95	0.90	0.00	0.00	0.20	11.3	0.20	0.00	19.8	0.36	
NON OVERBURDEN	125	95	0.90	0.00	0.00	0.20	11.3	0.20	0.00	26.6	0.50	
AS	40	40						0.00		26.6	0.50	
QUA	40	40						0.00		31.0	0.61	
								0.10		16.7	0.30	

ACTIVITY - LIQUID LIMIT

LIQUID LIMIT -60
RANDOM ZONE
STAGE II


Revisions	Date	Approved
Descriptions		
U.S. ARMY ENGINEER DISTRICT CORPS OF ENGINEERS KANSAS CITY, MISSOURI		
LITTLE BLUE RIVER, MISSOURI LONGVIEW LAKE EMBANKMENT CRITERIA AND PERFORMANCE REPORT TEST DATA SUMMARIES LIQUID LIMIT-60 RANDOM ZONE STAGE II		
WBE	AS SHOWN	
RAC		
RGD/WBE		
FCW		
RBL-3-1461		




3

2


1

PLATE NO 61





Revisions			
Symbol	Descriptions	Date	Approved
U S ARMY ENGINEER DISTRICT CORPS OF ENGINEERS KANSAS CITY, MISSOURI			
Designed by	WBE	LITTLE BLUE RIVER, MISSOURI LONGVIEW LAKE EMBANKMENT CRITERIA AND PERFORMANCE REPORT	
Drawn by	MAW	SHEAR TEST SUMMARIES LIQUID LIMIT-60 RANDOM ZONE STAGE II	
Checked by	RGW/WBE	Scale	AS SHOWN
Submitted by	PCW	Date	
		Drawn by	
		File No	RBL-3-1462




PERCENT
ATION
6
-96
-97
-99
-100
-99

RANGE	WATER CONTENT			"Q" TEST		"R" TEST		"R" TEST		"S" TEST	
	OPT.	INITIAL RANGE	PER CENT SATURATION	TAN ϕ	C TSF	TAN ϕ	C TSF	TAN ϕ	C TSF	TAN ϕ	C TSF
06.1	22.7	209 - 218	96	0.065	148	0.404	0.13	0.246	0.28	0.505	0
00.1	207	236 - 241	95-96	0.099	100	0.521	0.14	0.268	0.53		
02.4	233	244 - 249	96-97	0.045	113	0.379	0.17	0.213	0.30		
06.5	197	212 - 218	94-99	0.040	150	0.344	0.21	0.216	0.53		
04.2		22.8 - 23.3	92-100	0.052	148	0.240	0.58	0.194	0.65		
04.1		22.3 - 23.5	96-99	0.070	0.75						

THE SUMMARY TABLE ABOVE WERE DERIVED FROM A BEST FIT TANGENT TO THE MOHR'S CIRCLES FOR EACH SAMPLE TESTED.
THE POINTS PLOTTED AS DESIGNATED BY THE CORRESPONDING MOHR'S DIAGRAM.

SOIL C

SOIL CLASSIFICATION		PHYSICAL SOIL CONSTANTS											
Q	TAN	MATERIAL	UNIT WEIGHT		DESIGN SHEAR STRENGTHS								
			P.C.F.		Q	TAN	R	S					
0.00	0.00		SAT.	MOIST	(C.T.S.F.)	0.00	0.00	0.10	11.3	0.20	0.00	16.7	0.30
0.00	0.00		125	115	0.30	0.00	0.00	0.20	11.3	0.20	0.00	19.8	0.36
0.00	0.00	E BORROW	125	115	0.30	0.00	0.00	0.20	11.3	0.20	0.00	26.6	0.50
0.00	0.00	BORROW	125	115	0.30	0.00	0.00	0.20	11.3	0.20	0.00	26.6	0.50
0.00	0.00	ION OVERBURDEN	115	110	0.60	0.00	0.00	0.20	11.3	0.20	0.00	26.6	0.50
0.00	0.00	PFAX	140	140	-	-	-	-	-	-	0.00	31.0	0.60
0.00	0.00	PCSDIAL	140	140	-	-	-	-	-	-	0.00	16.7	0.30




Symbols	Revisions Descriptions	Date	Approved

U S ARMY ENGINEER DISTRICT
CORPS OF ENGINEERS
KANSAAS CITY MISSOURI

4-2-67

WBE



US Army Corps
of Engineers

JAN 71

EUM

FEB 71




RCD,WBE

FLW

LITTLE BLUE RIVER, MISSOURI
LONGVIEW LAKE
EMBANKMENT CRITERIA AND
PERFORMANCE REPORT
TEST DATA SUMMARIES
LIQUID LIMIT-65 IMPERVIOUS ZONE
STAGE II

AS SHOWN

RBL-3-1463



Revisions			
Symbol	Descriptions	Date	Approved

U S ARMY ENGINEER DISTRICT
CORPS OF ENGINEERS
KANSAS CITY, MISSOURI

Designed by: WBE

Drawn by: JGS

Checked by: RGD/WBE

Submitted by: FCW

LITTLE BLUE RIVER, MISSOURI
LONGVIEW LAKE
EMBANKMENT CRITERIA AND
PERFORMANCE REPORT
SHEAR TEST SUMMARIES
LIQUID LIMIT-65 IMPERVIOUS ZONE
STAGE II

Scale: AS SHOWN

Sheet number:

Date:


Tag:

File no: RBL-3-1464

PLATE NO 64



DATA ON RECORD CONTROL SAMPLES STAGE II LIQUID LIMIT-65 RANDOM ZONE										
HOLE NO.	SAMPLE DEPTH	CLASSIFICATION				DRY DENSITY		WATER CONTENT		
		SYN	L L.	PL	P.I.	MAX	INITIAL RANGE	OPT	INITIAL RANGE	PER CENT SATURATION
RC-659-22		CH	57	16	41	99.7	1039 - 1056	20.8	19.5 - 20.5	84-90
RC-592-21		CH	62	16	46	97.5	1010 - 1016	22.6	24.0 - 24.4	99
RC-452-16		CH	54	16	38	100.2	1053 - 1065	21.6	21.2 - 21.9	98
PPE-92-1	58.3									
PPE-95-1	188-193	CH	78	20	58		1032 - 1046		20.7 - 20.8	89-92
	288-293	CH	65	18	47		1041 - 105.0		22.2 - 22.5	100
PPE-93-12	5.4-5.9	CH	55	21	34		1075 - 1094		18.4 - 19.3	93-94

NOTE: EXCEPT FOR THE 'R' TEST, ALL SHEAR STRENGTH PARAMETERS PROVIDED ON THE SUMMARY TABLE ABOVE WERE DERIVED FROM A BEST FIT OF THE 'R' TEST-EFFECTIVE STRESS STRENGTH PARAMETERS WERE DERIVED FROM THE POINTS PLOTTED AS DESIGNATED BY THE CORRESPONDING



LIQUID LIMIT - 65 RANDOM ZONE STAGE II
GRADATION LIMITS FOR RECORD CONTROL SAMPLES TESTED.

PHYSICAL SOIL CONSTANTS					
MATERIAL	UNIT WEIGHT		DESIGN STRENGTH		
	SAT. MOIST	P.C.F.	φ	TAN φ	CIT. S.F.
BERM	85	80	0.45	0.00	0.00
HILLSIDE BORROW	125	85	0.90	0.00	0.20
VALLEY BORROW	125	85	0.90	0.00	0.20
FOUNDATION OVERBURDEN	85	80	0.60	0.00	0.00
SHALE - PEAK	140	140	-	-	-
SHALE - RESIDUAL	140	140	-	-	-











D

C

B

A





Revisions		Date	Approved
Symbol	Descriptions		

U.S. ARMY ENGINEERING DISTRICT
CORPS OF ENGINEERS
KANSAS CITY, MISSOURI

Designed by: **WBE**

Drawn by: **JOS**

Checked by: **RGD/WBE**

Submitted by: **FCW**

Scale: **AS SHOWN**


Project: **LITTLE BLUE RIVER, MISSOURI
LONGVIEW LAKE
EMBANKMENT CRITERIA AND
PERFORMANCE REPORT
SHEAR TEST SUMMARIES
LIQUID LIMIT-65 RANDOM ZONE
STAGE II**

Number: **RBL-3-1466**

DATA ON RECORD CONTROL SAMPLES STAGE II LIQUID LIMIT-70 RANDOM ZONE



HOLE NO.	SAMPLE DEPTH	CLASSIFICATION			DRY DENSITY			WATER CONTENT			'O' TEST		'R' TEST		'S' TEST		T ₁
		SYM.	L.L.	P.L.	P.I.	MAX.	INITIAL RANGE	OPT.	INITIAL RANGE	(%) SATURAT.	TAN ϕ	C T.S.F.	TAN ϕ	C T.S.F.	TAN ϕ	C T.S.F.	
PC-855-3		CH	62	19	43	95.6	99.8-103.2	24.8	23.4-25.9	100	0.05	1.80	0.306	0.5	0.249	0.25	
PC-878-32		CH	59	19	40	97.7	99.6-102.2	23.7	22.4-24.4	89-100	0.059	0.98	0.264	0.33	0.187	0.25	
PPE-92-1	1.3-1.8	CH	66	19	47		93.5-101.3		24.3-25.5	98	0	1.75	0.259	0.55	0.374	0.26	
	6.3-6.8	CH	72	20	52		100.9-102.2		22.9-23.2	93-96	0.48	1.38	0.277	0.54	0.394	0.3	
	13.8-15.0						101.2-104.7		21.6-23.6	96							
PPE-95-1	30.8-39.3	CH	78	22	56		98.0-99.5		25.4-25.6	98-99	0.061	1.03	0.306	0.50	0.394	0.4	
	0.0-0.5	CH	57	19	38		99.0-100.2		25.0-25.8	97-98	0.096	0.55	0.466	0.33	0.364	0.3	
	8.3-8.8						98.8-95.4		28.5-31.2	100	0.58	1.05	0.485	0.25	0.222	0.25	
U-749	6.4-6.9	CH	77	19	58		93.4-96.7		28.4-29.2	99-100	0.013	1.48	0.26	0.34	0.449	0.45	
	10.5-11.0	CH	70	16	54		103.7-106.9		20.9-22.3		0	1.50	0.257	0.40	0.154	0.60	
	20.3-20.6	CH	83	19	64		99.8-100.6		23.7-24.2		0	1.10	0.325	0.21	0.173	0.30	

NOTE: EXCEPT FOR THE 'R' TEST, ALL SHEAR STRENGTH PARAMETERS PROVIDED ON THE SUMMARY TABLE ABOVE WERE DERIVED FROM A BEST FIT TANGENT TO THE MOHR'S CIRCLES FOR EACH SAMPLE TEST. THE 'R' TEST-EFFECTIVE STRESS STRENGTH PARAMETERS WERE DERIVED FROM THE POINTS PLOTTED AS DESIGNATED BY THE CORRESPONDING MOHR'S DIAGRAM.



LIQUID LIMIT - 70 RANDOM ZONE STAGE II
GRADATION LIMITS FOR RECORD CONTROL SAMPLES TESTED.

PHYSICAL SOIL CONSTANTS							
MATERIAL	UNIT WEIGHT			DESIGN SHEAR ST			
	P.C.F.			O		R	
	SAT.	MOIST	(C.T.S.F.)	0	TAN 0	(C.T.S.F.)	0
BERM	95	10	0.45	0.00	0.00	0.30	1.3
HILLSIDE BORROW	125	15	0.90	0.00	0.00	0.20	1.3
VALLEY BORROW	125	15	0.90	0.00	0.00	0.20	1.3
FOUNDATION OVERBURDEN	15	10	0.60	0.00	0.00	0.20	1.3
SHALE - PEAR	140	140					
SHALE - RESIDUAL	140	140					



3

2


1

"S" TEST			"R" TEST			"B" TEST		
DIRECT			DIRECT			SHEAR		
TAN θ	C	T.S.F.	TAN θ	C	T.S.F.	TAN θ	C	T.S.F.
F.	TAN θ	T.S.F.	TAN θ	C <td>T.S.F.</td> <td>TAN θ</td> <td>C<td>T.S.F.</td></td>	T.S.F.	TAN θ	C <td>T.S.F.</td>	T.S.F.
3	0.306	0.6	0.249	0.25				
8	0.260	0.3	0.187	0.25				
	0.259	0.95	0.374	0.26				
0.538	0.277	0.5	0.304	0.3				
						0.538	0	
	0.306	0.50	0.394	0.4				
	0.466	0.3	0.364	0.3				
	0.185	0.25	0.222	0.25				
	0.26	0.34	0.49	0.45				
	0.257	0.40	0.54	0.60				
TEST:	0.325	0.21	0.73	0.30				

TO THE MOHR'S CIRCLES FOR EACH SAMPLE TESTED.
DIAGRAM.

PHYSICAL SOIL CONSTANTS											
R STRENGTH		DESIGN SHEAR STRENGTH									
R	WEIGHT	Q		R		S					
0	TAN P.C.F.	0	TAN @ (17.5%)	0	TAN @ (17.5%)	0	TAN @	0	TAN @		
4.3	0.2	MOIST (17.5%)	0.00	0.00	0.00	4.3	0.20	0.00	16.7	0.30	
4.3	0.2	10	0.45	0.00	0.00	4.3	0.20	0.00	16.7	0.30	
4.3	0.2	15	0.90	0.00	0.00	0.20	4.3	0.20	0.00	19.8	0.36
4.3	0.2	16	0.90	0.00	0.00	0.20	4.3	0.20	0.00	26.6	0.50
		10	0.60	0.00	0.00	0.20	4.3	0.20	0.00	26.6	0.50
		110						0.00		31.0	0.40
		140						0.00		16.7	0.30

VS. LIQUID LIMIT
MIT-70
VE










Revisions		Date	Approved
Symbol	Descriptions		
<p align="center">U.S. ARMY ENGINEER DISTRICT CORPS OF ENGINEERS KANSAS CITY, MISSOURI</p>			
Designed by:	 U.S. Army Corps of Engineers	LITTLE BLUE RIVER, MISSOURI LONGVIEW LAKE EMBANKMENT CRITERIA AND PERFORMANCE REPORT TEST DATA SUMMARIES LIQUID LIMIT-70 RANDOM ZONE STAGE II	
Drawn by:	R.A.C.		
Checked by:	A.L.P.	Scale: AS SHOWN	Plot Scale: 12 11
Submitted by:	R.G.D.	Date:	Design File: D00.622.VLRPT80 File No.: RBL-3-1467





PLATE NO. 67

3

2

1





Revisions			
Symbol	Descriptions	Date	Approved

U S ARMY ENGINEER DISTRICT
CORPS OF ENGINEERS
KANSAS CITY, MISSOURI

Designed by: WBE

Drawn by: EGM

Checked by: WBE/RGD

Submitted by: F.C.W.

LITTLE BLUE RIVER, MISSOURI
LONGVIEW LAKE
EMBANKMENT CRITERIA AND
PERFORMANCE REPORT
SHEAR TEST SUMMARIES
LIQUID LIMIT-70 RANDOM ZONE
STAGE II

Scale: AS SHOWN

Date:

Sheet Number:


File No.: RBL-3-1468

DATA ON RECORD CONTROL SAMPLES
STAGE II, UNSPECIFIED LIQUID LIMIT-BERM ZONE

HOLE NO	SAMPLE DEPTH	CLASSIFICATION				DRY DENSITY		WATER CONTENT			'O' TEST		'R' TEST		'R' TEST		'S' TEST DIRECT
		SYM.	L.L.	P.L.	P.I.	MAX.	INITIAL RANGE	OPT.	INITIAL RANGE	(%) SATURAT.	TAN θ	C T.S.F.	TAN θ	C T.S.F.	TAN θ	C T.S.F.	
RC-675-25		CH	58	15	43	99.9	95.0-103.4	21.8	21.1-21.7	75-90	0.259	0.75	0.404	0.20	0.203	0.35	
RC-514-18		CL	49	16	33	100.3	103.3-105.7	20.3	19.4-20.7	83-90	0.296	1.25	0.414	0.21	0.315	0.15	
PPF-93-10A	2.0-2.5	CL	38	16	22		96.2-96.8		26.7-27.5	95-100	0.052	1.38					
SACK 1*		CL	47	18	29	96.8	91.6-92.1	21.7	24.1-24.7	80-81	0.013	0.53	0.556	0	0.277	0.08	
U-594	3.0	CH	56	16	40		97.5-101.5		22.6-26.1	92-96			0.384	0.07	0.249	0.23	
	13.0	CH	54	15	39		105.2-106.8		20.5-21.3	96-97	0.249	2.0	0.364	0.20	0.259	0.325	



NOTE: EXCEPT FOR THE 'R' TEST, ALL SHEAR STRENGTH PARAMETERS PROVIDED ON THE SUMMARY TABLE ABOVE WERE DERIVED FROM A BEST FIT TANGENT TO THE MOHR'S CIRCLES FOR EACH SAMPLE TESTED. THE 'R' TEST-EFFECTIVE STRESS STRENGTH PARAMETERS WERE DERIVED FROM THE POINTS PLOTTED AS DESIGNATED BY THE CORRESPONDING MOHR'S DIAGRAM.

* COMPOSITE SAMPLE FROM RIGHT ABUTMENT SEEP AREA



UNSPECIFIED LIQUID LIMIT BERM ZONE STAGE II
GRADATION LIMITS FOR RECORD CONTROL SAMPLES TESTED.

PHYSICAL SOIL CONSTANTS							
MATERIAL	UNIT WEIGHT		DESIGN SHEAR ST				R
	SAT. MOIST	P.C.F.	ϕ	TAN θ	CIT.S.F.	ϕ	
BERM	115	80	0.45	0.00	0.00	0.10	11.3
HILLSIDE BORROW	125	95	0.90	0.00	0.00	0.20	11.3
VALLEY BORROW	125	95	0.90	0.00	0.00	0.20	11.3
FOUNDATION OVERBURDEN	115	80	0.60	0.00	0.00	0.20	11.3
SHALE - PEAK	140	140	-	-	-	-	-
SHALE - RESIDUAL	140	140	-	-	-	-	-



F.	R TEST		R TEST		S TEST	
	TAN θ	C T.S.F.	TAN θ	C T.S.F.	TAN θ	C T.S.F.
5	0.404	0.20	0.203	0.35		
5	0.44	0.21	0.35	0.15		
8						
3	0.556	0	0.277	0.08		
	0.384	0.07	0.249	0.23		
ESTED.	0.364	0.20	0.259	0.325		






1 TO THE MOHR'S CIRCLES FOR EACH SAMPLE TESTED.
3 DIAGRAM.

PHYSICAL SOIL CONSTANTS									
R	UNIT WEIGHT	DESIGN SHEAR STRENGTHS							
	P.C.F.	R		S		R		S	
	SAT. MOIST	(C.T.S.F.)	θ	TAN θ	(C.T.S.F.)	θ	TAN θ	(C.T.S.F.)	θ
1.3	45	10	0.45	0.00	0.00	0.10	0.3	0.20	0.00
1.3	25	15	0.90	0.00	0.00	0.20	0.3	0.20	0.00
1.3	25	15	0.90	0.00	0.00	0.20	0.3	0.20	0.00
1.3	25	15	0.90	0.00	0.00	0.20	0.3	0.20	0.00
40	140							0.00	0.60
41	142							0.00	0.60

10 LIMIT
RECFIED

EMPALEMENT CRITERIA
AND PERFORMANCE REPORT
TEST DATA SUMMARIES
UNSPECIFIED LIQUID LIMIT BERM ZONE
STAGE 11



RB 1469



3

2

1



EFFECTIVE STRESS
MOHR'S DIAGRAM

SYMBOL	DATE	BY	APPROVED
U.S. ARMY ENGINEERING DISTRICT CORPUS CHRISTI, TEXAS			
<div style="display: flex; align-items: center;"> <div style="border: 1px solid black; padding: 2px; margin-right: 5px;">W</div> <div> <p>WATER RESOURCES DIVISION</p> <p>EMBANKMENT CRITERIA AND PERFORMANCE REPORT</p> <p>SHEAR TEST SUMMARIES</p> <p>UNSPECIFIED LIQUID LIMIT BERM ZONE STAGE II</p> </div> </div>			
PROJECT	WBE	AS SHOWN	
NO.	225		
DATE			
BY	FTW		

RBL-3-1470

PLATE NO. 10

3

2

1

DENSITY

NE DA

DENSITY AND MOISTURE CONTENT											
COMPACTION TEST				DENSITY AND MOISTURE CONTENT							
M.R.D. LAB				SAND CONE DATA				* UNDISTURBED DATA			
WATER CONTENT (%)	OPT. MOIST. (%)	MAX. DRY DENSITY (P.C.F.)	OPT. MOIST. (%)	DRY DENSITY (P.C.F.)	COMPACTION (%)	WATER CONTENT (%)	WATER CONTENT (+/- 20PT)	DRY DENSITY (P.C.F.)	COMPACTION (%)	WATER CONTENT (%)	WATER CONTENT (+/- 20PT)
23.7	97.2	23.5	96.6	99.4	26.8	+3.3		96.6	99.4	27.4	+3.9
19.3	105.2	16.5	105.9	100.7	20.1	+4.6		107.0	104.7	20.3	+3.8
19.8	105.0	17.8	107.3	102.2	19.0	+1.2		107.7	102.6	19.2	+1.4
23.1	97.4	26.2	100.4	103.1	24.8	+3.6		99.6	102.3	23.6	+2.4
9.7	103.0	19.0	109.2	106.0	19.9	+0.9		107.7	104.6	19.2	+0.2
9.0	102.2	18.7	107.9	105.6	20.5	+1.8		106.5	104.2	20.6	+1.9
10.3	103.8	18.8	104.3	100.5	21.9	+3.1		104.1	97.4	24.3	+5.5
20.5	99.7	21.3	100.5	100.8	23.8	+2.5		96.4	96.7	27.2	+5.9
10.5	105.3	18.7	102.3	97.2	20.1	+2.4		104.4	99.1	21.9	+3.2
10.6	106.0	20.3	98.9	90.5	22.8	+2.5		99.7	98.1	24.7	+4.4
10.6	105.6	24.3	98.0	102.5	23.5	+0.8		99.9	104.5	23.0	+1.1
9.7	97.7	22.2	104.7	107.2	19.7	+2.5		106.9	109.4	20.4	+1.8

RIVER

LIMIT-55
IMPERVIOUS ZONE
STAGE I

MISSOURI RIVER DIVISION LABORATORY DATA

DEPTH	WATER CONTENT (%)	DRY DENSITY (LBS/FT ³)	SATURATION %	LL	PL	PI	SPECIFIC GRAVITY
1	10.7	105.0	100				
2	20.3	97.6	85				
3	10.7	107.0	98				
4	10.4	100.6	96				
5	10.3	101.6	94	42	20	22	
6	10.7	104.7	97				
7	10.7	106.9	95				
8	10.4	101.2	95				
9	10.6	102.8	99				2.64
10	8.6	106.7	92				2.62
11	10.4	107.0	89				2.66
12	8.6	109.8	98				2.65
13	10.7	101.2	96				2.65
14	10.1	109.4	97				2.62
15	22.7	101.4	97				2.63
16	18.9	104.8	87				
17	19.2	104.8	88	42	17	25	
18	20.0	103.6	89				
19	19.1	105.7	90				
20	18.8	107.4	92	42	17	25	
21	20.5	103.0	91	43	18	25	2.60
22	20.6	96.9	79				
23	9.9	104.3	93				
24	19.9	104.2	93				
25	20.5	99.5	85				
26	20.8	100.0	89				
27	20.8	101.3	90	49	16	33	2.60


NOTE: ALL VALUES ARE BASED ON A SPECIFIC GRAVITY OF 2.65

NOTE: ALL VALUES ARE BASED ON A 16 INCH DIAMETER BUCKET AUGER HOLE.

Revisions	Date	Approved
Descriptions		
<p>U.S. ARMY ENGINEER DISTRICT CORPS OF ENGINEERS KANSAS CITY, MISSOURI</p>		
Designed by	<p>LITTLE BLUE RIVER, MISSOURI LONGVIEW LAKE EMBANKMENT CRITERIA AND PERFORMANCE REPORT LIQUID LIMIT-55 IMPERVIOUS ZONE STAGE I DENSITY AND COMPACTION TEST SUMMARIES</p>	
Drawn by	<p>R.G.D.</p>	
Checked by	<p>R.D.T.</p>	
Submitted by	<p>A.L.P.</p>	
AS SHOWN	Sheet	Page
	Number	Design
		File
		No.
		RBL-3-1471

LIQUID LIMIT-55 IMPERVIOUS ZONE, STAGE II																		
RECORD CONTROL SAMPLE				SOIL CLASSIFICATION DATA									STANDARD COMPACTION TEST					
				FIELD			M.R.D. LABORATORY						FIELD			M.R.D. LAB		
NUMBER	STATION	RANGE	ELEV.	LL	PI	CLASS	SHEAR TEST SPECIMEN UNDISTURBED SAMPLE			COMPACTION TEST SPECIMEN SACK SAMPLE			MAX. DRY DENSITY (P.C.F.)	OPT. MOIST. CONT. (%)	MAX. DRY DENSITY (P.C.F.)	OPT. MOIST. CONT. (%)	DRY DENSITY (P.C.F.)	COMPACTION (%)
RC-530-19	94+25	0+50u/s	815.0	43	18	CL	48	32	CL	44	26	CL	104.0	22.0	100.6	20.6	102.9	102.3
RC-591-20	95+50	0+65u/s	828.0	49	27	CL	55	40	CH	48	31	CL	106.6	22.5	98.3	22.1	97.5	99.2
RC-661-23	95+50	0+30u/s	857.0	51	26	CH	46	30	CL	45	28	CL	100.5	22.2	98.1	22.7	99.2	101.1
RC-682-26	93+00	0+25u/s	862.0	45	26	CL	44	28	CL	38	23	CL	100.5	21.5	100.5	19.8	103.5	103.7
RC-701-27	99+30	1+85u/s	865.0	44	22	CL	51	33	CH	46	28	CL	98.0	22.5	98.5	22.5	99.4	100.3

* UNDISTURBED DATA OBTAINED BY AVERAGING MOISTURE AND DENSITY VALUES OF ALL AVAILABLE SHEAR TEST SPECIMENS.
 NOTE: ALL DRY DENSITIES AND WATER CONTENTS ARE COMPARED TO M.R.D. DATA TO OBTAIN PERCENT COMPACTION AND WATER CONTENT PERCENT ± OPTIMUM.



THE COMPACTION CURVES ARE BASED ON MISSOURI RIVER DIVISION LABORATORY STANDARD COMPACTION TESTS.

DENSITY TEST					
LIQUID LIMIT-55 IMPERVIOUS ZONE STAGE II		K.C.D. LAB SAND CONE			
SAMPLE	DEPTH	W (%)	DRY DENSITY (LBS./FT.³)	L.L.	P.L.
RC-530-19		20.9	102.9	43	25
RC-591-20		24.5	97.5	49	22
RC-661-23		21.2	98.1	48	21
RC-682-26		17.7	98.6	45	19
RC-701-27		21.0	95.9	44	22


3

2

1

STANDARD COMPACTION TEST DENSITY AND MOISTURE CONTENT												
FIELD			M.R.D. LAB				SAND CONE DATA			*UNDISTURBED DATA		
COM- ACTION (%)	DRY DENSITY (P.C.F.)	OPT. MOIST. CONT. (%)	MAX. DRY DENSITY (P.C.F.)	OPT. MOIST. CONT. (%)	DRY DENSITY (P.C.F.)	COM- PACTION (%)	WATER CONTENT (%)	WATER CONTENT (+-%OPT)	DRY DENSITY (P.C.F.)	COM- PACTION (%)	WATER CONTENT (%)	WATER CONTENT (+-%OPT)
102.3	4.0	22.0	100.6	20.6	102.9	102.3	20.3	+0.5	100.0	99.4	20.7	+0.1
99.2	1.6	22.5	98.3	22.1	97.5	99.2	24.5	+2.4	101.0	102.8	23.2	+1.1
101	0.5	22.2	98.1	22.7	99.2	101	23.4	-0.7	99.6	101.5	23.8	+1.1
100.9	0.5	21.5	100.5	19.8	103.5	103.0	19.6	-0.2	101.5	101.0	18.9	-0.9
1.0	22.5	98.5	22.5	99.4	100.9	23.5	+1.0	98.1	99.6	23.4	+0.9	

DENSITY TEST SUMMARY											
MIT-55 JS ZONE		K.C.D. LAB					M.R.D. LAB				
		SAND CONE					RE ORD. CRITERIA UNDISTURBED				
P.L.	DEPTH	W (%)	DRY DENSITY (LBS/FT ³)	L.L.	P.L.	P.I.	W (%)	DRY DENSITY (LBS/FT ³)	L.L.	P.L.	P.I.
25		20.9	102.9	43	25	18	20.7	100.0	48	16	37
22		24.5	97.5	49	22	27	23.2	101.0	55	15	40
21		21.2	98.1	48	21	27	23.8	99.6	46	16	30
19		17.7	98.6	45	19	26	18.9	101.5	44	16	28
22		21.0	95.9	44	22	22	23.4	98.1	51	18	31

Revisions		Date	Approved
Signature	Descriptions		
U.S. ARMY ENGINEER DISTRICT CORPS OF ENGINEERS KANSAS CITY, MISSOURI			
Designed by	R.C.D.	 LITTLE BLUE RIVER, MISSOURI LONGVIEW LAKE EMBANKMENT CRITERIA AND PERFORMANCE REPORT LIQUID LIMIT-55 IMPERVIOUS ZONE STAGE II DENSITY AND COMPACTION TEST SUMMARIES	
Drawn by	R.D.T.		
Checked by	A.L.P.		
Submitted by	R.C.D.		
Scale	AS SHOWN	Sheet numbers	Plot Scale
Date			Design File
Dwg No			File No
			RBL-3-1472

3

2

1

5

4

3

D


LIQUID LIMIT-60 IMPERVIOUS ZONE, STAGE II																		
RECORD CONTROL SAMPLE				SOIL CLASSIFICATION DATA									STANDARD COMPACTION TEST					
				FIELD			M.R.D. LABORATORY						FIELD		M.R.D. LAB		SAND	
NUMBER	STATION	RANGE	ELEV.	LL	PI	CLASS	SHEAR TEST SPECIMEN UNDISTURBED SAMPLE			COMPACTION TEST SPECIMEN SACK SAMPLE			MAX. DRY DENSITY (P.C.F.)	OPT. MOIST. CONT. (%)	MAX. DRY DENSITY (P.C.F.)	OPT. MOIST. CONT. (%)	DRY DENSITY (P.C.F.)	C
							LL	PI	CLASS	LL	PI	CLASS						
RC-803-29	99+00	0+90u/s	890.0	54	31	CH	53	29	CH	51	29	CH	98.9	23.3	98.0	23.2	96.1	
RC-899-36	98+00	1+50u/s	898.0	64	43	CH				52	34	CH	99.3	24.2	98.5	22.7	104.5	
U-746*4	98+40	1+70u/s	828.0				43	25	CL	46	29	CL			100.0**	18.3		
U-746*5	98+40	1+70u/s	826.3				43	25	CL	45	26	CL			97.2**	22.2		

*UNDISTURBED DATA OBTAINED BY AVERAGING MOISTURE AND DENSITY VALUES OF ALL AVAILABLE SHEAR TEST SPECIMENS.

NOTE: ALL DRY DENSITIES AND WATER CONTENTS ARE COMPARED TO M.R.D. DATA TO OBTAIN PERCENT COMPACTION AND WATER CONTENT PERCENT ± OPTIMUM.

**HARVARD MINIATURE COMPACTION TEST

C



THE COMPACTION CURVES ARE BASED ON MISSOURI RIVER DIVISION LABORATORY STANDARD COMPACTION TESTS.

DENSITY				
LIQUID LIMIT-60 IMPERVIOUS ZONE STAGE II		K.C.D. LAB		
SAMPLE	DEPTH	W (%)	DRY DENSITY (LBS./FT.³)	LI
RC-803-29		25.6	96.1	
U-746	70 ± 71.1			
J-16	72.3-72.8			

B

A

5

4


3

↑

LIQUID LIMIT-60 RANDOM ZONE, STAGE I															
RECORD CONTROL SAMPLE				SOIL CLASSIFICATION DATA									STANDARD COMPACTION TEST		
NUMBER	STATION	RANGE	ELEV.	FIELD			M.R.D. LABORATORY						FIELD		DRY DENSITY P (P.C.F.)
				LL	PI	CLASS	SHEAR TEST SPECIMEN			COMPACTION TEST SPECIMEN			MAX. DRY DENSITY (P.C.F.)	OPT. MOIST. CONT. (%)	
RC-8	92+00	1+30u/s	821.7	50		CH	51	36	CH	52	35	CH	105.2	20.3	105.6
LIQUID LIMIT-60 RANDOM ZONE, STAGE II															
RC-479-17	93+00	1+80u/s	818.0	55	32	CH	52	34	CH	45	29	CL	98.6	22.5	99.5
RC-674-24	94+75	1+10u/s	861.5	55	33	CH	56	41	CH	47	34	CL	100.8	21.0	102.4

* UNDISTURBED DATA OBTAINED BY AVERAGING MOISTURE AND DENSITY VALUES OF ALL AVAILABLE SHEAR TEST SPECIMENS.

NOTE: ALL DRY DENSITIES AND WATER CONTENTS ARE COMPARED TO M.R.D. DATA TO OBTAIN PERCENT COMPACTION AND WATER CONTENT PERCENT ± OPTIMUM.



LIQUID LIMIT-60 RANDOM ZONE STAGE II			
SAMPLE	ELEV.	W (%)	DRY DENSITY (LBS./FT.³)
RC-479-17	818.0	24.0	98.4
RC-674-24	861.5	20.6	97.5
*PPE-94-1	852.5		

3

2

1

SAMPLE	STANDARD COMPACTION TEST				DENSITY AND MOISTURE CONTENT							
	FIELD		M.R.D. LAB		SAND CONE DATA				*UNDISTURBED DATA			
	MAX. DRY DENSITY (P.C.F.)	OPT. MOIST. CONT. (%)	MAX. DRY DENSITY (P.C.F.)	OPT. MOIST. CONT. (%)	DRY DENSITY (P.C.F.)	COMPACTION (%)	WATER CONTENT (%)	WATER CONTENT (+/-2.0PT)	DRY DENSITY (P.C.F.)	COMPACTION (%)	WATER CONTENT (%)	WATER CONTENT (+/-2.0PT)
105.6	105.2	20.3	100.8	20.4	105.6	104.8	22.5	+2.0	100.6	99.8	24.3	+3.9
99.5	98.6	22.5	97.8	22.7	99.5	101.7	23.8	+1.1	104.4	106.8	22.3	-0.4
102.4	100.8	21.0	98.0	22.8	102.4	104.5	22.1	-0.4	98.6	100.6	24.3	+1.5


DENSITY TEST SUMMARY											
LIQUID LIMIT-60 RANDOM ZONE STAGE II		K.C.D. LAB					M.R.D. LAB				
SAMPLE	ELEV.	W (%)	DRY DENSITY (LBS/FT ³)	L.L.	P.L.	P.I.	W (%)	DRY DENSITY (LBS/FT ³)	L.L.	P.L.	P.I.
RC-470-17	818.0	24.0	98.4	53	22	31	22.3	104.4	52	18	34
RC-614-24	861.5	20.6	97.5	55	22	33	24.3	98.6	56	15	41
*PPE-94-1	852.5						23.7	99.4	53	17	36

Revisions			
Symbol	Descriptions	Date	Approved
U.S. ARMY ENGINEER DISTRICT CORPS OF ENGINEERS KANSAS CITY, MISSOURI			
Designed by:	R.G.D.	LITTLE BLUE RIVER, MISSOURI LONGVIEW LAKE EMBANKMENT CRITERIA AND PERFORMANCE REPORT LIQUID LIMIT-60 RANDOM ZONE STAGES I AND II DENSITY AND COMPACTION TEST SUMMARIES	
Drawn by:	R.A.C.		
Checked by:	A.L.P.		
Submitted by:	R.G.D.		
Scale:	AS SHOWN	Sheet Number:	Plot Scale:
Date:		Design File:	
Dwg No.:		File No.:	RBL-3-1474

LIQUID LIMIT-65 IMPERVIOUS ZONE; STAGE II																		
RECORD CONTROL SAMPLE				SOIL CLASSIFICATION DATA									STANDARD COMPACTION TEST					
				FIELD			M.R.D. LABORATORY						FIELD		M.R.D. LAB		SANC	
NUMBER	STATION	RANGE	ELEV.	LL	PI	CLASS	SHEAR TEST SPECIMEN UNDISTURBED SAMPLE			COMPACTION TEST SPECIMEN SAG SAMPLE			MAX. DRY DENSITY (P.C.F.)	OPT. MOIST. CONT. (%)	MAX. DRY DENSITY (P.C.F.)	OPT. MOIST. CONT. (%)	DRY DENSITY (P.C.F.)	C/PAC
							LL	PI	CLASS	LL	PI	CLASS						
RC-445-15	100+10	2+30u/s	896.0	49	27	CL	41	23	CL	45	28	CL	99.4	23.0	99.2	22.7	102.4	10
RC-724-28	90+20	0+05d/s	874.0	55	30	CH	55	38	CH	47	32	CL	97.5	24.2	97.7	20.7	97.4	5
RC-821-30	93+20	0+10d/s	900.0	56	34	CH	56	31	CH	60	43	CH	99.4	24.3	97.3	23.3	98.2	10
RC-882-33	106+15	0+08d/s	921.0	43	27	CL	49	33	CL	51	37	CH	102.2	23.0	102.4	19.7	98.1	5
RC-892-34	99+75	0+10d/s	923.5	53	34	CH				55	40	CH	103.0	22.3	99.2	21.5	103.8	10

* UNDISTURBED DATA OBTAINED BY AVERAGING MOISTURE AND DENSITY VALUES OF ALL AVAILABLE SHEAR TEST SPECIMENS.

NOTE: ALL DRY DENSITIES AND WATER CONTENTS ARE COMPARED TO M.R.D. DATA TO OBTAIN PERCENT COMPACTION AND WATER CONTENT PERCENT ± OPTIMUM.



THE COMPACTION CURVES ARE BASED ON MISSOURI RIVER DIVISION LABORATORY STANDARD COMPACTION TESTS.

DENSITY				
LIQUID LIMIT-65 IMPERVIOUS ZONE STAGE II		K.C.D. LAB		
SAMPLE	DEPTH	W (%)	DRY DENSITY (LBS/FT ³)	L.L.
RC-445-15		22.6	102.4	45
RC-724-28		23.9	96.4	55
RC-821-30		24.7	98.2	56

STANDARD COMPACTION TEST				DENSITY AND MOISTURE CONTENT							
FIELD		M.R.D. LAB		SAND CONE DATA				* UNDISTURBED DATA			
MAX. DRY DENSITY (P.C.F.)	OPT. MOIST. CONT. (%)	MAX. DRY DENSITY (P.C.F.)	OPT. MOIST. CONT. (%)	DRY DENSITY (P.C.F.)	COM-PACTION (%)	WATER CONTENT (%)	WATER CONTENT (+/-2.0PT)	DRY DENSITY (P.C.F.)	COM-PACTION (%)	WATER CONTENT (%)	WATER CONTENT (+/-2.0PT)
99.4	23.0	99.2	22.7	102.4	103.2	22.6	-0.1	105.9	106.8	21.0	-1.7
97.5	24.2	97.7	20.7	97.4	99.7	25.2	+4.5	98.2	100.5	23.9	+3.2
99.4	24.3	97.3	21.3	98.2	100.9	24.7	+1.4	100.4	103.2	24.8	+1.5
102.2	23.0	102.4	19.7	98.1	95.8	22.4	+2.7	104.1	101.7	21.2	+1.5
103.0	22.3	99.2	21.5	103.8	104.6	20.3	-1.2				

DENSITY TEST SUMMARY											
LIQUID LIMIT-65 IMPERVIOUS ZONE STAGE II			K.C.D. LAB				M.R.D. LAB				
SAMPLE	DEPTH	W (%)	DRY DENSITY (LBS/FT ³)	L.L.	P.L.	P.I.	W (%)	DRY DENSITY (LBS/FT ³)	L.L.	P.L.	P.I.
RC-445-15		22.6	102.4	49	27	22	21.0	105.9	41	18	23
RC-724-26		23.9	96.4	55	25	30	23.9	98.2	55	17	38
RC-821-30		24.7	98.2	56	22	34	24.8	100.4	56	25	31

Revisions	Date	Approved
Descriptions		
<p>U.S. ARMY ENGINEER DISTRICT CORPS OF ENGINEERS KANSAS CITY, MISSOURI</p>		
Designed by	<p>LITTLE BLUE RIVER, MISSOURI LONGVIEW LAKE EMBANKMENT CRITERIA AND PERFORMANCE REPORT LIQUID LIMIT-65 IMPERVIOUS ZONE STAGE II DENSITY AND COMPACTION TEST SUMMARIES</p>	
Reviewed by	AS SHOWN	DESIGNED BY
Checked by		DESIGNED BY
Approved by		DESIGNED BY
		RBL-3-1475

5

4

3


VALUE

LIQUID LIMIT-65 RANDOM ZONE, STAGE II

RECORD CONTROL SAMPLE				SOIL CLASSIFICATION DATA						STANDARD COMPACTION TEST					
				FIELD			M.R.D. LABORATORY			FIELD			M.R.D. LAB		
NUMBER	STATION	RANGE	ELEV.	LL	PI	CLASS	SHEAR TEST SPECIMEN			COMPACTION TEST SPECIMEN			MAX. DRY DENSITY (P.C.F.)	OPT. MOIST. CONT. (%)	DR. DEN. (P.C.F.)
							LL	PI	CLASS	LL	PI	CLASS			
RC-452-16	91+20	0+60d/s	822.0	53	29	CH	54	38	CH	46	31		100.4	24.1	91.6
RC-592-21	95+10	1+10d/s	825.5	54	33	CH	62	46	CH	47	33		101.0	22.8	97.5
RC-659-22	95+70	2+60d/s	849.0	50	32	CH	57	41	CH	47	31	CL	99.5	22.0	99.7

* UNDISTURBED DATA OBTAINED BY AVERAGING MOISTURE AND DENSITY VALUES OF ALL AVAILABLE SHEAR TEST SPECIMENS.

NOTE: ALL DRY DENSITIES AND WATER CONTENTS ARE COMPARED TO M.R.D. DATA TO OBTAIN PERCENT COMPACTION AND WATER CONTENT PERCENT + OPTIMUM.



THE COMPACTION CURVES ARE BASED ON MISSOURI HIGHWAY DIVISION LABORATORY STANDARD COMPACTION TESTS

LIQUID LIMIT-65 RANDOM ZONE STAGE II				DENSITY	
				K.C.D. LAB	
SAMPLE	DEPTH	W (%)	DRY DENSITY (LBS./FT. ³)		
RC 452-16		23.6	97.6		
RC 592-21		22.4	97.7		
RC 659-22		19.2	96.3		
PVE 13-12	5.4 5.9				
PVE 35-1	18.8 19.3				

5

4

3

ALUE

VALUE ENGINEERING PAYS

3

2

1

STANDARD COMPACTION TEST

DENSITY AND MOISTURE CONTENT

FIELD

M.R.D. LAB

SAND CONE DATA

* UNDISTURBED DATA

DR DEN. (P.C.F.)	MAX. DRY DENSITY (P.C.F.)	OPT. MOIST. CONT. (%)	MAX. DRY DENSITY (P.C.F.)	OPT. MOIST. CONT. (%)	DRY DENSITY (P.C.F.)	COM- PACTION (%)	WATER CONTENT (%)	WATER CONTENT (+-%OPT)	DRY DENSITY (P.C.F.)	COM- PACTION (%)	WATER CONTENT (%)	WATER CONTENT (+-%OPT)
9	92.4	24.1	100.2	20.6	97.6	97.4	23.6	+2.0	104.9	94.7	2.4	
9	92.0	22.8	97.5	22.6	97.3	99.3	22.4	0.2	97.8	99.7	2.4	
9	90.5	22.0	99.7	20.8	99.7	99.0	20.3	-0.5	99.9	99.0		

ENSIT

DENSITY TEST SUMMARY

LIQUID LIMIT-65 RANDOM ZONE STAGE II		K.C.D. LAB					M.R.D. LAB				
AMPLE	DEPTH	W	DRY DENSITY (LBS./FT. 3)	L.L.	P.L.	P.I.	W	DRY DENSITY (LBS./FT. 3)	L.L.	P.L.	P.I.
		11.6	97.6	53	24	79	21.4	11.4	54		76
		2.4	97				24.7	37.2	66		41
		1	10.3	52	27	80	20.5	31.4	5		4
P.L. 11	5.4 ft.						25.1	47.4			
P.L. 15	9.4 ft.						10.9	44.9			

U.S. ARMY ENGINEER DISTRICT
CORPS OF ENGINEERS
KANSAS CITY, MISSOURI

LITTLE BLUE RIVER MISSOURI
LONGVIEW LAKE

EMBANKMENT CRITERIA
AND PERFORMANCE REPORT
LIQUID LIMIT-65 RANDOM ZONE
STAGE II DENSITY AND
COMPACTION TEST SUMMARIES

R.G.D.

US Army Corps
of Engineers

R.A.C.

A.L.P.

R.G.D.

AS SHOWN

DATE

BY

NO.

Sheet

Number

Plot

Sheet

Design

Title

File

No.

RBL-3-1476


PLATE NO. 76

LIQUID LIMIT-70 RANDOM ZONE, STAGE II

RECORD CONTROL SAMPLE				SOIL CLASSIFICATION DATA									STANDARD COMPACTION TEST				
				FIELD			M.R.D. LABORATORY						FIELD		M.R.D. LAB		
NUMBER	STATION	RANGE	ELEV.	LL	PI	CLASS	SHEAR TEST SPECIMEN			COMPACTION TEST SPECIMEN			MAX. DRY DENSITY (P.C.F.)	OPT. MOIST. CONT. (%)	MAX. DRY DENSITY (P.C.F.)	OPT. MOIST. CONT. (%)	DRY DENSITY (P.C.F.)
RC 855 34	94+00	0+300 8	909	65	41	CH	LL	PI	CLASS	LL	PI	CLASS	95.5	26.0	95.6	24.8	97.5
RC 878 32	86+51	0+220 5	909	61	40	CH	59	40	CH	60	44	CH	95.5	25.5	97.7	23.7	100.6
RC 895 35	102+90	0+900 5	114	51	35	CH	49	16	CL				102.6	20.6	98.7	22.5	109.0

* UNDISTURBED DATA OBTAINED BY AVERAGING MOISTURE AND DENSITY VALUES OF ALL AVAILABLE SHEAR TEST SPECIMENS

NOTE: ALL DRY DENSITIES AND WATER CONTENTS ARE COMPARED TO M.R.D. DATA TO OBTAIN PERCENT COMPACTION AND WATER CONTENT PERCENT - OPTIMUM



LIQUID LIMIT-70 RANDOM ZONE STAGE II		DENSITY	
SAMPLE	DEPTH	W (%)	DRY DENSITY (LBS./FT.³)
RC 855 34		24.3	97.5
RC 878 32		24.0	100.6
RC 895 35	13.8-14.3		
RC 895 35	0.0-0.5		

THE COMPACTION CURVES ARE BASED ON M. R. D. DIVISION LABORATORY STANDARD COMPACTION TEST

D

SAN

ITY
SITY
F.)

.5
.6
.6

STANDARD COMPACTION TEST					DENSITY AND MOISTURE CONTENT							
FIELD		M.R.D. LAB			SAND CONE DATA				* UNDISTURBED DATA			
MAX. DRY DENSITY (P.C.F.)	OPT. MOIST. CONT. (%)	MAX. DRY DENSITY (P.C.F.)	OPT. MOIST. CONT. (%)	DRY DENSITY (P.C.F.)	COMPACTION (%)	WATER CONTENT (%)	WATER CONTENT (+/-2OPT)	DRY DENSITY (P.C.F.)	COMPACTION (%)	WATER CONTENT (%)	WATER CONTENT (+/-2OPT)	
95.5	26.0	95.6	24.8	97.5	102.0	24.9	+0.1	104.0	108.8	22.5	-2.3	
95.5	25.5	97.7	23.7	100.6	103.0	24.0	+0.3	100.7	103.1	24.4	+0.7	
92.6	25.6	98.7	22.5	109.0	101.4	26.2	-2.3					

DENSI

R. D.

3)

DENSITY TEST SUMMARY											
LIQUID LIMIT-70 RANDOM ZONE STAGE II		M.R.D. LAB					M.P.D. LAB				
SAMPLE	DEPTH	W	DRY DENSITY (LBS/FT ³)	L.L.	P.L.	P.I.	W	DRY DENSITY (LBS/FT ³)	L.L.	P.L.	P.I.
PT-REF 1		24.9	97.5	65	24		22.5	104.0	61	2	
PT-REF 2		24.0	100.6	61			24.4	100.7	19		
PT-96	3.9-4.3						24.4	98.0			
PT-95	4.0-5.5						25.3	97.2			

C

B

A

Symbol	Revision	Date	App. Cond.
U.S. ARMY ENGINEER DISTRICT CORPS OF ENGINEERS KANSAS CITY, MISSOURI			
Prepared by	R.G.D.	LITTLE BLUE RIVER, MISSOURI LONGVIEW LAKE EMBANKMENT CRITERIA AND PERFORMANCE REPORT LIQUID LIMIT-70 RANDOM ZONE STAGE II DENSITY AND COMPACTION TEST SUMMARIES	
Checked by	R.A.C.		
Approved by	A.L.P.	AS SHOWN	
Reviewed by	R.G.D.		
		RBL-3-1477	

5

4

3

D

LIQUID LIMIT-UNSPECIFIED BERM ZONE, STAGE II																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																								
RECORD CONTROL SAMPLE										SOIL CLASSIFICATION DATA										STANDARD COMPACTION TEST																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																				
										M.J.R.D. LABORATORY																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																														
FIELD										FIELD										M.J.R.D. LAB										SAND																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																										
										SHEAR TEST SPECIMEN										COMPACTION TEST SPECIMEN																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																				
										MAX. DRY DENSITY (P.C.F.)										OPT. MOIST. CONT. (%)										MAX. DRY DENSITY (P.C.F.)										OPT. MOIST. CONT. (%)										DRY DENSITY (P.C.F.)																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																						
NUMBER	STATION	RANGE	ELEV.	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	PI	CLASS	LL	


* UNDISTURBED DATA OBTAINED BY AVERAGING MOISTURE AND DENSITY VALUES OF ALL AVAILABLE SHEAR TEST SPECIMENS.
NOTE: ALL DRY DENSITIES AND WATER CONTENTS ARE COMPARED TO M.J.D. DATA TO OBTAIN PERCENT COMPACTION AND WATER CONTENT PERCENT OF MAX.

C



B

A



THE COMPACTION CURVE ARE PAVED IN M.J.D. LAB BY STANDARD COMPACTION TESTS

LIQUID LIMIT-UNSPECIFIED BERM ZONE		STAGE II		FIELD LAB	
NUMBER	STATION	DEPTH	W	DRY DENSITY (LBS/FT³)	
RC 54 18	96+56	1.5	119	14	
RC 675 25	93+30	1.5	114	8	
SACK #1	RIGHT	1.5	96.8	21.7	

5

4

3



3

2

1

STANDARD COMPACTION TEST

DENSITY AND MOISTURE CONTENT

SAND	FIELD	M.R.D. LAB				SAND CONE DATA				*UNDISTURBED DATA			
		DRY DENSITY (P.C.F.)	OPT. MOIST. CONT. (%)	MAX. DRY DENSITY (P.C.F.)	OPT. MOIST. CONT. (%)	DRY DENSITY (P.C.F.)	COMPACTION (%)	WATER CONTENT (%)	WATER CONTENT (+-%OPT)	DRY DENSITY (P.C.F.)	COMPACTION (%)	WATER CONTENT (%)	WATER CONTENT (+-%OPT)
A	2.5	104.7	19.3	105.0	19.3	104.7	98.0	22.7	+0.8	104.7	99.4	19.3	+0.6
4	2.8	99.9	21.8	98.0	21.8	98.0	98.0	22.7	+0.9	99.4	99.5	21.2	-0.6


DENSITY TEST SUMMARY



M.T. UNSPEC. ZONE		P.C.D. LAB			M.R.D. LAB					
					HEAVY COMPACTION METHOD					
DEPTH		DRY DENSITY (LBS/FT ³)	L.L.	P.L.	P.L.	W (%)	DRY DENSITY (LBS/FT ³)	L.L.	P.L.	P.L.
5		51	22	30	19.3	104.7	49	16	13	
4		54	20	34	2	99.4	58	15	43	

U.S. ARMY ENGINEER DISTRICT
CORPS OF ENGINEERS
KANSAS CITY, MISSOURILITTLE BLUE RIVER, MISSOURI
LONGVIEW LAKE
EMBANKMENT CRITERIA
AND PERFORMANCE REPORT
BERM ZONE (NO SPECIFIED LIQUID LIMIT)
STAGE II DENSITY AND
COMPACTION TEST SUMMARIES

RBL-3-1478

PLATE NO. 78





*NOTE
THE UNDISTURBED DATA WAS OBTAINED BY AVERAGING
MOISTURE AND DENSITY VALUES OF ALL AVAILABLE
SHEAR TEST SPECIMENS FOR EACH RECORD CONTROL
SAMPLE

Revisions		Date	Approved
Symbol	Descriptions		


U S ARMY ENGINEER DISTRICT
CORPS OF ENGINEERS
KANSAS CITY, MISSOURI

Designed by: W.B.E.
Drawn by: R.A.C.
Checked by: W.B.E./R.G.D.
Submitted by: F.C.W.

**LITTLE BLUE RIVER, MISSOURI
LONGVIEW LAKE
EMBANKMENT CRITERIA
AND PERFORMANCE REPORT**

**COMPACTION TEST SUMMARIES
STAGE I**

Scale: _____
Date: _____
Sheet Number: _____
File No: RBL-3-1479



OPTIMUM WATER CONTENT, % (M R D LAB)

24

23

22

21

20


19

18

3

2

1




D

C

B

A



Symbol	Revisions	Date	Approved

U. S. ARMY ENGINEER DISTRICT
CORPS OF ENGINEERS
KANSAS CITY, MISSOURI

LITTLE BLUE RIVER, MISSOURI
LONGVIEW LAKE
EMBANKMENT CRITERIA
AND PERFORMANCE REPORT

COMPACTION TEST SUMMARIES
STAGE I

WBE
JGS
WBE/RGD
FCW

AS SHOWN

RBL-3-1480

PLATE NO 80

3


2


1

PERCENT COMPACTION
UNDISTURBED *
VS
SAND CONE
STAGE I

CTION WAS OBTAINED BY COMPARING
TO THE MRD DATA UNDISTURBED
BY AVERAGING THE DENSITY VALUES
NEAR TEST SPECIMENS FOR EACH
MPLE

OPTIMUM WATER CONTENT, % (MRD LAB)





NOTE:
SOME OF THE IMPERVIOUS ZONE LIQUID LIMIT 55 RECORD
CONTROL SAMPLES HAVE A LIQUID LIMIT GREATER THAN 55
THESE SAMPLES WERE LOCATED IN THE LOWER PORTION
OF THE CUTOFF TRENCH

Revisions		Date	Approved
Symbol	Descriptions		

U. S. ARMY ENGINEER DISTRICT
CORPS OF ENGINEERS
KANSAS CITY, MISSOURI

Described by: WBE

Drawn by: SEV


Revised by: RGD/WBE


Submitted by: FCW

AS SHOWN


Sheet number: RBL-3-1481

PLATE NO. 81






D



C



A

5

4


3

5

4

3



7-77 F.V. 17 (UNDISTURBED SAMPLE)



LEGEND - STAGE II		
SYMBOL	SAMPLE	LOCATION
□	LIQUID LIMIT	55 IMP ZONE
○	LIQUID LIMIT	60 IMP ZONE
△	LIQUID LIMIT	60 RDM ZONE
■	LIQUID LIMIT	65 IMP ZONE
●	LIQUID LIMIT	65 RDM ZONE
▲	LIQUID LIMIT	70 RDM ZONE
○	BERM ZONE	UNSPEC' LIQUID LIMIT

NOTE
THE UNDISTURBED DATA WAS OBTAINED BY AVERAGING MOISTURE
AND DENSITY VALUES OF ALL AVAILABLE SHEAR TEST SPECIMENS
FOR EACH RECORD CONTROL SAMPLE

Symbol	Revisions	Description	Date	Approved
+				
+				
+				
U.S. ARMY ENGINEER DISTRICT CHIEFS OF ENGINEERS KANSAS CITY, MISSOURI				
LITTLE BLUE RIVER, MISSOURI LONGVIEW LAKE EMBANKMENT CRITERIA AND PERFORMANCE REPORT COMPACTION TEST DATA SUMMARY STAGE II				
WBE	Scale	As Shown	Sheet	
EGM	Date		Number	
RGD-WBE	Tag		No.	
ECW	File No.			
				RBL-3-1483



NOTE
THE REFERENCE
BY MISSOURI RIV


B

A


5


4

3




NOTE
THE REFERENCED OPTIMUM MOISTURE CONTENT WAS DETERMINED
BY MISSOURI RIVER DIVISION LABORATORY STANDARD COMPACTION TEST

Revisions		Date	Approved
Symbol	Descriptions		
U S ARMY ENGINEER DISTRICT CORPS OF ENGINEERS KANSAS CITY, MISSOURI			
Designed by WBE	 LITTLE BLUE RIVER, MISSOURI LONGVIEW LAKE EMBANKMENT CRITERIA AND PERFORMANCE REPORT COMPACTION TEST SUMMARIES STAGE II	Scale	AS SHOWN
Drawn by SEY		Sheet number	
Checked by WBE/RGD		Date	
Submitted by FCW		File No	3 of 3 RBL-3-1485



GENERALIZED CROSS-SECTION SHOWING A TYPICAL SLIDE PLANE

ACTIVE WEDGE ANALYSIS



$$\begin{aligned} W &= W_0 \hat{i} & (1a) \\ F &= F_0 \hat{i} & (1b) \\ N &= N_0 \sin(\theta_A) \cos(\theta_A) & (1c) \\ T &= T_0 \sin(\theta_A) \sin(\theta_A) & (1d) \\ T &= T_0 \cos(\theta_A) \sin(\theta_A) & (1e) \end{aligned}$$

For the above freebody to be in equilibrium the following condition must be satisfied:

$$\sum F = 0 \quad (2)$$

But N can be represented as,

$$N = A \sigma_n$$

where,

A = area of slice = $L \cos \theta_A$
 σ_n = average normal stress

Therefore,

$$N = A \sigma_n \cos \theta_A \quad (3)$$

Similarly, T can be represented as

$$T = A \tau$$

where A is defined as above

$$\tau = T / A$$

with

$F.S.$ = Factor of safety against sliding
 τ = Average shear stress acting on slice

From Coulomb's Law

$$\tau = c + \sigma_n \tan \phi$$

where c and $\tan \phi$ are soil constants
 therefore,

$$\tau = \frac{c}{F.S.} + \frac{\sigma_n \tan \phi}{F.S. \cos \theta_A} \quad (4)$$

Substituting Equations (1a), (1b), (1c), (1d), and (4) into Equation (2), and expressing in matrix form the condition that the algebraic summation of the coefficients of F and T equals zero yields

$$\begin{Bmatrix} F_0 \\ T_0 \end{Bmatrix} \begin{Bmatrix} A_1 \\ A_2 \end{Bmatrix} = 0 \quad (5)$$

where

$$A_1 = \frac{1}{F.S.} \left[\frac{\cos \theta_A}{L} + \frac{\tan \phi \sin \theta_A}{L \cos \theta_A} \right]$$

$$A_2 = \frac{1}{F.S.} \left[\frac{\sin \theta_A}{L} + \frac{\tan \phi \cos \theta_A}{L \cos \theta_A} \right]$$

The solution to Equation (5) is

$$\begin{Bmatrix} F_0 \\ T_0 \end{Bmatrix} \begin{Bmatrix} A_1 \\ A_2 \end{Bmatrix} = 0 \quad (6)$$

where

$$A_1 = \frac{1}{F.S.} \left[\frac{\cos \theta_A}{L} + \frac{\tan \phi \sin \theta_A}{L \cos \theta_A} \right]$$

$$A_2 = \frac{1}{F.S.} \left[\frac{\sin \theta_A}{L} + \frac{\tan \phi \cos \theta_A}{L \cos \theta_A} \right] \quad (7)$$

Using the solution for T_0 given by Equation (6) and substituting it into Equation (4), the horizontal component of the driving force is expressed as follows:

$$F_0 = \frac{c}{F.S.} \left[\frac{\cos \theta_A}{L} + \frac{\tan \phi \sin \theta_A}{L \cos \theta_A} \right]$$


where

$$F_0 = \frac{c}{F.S.} \left[\frac{\cos \theta_A}{L} + \frac{\tan \phi \sin \theta_A}{L \cos \theta_A} \right]$$

DEFINITION OF SYMBOLS USED IN DERIVATION OF STABILITY EQUATIONS

- \hat{i} unit vector in x direction
- \hat{j} unit vector in y direction
- \vec{W} Effective weight vector
- \vec{H} Net horizontal seepage force vector (equal to the vector summation of the horizontal components of all water forces acting on the slice)
- N Normal force vector acting perpendicular to slice base
- T Tangential force vector acting tangentially to slice base
- \vec{D} Driving earth force vector contributed by active wedge
- \vec{R} Resisting earth force vector contributed by passive wedge
- \vec{C} Central block force
- \vec{M} Moment vector
- θ Slope of driving earth force vector

PASSIVE WEDGE ANALYSIS



The passive wedge analysis is used to determine the resisting force for a slice of soil on a slope. The analysis involves summing the forces acting on the slice and setting the sum equal to zero for equilibrium.

$$\sum F_x = 0$$

$$\sum F_y = 0$$

$$\sum M = 0$$

$$\sum F_x = 0$$

$$\sum F_y = 0$$

$$\sum M = 0$$


$$\sum F_x = 0$$

$$\sum F_y = 0$$

$$\sum M = 0$$

$$\sum F_x = 0$$

CENTRAL BLOCK ANALYSIS



The central block analysis is used to determine the resisting force for a slice of soil on a slope. The analysis involves summing the forces acting on the slice and setting the sum equal to zero for equilibrium.

SYM

DESCRIPTION
REVISIONS

DATE APP'D

LITTLE BLUE RIVER, MISSOURI
LONGVIEW LAKE
EMBANKMENT CRITERIA AND PERFORMANCE REPORT
DERIVATION OF STABILITY EQUATIONS

In 1 sheet
CORPS OF ENGINEERS
KANSAS CITY DISTRICT

Sheet No. 1

Scale as shown
U. S. ARMY
JUNE 1978

Designed by
Checked by
Reviewed by
Approved by
R. L. W.

Reviewed by
Approved by
R. L. W.


Reviewed by
Approved by
R. L. W.

RBL-3-1564

PLATE NO. 8



"Q" TEST DATA ON COMPOSITE SAMPLES													
INDEX NUMBER	COMPOSITE NUMBER	CLASSIFICATION			DRY DENSITY		WATER CONTENT		N	T	C	TAN ϕ	LOCATION
		SYMBOL	LL	PL	PI	MAXIMUM	AT TEST	OPTIMUM					
6*	6	CL	44	17	27	95.5	90.8	18.5	21.8	1.75	1.30	100	HILLSIDE BORROW
			50		33		90.7		21.6	3.97	1.68		
							90.1		22.4	3.99	1.72		
6A*	6	CL	44	17	27	95.5	95.9	18.5	20.9	1.80	1.38	13	HILLSIDE BORROW
			50		33		95.4		21.8	3.91	1.58		
7	7	CH	50	15	40	98.5	94.4	23.5	26.1	1.32	.54	50	HILLSIDE BORROW
			52	6	36		93.6		26.3	3.32	.56		
8	8	CL	45	15	30	103.5	99.0	19.5	22.2	1.59	1.02	80	DOWNSTREAM VALLEY
							98.6		22.6	3.89	1.54		
							98.1		22.2	6.00	1.73		
9	9	CL	43	17	26	101.5	97.4	21.0	22.5	1.53	.92	60	VALLEY
							96.9		23.1	3.55	.95		
							96.7		23.6	5.54	.93		
							96.7		23.8	1.40	.69		
9A	9	CL	43	17	26	101.5	97.7	21.0	20.0	1.72	1.25	100	VALLEY
							97.3		19.8	3.99	1.71		
							96.7		20.6	6.04	1.89		
9B	9	CL	43	17	26	101.5	96.7	21.0	18.8	1.86	1.52	110	VALLEY
							96.6		18.6	4.23	2.13		
							96.9		19.7	6.46	2.48		
10	10	CL	38	18	20	105.0	99.2	17.0	19.7	1.59	1.03	85	VALLEY
							99.3		19.3	2.67	1.16		
							99.4		19.5	4.84	1.45		
11	11	CH	51	16	35	103.5	99.5	19.5	21.7	.94	.77	08	VALLEY
							98.8		21.9	2.53	.92		
							98.8		22.2	6.58	1.01		
11A	11	CH	51	6	35	103.5	100.0	10.5	17.7	1.30	1.39	13	VALLEY
							99.5		18.6	2.98	1.71		
							99.0		19.2	7.19	2.06		
11B	11	CH	51	16	35	103.5	99.3	10.5	16.5	1.43	1.61	13	VALLEY
							98.6		16.9	3.29	2.24		
							93.7		17.4	7.67	2.89		
11C	11	CH	51	16	35	103.5	99.3	19.5	18.3	1.24	1.20	14	VALLEY
13	13	CH	50	17	33	103.5	98.5	19.5	22.5	1.54	.94	92	OUTLET WORKS
							98.4		22.5	2.59	1.02		
							98.5		22.5	5.72	1.25		
15	15	CH	55	16	39	102.0	93.8	20.0	23.0	1.44	.77	75	SPILLWAY
							92.9		23.4	3.47	.81		
15A	15	CH	55	16	39	102.0	82.4	20.0	23.5	1.31	.54	75	SPILLWAY
							82.5		23.2	3.41	.71		

* COMPOSITE NO 6 TAKEN OUTSIDE THE PROPOSED BORROW AREA



DATE
IDEN

LLS DE
N. L. A
LLS JE
ITS E
ULLEY
DEF 18



SYM DESCRIPTION REVISIONS DATE APP'D

LITTLE BLUE RIVER, MISSOURI
LONGVIEW LAKE
EMBANKMENT CRITERIA AND
PERFORMANCE REPORT
TEST DATA SUMMARY
COMPACTED EMBANKMENT MATERIAL
Q-TESTS AND ATTERBERG LIMIT TESTS


In 1 sheet Sheet No. 1 Scale as shown
CORPS OF ENGINEERS U.S. ARMY
KANSAS CITY DISTRICT JUNE 1978


Submitted Recommended
G.L.G. J.P.M. R.G.D.

RBL-3-1686

"R" TEST DATA ON COMPOSITE SAMPLES															
INDEX	COMPOSITE	CLASSIFICATION				DRY DENSITY		WATER CONTENT		N	P	C	TAN ϕ	LOCATION	
NUMBER	NUMBER	SYMBOL	LL	PL	PI	MAXIMUM	AT TEST	OPTIMUM	AT TEST	T S F	T S F	T S F	TAN ϕ	LOCATION	
6*	6	CL	44	17	27	95.5	91.7 90.7	18.5	21.0 21.7	129 358	50 100	25	22	HILLSIDE BORROW	
6A*	6	CL	44	17	27	95.5	95.5 95.5	18.5	21.0 21.1	121 356	37 97	01	28	HILLSIDE BORROW	
7	7	CH	55	15	40	98.5	93.7 93.7	25.5	26.3 26.2	134 359	58 102	30	20	HILLSIDE BORROW	
8	8	CL	45	15	30	103.5	99.0 98.9 98.1	19.5	22.0 22.1 22.1	129 360 594	50 104 163	20	24	DOWNSTREAM VALLEY	
9	9	CL	43	17	26	101.5	96.8 96.7 96.4	21.0	23.6 23.8 24.2	132 359 579	55 103 137	40	18	VALLEY	
9A	9	CL	43	17	26	101.5	98.1 100.5 96.4	21.0	20.9 20.7 21.1	115 360 594	26 104 164	00	28	VALLEY	
9B	9	CL	43	17	26	101.5	96.7 96.6 96.6	21.0	18.9 19.1 18.7	121 343 708	36 74 186	10	26	VALLEY	
11	11	CH	51	16	35	103.5	98.9 98.9 99.0	19.5	22.1 21.8 22.0	68 247 687	31 81 150	20	20	VALLEY	
11A	11	CH	51	16	35	103.5	99.1 98.6 98.6	19.5	19.2 19.3 19.5	67 239 710	29 68 191	20	25	VALLEY	
11B	11	CH	51	16	35	103.5	98.5 98.1 97.9	19.5	17.6 17.9 18.0	64 233 702	25 57 176	10	24	VALLEY	
13	13	CH	50	17	33	103.5	98.5 99.5 98.8	19.5	22.5 22.5 22.4	124 241 578	40 70 135	18	20	OUTLET WORKS	
15	15	CH	55	16	39	102.0	93.1 93.4	20.0	23.2 23.4	122 346	38 80	19	19	SPILLWAY	
15A	15	CH	55	16	39	102.0	81.7 82.1	20.0	24.4 23.7	117 346	29 80	05	22	SPILLWAY	

* COMPOSITE NO 6 TAKEN OUTSIDE THE PROPOSED BORROW AREA





LONGVIEW LAKE


TESTS

S TEST DATA ON COMPOSITE SAMPLES													
INDEX NO	COMPOSITE NO	CLASSIFICATION			DRY DENSITY		WATER CONTENT		T M ₅₀	C	TAN ϕ	LOC.	REMARKS
		SYMBOL	LL	PL	PI	AT TEST	OPTIMUM	AT TEST					
2	2	CL	37	21	16	106.5	100.5	17.0	1	0.24	0.05	15	1A, 1B
3	3	CH	67	21	46	101.0	96.5	21.0	1	0.29	0.32	44	1A, 1B
8	8	CH	50	22	28	103.5	98.5	19.5	2	1.84	0.0	67	DOCK, 1A, 1B
9	9	CL	48	24	24	101.5	96.5	21.0	4	2.70	0.0	52	1A, 1B
10	10	CL	40	21	19	105.9	99.9	17.0	5	1.1	0.0	14	1A, 1B
11	11	CL	46	20	16	103.5	99.0	19.5	6	1.4	0.0	1	1A, 1B
12	12	CL	47	21	16	105.0	100.0	19.0	7	1.1	0.0	1	1A, 1B
12A	12	CL	47	21	16	105.0	100.0	19.0	8	1.1	0.0	1	1A, 1B
12B	12	CL	47	21	16	105.0	100.0	19.0	9	1.1	0.0	1	1A, 1B
12C	12	CL	48	16	14	105.0	94.0	19.0	10	1.1	0.0	1	1A, 1B
13	13	CH	54	22	12	105.0	96.0	19.0	11	1.1	0.0	1	1A, 1B
13A	13	CH	54	22	12	105.0	96.0	19.0	12	1.1	0.0	1	1A, 1B
13B	13	CH	54	22	12	105.0	96.0	19.0	13	1.1	0.0	1	1A, 1B
14	14	CH	53	20	10	105.0	98.0	19.0	14	1.1	0.0	1	1A, 1B
14A	14	CH	53	20	10	105.0	98.0	19.0	15	1.1	0.0	1	1A, 1B
15	15	CH	50	20	10	105.0	98.0	19.0	16	1.1	0.0	1	1A, 1B
16	16	CH	54	22	12	105.0	96.0	19.0	17	1.1	0.0	1	1A, 1B
17	17	CH	54	22	12	105.0	96.0	19.0	18	1.1	0.0	1	1A, 1B
18	18	CH	54	22	12	105.0	96.0	19.0	19	1.1	0.0	1	1A, 1B
19	19	CH	54	22	12	105.0	96.0	19.0	20	1.1	0.0	1	1A, 1B
20	20	CH	54	22	12	105.0	96.0	19.0	21	1.1	0.0	1	1A, 1B
21	21	CH	54	22	12	105.0	96.0	19.0	22	1.1	0.0	1	1A, 1B
22	22	CH	54	22	12	105.0	96.0	19.0	23	1.1	0.0	1	1A, 1B
23	23	CH	54	22	12	105.0	96.0	19.0	24	1.1	0.0	1	1A, 1B
24	24	CH	54	22	12	105.0	96.0	19.0	25	1.1	0.0	1	1A, 1B
25	25	CH	54	22	12	105.0	96.0	19.0	26	1.1	0.0	1	1A, 1B
26	26	CH	54	22	12	105.0	96.0	19.0	27	1.1	0.0	1	1A, 1B
27	27	CH	54	22	12	105.0	96.0	19.0	28	1.1	0.0	1	1A, 1B
28	28	CH	54	22	12	105.0	96.0	19.0	29	1.1	0.0	1	1A, 1B
29	29	CH	54	22	12	105.0	96.0	19.0	30	1.1	0.0	1	1A, 1B
30	30	CH	54	22	12	105.0	96.0	19.0	31	1.1	0.0	1	1A, 1B
31	31	CH	54	22	12	105.0	96.0	19.0	32	1.1	0.0	1	1A, 1B
32	32	CH	54	22	12	105.0	96.0	19.0	33	1.1	0.0	1	1A, 1B
33	33	CH	54	22	12	105.0	96.0	19.0	34	1.1	0.0	1	1A, 1B
34	34	CH	54	22	12	105.0	96.0	19.0	35	1.1	0.0	1	1A, 1B
35	35	CH	54	22	12	105.0	96.0	19.0	36	1.1	0.0	1	1A, 1B
36	36	CH	54	22	12	105.0	96.0	19.0	37	1.1	0.0	1	1A, 1B
37	37	CH	54	22	12	105.0	96.0	19.0	38	1.1	0.0	1	1A, 1B
38	38	CH	54	22	12	105.0	96.0	19.0	39	1.1	0.0	1	1A, 1B
39	39	CH	54	22	12	105.0	96.0	19.0	40	1.1	0.0	1	1A, 1B
40	40	CH	54	22	12	105.0	96.0	19.0	41	1.1	0.0	1	1A, 1B
41	41	CH	54	22	12	105.0	96.0	19.0	42	1.1	0.0	1	1A, 1B
42	42	CH	54	22	12	105.0	96.0	19.0	43	1.1	0.0	1	1A, 1B
43	43	CH	54	22	12	105.0	96.0	19.0	44	1.1	0.0	1	1A, 1B
44	44	CH	54	22	12	105.0	96.0	19.0	45	1.1	0.0	1	1A, 1B
45	45	CH	54	22	12	105.0	96.0	19.0	46	1.1	0.0	1	1A, 1B
46	46	CH	54	22	12	105.0	96.0	19.0	47	1.1	0.0	1	1A, 1B
47	47	CH	54	22	12	105.0	96.0	19.0	48	1.1	0.0	1	1A, 1B
48	48	CH	54	22	12	105.0	96.0	19.0	49	1.1	0.0	1	1A, 1B
49	49	CH	54	22	12	105.0	96.0	19.0	50	1.1	0.0	1	1A, 1B
50	50	CH	54	22	12	105.0	96.0	19.0	51	1.1	0.0	1	1A, 1B
51	51	CH	54	22	12	105.0	96.0	19.0	52	1.1	0.0	1	1A, 1B
52	52	CH	54	22	12	105.0	96.0	19.0	53	1.1	0.0	1	1A, 1B
53	53	CH	54	22	12	105.0	96.0	19.0	54	1.1	0.0	1	1A, 1B
54	54	CH	54	22	12	105.0	96.0	19.0	55	1.1	0.0	1	1A, 1B
55	55	CH	54	22	12	105.0	96.0	19.0	56	1.1	0.0	1	1A, 1B
56	56	CH	54	22	12	105.0	96.0	19.0	57	1.1	0.0	1	1A, 1B
57	57	CH	54	22	12	105.0	96.0	19.0	58	1.1	0.0	1	1A, 1B
58	58	CH	54	22	12	105.0	96.0	19.0	59	1.1	0.0	1	1A, 1B
59	59	CH	54	22	12	105.0	96.0	19.0	60	1.1	0.0	1	1A, 1B
60	60	CH	54	22	12	105.0	96.0	19.0	61	1.1	0.0	1	1A, 1B
61	61	CH	54	22	12	105.0	96.0	19.0	62	1.1	0.0	1	1A, 1B
62	62	CH	54	22	12	105.0	96.0	19.0	63	1.1	0.0	1	1A, 1B
63	63	CH	54	22	12	105.0	96.0	19.0	64	1.1	0.0	1	1A, 1B
64	64	CH	54	22	12	105.0	96.0	19.0	65	1.1	0.0	1	1A, 1B
65	65	CH	54	22	12	105.0	96.0	19.0	66	1.1	0.0	1	1A, 1B
66	66	CH	54	22	12	105.0	96.0	19.0	67	1.1	0.0	1	1A, 1B
67	67	CH	54	22	12	105.0	96.0	19.0	68	1.1	0.0	1	1A, 1B
68	68	CH	54	22	12	105.0	96.0	19.0	69	1.1	0.0	1	1A, 1B
69	69	CH	54	22	12	105.0	96.0	19.0	70	1.1	0.0	1	1A, 1B
70	70	CH	54	22	12	105.0	96.0	19.0	71	1.1	0.0	1	1A, 1B
71	71	CH	54	22	12	105.0	96.0	19.0	72	1.1	0.0	1	1A, 1B
72	72	CH	54	22	12	105.0	96.0	19.0	73	1.1	0.0	1	1A, 1B
73	73	CH	54	22	12	105.0	96.0	19.0	74	1.1	0.0	1	1A, 1B
74	74	CH	54	22	12	105.0	96.0	19.0	75	1.1	0.0	1	1A, 1B
75	75	CH	54	22	12	105.0	96.0	19.0	76	1.1	0.0	1	1A, 1B
76	76	CH	54	22	12	105.0	96.0	19.0	77	1.1	0.0	1	1A, 1B
77	77	CH	54	22	12	105.0	96.0	19.0	78	1.1	0.0	1	1A, 1B
78	78	CH	54	22	12	105.0	96.0	19.0	79	1.1	0.0	1	1A, 1B
79	79	CH	54	22	12	105.0	96.0	19.0	80	1.1	0.0	1	1A, 1B
80	80	CH	54	22	12	105.0	96.0	19.0	81	1.1	0.0	1	1A, 1B
81	81	CH	54	22	12	105.0	96.0	19.0	82	1.1	0.0	1	1A, 1B
82	82	CH	54	22	12	105.0	96.0	19.0	83	1.1	0.0	1	1A, 1B
83	83	CH	54	22	12	105.0	96.0	19.0	84	1.1	0.0	1	1A, 1B
84	84	CH	54	22	12	105.0	96.0	19.0	85	1.1	0.0	1	1A, 1B
85	85	CH	54	22	12	105.0	96.0	19.0	86	1.1	0.0	1	1A, 1B
86	86	CH	54	22	12	105.0	96.0	19.0	87	1.1	0.0	1	1A, 1B
87	87	CH	54	22	12	105.0	96.0	19.0	88	1.1	0.0	1	1A, 1B
88	88	CH	54	22	12	105.0	96.0	19.0	89	1.1	0.0	1	1A, 1B
89	89	CH	54	22	12	105.0	96.0	19.0	90	1.1	0.0	1	1A, 1B
90	90	CH	54	22	12	105.0	96.0	19.0	91	1.1	0.0	1	1A, 1B
91	91	CH	54	22	12	105.0	96.0	19.0	92	1.1	0.0	1	1A, 1B
92	92	CH	54	22	12	105.0	96.0	19.0	93	1.1	0.0	1	1A, 1B
93	93	CH	54	22	12	105.0	96.0	19.0	94	1.1	0.0	1	1A, 1B
94	94	CH	54	22	12	105.0	96.0	19.0	95	1.1	0.0	1	1A, 1B
95	95	CH	54	22	12	105.0	96.0	19.0	96	1.1	0.0	1	1A, 1B
96	96	CH	54	22	12	105.0	96.0	19.0	97	1.1	0.0	1	1A, 1B
97	97	CH	54	22	12	105.0	96.0	19.0	98	1.1	0.0	1	1A, 1B
98	98	CH	54	22	12	105.0	96.0	19.0	99	1.1	0.0	1	1A, 1B
99	99	CH	54	22	12	105.0	96.0	19.0	100	1.1	0.0	1	1A, 1B

COMPACTED "S" TESTS HILLSIDE OVERBURDEN

LEGEND



- CL CH
- HILLSIDE BORROW
- SAILWAY BORROW
- HILLSIDE BORROW
- OUTSIDE PROPOSED AREA
- NCFA NC



DATA ON COMPOSITE SAMPLES										
INDEX NUMBER	COMP NUMBER	HOLE NUMBER	SACK NUMBER	DEPTH	CLASSIFICATION			MAXIMUM DRY DENSITY	OPTIMUM WATER CONTENT	LOCATION
					SYMBOL	LL	PL			
2	2	A 33	1.62	103.0	CL	37	21	106.5	17.0	VALLEY BORROW
		A 34	2	60.110						
		P 76	1	05.78						
3	3	A 75	1	05.75	CH	67	21	101.0	21.0	HILLSIDE BORROW
		A 76	1	05.0						
4	4	A 79	1.62	05.0	CH	55	24	102.0	19.5	HILLSIDE BORROW
		A 79	1.62	05.0						
5	5	A 79	1.62	05.0	CH	55	24	112.0	16.0	HILLSIDE BORROW
		A 79	1.62	05.0						
		A 66	1	30.125	CH	55	21	103.5	19.5	HILLSIDE BORROW
		A 69	1	06.67						
		A 68	1	30.125	CH	55	21	111.5	16.6	HILLSIDE BORROW
		A 69	1	06.67						
		A 81	1	20.02	CL	44	17	95.5	18.5	HILLSIDE BORROW
		A 67	1	25.110						
		A 72	1	015.0	CH	55	15	98.5	22.5	HILLSIDE BORROW
		A 80	1	032.0						
		D 90	1	025.0	CH	50	22	103.5	19.5	DOWNSTREAM BORROW
		D 91	1	017.8						
		D 84	1	012.0	CL	48	24	101.5	21.0	VALLEY BORROW
		D 85	1	06.8						
		A 62	1	05.5	CL	40	21	105.0	17.0	VALLEY BORROW
		A 63	1	05.8						
		A 73	1	05.4	CL	46	20	103.5	19.5	VALLEY BORROW
		D 86	1	07.5						
		A 57	1.62	10.20.0						
		AC 21	3.64	16.0.26.0						
		AC 30	1.62	2.0.0.0						
		AC 55	1	10.7.5	CH	54	27	102.5	19.5	OUTLET WORKS
		AC 52	1	10.11.0	CH	53	22	103.0	19.5	SPILLWAY
		AC 53	1	10.7.0						
		AC 52	2	11.5.15.0	CH	59	21	102.0	20.0	SPILLWAY
		AC 54	1	1.0.0.0						
		A 65	1	17.12.7	CH	51	23	102.0	20.0	HILLSIDE BORROW
		A 66	1	03.4						
		D 171	1	4.0.6.0	CL	43	24	106.0	18.0	VALLEY BORROW
		D 172	2	8.0.11.0						
		D 173	1	2.0.4.0	CL	45	23	102.5	20.5	VALLEY BORROW
		D 40A	1	2.0.4.0						
		D 20A	1.62	23.5.6.4.6.0	CH	55	20	103.0	20.5	VALLEY BORROW
		D 175	1	6.0.0.0	CH	52	17	107.0	19.0	HILLSIDE BORROW
		D 184	1	2.0.8.0						
		D 176	1	2.0.4.0	CH	67	23	96.0	23.5	HILLSIDE BORROW
		D 177	1	2.0.4.0						
		D 180	1	2.0.4.0	CH	54	20	102.5	20.5	HILLSIDE BORROW
		D 181	1	4.0.6.0						
		D 131A	2	4.0.6.0	CH	59	18	100.0	22.2	HILLSIDE BORROW
		D 184	1	2.0.4.0						
		D 131A	1	4.0.6.0	CH	53	15	107.0	21.2	HILLSIDE BORROW
		D 182	2	8.4.10.0						
		D 88	2	12.0.21.5	CH	63	21	96.5	24.3	HILLSIDE BORROW
		A 135	2	6.0.11.0						
		A 71	1	2.5.10.0	CH	58	16	96.0	23.3	HILLSIDE BORROW
		D 178	2	10.0.12.0						
		D 184	1	2.0.4.0						
		D 18A	2	10.0.12.0	CH	51	20	98.5	22.8	HILLSIDE BORROW
		D 178	2	8.0.10.0						

MODIFIED PROCTOR TEST

NOTE COMPOSITES NO. 3, 4, 5, 6 AND 16 ARE OUTS. OF THE PROPOSED BORROW AREA




20
PERCENT

COMPACTION CURVES HILLSIDE OVERBURDEN

LEGEND


- CL CH
○ ● HILLSIDE BORROW
□ ■ SPILLWAY



COMPACTION CURVES HILLSIDE OVERBURDEN

LEGEND


- CL CH
○ ● HILLSIDE BORROW
(OUTSIDE PROPOSED
BORROW AREA)



COMPACTION CURVES VALLEY OVERBURDEN

LEGEND


- CL CH
○ ▲ VALLEY BORROW AREA



ACTIVITY

LEGEND

- ★ FOUNDATION OVERBURDEN
▲ VALLEY BORROW COMPOSITES
■ SPILLWAY BORROW COMPOSITES



NOTE: Composites 4A B 4A are from Modified Proctor Test

SYM

REVISION

DATE: APR 1978

LITTLE BLUE RIVER, MISSOURI
LONGVIEW LAKE
EMBANKMENT CRITERIA AND PERFORMANCE REPORT
TEST DATA SUMMARY
COMPACTION CURVES
GRADATIONS AND ACTIVITY DATA




Prepared by
U.S. Army Corps of Engineers
YANKEE CITY, MISSOURI
Submitted

Scale as shown


U.S. ARMY
JUNE 1978

RBL-3-1689


PLATE NO. 860





TRIAXIAL "Q" TEST DATA																
INDEX NUMBER	HOLE NUMBER	SAMPLE NUMBER	DEPTH	CLASSIFICATION			INITIAL CONDITIONS			σ_3	σ_1	$\frac{(\sigma_1 - \sigma_3)}{2}$	$\frac{(\sigma_1 + \sigma_3)}{2}$	C	TAN ϕ	LOCATION
				SYMBOL	L. L.	P. L.	DRY DENSITY	WATER CONTENT	% SAT.							
1	U-10A	WAX 4	7.0-7.9	CL	48	20	87.6 88.1	32.3 31.6	98 96	4 8	5.85 7.13	.53 .55	4.53 6.56	0.52	0.0	VALLEY
2	U-83	WAX 4	7.2-7.9	CL	37	17	98.6 98.7	23.4 23.7	90 91	4 6	6.24 6.27	1.12 1.13	5.12 7.13	1.00	.08	TERRACE
3	U-83	WAX 6	10.0-11.2	CL	41	17	94.4 94.6 94.6 92.9	26.4 26.3 27.1 26.0	93 93 96 88	2 4 1 4	2.86 5.77 2.84 5.74	.38 .86 .52 .87	2.86 4.86 1.92 4.87	0.4	.10	TERRACE
4	U-87	WAX 3	4.0-5.9	CL	41	21	81.8 83.4	22.2 21.4	98 94	2 4	5.18 7.94	1.98 1.97	3.98 5.97	1.0	.18	VALLEY
5	U-87A	WAX 4	7.5-7.9	CL	38	20	91.2 90.8	29.8 29.7	98 97	4 6	5.08 7.05	.94 .52	4.94 6.52	.52	0.0	VALLEY
6	U-142	WAX 5	7.1-8.0	CH	30	20	97.2 98.5	24.1 24.6	88 95	2 6	5.87 10.82	1.83 2.31	3.83 8.31	.95 (CH-8) 2.4 (CH-6)	.24 0.0	TERRACE
7	U-142	WAX 7	10.0-11.5	CL	44	18	93.9 93.3 94.6	28.1 27.7 27.7	96 98 96	4 6 2	6.02 8.19 3.85	1.01 1.08 .63	5.01 7.08 2.83	.6 (CH-8) 1.1 (CH-6)	.08 0.0	TERRACE
8	U-143	WAX 10	18.0-19.0	CL	40	18	96.2 95.9	28.1 28.5	100 100	4 6	5.05 6.96	.52 .46	4.52 6.46	.50	0.0	TERRACE
9	U-144	WAX 1	0.5-1.8	CL	46	20	88.6 88.9 89.0	26.9 26.6 27.1	83 84 84	1 3 5	3.22 6.21 8.80	1.11 1.87 1.80	2.11 4.81 6.80	0.8 (CH-6) 1.8 (CH-6)	.18 0.0	VALLEY
10	U-145	WAX 5	4.0-5.9	CL	45	17	93.5 95.2 93.2	16.3 16.1 16.4	56 57 63	3 5 7	11.29 14.80 18.18	4.14 4.80 5.99	7.14 9.80 12.59	2.4	.28	VALLEY
11	U-153	WAX 2	2.0-3.6	CL	40	20	89.6 89.6 91.6	28.7 28.0 27.7	90 88 91	1 4 6	2.45 6.00 7.92	.72 1.00 .96	1.72 5.00 6.96	.75	0.0	VALLEY
12	U-154	WAX 4	6.0-7.9	CL	45	'9	90.8 87.7 88.1	24.7 24.9 23.7	73 73 72	4 6 2	6.24 8.56 4.36	1.12 1.28 1.18	5.12 7.28 3.18	1.2	0.0	VALLEY
13	U-163	WAX 3	4.0-5.9	CH	50	17	100.7 101.3 101.2 101.5	22.7 21.9 22.1 22.6	90 86 88 92	2 4 6 ?	4.83 8.43 10.28 5.00	1.41 2.21 2.14 1.50	3.41 6.21 8.14 3.30	0.7 (CH-8) 2.1 (CH-6)	.24 0.0	TERRACE
14	UC-164	WAX 2	2.0-3.9	CL	38	16	97.4 97.0 96.9	20.6 20.6 20.9	77 76 77	5 2 4	2.08 4.62 7.11	.79 1.31 1.55	1.29 3.31 5.55	0.5 (CH-3) 1.0 (CH-3)	.23 .10	VALLEY
15	UC-185	WAX 4	6.0-7.9	CL	38	17	100.6 101.0 101.1	22.8 23.4 23.4	94 97 97	1 3 5	2.75 4.77 6.93	.87 .88 .96	1.87 3.88 5.96	.85	.02	VALLEY
16	UC-186	WAX 3	4.0-5.7	CL	33	18	100.5 100.6 100.0	24.2 24.3 24.2	98 99 97	1 3 5	2.56 4.39 6.39	.78 .69 .69	1.78 3.69 5.69	.70	0.0	VALLEY
17	U 201	WAX 1	1.0-2.0	CH	56	18	96.6 96.9 96.7	26.2 26.2 26.1	97 98 97	5 1 3	2.11 2.74 4.84	.80 .87 .92	1.30 1.87 3.92	.75	.05	ABUTMENT



SYM	DESCRIPTION	DATE	APP'D
	REVISIONS		
	LITTLE BLUE RIVER, MISSOURI		
	LONGVIEW LAKE		
	EMBANKMENT CRITERIA AND		
	PERFORMANCE REPORT		
	TEST DATA SUMMARY		
	UNDISTURBED FOUNDATION OVERBURDEN		
	Q-TESTS		
In 1 sheet	Sheet No. 1	Scale as shown	
CORPS OF ENGINEERS		U. S. ARMY	
KANSAS CITY DISTRICT		JUNE 1978	
Submitted	Recommended	Approved	
CHIEF, DISTRICT ENGINEERING DIVISION	CHIEF, ENGINEERING DIVISION	CHIEF, ENGINEERING DIVISION	
GLG	JPM	RGD	
			RBL-3-1690



INDEX NUMBER	HOLE NUMBER
1	U-10A
2	U-83
3	U-83
4	U-87
5	U-142
6	U-142
7	U-143
8	U-143
9	U-144
10	U-145
11	U-153
12	U-154
13	U-163
14	UC-164
15	UC-165
16	UC-166
17	U-201



OLE

MBCR

-10A

-83

-83

-87

-142

-142

-143

-143

-144

-145

-153

U-154

U-163

U-164

U-165

U-166

U-201

ATTER

SHE

CH


●

12

10

TRIAXIAL "R" TEST DATA

INDEX NUMBER	HOLE NUMBER	SAMPLE NUMBER	DEPTH	CLASSIFICATION			INITIAL CONDITIONS			σ_3	σ_1	$\frac{\sigma_1 - \sigma_3}{2}$	$\frac{\sigma_1 + \sigma_3}{2}$	C	TAN ϕ	LOCATION	
				SYMBOL	LL	PL	SL	DRY DENSITY	WATER CONTENT								% SAT.
1	U-10A	WAX 4	7.0-7.9	CL	43	20	23	81.1 85.8 85.1	33.7 32.5 32.3	86 92 90	2 4 6	3.89 8.92 9.71	.84 1.46 1.86	2.84 5.46 7.86	.25	.22	VALLEY
2	U-83	WAX 4	7.2-7.9	CL	37	17	20	98.7 98.4 98.9	23.6 23.8 23.8	91 92 92	4 6 2	6.68 10.79 3.80	1.34 2.40 .96	5.34 8.40 2.86	.20	.26	TERRACE
3	U-83	WAX 6	10.0-11.9	CL	41	17	24	94.5 95.2	26.2 26.3	93 97	2 4	3.82 6.25	.91 1.12	2.91 5.12	0.70	.33	TERRACE
4	U-87	WAX 3	4.0-5.9	CL	41	21	20	87.3 87.4 82.0 84.4	22.6 23.9 21.1 20.6	88 72 56 56	2 4 6 6	3.84 6.94 9.49 9.50	.77 1.47 1.74 1.75	2.77 5.47 7.74 7.73	.25	.21	VALLEY
5	U-142	WAX 6	7.1-8.0	CH	50	20	30	96.3 96.6	25.0 25.0	83 90	2 6	4.64 11.39	1.32 2.70	3.32 8.70	.50	.27	TERRACE
6	U-142	WAX 7	10.0-11.9	CL	44	19	26	93.2 93.2	27.8 27.5	93 93	4 6	7.67 10.67	1.84 2.34	5.84 8.34	1.00	.17	TERRACE
7	U-143	WAX 4	6.0-7.9	CL	40	16	24	97.2 97.7	24.7 24.7	92 93	4 6	6.29 9.55	1.14 1.78	5.14 7.78	0.0	.24	TERRACE
8	U-143	WAX 10	18.0-19.0	CL	40	18	22	94.1 94.0	28.1 28.8	96 96	4 6	6.68 9.66	1.34 1.83	5.34 7.83	.25	.21	TERRACE
9	U-144	SHELBY 1	0.5-1.8	CL	46	20	26	91.7 91.4 93.2	26.6 26.6 26.5	88 88 91	1 3 5	2.39 5.60 8.67	.70 1.30 1.84	1.70 4.30 6.84	.30	.20	VALLEY
10	U-145	SHELBY 3	4.0-5.9	CL	45	17	28	97.0 96.1 96.1 96.5	15.7 16.2 16.2 16.2	58 59 59 60	3 5 7 3	5.37 8.25 11.37 5.01	1.18 1.62 2.18 1.00	4.18 6.62 9.18 4.00	.20	.23	VALLEY
11	U-153	SHELBY 2	2.0-3.6	CL	40	20	20	87.1 87.2 87.5	28.2 28.7 28.3	84 85 85	1 4 6	2.33 7.03 10.34	.68 1.52 2.17	1.68 5.52 8.17	.30	.235	VALLEY
12	U-154	WAX 4	6.0-7.9	CL	48	19	26	88.4 90.8	27.7 27.1	83 86	4 6	6.63 10.23	1.32 2.12	5.32 8.12	0.0	.26	VALLEY
13	U-163	SHELBY 3	4.0-5.9	CH	50	17	33	102.2 102.3 102.5	21.8 21.8 22.4	90 90 93	2 4 6	5.09 8.05 11.84	1.54 2.02 2.92	3.54 6.02 8.92	.90	.22	TERRACE
14	UC-164	WAX 2	2.0-3.9	CL	38	16	23	95.0 96.7 96.0	21.3 21.7 21.6	75 80 78	0.5 2 4	1.19 3.53 6.18	.34 .76 1.08	.84 2.76 5.08	.25	.17	VALLEY
15	UC-165	SHELBY 4	6.0-7.9	CL	38	17	21	101.5 101.2 101.6	23.4 23.4 23.3	98 98 98	1 3 5	3.17 6.76 10.09	1.08 1.88 2.54	2.08 4.88 7.54	.60	.38	VALLEY
16	UC-166	SHELBY 3	4.0-5.7	CL	33	18	15	99.9 100.8 101.2	24.5 24.7 24.6	98 100+ 100+	1 3 5	2.51 5.77 8.96	.76 1.38 1.98	1.76 4.38 6.98	.40	.24	VALLEY
17	U-201	SAMPLE 1	1.0-2.0	CH	56	18	38	94.9 95.7 93.7	28.1 28.1 27.8	100 100+ 96	0.5 1 3	1.22 1.90 5.14	.36 .45 1.07	.86 1.45 4.07	.20	.22	ABUTMENT



SYM

DESCRIPTION
REVISIONS

DATE APP'D

LITTLE BLUE RIVER, MISSOURI
LONGVIEW LAKE
EMBANKMENT CRITERIA AND
TEST DATA SUMMARY
UNDISTURBED FOUNDATION OVERBURDEN
R-TESTS

In 1 sheet
CORPS OF ENGINEERS
KANSAS CITY DISTRICT

Sheet No 1

Scale as shown
U S ARMY
JUNE 1978

Submitted
Checked by
G L S

Recommended
Checked by
R G D

Approved
Checked by
RBL-3-1691

PLATE NO. 86F

SUMMARY UNDISTURBED "S" TEST DATA OVERBURDEN MATERIALS

INDEX NUMBER	HOLE NUMBER	SAMPLE NUMBER	DEPTH	CLASSIFICATION				INITIAL CONDITIONS			0% T.S.F.	T MAX. T.S.F.	RESIDUAL T.S.F.	C T.S.F.	TAN ϕ	LOCATION
				SYMBOL	L. L.	P. L.	P. I.	DRY DENSITY	WATER CONTENT	% SAT.						
1	UC-9	WAX 2	33.37	OH	51	30	21	80.5	34	85	6	3.8 3.9		0.0	0.60	VALLEY
2	UC-9	WAX 4	68.72	CL	50	23	27	91.5	30.5	98	6	4.0 3.76		0.0	0.65	VALLEY
3	U-9A	WAX 4	74.76	CL	42	21	21	91.5	27	89	2	1.02 1.31		0.0	0.58	VALLEY
4	U-10A	WAX 4	65.68	CL	46	24	22	91.0	31.5	100	6	3.81 3.60		0.0	0.62	VALLEY
5	U-10B	WAX 3	49.53	CL	44	24	20	89.0	25.0	77	4	2.41 2.65		0.0	0.63	VALLEY
6	U-10B	WAX 5	85.90	CL	41	21	20	95.0	33.0	95	4	2.20 2.75		0.0	0.67	VALLEY
7	U-82	WAX 1	10.15	CL	44	27	7	91.5	28	93	6	4.24 3.84		0.0	0.67	VALLEY
8	U-82	WAX 5	88.91	CL	40	22	18	97.0	26	97	6	3.74 3.81		0.0	0.63	VALLEY
9	U-83	WAX 2	28.31	CL	34	23	11	90.5	14.5	90.5	4	2.70 3.81		0.5	0.74	TERRACE
10	U-83	WAX 2	28.31	CL	34	23	11	90.5	14.5	90.5	4		2.50 3.50	0.5	0.70	TERRACE
11	U-83	WAX 4	66.69	CL	42	22	20	94.5	24.0	84	4	2.59 3.57		0.5	0.53	TERRACE
12	U-83	WAX 6	100.11.9	CL	41	17	24	92.1 91.0 95.7	27.9 28.2 28.2	93 92 100	2 4 6	1.06 2.24 3.58		0.0	0.53	TERRACE
13	U-83	WAX 10	18.618.9	CL	38	23	15	96.0	27.5	98	4	2.39 3.62		0.0	0.69	TERRACE
14	U-87	WAX 1	10.13	CL	40	24	16	87.5	20.0	87.5	6	3.35 3.92		0.0	0.62	VALLEY
15	U-87	WAX 1	10.13	CL	40	24	16	87.5	20.0	87.5	6		3.40 3.69	0.0	0.72	VALLEY
16	U-87	WAX 3	40.5.9	CL	41	21	20	79.3 81.9 87.8	21.0 19.0 17.9	52 50 55	2 4 6	1.42 2.63 4.37		0.9	0.7	VALLEY
17*	U-87	WAX 3	40.5.9	CL	41	21	20	87.3 87.4	22.6 23.9	68 72	1 2.2	0.65 1.40		0.0	0.65	VALLEY
18	U-87	WAX 4	61.6.6	CL	46	22	24	90.0	27.5	90	6	3.57 3.74		0.0	0.61	VALLEY
19	U-87A	WAX 1	12.1.6	CL	46	24	22	92.0	28.0	92	5	3.04 3.28		0.0	0.65	VALLEY
20	U-87A	WAX 4	69.7.3	CL	46	24	22	85.0	31.0	85.5	6	3.60 3.93		0.0	0.63	VALLEY
21	U-142	WAX 3	53.5.9	CH	61	19	42	97.0	25.5	93	2 4 6 6	1.14 2.25 2.90 2.94		0.16	0.46	TERRACE
22	U-142	WAX 4	65.6.8	CH	57	24	33	95.5	26.0	93	2 4 6	1.10 2.29 3.09		0.22	0.49	TERRACE
23	U-142	WAX 5	80.8.9	CH	52	26	26	92.5	25.5	92.5	6	2.74 3.18		0.0	0.49	TERRACE
24	U-142	WAX 5	80.8.9	CH	52	26	26	92.5	25.5	92.5	6		2.40 3.06	0.0	0.46	TERRACE
25	U-142	WAX 9	15.415.9	CL	44	19	25	96.5	27.0	99	4 6	2.31 3.59		0.0	0.60	TERRACE
26	U-143	WAX 4	60.9.0	CL	40	16	24	96.2	24.6	89	6	3.36		0.0	0.56	TERRACE
27	U-143	WAX 4	60.7.9	CL	40	16	24	96.2 96.7	24.6 24.2	89 93	6		3.28 3.39	0.0	0.54	TERRACE
28*	U-143	WAX 4	60.7.9	CL	40	16	24	97.2 97.7	24.7 24.7	92 93	19 2.5	50 1.75		0.0	0.53	TERRACE
29	U-143	WAX 5	90.9.8	CL	42	18	24	95	27	93	2 6	1.34 3.53		0.25	0.55	TERRACE
30	U-143	WAX 9	17.017.5	CL	43	21	22	94	28.5	97	1 4 6	67 2.59 3.45		0.23	0.55	TERRACE
31	U-143	WAX 10	19.319.7	CL	44	22	22	86.5	31	87	6 6	3.45 1.04		0.0	0.625	TERRACE
32	U-143	WAX 12	22.227.7	CL	49	18	31	90.5	31.5	100	6 6	3.25 3.62		0.0	0.57	TERRACE
33*	U-144	WAX 1	0.51.8	CL	46	20	26	93.2	26.5	91	2.4	1.75		0.0	0.70	VALLEY

* NOTE

INDEX NUMBER
34
35
36*
37
38
39
40
41
42
43
44*
45
46*
47
48
49
50
51
52*

[illegible]

NOTE

PRACE
PRACE
PRACE
PRACE
PRACE
-PRACE
PRACE
PRACE

PRACE
PRACE

A EY

NOTE

PRACE
PRACE
PRACE
PRACE
PRACE
-PRACE
PRACE
PRACE

PRACE
PRACE

A EY

DATE * APR 20 1964

Sheet No. 1

Scale as shown
U S ARMY
JUNE 1978

2014年12月

406 vol.

PAGE NO
CDL - 3-1692

PLATE NO. 86G



UNDISTURBED "S" TESTS VALLEY, TERRACE AND ABUTMENT OVERBURDEN

LEGEND

CL	CH	OH	
△	●	●	VALLEY
○	●	●	TERRACE
□	■	■	ABUTMENT
		33	INDEX NO

* THESE RESULT FROM R TEST

SHEAR STRESS, T/SF









UNDISTURBED "S" TESTS VALLEY, TERRACE AND ABUTMENT OVERBURDEN

LEGEND

CL	CH	OH	
△	●	●	VALLEY
○	●	●	TERRACE
□	■	■	ABUTMENT
		33	INDEX NO

* THESE RESULT FROM R TEST





SYMBOL

DEFINITION

RIVERBANKS

LITTLE BLUE RIVER MISSOURI

LONGVIEW LAKE

EMBANKMENT CRITERIA AND PERFORMANCE REPORT

TEST DATA SUMMARY

UNDISTURBED FOUNDATION OVERBURDEN

S-TESTS, PLOTS

Sheet No. 1

Scale as shown

DATE

APPROVED



BY

FOR

U.S. ARMY

JUNE 1978

RBL-3-1693



**CONSOLIDATION TEST DATA
VALLEY (DAM AXIS STA 90+00 - 97+00)**

INDEX NUMBER	HOLE NUMBER	SAX NUMBER	DEPTH IN	TSF	TSF	TSF	TSF	TSF	TSF	TSF	TSF	TSF	TSF
1	U 10A	5	3.5	14	0.10	0.046	0.31	0.0245	0.0175	0.0272			
2	U 10A	4	4.5	16	0.10	0.046	0.31	0.0245	0.0175	0.0272			
3	U 10B	4	2.0	10	0.10	0.046	0.31	0.0245	0.0175	0.0272			
4	U 10A	5	3.5	14	0.10	0.046	0.31	0.0245	0.0175	0.0272			
5	U 10A	5	3.5	14	0.10	0.046	0.31	0.0245	0.0175	0.0272			
6	U 10A	5	3.5	14	0.10	0.046	0.31	0.0245	0.0175	0.0272			


**CONSOLIDATION TEST DATA
TERRACE (DAM AXIS STA 97+00 - 100+00)**

INDEX NUMBER	HOLE NUMBER	SAX NUMBER	SAMPLE DEPTH	TSF	TSF	TSF	TSF	TSF	TSF	TSF	TSF	TSF	TSF
8	U 10A	4	6.9 - 7.0	43	0.38	2.7							
9	U 10A	4	12.5 - 12.6	40	0.31	1.9							
10	U 10A	4	17.2 - 17.4	45	0.38	2.8							
11	U 10A	4	6.3 - 6.5	53	0.38	5.9							
12	U 10A	4	7.8 - 8.0	54	0.48	5.7							
13	U 10A	4	15.1 - 15.4	46	0.32	4.5							
14	U 10A	4	5.2 - 5.4	40	0.16	2.7							
15	U 10A	4	19.0 - 19.1	46	1.19	2.7							
16	U 10A	4	2.3 - 3.2	44	0.19	2.6							

VES

CONSOLIDATION TESTS VPO RATIO VS. PRESSURE CURVES TERRACE S-SHEET NUMBER

1280




PRESSURE T/SF

CONSOLIDATION TESTS COEFFICIENT OF CONSOLIDATION VS LIQUID LIMIT LEGEND

PRESSURE
TYPE TERRACE VALLEY

4 ● ○
8 ■ □
16 ▲ △



LIQUID LIMIT

CONSOLIDATION TEST DATA TEST PLACE: DAM SITE #77 97+00 - 99+50

TESTS: 0
REF: 01


TEST NO.	SAMP. NO.	DEPTH	L	w		P		e ₀	e ₁₆	C ₁	C ₂	C _u (mm ² /min)		
				%	T S F	%	T S F					4 T S F	8 T S F	16 T S F
1	6	6.5 - 10	43	9.36	2.7	0.887	0.640	0.42	0.22	0.0107	0.0661	0.0342		
2	7	12.5 - 17.9	40	0.71	1.9	0.878	0.544	0.028	0.25	0.0213	0.0089	0.0059		
3	8	17.1 - 18.4	45	0.98	2.8	0.852	0.658	0.036	0.24	0.0204	0.0084	0.0121		
4	9	4.3 - 6.5	53	0.39	5.8	0.745	0.565	0.034	0.22	0.0054	0.0061	0.0032		
5	10	2.4 - 4.6	54	0.48	5.7	0.744	0.576	0.060	0.21	0.0049	0.0066	0.0102		
6	11	5.1 - 7.4	46	0.92	4.5	0.845	0.640	0.051	0.24	0.0245	0.0245	0.0102		
7	12	7.4 - 9.8	42	0.56	2.2	0.749	0.571	0.033	0.25	0.0229	0.0110	0.0090		
8	13	1.1 - 2.9	46	1.19	2.2	0.841	0.560	0.032	0.21	0.0140	0.0102	0.0064		
9	14	4.4 - 6.8	44	0.19	2.6	0.687	0.493	0.032	0.17	0.0112	0.0061	0.0049		

SYM

DESCRIPTION
REVISIONS
LITTLE BLUE RIVER, MISSOURI
LONGVIEW LAKE
EMPALEMENT CRITERIA AND
PERFORMANCE REPORT
TEST DATA SUMMARY
FOUNDATION OVERBOLT
CONSOLIDATION TESTS

WWR

RBL-169
ATC NO. 051



DIRECT SHEAR "S" TESTS										
TEST NUMBER	HOLE NUMBER	BOX NUMBER	SAMPLE DEPTH	INITIAL CONDITION			TEST RESULTS			
				DRY (LB/FT ³)	WETTING COEFFICIENT	WETTING	NORMAL STRESS (T/SF)	MAX. SHEAR STRESS (T/SF)	PEAK TAN ϕ	RESIDUAL SHEAR STRESS (T/SF)
1	DC-32	1	22.6-23.1	132		27	6		1.67	
2	DC-32	1	22.6-23.1	132		27	6		1.67	
3	DC-32	3	40.1-40.6	100	0	28	6	7.22	1.2	
4	DC-32	3	40.1-40.6	100	0	28	6	9.90	1.06	
5	DC-32	5	60.9-60.9	142		30	6		1.67	
6	DC-32	5	60.9-60.9	142		30	6		1.67	
7	AC-46	13	31.7-32.5	136.2	1.2	29	6	13.40	2.22	
8	AC-46	13	31.7-32.5	136.2	0.3	28	6	14.56	2.42	2.21
9	AC-46	13	31.7-32.5	136.4	5.5	27	6			2.00
10	C-56	1	24.0-24.0	116.3	15.0	30	6	4.16	0.0	
11	C-56	2	24.0-24.0	119.0	11.0	27	6	2.96	0.0	
12	C-56	11	50.2-50.2	120.6	9.6	26	6	2.85	0.0	
13	C-56	7	31.3-32.2	129.9	7.7	27	6	0.44	7.0	
14	C-41	2	20.6-20.5	130.0	5.2	34	6			2.00
15	C-41	2	20.6-20.5	141.1	6.3	34	6	13.6	2.27	2.93
16	C-41	2	20.6-20.5	142.0	5.0	35	6	13.2	1.95	3.67
17	C-41	9	46.4-47.9	132.1	6.7	35.6	6			2.79
18	C-41A	2	33.4-34.7	141.0	3.6	40.0	6	4.64	7.0	3.12
19	UC-164	9	19.3-19.6	132.0	9.5	32	6			2.0
20	UC-164	9	19.3-19.6	132.0	9.5	32	6			2.1
21	UC-164	10	20.5	134	9.5	30	6			2.04
22	UC-164	10	20.7-21.0	134.5	9.5	30	6			2.1
23	UC-164	10	20.7-21.0	134.5	9.5	30	6			2.0
24	UC-165	1	17.4-19.5	119.9	12.0	33	6			2.0
25	UC-165	1	17.7-19.5	151.2	2.6	35	6			1.67
26	UC-165	3	20.8-22.4	150.4	2.6	37	6	3.42	5.7	2.13
27	DC-167	1	14.8	137.0	0	31	6			1.9
28	DC-167	1	15.0	137.0	0	32	6			2.0
29	UC-168	1	14.9	123	10	35	6	3.07	5.1	1.7
30	UC-168	4	19.0-20.0	126.4	4.5	36	6	7.77	1.29	

TESTED SAMPLES (SEE LAST PAGE) WERE 15 TO 10 T/SF
4.0% WET AREA

RESIDUAL TAN 0		DIRECT SHEAR TESTS						TYPE OF SHEAR SURFACE	GEOLOGIC MEMBER
STATION	TEST NO.	TEST RESULTS					RESIDUAL TAN 0		
		NORMAL STRESS (SF)	MOISTURE CONTENT (%)	PEAK TAN 0	RESIDUAL SHEAR STRESS (SF)	RESIDUAL TAN 0			
3	37	6		1.67				INTACT	PLEASANTON SHALE
	37	6		1.67				INTACT	PLEASANTON SHALE
	38	6	7.22	1.2				INTACT	PLEASANTON SHALE
	38	6	9.75	1.66				INTACT	PLEASANTON SHALE AND SANDSTONE
	39	6		1.67				INTACT	PLEASANTON SHALE
	39	6		1.67				INTACT	PLEASANTON SHALE
	79	6	13.40	2.23				INTACT	P. Pleasanton Shale
	78	6	14.56	2.42	2.25	31		INTACT	P. Pleasanton Shale
	63	6				2.00	33	PRESERVED	P. Pleasanton Shale
	90	6	4.36	.89				INTACT	SEA SHALE
4	72	6	2.96	.49				INTACT	SEA SHALE
	76	6	2.85	.48				INTACT	STANN GALESDURG RD
	71	6	4.44	.74				INTACT	PLEASANTON SHALE
	64	6				2.80	48	PRESERVED	PLEASANTON SHALE
	84	6	13.6	2.27	7.93	49		INTACT	PLEASANTON SHALE
	81	6	13.2	1.65	3.53	45		INTACT	P. Pleasanton Shale
	65.6	6				2.79	47	PRESERVED	PLEASANTON SHALE
	48.0	6	4.67	.75	3.11	52		INTACT	PLEASANTON SHALE
	92	6			2.0	33		PRESERVED	PLEASANTON SHALE
	92	6			2.1	35		PRESERVED	PLEASANTON SHALE
7	100	6			2.00	46		EXISTING BREAK	PLEASANTON SHALE
	99	6			2.1	35		PRESERVED	P. Pleasanton Shale
	99	6			2.0	33		PRESERVED	PLEASANTON SHALE
	83	6			2.55	49		PRESERVED	P. Pleasanton SILTSTONE
	50	6			1.62	60		PRESERVED	PLEASANTON SILTSTONE
	43	6	3.42	.57	2.13	34		EXISTING BREAK	PLEASANTON SILTSTONE
	93	6			1.6	30		PRESERVED	PLEASANTON SILTSTONE
	92	6			2.0	33		PRESERVED	P. Pleasanton SILTSTONE
	99	6	3.0	.51	1.7	28		INTACT	PLEASANTON SHALE
	36	6	2.11	1.29				INTACT	PLEASANTON SHALE

17 OF 10 13



DESCRIPTION
REVISIONS

DATE APP D

LITTLE BLUE RIVER MISSOURI
LONGVIEW LAKE
EMBANKMENT CRITERIA AND
PERFORMANCE REPORT
TEST DATA SUMMARY
FOUNDATION SHALES

In 1 sheet
CORPS OF ENGINEERS
KANSAS CITY DISTRICT


Sheet No 1

Scale as shown
U.S. ARMY
JUNE 1976



W.W.B. S. R.

RBL-3-1695


PLATE NO. 86J



END OF CONSTRUCTION CASE EL 915.0														
SLICE	SO STRENGTH		L (FT)	W _{EFF} (KIPS)	W _{TOTAL} (KIPS)	TAN $\phi/2$	γ	H	EARTH FORCES (KIPS)	FS	1.0	1.34	1.80	2.0
	C (KIPS)	TAN ϕ												
1	180	0	118	682.1	682.1	.09	0	0	Driving	195.9	281.3	308.2	344.3	
2	120	0	15	162.2	167.7	.09	0	0	Driving	98.1	105.4	107.6	112.4	
3	120	0	300	2187.2	2408.1	0	0	0	Resisting	360.0	268.7	240.0	180.5	
4	120	0	18	59.1	65.7	0	0	0	Resisting	73.6	65.4	62.8	57.5	
5	90	0	28	38.5	38.5	0	0	0	Resisting	64.5	55.0	52.0	45.7	




PARTIAL POOL CASE EL.878													
SLICE	S ^o STRENGTH		B ^o STRENGTH		L (FT)	W _{EFF} (KIPS)	W _{TOTAL} (KIPS)	TAN $\phi/2$	γ H	F S	10	153	20
	C (KIPS)	TAN ϕ	C (KIPS)	TAN ϕ									
1	0	36			56	607	607	09	0	Driving	217	293	331
2			20	28	225	101.6	101.6	09	0	Driving	38.3	50.9	57.0
3			20	28	72	431.8	573.8	09	0	Driving	169.0	220.7	245.6
4			20	28	102	620.0	1002.3	0	0	Resisting	194.0	126.8	97.0
5			20	28	68	797.7	529.4	0	0	Resisting	98.2	64.2	49.1
6			10	25	202	475.5	951.0	0	0	Resisting	139.2	91.0	69.6
7	0	30			117	73.9	147.8	0	0	Resisting	22.2	14.5	7.1



PARTIAL POOL CASE EL 878			
FACTOR OF SAFETY	1.0	1.34	2.0
RESISTING FORCES (KIPS)	453.5	296.9	226.4
DRIVING FORCES (KIPS)	2290	300.9	339.7
STATIC ANALYSIS (KIPS)	3977	469.6	504.4

SUMMARY - PARTIAL POOL CASE			
TYPE OF ANALYSIS	HAND ANALYSIS FS	COMPUTER FS	REQUIRED FS
STATIC	1.52	1.53	1.50
EARTHQUAKE	1.11		1.00

Σ Driving forces (Earthquake Analysis) =
 Σ Driving forces (Static analysis) =
 Δ Driving forces
 Where
 Δ Driving forces = $\Psi \cdot W_T$
 $= 0.05 \cdot 3374.5 \text{ K}$
 $= 168.7 \text{ K}$




SUMMARY - END OF CONSTRUCTION CASE			
TYPE OF ANALYSIS	HAND ANALYSIS F.S.	COMPUTER F.S.	REQUIRED F.S.
STATIC	1.35	1.34	1.30
EARTHQUAKE	1.05	—	1.00

END OF CONSTRUCTION CASE EL 915.0				
FACTOR OF SAFETY	1.0	1.34	1.5	2.0
Σ RESISTING FORCES (KIPS)	498.1	389.1	354.8	283.2
Σ DRIVING FORCES (KIPS)	294.0	386.0	415.8	476.7
Σ EARTHQUAKE ANALYSIS (KIPS)	462.1	554.1	583.9	644.8

Σ Driving forces (Earthquake Analysis) =
Σ Driving forces (static analysis) + Δ Driving forces

Where Δ Driving forces = $\frac{P}{\Sigma W} \times W$
= 0.05×3362.1
= 168.1 (Kips)

PHYSICAL SOIL CONSTANTS								
MATERIAL	UNIT WEIGHT		DESIGN SHEAR STRENGTHS					
	SAT.	DRAINED	C (KIPS)	TAN Ø	C (KIPS)	TAN Ø	C (KIPS)	TAN Ø
BERM	115	110	90	0.0	20	20	0.0	.30
COMPACTED FILL (HILLSIDE SLOPE)	125	115	180	0.0	40	.20	0.0	.36
FOUNDATION CLAY	115	110	120	0.0	.40	.20	0.0	.50
SHALE - PEAK	140	140	—	—	—	—	0.0	.06



SYM

DESCRIPTION
REVISIONS

DATE APP'D

LITTLE BLUE RIVER, MISSOURI
LONGVIEW LAKE
EMBANKMENT CRITERIA AND PERFORMANCE REPORT

TYPICAL STABILITY ANALYSIS
END OF CONSTRUCTION AND PARTIAL POOL CASE


In 1 sheet
CORPS OF ENGINEERS
KANSAS CITY DISTRICT

Sheet No 1

Submitted
Checked by
RGD

Recommended
Checked by
RGD


ED F.S.



STEADY SEEPAGE SPILLWAY CREST EL. 911.3


STEADY SEEPAGE CASE AT SPILLWAY CREST EL. 911.3													
SLICE	"S" STRENGTH		"R" STRENGTH		L (FT)	W _{EFF} (KIPS)	W _{TOTAL} (KIPS)	TAN $\phi/2$	λ/h	F.S. EARTH FORCES (KIPS)	1.0	1.5	2.0
	C (KIPS)	TAN ϕ	C (KIPS)	TAN ϕ									
1	0	36			300	54.6	694	.09	0	Driving	24.7	31.7	35.7
2			.20	.28	42.5	177.9	206.4	.09	0	Driving	82.6	105.9	118.7
3			.20	.28	30.0	236.8	329.4	.09	185.3	Driving	29.2	32.0	335.9
4			.20	.28	17	182.2	201.6	0	38.1	Resisting	16.3	-1.8	-10.9
5			.20	.28	212	1728.1	1748.1	0	0	Resisting	526.3	350.8	263.1
6			.10	.25	72	565.8	577.2	0	0	Resisting	155.9	103.9	77.9
7	0	.30			107	131.7	139.8	0	0	Resisting	39.5	26.3	19.8
8													

Sample calculation for λ/h (Seepage Force)



$$\lambda/h = \gamma_w A_1$$

Where γ_w = unit wt of water
 $A = (w)(h_1 + h_2)/2$
 i = hydraulic gradient
 $i = h_2/w$




RAPID DRAWDOWN FROM SPILLWAY CREST EL. 911.3

RAPID DRAWDOWN FROM SPILLWAY CREST EL 911.3														
SLICE	"S" STRENGTH		"R" STRENGTH		L (FT)	W _{EFF} (KIPS)	TAN ϕ	TAN $\phi/2$	λ/h	EARTH FORCES (KIPS)	FS			
	C (KIPS)	TAN ϕ	C (KIPS)	TAN ϕ							10	121	150	20
1	0	50			15	4.3	81	.09	0	Driving	3.4	4.4	5.5	6.7
2			40	20	119	458.9	81	.09	293	Driving	231.3	262.3	292.0	324.4
3			40	20	250	1164.8	0	0	88.4	Resisting	244.6	186.8	133.6	78.1
4			40	20	62	108.7	.27	0	0	Resisting	82.1	72.5	63.9	55.0
5	0	50			22	8.1	27	0	0	Resisting	7.2	6.2	5.4	4.5

SUMMARY - I
TYPE OF AN
STATI

RAPID D
FACTOR
RESISTIN
DRIVING

RAPID I



SUMMARY-STEADY SEEPAGE SPILLWAY CREST			
TYPE OF ANALYSIS	HAND ANAL. F.S.	COMP. F.S.	REQ'D F.S.
STATIC	1.53	1.53	1.50
EARTHQUAKE	1.20	—	1.0

STEADY SEEPAGE AT SPILLWAY CREST			
FACTOR OF SAFETY	1.0	1.5	2.0
Σ RESISTING FORCES (KIPS)	7380	4732	3499
Σ DRIVING FORCES (KIPS)	101.5	158.6	140.3
Σ EARTHQUAKE ANALYSIS (KIPS)	5691	6262	6579


Driving forces (Earthquake Analysis) =
Σ Driving forces (Static analysis) + Δ Driving forces

Where Δ Driving forces = $\frac{1}{2}$ Total weight
= $0.5 \times 3351.9 K$
= 1676 (Kips)

SUMMARY-RAPID DRAWDOWN FROM SPILLWAY CREST			
TYPE OF ANALYSIS	HAND ANAL. F.S.	COMPUTER F.S.	REQUIRED F.S.
STATIC	1.21	1.21	1.20

PHYSICAL SOIL CONSTANTS							
MATERIAL	UNIT WEIGHT PCF	DESIGN SHEAR STRENGTHS					
		Q		R		S	
	SAT	DRAINED	C OUPLES TAN δ	C OUPLES TAN δ	C OUPLES TAN δ	C OUPLES TAN δ	C OUPLES TAN δ
BERM	1150	1100	90	0	20	20	0
COMPACTED FILL	1250	1150	180	0	40	20	0
FDN. CLAY	1150	1100	120	0	40	20	0
SHALE	1400	1400	—	—	—	—	0

RAPID DRAWDOWN FROM SPILLWAY CREST EL.911.3				
FACTOR OF SAFETY	1.0	1.21	1.50	2.0
Σ RESISTING FORCES	-333.9	-265.5	-202.9	-137.6
Σ DRIVING FORCES	2347	2667	297.5	331.1




NOTES:
1 Tan (1/2) for active wedge is assumed to be one half the average slope of the outer embankment
2 Tan (1/2) for central block and passive wedge is assumed to be zero.
Seepage force equation is from book entitled Soil Mechanics, T.H. Wu, Section 3.12.
4 $\frac{1}{2}$ = seismic coefficient.


SYN DESCRIPTION REVISIONS DATE APP'D
LITTLE BLUE RIVER, MISSOURI
LONGVIEW LAKE
EMBANKMENT CRITERIA AND PERFORMANCE REPORT
TYPICAL STABILITY ANALYSIS
RAPID DRAWDOWN AND STEADY SEEPAGE

In 1 sheet Sheet No. 1 Scale as shown
CORPS OF ENGINEERS U.S. ARMY
KANSAS CITY DISTRICT JUNE 1978
Submitted Recommended Approved
CHIEF ENGINEER & DIST. BY
CHIEF OF DIST. BY
R.G.D.


RBL-3 1566

PLATE NO. 8H






END OF CONSTRUCTION CASE			
SURFACE	FAILURE PLANE EL.	ELEVATION	FS
A	816	U/S	1.03
B	802	U/S	1.47
C	816	D/S	1.47
F	802	D/S	1.34





PHYSICAL SOIL CONSTANTS								
MATERIAL	UNIT WEIGHT PCF	DESIGN SHEAR STRENGTH						
		SAT	DRAINED	CU (PSI)	TAN ϕ	CU (PSI)	TAN ϕ	S
BERM	115	110	0.90	0.0	0.20	0.20	0.0	0.30
COMPACTED FILL (HILLSIDE BORROW)	125	115	1.80	0.0	0.40	0.20	0.0	0.36
COMPACTED FILL (VALLEY BORROW)	125	115	1.80	0.0	0.40	0.20	0.0	0.50
FOUNDATION CLAY	115	110	1.20	0.0	0.40	0.20	0.0	0.50
SHALE (PEAK)	140	140	—	—	—	—	0.0	0.60
SHALE (RESIDUAL)	140	140	—	—	—	—	—	0.30

NOTE: ALL SAFETY FACTORS COMPUTED UTILIZING HILLSIDE BORROW MATERIAL

STABILITY STUDIES USING RESIDUAL STRENGTHS FOR FOUNDATION SHALES		
SURFACE	CASE	FS
B-B	Partial pool	1.30
F-F	Steady seepage	1.47



RAPID DRAWDOWN FROM SPILLWAY CREST PEAK STRENGTHS			
SURFACE	FAILURE PLANE EL.	POOL LEVELS	FS
A	816	911.3/891	1.25
B	802	911.3/891	1.25
C	802	911.3/891	1.35
D	816	911.3/891	1.40



RAPID DRAWDOWN FROM MAXIMUM SURCHARGE PEAK STRENGTHS			
SURFACE	FAILURE PLANE EL.	POOL LEVELS	FS
A	816	922.9/891	1.20
B	802	922.9/891	1.23
C	802	922.9/891	1.22
D	816	922.9/891	1.21

STEADY SEEPAGE SPILLWAY CREST EL. 911.3 PEAK STRENGTHS			
SURFACE	FAILURE PLANE EL.	POOL LEVELS	FS
A	802	911.3/891	1.70
B	802	911.3/891	1.72
C	816	911.3/891	1.53
D	816	911.3/891	1.55
E	816	911.3/891	1.53

SYN DESCRIPTION REVISIONS DATE APP'D

LITTLE BLUE RIVER, MISSOURI
LONGVIEW LAKE
EMBANKMENT CRITERIA AND PERFORMANCE REPORT
EMBANKMENT STABILITY ANALYSIS SUMMARY
VALLEY SECTION






In 1 sheet
CORPS OF ENGINEERS
KANSAS CITY DISTRICT
Submitted by
Checked by
Compiled by
RCS




Sheet No. 1


Scale as shown
U & ARMY
JUNE 1976

Recommended by
Checked by
Compiled by
RCS

RBL-3-1587









STEADY SEEPAGE CASE POOL EL. 882.3		
SURFACE	FAILURE PLANE EL.	F.S.
A	816	1.29
B	802	1.18

MATERIAL	UNIT WEIGHT PCF		DESIGN SHEAR STRENGTH							
			"Q"		"R"		"S"			
	SAT.	DRAINED	CD/PSI	TAN ϕ	CD/PSI	TAN ϕ	CD/PSI	TAN ϕ	CD/PSI	TAN ϕ
BERM	115	110	0.90	0	0.20	0.20	0.0	0.30		
COMPACTED FILL	125	115	1.80	0	0.40	0.20	.3	0.36		
FOUNDATION CLAY	115	110	1.20	0	0.40	0.20	0	0.50		
SHALE	140	140	—	—	—	—	0.0	0.60		



STEADY SEEPAGE CASE POOL EL. 882.5		
SURFACE	FAILURE PLANE EL.	F.S.
A	816	1.50
B	802	1.36

Notes
 1. Elevation 882.3 is the maximum lake elevation for the all season flood of record routed through the outlet works
 2. Elevation 882.5 is maximum elevation for the third flood of record for the period 1 Aug - 23 Feb routed through outlet works



END OF CONSTRUCTION POOL EL. 887.0			
SURFACE	FAILURE PLANE EL.	LOCATION	F.S.
A	816	D/S *	1.80
B	802	D/S *	1.41
C	816	U/S	1.59
D	802	U/S	1.60

* DOWNSTREAM & OF COFFERDAM

SYN

DESCRIPTION
REVISIONS

DATE APPD.

LITTLE BLUE RIVER, MISSOURI
LONGVIEW LAKE
 EMBANKMENT CRITERIA AND PERFORMANCE REPORT
 EMBANKMENT STABILITY ANALYSIS
 SUMMARY COFFERDAM

In 1 sheet
 CORPS OF ENGINEERS
 KANSAS CITY DISTRICT


Sheet No. 1

Scale: as shown
 U. S. ARMY
 JUNE 1978

Checked by
 JPM

Recommended
 Checked by
 SCD

Approved
 RBL-3-1568




3

2

1

END OF CONSTRUCTION CASE			
SURFACE	FAILURE PLANE EL.	LOCATION	F.S.
A	827	U/S	1.25
B	827	U/S	1.10
C	827	U/S	1.23
D	CIRC. FAILURE SURF.	U/S	1.63
E	827	U/S	1.87
F	827	U/S	1.24

PHYSICAL SOIL CONSTANTS								
MATERIAL	UNIT WEIGHT PCF		DESIGN SHEAR STRENGTH					
			"C"		"φ"		"S"	
	SAT.	DRAINED	(KIPS/FT ²)	(TAN θ)	(KIPS/FT ²)	(TAN θ)	(KIPS/FT ²)	(TAN θ)
EMBANKMENT	125.0	115.0	1.80	0.0	.40	.20	0.2	.50
ZONE OF LOW STRENGTH MTRL.	125.0	115.0	1.00	0.0				
SHALE (PEAK)	140.0	140.0	2.0	2.0	2.0	2.00	2.0	2.0



LONGVIEW CONDUIT SECTION - UPSTREAM
EFFECTIVE STRESS ANALYSIS WITH PORE PRESSURE CONTOURS

Revisions		Date	Approved
Symbol	Descriptions		
U.S. ARMY ENGINEER DISTRICT CORPS OF ENGINEERS KANSAS CITY, MISSOURI			
Designed by:	D.A.R.	LITTLE BLUE RIVER, MISSOURI LONGVIEW LAKE EMBANKMENT CRITERIA AND PERFORMANCE REPORT STAGE II EMBANKMENT STABILITY ANALYSIS SUMMARY CONDUIT SECTION	
Drawn by:	L.M.P.		
Checked by:	L.L.L.	Scale: 1" = 50'	Sheet Number: S-50
Submitted by:	R.G.D.	Date: X	Design File: 100.55X.05AB
		Deg. No.:	File No.: RBL-3-1486

D							PLACEMENT REQUIREMENTS				
	MATERIAL	STAGE	MAJOR SOURCE	MATERIAL DESCRIPTION	CLASS.	ZONE USAGE	EQUIPMENT	MAXIMUM UNCOMPACTED LIFT THICKNESS (INCHES)	NUMBER OF PASSES	DENSITY	MOISTURE
	IMPERVIOUS ^o	I	REQUIRED EXCAVATION AND BORROW	CLAY WITH LL < 65 AND 100 THAT BE CONSISTENTLY OF 80% AND	CL CH	SEPARATION ZONE AND SPECIAL BACKFILL IN SEPARATION AND RANDOM ZONES	TAMPING ROLLER	8	6	% OF MAXIMUM DRY DENSITY AT OPTIMUM MOISTURE CONTENT	+2% TO -2% OF OPTIMUM MOISTURE CONTENT
	IMPERVIOUS ^o	II	REQUIRED EXCAVATION AND STOCKPILE	CLAY WITH 60% CHANNEL UPSTREAM OF DAM AREA. RELAY CL. NOT LL.05 RELAY CL. NOT BETWEEN 57-60 AND 101-60 LL.05 RELAY CL. NOT BETWEEN 57-60 AND 101-60 LL.05 CUTOFF AND INSPECTION TRENCH LL.05 RELAY CL. NOT INCLUDING CUTOFF AND INSPECTION TRENCH AND BETWEEN 57-60 AND 101-60 LL.05	CL CH	SEPARATION ZONE AND SPECIAL BACKFILL IN SEPARATION AND RANDOM ZONES	TAMPING ROLLER	8	6	% OF MAXIMUM DRY DENSITY AT OPTIMUM MOISTURE CONTENT	+2% TO -2% OF OPTIMUM MOISTURE CONTENT
	RANDOM ^o	I	REQUIRED EXCAVATION AND BORROW	PERVIOUS MATERIAL, EXCEPT MATERIAL OF SIZED WITH LARGER LIFT LESS THAN 60	VARIABLES	RANDOM ZONE	TAMPING ROLLER PNEUMATIC ROLLER	8 12	6 3	% OF MAXIMUM DRY DENSITY AT OPTIMUM MOISTURE CONTENT	+2% TO -2% OF OPTIMUM MOISTURE CONTENT
	RANDOM ^o	II	REQUIRED EXCAVATION AND BORROW	MATERIAL NOT SUITABLE FOR PLACEMENT ELEMENTS RELAY CL. NOT LL.05 RELAY CL. NOT LL.05 RELAY CL. NOT LL.05 RELAY CL. NOT LL.05 RELAY CL. NOT LL.05 RELAY CL. NOT LL.05	VARIABLES	RANDOM ZONE AND SPILLWAY DISE	TAMPING ROLLER PNEUMATIC ROLLER	8 12	6 3	% OF MAXIMUM DRY DENSITY AT OPTIMUM MOISTURE CONTENT	+2% TO -2% OF OPTIMUM MOISTURE CONTENT
	BERM	I	REQUIRED EXCAVATION AND BORROW	MATERIAL NOT SUITABLE FOR PLACEMENT ELEMENTS RELAY CL. NOT LL.05 RELAY CL. NOT LL.05 RELAY CL. NOT LL.05 RELAY CL. NOT LL.05 RELAY CL. NOT LL.05 RELAY CL. NOT LL.05	VARIABLES OUTER 5' IS CH	BERM ZONE	PNEUMATIC ROLLER TAMPING ROLLER	24 8	2 2	NONE SPECIFIED	CONTROLLED TO ALLOW UNASSISTED MOVEMENT OF COMPACTION EQUIPMENT
	BERM	II	REQUIRED EXCAVATION AND BORROW	CLAY AS ABOVE WITH 5% HUMIDITY TO THE SLAKE IS FAT CLAY 10%.	VARIABLES	BERM ZONE	TAMPING ROLLER PNEUMATIC ROLLER	8 12	4 2	NONE SPECIFIED	+2% TO -2% OF OPTIMUM MOISTURE CONTENT
	DIVERSION DIKE AND DOWNSTREAM COFFERDAM	I	REQUIRED EXCAVATION AND BORROW	MATERIAL NOT SUITABLE FOR PLACEMENT ELEMENTS	VARIABLES	DIVERSION DIKE AND DOWNSTREAM COFFERDAM	TRAFFIC COMPACTED	24	EVEN ROUTING	NONE SPECIFIED	CONTROLLED TO ALLOW UNASSISTED MOVEMENT OF COMPACTION EQUIPMENT
	CHANNEL FILL, DIVERSION DIKE	II	REQUIRED EXCAVATION AND BORROW	MATERIAL NOT SUITABLE FOR PLACEMENT ELEMENTS RELAY CL. NOT LL.05 RELAY CL. NOT LL.05 RELAY CL. NOT LL.05 RELAY CL. NOT LL.05 RELAY CL. NOT LL.05 RELAY CL. NOT LL.05	VARIABLES	CHANNEL FILL AND DIVERSION DIKE	TRAFFIC COMPACTED	24	EVEN ROUTING	NONE SPECIFIED	+2% TO -2% OF OPTIMUM MOISTURE CONTENT
	DOWNSTREAM COFFERDAM	II	REQUIRED EXCAVATION AND BORROW	MATERIAL NOT SUITABLE FOR PLACEMENT ELEMENTS	VARIABLES	DOWNSTREAM COFFERDAM	TAMPING ROLLER PNEUMATIC ROLLER	8 12	6 3	NONE SPECIFIED	+2% TO -2% OF OPTIMUM MOISTURE CONTENT
	IMPERVIOUS CLAY BLANKET	II	REQUIRED EXCAVATION AND STOCKPILE	CLAY WITH < 65 GRAVEL AND LIQUID LIMIT LESS THAN 60	CL CH	RIGHT ABUTMENT CLAY BLANKET	TAMPING ROLLER PNEUMATIC ROLLER	8 12	6 3	% OF MAXIMUM DRY DENSITY AT OPTIMUM MOISTURE CONTENT	+2% TO -2% OF OPTIMUM MOISTURE CONTENT
	SPECIAL BACKFILL	I AND II	REQUIRED EXCAVATION BORROW OR OFFSITE SOURCES	IMPERVIOUS IN SEPARATION ZONE RANDOM IN RANDOM ZONE PERVIOUS IN PERVIOUS ZONE	VARIABLES	ADJACENT TO STRUCTURES PRESERVATION SURFACES AND TO FILL IRREGULARITIES	POWER TAMPER RANDOM AND RANDOM VIBRATORY PLATE IMPERVIOUS	3 ----	AS REQUIRED AS REQUIRED	% MAXIMUM DRY DENSITY 80% RELATIVE DENSITY ^o	MOISTURE SPECIFIC TO THE BACKFILL
	TOPSOIL	I AND II	REQUIRED EXCAVATION BORROW STOCKPILE OR OFFSITE SOURCES	MATERIAL CONTAINING ORGANIC MATTER NOT SUITABLE FOR PLACEMENT ELEMENTS	VARIABLES	AREAS TO BE TOPSOILED AND SEEDING	TRAFFIC COMPACTED	12	EVEN ROUTING	FIRM, WELL-PACKED CONDITION	CONTROLLED TO ALLOW UNASSISTED MOVEMENT OF EQUIPMENT
	PERVIOUS	I	OFFSITE SOURCES MEDIUM OR LARGE RIVERS	CLEANABLE MATERIAL SAND 10 - 100 PASS NO. 4 10 - 100 PASS NO. 10 10 - 100 PASS NO. 20 10 - 100 PASS NO. 30	SP	PERVIOUS BLANKET, PERVIOUS ROCK AND SPECIAL BACKFILL IN PERVIOUS ZONES.	PLATE VIBRATORY COMPACTOR VIBRATORY ROLLER	4 12	AS REQUIRED 3	80% RELATIVE DENSITY ^o	SATURATED
	PERVIOUS	II	OFFSITE SOURCES MEDIUM OR LARGE RIVERS	CLEANABLE MATERIAL SAND 10 - 100 PASS NO. 4 10 - 100 PASS NO. 10 10 - 100 PASS NO. 20 10 - 100 PASS NO. 30	SP	PERVIOUS BLANKET, PERVIOUS ROCK AND SPECIAL BACKFILL IN PERVIOUS ZONES.	PLATE VIBRATORY COMPACTOR VIBRATORY ROLLER	4 12	AS REQUIRED 3	80% RELATIVE DENSITY ^o	SATURATED
	ROCK FILL	I	REQUIRED EXCAVATION	BETTER QUALITY LIMESTONE WITH LESS THAN 10% FINE PARTICLES LIMESTONE SAND, SOFT LIME 0 - 100 LESS THAN 2 INCHES.	RO OF	ROCK FILL ZONE OVER AND UNDER CLAY BLANKET	-----	36	NONE	NONE	NONE
	ROCK FILL	II	REQUIRED EXCAVATION AND STOCKPILE	BETTER QUALITY LIMESTONE WITH LESS THAN 10% FINE PARTICLES LIMESTONE SAND, SOFT LIME 0 - 100 LESS THAN 2 INCHES.	RO OF	ROCK FILL ZONE OVER CLAY BLANKET	-----	36	NONE	NONE	NONE
	BEDDING	I	REQUIRED EXCAVATION	PERVIOUS MATERIAL WITH LESS THAN 10% FINE PARTICLES PERVIOUS MATERIAL WITH LESS THAN 10% FINE PARTICLES PERVIOUS MATERIAL WITH LESS THAN 10% FINE PARTICLES PERVIOUS MATERIAL WITH LESS THAN 10% FINE PARTICLES PERVIOUS MATERIAL WITH LESS THAN 10% FINE PARTICLES PERVIOUS MATERIAL WITH LESS THAN 10% FINE PARTICLES	RO OF	BEDDING FOR SEPARATION ZONE PROTECTION	-----	12	NONE	NONE	NONE
	BEDDING (9-INCH)	II	OFFSITE COMMERCIAL QUARRY	PERVIOUS MATERIAL WITH LESS THAN 10% FINE PARTICLES PERVIOUS MATERIAL WITH LESS THAN 10% FINE PARTICLES PERVIOUS MATERIAL WITH LESS THAN 10% FINE PARTICLES PERVIOUS MATERIAL WITH LESS THAN 10% FINE PARTICLES PERVIOUS MATERIAL WITH LESS THAN 10% FINE PARTICLES PERVIOUS MATERIAL WITH LESS THAN 10% FINE PARTICLES	RO OF	BEDDING FOR SEPARATION ZONE PROTECTION	-----	FULL LAYER THICKNESS	-----	NONE	NONE
	BEDDING (12-INCH)	II	OFFSITE COMMERCIAL QUARRY	PERVIOUS MATERIAL WITH LESS THAN 10% FINE PARTICLES PERVIOUS MATERIAL WITH LESS THAN 10% FINE PARTICLES PERVIOUS MATERIAL WITH LESS THAN 10% FINE PARTICLES PERVIOUS MATERIAL WITH LESS THAN 10% FINE PARTICLES PERVIOUS MATERIAL WITH LESS THAN 10% FINE PARTICLES PERVIOUS MATERIAL WITH LESS THAN 10% FINE PARTICLES	RO OF	BEDDING FOR SEPARATION ZONE PROTECTION	-----	FULL LAYER THICKNESS	-----	NONE	NONE
	RAPRAP	II	OFFSITE COMMERCIAL QUARRY	PERVIOUS MATERIAL WITH LESS THAN 10% FINE PARTICLES PERVIOUS MATERIAL WITH LESS THAN 10% FINE PARTICLES PERVIOUS MATERIAL WITH LESS THAN 10% FINE PARTICLES PERVIOUS MATERIAL WITH LESS THAN 10% FINE PARTICLES PERVIOUS MATERIAL WITH LESS THAN 10% FINE PARTICLES PERVIOUS MATERIAL WITH LESS THAN 10% FINE PARTICLES	RO OF	SLOPE PROTECTION	CLAMBRADALL ROCK BLANKET OR GRASS PEEL	FULL LAYER THICKNESS	NONE	NONE	NONE

[illegible]

MATERIAL	STAGE I (YD ³)	STAGE II (YD ³)	TOTAL (YD ³)
PERVIOUS	24,387	74,197	104,584
IMPERVIOUS	99,886	918,662	1,028,548
ARMOR	215,958	898,361	914,319
SAND	246,467	621,354	867,821

* WHEN PLACED OVER A ROCK FOUNDATION, THE LIFT THICKNESS WAS 6 INCHES AND COMPACTION WAS ACHIEVED WITH TWO PASSES OF A RUBBER-TYRED ROLLER UNTIL THE FILL REACHED 12 INCHES THICKNESS OVER THE ROCK FOUNDATION. THE RUBBER-TYRED ROLLER CAUSED BREAKAGE OF SHALE FOUNDATION. THE BALLAST WAS LESSENED ON OTHER ROLLERS WERE USED AS APPROVED BY THE CONTRACTING OFFICER.




*70% RELATIVE DENSITY WAS NOT ACHIEVABLE AND THE SPECIFIED DENSITY WAS REDUCED TO 70% RELATIVE DENSITY.

Revisions	
Symbol	Descriptions
Date	Approved

U.S. ARMY ENGINEER DISTRICT
CORPS OF ENGINEERS
KANSAS CITY, MISSOURI

Designed by: R.G.O.	 US Army Corps of Engineers	LITTLE BLUE RIVER, MISSOURI LONGVIEW LAKE EMBANKMENT CRITERIA AND PERFORMANCE REPORT	
Drawn by:			
R.A.A.			
		EMBANKMENT MATERIAL PLACEMENT REQUIREMENTS AND QUANTITIES	
Checked by:			
L.L.L.			
Submitted by: X	Sheet numbers	Scales NO SCALE	Plot Scales 0.0833H
		Dates X	Design Files D00,SS,LONGEMBU
		Draw No's	File Nos RBL-3-1487

ELEVATION IN FEET BASED ON NATIONAL GEODETIC VERTICAL DATUM OF 1929



LE

INITIAL PROFILE 8 M




5 M

4 M

13 M

12 M

23 M



LEGEND

FILE 8 NOV '85
5 MAR '87
4 JUN '87
13 MAR '88
12 JAN '89
23 APR '90

LEGEND	
INITIAL PROFILE 8 NOV '85	○
5 MAR '87	○
4 JUN '87	○
13 MAR '88	△
12 JAN '89	●
23 APR '90	▲

Revisions			
Symbol	Descriptions	Date	Approved
	Revised March 1990		

U S ARMY ENGINEER DISTRICT
CORPS OF ENGINEERS
KANSAS CITY, MISSOURI

DESIGNED BY: RGO

DRAWN BY: VAB

CHECKED BY: RLA

SUBMITTED BY: WBE

LITTLE BLUE RIVER, MISSOURI
LONGVIEW LAKE
EMBANKMENT CRITERIA AND
PERFORMANCE REPORT


TOP OF DAM PROFILE PLOTS

Scale: AS SHOWN

Date: DECEMBER 1986

Sheet number: 1

File No: RBL-3-1570





3

2

1

927

926

2001 1997 1998 1999 2000 2001 2002 2003 2004 2005 2006

0+36 D

925

924

2001 1997 1998 1999 2000 2001 2002 2003 2004 2005 2006

0+36 D

925

924

2001 1997 1998 1999 2000 2001 2002 2003 2004 2005 2006

0+36 D

925

924

2001 1997 1998 1999 2000 2001 2002 2003 2004 2005 2006

0+36 D

3

2

1

D

C

B

A





Revisions			
Symbol	Descriptions	Date	Approved
	Revised March 1990		
U. S. ARMY ENGINEER DISTRICT CORPS OF ENGINEERS KANSAS CITY, MISSOURI			
Designed by RCD	 LITTLE BLUE RIVER, MISSOURI LONGVIEW LAKE EMBANKMENT CRITERIA AND PERFORMANCE REPORT CREST SETTLEMENT MONUMENT PLOTS		
Drawn by: EGM			
Checked by: RLA			
Submitted by WBE			
Scale: AS SHOWN		Sheet number.	
Date: DECEMBER 1986			
Draw No 1 OF 2		File No	RBL-3-1571

PLATE NO. 95







3

2


1



Q+36 D



Q+36 D



Q+36 D

D

C

B



A


3




2

1



Revisions			
Symbol	Descriptions	Date	Approved
	Revised March 1990		
U. S. ARMY ENGINEER DISTRICT CORPS OF ENGINEERS KANSAS CITY, MISSOURI			
Designed by: R G D		LITTLE BLUE RIVER, MISSOURI LONGVIEW LAKE EMBANKMENT CRITERIA AND PERFORMANCE REPORT	
Drawn by: J G S		CREST SETTLEMENT MONUMENT PLOTS	
Checked by: R L A		Scale: AS SHOWN	Sheet number
Submitted by: W B E		Date: DECEMBER 1986	File No
		Draw No 2 OF 2	RBL-3-1572





Revisions		Date	Approved
Symbol	Description		
	Revised March 1990		

U S ARMY ENGINEER DISTRICT
CORPS OF ENGINEERS
KANSAS CITY, MISSOURI

LITTLE BLUE RIVER, MISSOURI
LONGVIEW LAKE
EMBANKMENT CRITERIA AND
PERFORMANCE REPORT

Settlement Plate Data Plots
SPPF 91-1 and SPPF 93-7

Designed by R G D	Scale AS SHOWN	Sheet number 1
Drawn by S E Y	Date DECEMBER 1986	
Checked by R L A	Drawn by W B E	File No RBL-3-1573

PLATE NO. 97

5

4

3



LEGEND**ORIGINAL MEANED SURVEY**

3 SEPT 87	○
7 JAN 88	□
13 APR 88	○
11 JAN 89	△
9 AUG 89	●
23 APR 90	▲
17 MAY 90	■
1 JUN 90	+

ORIGINAL MEANED SURVEY DATES



LINE "A"	LINE "B"
26 JULY 1985	20 AUG 1985
20 AUG 1985	30 SEPT 1985 ¹
30 SEPT 1985 ¹	30 SEPT 1985 ²

HORIZONTAL MOVEMENT IN CENTIMETERS



ALIGNMENT LINE "B" MONUMENTS
RANGE 1+70 UPSTREAM

5



Symbol	Revisions		Date	Approved
	Descriptions			
	Revised March 1990			

U. S. ARMY ENGINEER DISTRICT
 CORPS OF ENGINEERS
 KANSAS CITY, MISSOURI


DESIGNED BY: RGD
 DRAWN BY: RDT
 CHECKED BY: RLA
 SUBMITTED BY: WBE




**LITTLE BLUE RIVER, MISSOURI
 LONGVIEW LAKE
 EMBANKMENT CRITERIA AND
 PERFORMANCE REPORT**

**ALIGNMENT MONUMENT HORIZONTAL PROFILE
 ORIGINAL SURVEY BASE LINES
 LINES "A" AND "B" SUMMARY**

Scale: AS SHOWN
 Date: _____
 Draw No: 4 of 4

Sheet number: _____
 File No: RBL-3-1574





LEGEND
 VERTICAL MOVEMENT ----- □
 HORIZONTAL MOVEMENT ----- ○




Revisions			
Symbol	Description	Date	Approved
	Revised March 1990		

U. S. ARMY ENGINEER DISTRICT
 CORPS OF ENGINEERS
 KANSAS CITY, MISSOURI

Designed by: RGD
 Drawn by: SEY
 Checked by: RLA
 Submitted by: WSE

LITTLE BLUE RIVER, MISSOURI
 LONGVIEW LAKE
 EMBANKMENT CRITERIA AND
 PERFORMANCE REPORT
 ALIGNMENT MONUMENTS HORIZONTAL AND
 VERTICAL DATA PLOTS MONUMENTS A-4,
 A-5 AND A-6.

Scale: AS SHOWN
 Date: DECEMBER 1986
 Sheet number:
 File No: RBL-3-1575



LEGEND

VERTICAL MOVEMENT — □


HORIZONTAL MOVEMENT — ○


Revisions			
Symbol	Descriptions	Date	Approved
	Revised March 1990		

U S ARMY ENGINEER DISTRICT
CORPS OF ENGINEERS
KANSAS CITY, MISSOURI

Designed by: RGD	<p>LITTLE BLUE RIVER, MISSOURI LONGVIEW LAKE EMBANKMENT CRITERIA AND PERFORMANCE REPORT ALIGNMENT MONUMENTS HORIZONTAL AND VERTICAL DATA PLOTS MONUMENTS B-1, B-2 AND B-3</p>	Scale AS SHOWN	Sheet number
Drawn by: EDP		Date DECEMBER 1986	
Checked by: RLA			
Submitted by: WBE			

File No. RBL-3-1576





LEGEND

PZ PRESSURE CELL PIEZOMETER ——— □

PZ OPEN TUBE PIEZOMETER ——— ○

PP PRESSURE CELL PORE PRESSURE DEVICE ——— ■

PP OPEN TUBE PORE PRESSURE DEVICE ——— ●

MB MONITOR BOX ——— ⊠

Bethany Falls L.S.
 Hushpuckney Sh
 Middle Creek L.S.
 Ladore Sh.
 Snider L.S.
 Mound City Sn.
 Grizer L.S.
 Pleasanton Zone A SS.

Symbol	Revisions	Date	Approved
	Revised March 1990		


U.S. ARMY ENGINEER DISTRICT
 CORPS OF ENGINEERS
 KANSAS CITY, MISSOURI



DESIGNED BY: RGD
 DRAWN BY: PST
 CHECKED BY: RLA
 SUBMITTED BY: WBE

**LITTLE BLUE RIVER, MISSOURI
 LONGVIEW LAKE
 EMBANKMENT CRITERIA AND
 PERFORMANCE REPORT**

**PIEZOMETER PLOTS
 OPEN TUBE PZ
 PPF 84-1**

Scale: AS SHOWN
 Date: DECEMBER 1986
 Sheet number:
 File No: RBL-3-1577





Revisions		Date	Approved
Symbol	Descriptions		
	Revised March 1990		

U S ARMY ENGINEER DISTRICT
CORPS OF ENGINEERS
KANSAS CITY, MISSOURI

Designed by: H. D. [Signature]

Drawn by: P. S. T.

Checked by: R. L. A.

Submitted by: W. B. E.


LITTLE BLUE RIVER, MISSOURI
LONGVIEW LAKE
EMBANKMENT CRITERIA AND
PERFORMANCE REPORT
PIEZOMETER PLOTS
OPEN TUBE PZ
PPF 86-1A



Scale: AS SHOWN

Date: DECEMBER 1986

Sheet Number: [Blank]

File No: RBL-3-1578





Symbol	Revisions	Date	Approved
	Revised March 1990		


U S ARMY ENGINEER DISTRICT
CORPS OF ENGINEERS
KANSAS CITY, MISSOURI

LITTLE BLUE RIVER, MISSOURI
LONGVIEW LAKE
EMBANKMENT CRITERIA AND
PERFORMANCE REPORT

PIEZOMETER PLOTS
OPEN TUBE PZ
PPF 87-3

Designed by: NGD
Drawn by: P S T
Checked by: R L A
Submitted by: W B E

Scale: AS SHOWN
Date: DECEMBER 1986
Sheet number:
File No: RBL-3-1579



3

2

1

D

C

B

A


ADDED 17 PINTS WATER

ADDED 17 PINTS WATER

LEGEND

- PZ PRESSURE CELL PIEZOMETER
- PZ OPENTUBE PIEZOMETER
- PP PRESSURE CELL PORE PRESSURE DEVICE
- PP OPENTUBE PORE PRESSURE DEVICE
- MB MONITOR BOX

1988 1989 1990



Symbol	Revisions	Descriptions	Date	Approved
	Revised	March 1990		

U S ARMY ENGINEER DISTRICT
CORPS OF ENGINEERS
KANSAS CITY, MISSOURI

DESIGNED BY: RGD
DRAWN BY: FDN
CHECKED BY: RLA
SUBMITTED BY: WSE

LITTLE BLUE RIVER, MISSOURI
EMBRACEMENT STABILITY AND
PERFORMANCE REPORT
PIEZOMETER PLOTS
OPEN TUBE PZ
PPF-88-2

Scale: AS SHOWN
Date: DECEMBER 1988
Drawn By: WSE

Sheet number:
File No.: RBL-3-1580

3

2

1

PLATE NO. 104



PPF 88-3
 STATION: 88+02
 RANGE: 8+20
 TIP ELEV: 808.4
 MATERIAL: PLS
 INSTALLED: 25 APR 87



ELEVATION IN FEET BASED ON NATIONAL GEODETIC VERTICAL DATUM OF 1988

D

C

B

A





5

4

3



VALUE ENGINEERING PAYS



Revisions		Date	Approved
Symbol	Descriptions		

U.S. ARMY ENGINEER DISTRICT
CORPS OF ENGINEERS
KANSAS CITY, MISSOURI

Designed By: **JPM**
 Drawn By: **LJD**
 Checked By: **RLA**
 Submitted By: **JPM**

14
U.S. Army Corps of Engineers

LITTLE BLUE RIVER, MISSOURI
LONGVIEW AREA
EMBANKMENT CRITERIA AND
PERFORMANCE REPORT

PIEZOMETER PLOTS
OPENTUBE PZ
PPF 88-3

Scale: AS SHOWN	Sheet number: 1	Plot Scale: 125	Design File: 100.653 PROFILE
Date: AUGUST 1987		File No: RBL-3-1581	
Drawn By: MLJ			

U.S. ARMY ENGINEER DISTRICT
CORPS OF ENGINEERS
KANSAS CITY, MISSOURI

 US Army Corps

PIEZOMETER PLOTS
OPENTUBE PZ
PPF 88-3



US Army Corps
of Engineers


Score: 22



2070. AUGA

Score: AS SHOWN
Date: AUGUST 19
DWG
NO:

Sheet
number:

Plot Scale: 12x	
Design File: (100.65)PROFILE	
File No: RBL-3-1581	





Revisions			
Symbol	Descriptions	Date	Approved
	Revised March 1990		

U. S. ARMY ENGINEER DISTRICT
CORPS OF ENGINEERS
KANSAS CITY, MISSOURI

Designed by: RGD

Drawn by: PFL

Checked by: RLA

Submitted by: WEE


Scale: AS SHOWN



Date: DECEMBER 1988

Sheet number: 1

File No.: RBL-3-1582

PLATE NO. 106





Revisions		Date	Approved
Symbol	Descriptions		

U S ARMY ENGINEER DISTRICT
CORPS OF ENGINEERS
KANSAS CITY, MISSOURI


DESIGNED BY: RGD
DRAWN BY: MJK
CHECKED BY: RLA
SUBMITTED BY: WBE


LITTLE BLUE RIVER, MISSOURI
LONGVIEW LAKE
EMBANKMENT CRITERIA AND
PERFORMANCE REPORT
PIEZOMETER PLOTS
OPEN TUBE PZ
PPE 92-1



Scale: AS SHOWN
Date: DECEMBER 1986
Draw No: 1 OF 2

Sheet number: 1
File No: RBL-3-1583

PLATE NO. 107








Revisions			
Symbol	Description	Date	Approved
	Revised March 1990		


U S ARMY ENGINEER DISTRICT
CORPS OF ENGINEERS
KANSAS CITY, MISSOURI


DESIGNED BY: RGD
DRAWN BY: DML
CHECKED BY: RLA
SUBMITTED BY: WBE


**LITTLE BLUE RIVER, MISSOURI
LONGVIEW LAKE
EMBANKMENT CRITERIA AND
PERFORMANCE REPORT
PIEZOMETER PLOT
2" OPEN TUBE PVC
PPE 92-2**


Scale: AS SHOWN
Date: DECEMBER 1986
Sheet: 1 of 2
File No: RF-3-1585











VALUE E

VALUE ENGINEERING PAYS

3

2

1

D

C

B


A

LEGEND

- PZ PRESSURE CELL PIEZOMETER
- PZ OPEN TUBE PIEZOMETER
- PP PRESSURE CELL PORE PRESSURE DEVICE
- PP OPEN TUBE PORE PRESSURE DEVICE
- MB MONITOR BOX

-
-
-
-
-

2001 1998 1999 2000 2001 2002 2003 2004 2005 2006 2007 2008 2009 2010 2011 2012 2013




Symbol	Revisions	Date	Approved
	Descriptions		
<p>U.S. ARMY ENGINEER DISTRICT CORPS OF ENGINEERS KANSAS CITY, MISSOURI</p>			
Designed by	R.G.D.	LITTLE BLUE RIVER, MISSOURI LONGVIEW LAKE EMBANKMENT CRITERIA AND PERFORMANCE REPORT	
Drawn by	J.W.P.	PIEZOMETER PLOTS PNEUMATIC PZ PPE 94-1	
Checked by	W.B.E.	AS SHOWN	1211
Submitted by	W.B.F.	JULY 1990	PIEZOMETER PLOTS
		OF	RBL-3-1580


3


2


1

PLATE NO. 112









WICK #5

Downstream

Immersive

3' Pervious Blanket

Overburden
Top of rock

Revisions			
Symbol	Descriptions	Date	Approved

U S ARMY ENGINEER DISTRICT
CORPS OF ENGINEERS
KANSAS CITY, MISSOURI

Designed by: RGD

Drawn by: EER

Checked by: RLA

Submitted by: WBE

Scale: AS SHOWN


Date: DECEMBER 1986



Dwg No: 1 of 2

Sheet number:

File No: RBL-3-1590

PLATE NO. 114





Revisions		Date	Approved
Symbol	Descriptions		
	Revised March 1990		


U S ARMY ENGINEER DISTRICT
CORPS OF ENGINEERS
KANSAS CITY, MISSOURI

DESIGNED BY: RGD
DRAWN BY: ECR
CHECKED BY: RLA
SUBMITTED BY: WHE

LITTLE BLUE RIVER, MISSOURI
LONGVIEW LAKE
EMBANKMENT CRITERIA AND
PERFORMANCE REPORT

PIEZOMETER PLOTS
OPEN TUBE PZ
PPF 99-4

AS SHOWN
DECEMBER 1986
2 of 2
RBI-3-1680



3

2


1

D

C

B

A






3

2

1

PLATE NO. 116





Revisions			
Sym. of	Descriptions	Date	Approved
	Revised March 1990		

U. S. ARMY ENGINEER DISTRICT
CORPS OF ENGINEERS
KANSAS CITY, MISSOURI


Design: RGD
Drawn: EER
Checked: RLA
Submitted: WBI


**LITTLE BLUE RIVER, MISSOURI
LONGVIEW LAKE
EMBANKMENT CRITERIA AND
PERFORMANCE REPORT**


**PIEZOMETER PLOTS
PNEUMATIC PZ
PPE 99-8**

Scale: AS SHOWN
Date: DECEMBER 1986
Dwg No: 2 of 2

Sheet Number:
File No: RBL-3-1682







VALUE

VALUE ENGINEERING PAYS

3

2

1

DEVICE

FALL AT DEVICE

PLUGGED

D

C

B

A

LEGEND

PZ PRESSURE CELL PIEZOMETER
 PZ OPEN TUBE PIEZOMETER
 PP PRESSURE CELL PORE PRESSURE DEVICE
 PP OPEN TUBE PORE PRESSURE DEVICE
 MB MONITOR BOX

□
 ○
 ■
 ●
 ⊞

950

940

930

920

910

900

890

880

870

860

850

840

830

820

810

800

790

J F M

M J J A S O N D J F M A M J J A S O N D J F M A M J J A S O N D

1989

1990

1991

200
 850
 800

1+00 2+00 3+00 4+00 5+00 6+00

3

2

1

PLATE NO. 119

Revised March 1990

U.S. ARMY ENGINEER DISTRICT
 CORPS OF ENGINEERS
 KANSAS CITY, MISSOURI






LITTLE BLUE RIVER, MISSOURI
 LONGVIEW LAKE
 EMBANKMENT CRITERIA AND
 PERFORMANCE REPORT


PIEZOMETER PLOTS
 PNEUMATIC PZ
 PPE 99-II


DECEMBER 1986


1100.65) PROFILE
 RBL-3-1684





REVISED (Date of Revision)		Date	Approved
Revised March 1990			
U.S. ARMY ENGINEER DISTRICT CORPS OF ENGINEERS KANSAS CITY, MISSOURI			
NAME PM	 US Army Corps of Engineers	LITTLE BLUE RIVER, MISSOURI LONGVIEW LAKE EMBANKMENT CRITERIA AND PERFORMANCE REPORT	
DESIGN BY ROT		PIEZOMETER PLOTS OPEN TUBE PZ W-6	
DRAWN BY H. A.	SIZE A1, SHOWN	SHEET NUMBER	PLOT SCALE 12:1
CHECKED BY J. M.	DATE DECEMBER 1986		DESIGN TITLE (100,65) PROFILE
			FILE NO. RBL-3-1685





Revisions			
Symbol	Descriptions	Date	Approved

**U S ARMY ENGINEER DISTRICT
CORPS OF ENGINEERS
KANSAS CITY, MISSOURI**

Designed by RGD	<p>LITTLE BLUE RIVER, MISSOURI LONGVIEW LAKE EMBANKMENT CRITERIA AND PERFORMANCE REPORT INCLINOMETER DISPLACEMENTS I-99-1</p>	Scale A3 SHOWN	Sheet number
Drawn by DEJ		Date DECEMBER 1986	
Checked by RLA			
Submitted by WBE			

File No. **RBL-3-1697**

↓
3

4

5


D

C


B

A


LONGVIEW LAKE I-99-1 R2+570




LONGVIEW LAKE I-99-1 R2+570



LONGVIEW LAKE I-99-2 R0+85U



LONGVIEW LAKE I-99-2 R0+85U



5


4

3


↑

VALUE ENGINEERING PAYS

LONGVIEW LAKE Y-99-1 R2+570





LO'GV IEN LAKE I-33-2 R0+85U




Symbol	Revisions	Descriptions	Date	Approved

U.S. ARMY ENGINEER DISTRICT
CORPS OF ENGINEERS
KANSAS CITY, MISSOURI

Designed by:	WBE	 U.S. Army Corps of Engineers	LITTLE BLUE RIVER, MISSOURI LONGVIEW LAKE EMBANKMENT CRITERIA AND PERFORMANCE REPORT	
Drawn by:	KOS		INCLINOMETER DATA PLOTS 1-99-1 AND 1-99-2	
Checked by:	LLL			
Submitted by:	ROG		Scale: AS SHOWN Date: JANUARY 1991 Dwg. No.:	Sheet number: Plot Scale: Design File: File No.:



INCLINOMETER I-99-3
TOTAL AND INCREMENTAL UPSTREAM DISPLACEMENT VS TIME
DEPTH 74.5' ELEVATION 827.0



PLACEMENT VS. TIME

827.0

Revisions			
S. mbol	Descriptions	Date	Approved


U. S. ARMY ENGINEER DISTRICT
CORPS OF ENGINEERS
KANSAS CITY, MISSOURI

Designed by: R. G. D.
Drawn by: F. S. M.
Checked by: R. L. A.
Submitted by: W. B. F.

**LITTLE BLUE RIVER, MISSOURI
LONGVIEW LAKE
EMBANKMENT CRITERIA
AND PERFORMANCE REPORT
INCLINOMETER DISPLACEMENTS
I-99-3**

Scale: AS SHOWN
Date: DECEMBER 1986
Sheet Number: 1

RBL-3-1699




VALUE ENGINEERING PAYS

3


2

1

LONGVIEW LAKE 1-99-3 R1-80 U.S.



LONGVIEW LAKE 1-99-3 R1-80 U.S.



Symbol	Revisions	Descriptions	Date	Approved

U.S. ARMY ENGINEER DISTRICT
CORPS OF ENGINEERS
KANSAS CITY, MISSOURI

LITTLE BLUE RIVER, MISSOURI
LONGVIEW LAKE
EMBANKMENT CRITERIA
AND PERFORMANCE REPORT

INCLINOMETER DATA PLOTS
1-99-3 AND 1-97-1

Designated by: WBE
Order by: ADS
Checked by: LLS
Submitted by: RDU

AS SHOWN
JANUARY 1998

RBL-3-1700

3

2